

## Replace the defect valves

### Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**  
**IN THE HUB:**

Check the hydraulic circuit diagram.


Relevant documentation	
Description	DMS No.
Pitch Hydraulic circuit (Parker) Main manifold Diagram	<a href="#">5003018</a>
Pitch Hydraulic circuit (Parker) Pitch manifold Diagram	<a href="#">5003013</a>
Pitch Hydraulic circuit (Rexroth) Main manifold Diagram	<a href="#">5003347</a>
Pitch Hydraulic circuit (Rexroth) Pitch manifold Diagram	<a href="#">5003025</a>
Pitch Hydraulic circuit (Rexroth) Filter manifold Diagram	<a href="#">5002046</a>


Check the three blade pitch pressure through controller if any drop while turbine in the operation.


If anyone blade pitch pressure is drop –check the affected blade pitch hydraulic system.


If all three pitch pressure is drop – check the main distribution block hydraulic system.

**Circuit pressure line reference:**

 Pilot pressure line

 High pressure line


 Low pressure line

 Medium (Flush) Pressure

Relevant documentation	
Description	DMS No.
Hydraulic Pitch Control System Supplier Parker	<a href="#">0001-3199</a>

Main distribution block when pump pressurizing mode:

Hub Manual Mode: Press "R" then pitch to run, stop, pulse or charge.



Check the valve operation. If valve defect replace with new.


**Part number for valves:**

### Relevant spare parts

Description	Item No.	Position
CHECK VALVE, 0,3 BAR, 375L	<a href="#">60111616</a>	410
CHECK VALVE, 0,3 BAR, 82L	<a href="#">60111613</a>	425, 455
SOL. VALVE NO, DS201 NR	<a href="#">60112645</a>	440
COIL, 30 WATT 24 VDC DIN PLUG	<a href="#">60112646</a>	
RELIEF VALVE, RDH-08-2-S-50, 138 - 345 BAR	<a href="#">60112643</a>	435
RELIEF VALVE, RDH-08-2-S-30, 69 - 207 BAR	<a href="#">60104030</a>	437
SOL. VALVE NO, DSH081 NL	<a href="#">60112647</a>	445
COIL 24VDC DIN PLUG S8LDD024	<a href="#">60104025</a>	445A
NEEDLE VALVE, NVH-2201	<a href="#">60104032</a>	447
KNOB FOR NEEDLE VALVE	<a href="#">60112623</a>	447A



Pitch distribution block when turbine in ready for operation mode:



Check the below position valves,

Swap the valves one by one in to other manifolds and check valve operation.


If fault shifted to other blades the valve likely defect. If not check other valves.

**Part number for valves:**

Relevant spare parts		
Description	Item No.	Position
CHECK VALVE PILOT:CVEV-XCN A30	<a href="#">60096481</a>	230, 250




NEEDLE VALVE, NVH-2201	<a href="#">60104032</a>	222
KNOB FOR NEEDLE VALVE	<a href="#">60112623</a>	222A
3/2 DIRECTIONAL VALVE	<a href="#">60111617</a>	210, 215
LOGIC ELEMENT PIL. OPERATED	<a href="#">60111630</a>	240, 245
PRESSURE CONTROL VALVE: RDDT-QWN	<a href="#">60096477</a>	220
CHECK VALVE CVH103P20	<a href="#">60112628</a>	235
PROP. VALVE D31FHE01C	<a href="#">60112621</a>	205



## REXROTH SYSTEM -MAIN MANIFOLD:

Main distribution block when pump pressurizing mode:



Check the below position valves,

Check the valve operation. If valve defect replace with new.



Part number for valves:

Relevant spare parts		
Description	Item No.	Position
ACCUM HYDR 0BAR 0.7L 1/2" BS	<a href="#">103805</a>	475
CHECK VALVE: M-SR 15 KE02-1X/	<a href="#">60096479</a>	410, 425
PRESSURE CONTROL VALVE: KBD2HO	<a href="#">60096503</a>	437
VLV SOLENOI KSDER1PA/HG24N9K4M	<a href="#">60098803</a> (phased out)	445
CHECK VALVE COFA-XBN	<a href="#">60099554</a>	430

The part No. 60098803 is phased out. It is replaced by 780430.

Relevant spare parts		
Description	Item No.	Status
VLV SOLENOI KSDER1PA/HG24N9K4M	<a href="#">60098803</a>	Phased out
KSDER1PB/HN9V F BRAKE UNIT 3MW	<a href="#">780430</a>	Available

The part No.60096475 is phased out and henceforth replaced by 109795 & 60106201.


Pos. 210 & 215

Relevant spare parts		
Description	Item No.	Status
SOL VAL KSDEU1CA/HCG24N0K4M	<a href="#">60096475</a>	Phased out

ELECTRIC SEAT VALVE	<a href="#">109795</a>	Available
COIL GZ37-4 24VDC 19W	<a href="#">60106201</a>	Available


(Rexroth) Valve/Solenoid





**109795**

---




REXROTH SYSTEM -PITCH MANIFOLD:

Pitch distribution block when turbine in ready for operation mode:

Normal operation, pitch to RUN

Item	Action
V215	Energized: operation to run
V240	Closed
V245	Closed
V210	Energized
V230	Open
V235	Open
V205	Prop.-valve take position "open to run" acc. to 4-11,8 mA. The actuator is taking a corresponding position
V230	Oil is drained from the
V205	actuator's plus side to the return line.

Ready  
Ready  
Ready  
Ready



Check the below position valves,

Swap the valves one by one in to other manifolds and check valve operation.

If fault shifted to other blades the valve likely defect. If not check other valves

**Part number for valves:**

### Relevant spare parts

Description	Item No.	Position
THROTTLE VALVE NFCC-LCN A40122	<a href="#">105103</a>	222
PROP VAL 4WREE 10R75-2X/G24K31	<a href="#">60078979</a>	205
PRESSURE CONTROL VALVE: RDDT-QWN	<a href="#">60096477</a>	220
CHECK VALVE: M-SR 15 KE02-1X/	<a href="#">60096479</a>	225
CHECK VALVE: CXFA-XFN A30314JG	<a href="#">60096480</a>	226
CHECK VALVE PILOT: CDEV-XCN A30	<a href="#">60096481</a>	230, 235, 250
VALVE CHECK PILOT COFA-XAN A30	<a href="#">60096493</a>	240, 245

The part No.60096475 is phased out and henceforth replaced by 109795 & 60106201.

(Rexroth) Valve/Solenoid(Pos. 210 & 215)

Relevant spare parts		
Description	Item No.	Status
SOL VAL KSDEU1CA/HCG24N0K4M	<a href="#">60096475</a>	Phased out
ELECTRIC SEAT VALVE	<a href="#">109795</a>	Available
COIL GZ37-4 24VDC 19W	<a href="#">60106201</a>	Available

REXROTH NEEDLE VALVE TYPE-1 (POS: 447, 222)


Relevant spare parts



Description	Item No.
THROTTLE VALVE: NFBC-KCN A3031	<a href="#">60096478</a>
HANDLE FOR NFBC-KCN A30316JG01	<a href="#">60109005</a>

#### REXROTH NEEDLE VALVE TYPE-2 (POS: 447, 222)

Relevant spare parts	
Description	Item No.
THROTTEL VAVLE NFCC-LCN A40122	<a href="#">105103</a>
- HANDLE FOR THROTTLE VALVE NFCC	<a href="#">60112482</a>



Refer the service work instructions for more details,

Relevant documentation	
Description	DMS No.
Change of Valve in Parker Pitch Manifold	<a href="#">0002-4365</a>
Distribution Manifold Replacement	<a href="#">0021-3758</a>
Fast Active Stall Hydraulics Valve replacement	<a href="#">1000778</a>
Fast Active Stall System	<a href="#">0001-1672</a>

**Check the compensator valve setting and replace the defect valve**

### Does this solve the problem?

1] Yes

2] No


3] I don't know

- **Explanation  
IN THE HUB:**

Check the compensator valve (relief valve) setting in the hydraulic pitch pump.

Relevant documentation	
Description	DMS No.
Pressure Relief Valve Setting	<a href="#">0006-8149</a>

### REXROTH SYSTEM:






Part number for Rexroth compensator valve:

Relevant spare parts	
Description	Item No.
VALVE DFR1 RAL7032 240/14 BAR	<a href="#">60113742</a>


PARKER SYSTEM:







In parker hydraulic system have two different type of compensator valve,  
Ensure the valve type before replacing new valve.



Part number for Parker compensator valve:


Relevant spare parts		
Description	Item No.	
HYDR PUMP PRESSURE CONT. VALVE	<a href="#">60114042</a>	Old type
HYDR PRES. COMP. VALVE 245/15	<a href="#">60114132</a>	New type

Perform a visual inspection of the back of the pitch cylinder bore.

### Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**



The back 250 mm of the pitch cylinder bore may be susceptible to excessive wear. This area of the cylinder is where the piston operates during production. When excessive wear occurs in the cylinder barrel, the piston seals are also subjected to accelerated wear, and internal leakage will occur in both run and stop positions. The effect of this leakage is excessive pump run time during operation as well as during stop. In the event of a pump failure, grid outage or certain turbine faults, pressure within the accumulators will bleed off, and blades may be at risk of being pushed into the run position under high wind conditions. Check the back of the bore for abnormal wear.

### Actions:

Refer to DMS doc 0059-1574 for inspection instructions and criteria for running the turbine if wear is found.

Relevant documentation	
Description	DMS No.
V-82 Pitch Ram Bore inspections	<a href="#">0059-1574</a>
V82 Rexroth pitch ram installation on a Parker pitch system	<a href="#">0059-7339</a>

Relevant CIM case		
CIM case	Task list	Service Message
<a href="#">3699</a>	23210	<a href="#">0059-3323</a> Evo2 Pitch Cylinder Wear

## Replace the defect Proportional Valve and defect cables

### Does this solve the problem?

1] Yes


2] No

3] I don't know

- **Explanation**  
**IN THE HUB:**


First swap the signal wire to the proportional valve on the hub computer.

If the fault follows to the new blade then the fault is either in the proportional valve or one of the cables.



In the example below, we are swapping the plugs between blades A and B.





Place the cables back to their original position and then swap proportional valve from affected blade to another working blade.

If the alarm follows the valve to the other blade, the proportional valve is defective.

If it does not, the proportional valve is likely not the cause.

For Parker proportional valves check to see the color of the LED on the valve circuit board.


**Relevant documentation**



Description	DMS No.
V82 Hydraulic pitch control system	<a href="#">0001-3199</a>


The LED should be green with the pitch system pressurized.

If it is red and there is pressure verified on test port MP, then the valve may also be defective.



<b>Display Color</b>	<b>Indicates</b>
Green	Normal operation
Off	Supply voltage outside permissible range of 18 to 30 VDC
Red	Spool position error / Low pilot pressure

<b>Relevant documentation</b>	
<b>Description</b>	<b>DMS No.</b>
Replacement of proportional valve	<a href="#">0016-1690</a>





**Proportional Valve Item numbers:**

Relevant spare parts		
Description	Item No.	
PROP. VALVE D31FHE01C	<a href="#">60112621</a>	Parker
PROP VAL 4WREE 10R75-2X/G24K31	<a href="#">60078979</a>	Bosch Rexroth
Cable W 956 Proportional valve Y0205.0-1	<a href="#">60021544</a>	

CIM:

Relevant CIM case		
CIM case	Description	Task list
<a href="#">2303</a>	Proportional valve failure – Parker V82 1.65MW	14333
<a href="#">1914</a>	Proportional valve failure – Bosch Rexroth V82 1.65MW	14334

**Check the accumulator pre-charge pressure and recharge the accumulators**

**Does this solve the problem?**

1] Yes

2] No

3] I don't know

**Explanation**  
**IN THE HUB:**

Check the all pitch accumulator pre-charge pressure.

Low pressure accumulators also cause this alarm.

If any low pressure accumulators recharge as per SWI

Relevant documentation	
Description	DMS No.
Charging of Nitrogen Accumulators	<a href="#">941918</a>
Blade Accumulator Exchange	<a href="#">0001-2871</a>


If any failure accumulator replace with new:

Relevant spare parts		
Description	Item No.	
HYDR ACCU 20 L 115 BAR DUAL	<a href="#">60113096</a>	NM72
HYDR ACCU 24.5 L 115 BAR DUAL	<a href="#">60113097</a>	V82 other than Australia
HYDR ACCU 24.5 L 115 BAR AS1210	<a href="#">60113098</a>	V82 Australia

Check accumulator retrofit installation

Relevant documentation	
Description	DMS No.
Accumulator Retrofit Installation	<a href="#">0000-9402</a>





**Replace the defect actuator or replace the defect seal**


**Does this solve the problem?**

- 1] Yes
- 2] No
- 3] I don't know

**Explanation**  
**IN THE HUB:**


Check the Actuator rod surface thoroughly if any punch mark or damage.

Check the actuator seal if any damage or seal parts come out from push,



Check the oil leak when actuators in operation with system pressure.

If found actuator seal failure replace with new seal kit.



**PARKER System:**

Relevant spare parts		
Description	Item No.	
HYDR CYL 125/90x884 COMPLETE	<a href="#">60120439</a>	Actuator with manifold
HYDR CYL BUSHING W. SEALS ø90	<a href="#">60114033</a>	Seal with Bush



**REXROTH System:**

Relevant spare parts		
Description	Item No.	
ACTUATOR Ø140 WITH Ø100 TRUN.	<a href="#">60096442</a>	Actuator with manifold
ACTUATOR SEAL KIT	<a href="#">60110956</a>	Seal kit alone






Relevant documentation	
Description	DMS No.
V82 Pitch Actuator Exchange	<a href="#">0021-4366</a>
Pitch Actuator Piston Rod Replacement	<a href="#">0023-2047</a>

**Parker Return Hose Part number details:**

Relevant spare parts	
Description	Item No.
PIPE DRAINASSY	<a href="#">60120766</a>
EO HIGH PRESSURE BANJO TEE	<a href="#">60120767</a>
VALVE NON RETURN	<a href="#">60120764</a>
SWIVEL NUT ELBOW	<a href="#">60120765</a>
EO TEST POINT M16X2 FOR CONE	<a href="#">60120768</a>





ITEM	TITLE
#1	Seal Bushing Assembly
#2	Non return valve - 3 bar opening pressure
#3	Swivel nut elbow
#4	Drain pipe assembly PH080236
#5	EO High pressure banjo tee
#6	EO Test Point with threaded connection M16x2 for cone

Ensure proper fixing and installation

