

## Locate and repair leak

### Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**

Check for external leakage in nacelle and hub.


Check level of oil in tank after opening 222 needle valves on blade manifolds in hub. Note: open valves slowly to prevent hydraulic oil from being trapped in accumulators.



Mk3-5 turbines: Ensure the oil level is between the marks on the dip stick:




Mk1-2 turbines: Ensure the oil level is ~5cm from the lip on the tank.



Likely sources of leaks:

1. Parker system 410 Valve O-Ring (O-Ring replacement is usually a short term fix and the valve should be replaced to permanently alleviate the issue). [60111616](#)-CHECK VALVE, 0,3 BAR, 375L
2. Valve 225 on Blade manifold might have O-ring failure. Replace the Valve. [60111613](#)-CHECK VALVE, 0,3 BAR, 82L(Picture of damaged O-ring below)
3. Actuator seals. Replace actuator seals in accordance with [0009-1962](#) "Replacement of Actuator End Seal".
4. Proportional valve O-Rings. Usually a slow leak. If affected, valve should be replaced (Confirm that it is in the population for [CIM2303](#). O-ring seats may have burs so replacing O-ring will only be a temporary repair).
5. Compensator valve O-Rings. (Also a temporary repair, replacing the compensator is a permanent repair).
6. Filter housing O-Rings.
7. Filter housing manifold connection to main manifold loose (usually RexRoth).
8. Hoses and fittings.
9. Test nipple in blade manifold- MA position



Relevant spare parts	
Description	Item No.
TEST COUPLING 1/4"BSP FOR M16-	<a href="#">60037889</a>







- Check low pressure filter at nacelle for 'O' ring dislocate or damage which might cause the oil leakage. Ensure the filter is assembled as per supplier recommendations. Failure seal to be replaced and filter to be assembled as per below guidelines.

Relevant spare parts	
Description	Item No.
FLTR ELEMENT DONALDSON K513/01	<a href="#">60067838</a>



- few important installation instructions which mentioned in the filter housing as shown below;



- As per OEM as well as Vestas recommendation, these filters to be tighten with hand. Hence do not use ratchet or any type of tools for tightening which might cause over tightening issue which will damage the seal (O ring).



**Hand tighten the filter.**

- Tighten per the guidance of the icons which appear on the filter housing. Do not over-tighten.



- “Apply thin film of clean hydraulic oil on the O rings to lubricate” before start assembly, this will give smooth pressure across the entire O ring while tightening as shown below;





**Apply thin film of clean motor oil to gasket.**

- Lubricate seal(s) with clean system oil.



- Also lubricate the threads of filter assembly area with clean system oil



**Lubricate the threads.**

- Lubricate threads of filter head.

#### **Replace level switch**

**Does this solve the problem?**

1] Yes

2] No


3] I don't know

- **Explanation**

If oil level in tank is ok, check cable to level sensor and the level sensor itself. Remove level sensor from tank by disconnecting the electrical plug and turning the sensor counter clockwise

OLD STYLE FLOAT SENSOR:










NEW STYLE FLOAT SENSOR:



**NOTE:** Older plastic versions of the sensor should be replaced with the new version whenever removed from the tank as the old sensor floats are susceptible to deterioration and can come off into the tank when attempting to remove.

Test the level sensor using a multi-meter (unless you have three hands, use alligator clip probes on the multi-meter). Set the multi-meter to read  $\Omega$ .





Slide the float up the sensor shaft a few centimetres





Watch the resistance value on the multi-meter.

The value should change from OL to a low Ohm value when the float is in the position pictured.

If the value does not change or is unrealistic, replace the float sensor.





Relevant spare parts	
Description	Item No.
NIVEAUCONTROL HMFB-VT = 250 MM	<a href="#">60073714</a> (Screw Type)
LEVEL CONTROL LM1CTPA260 NA	<a href="#">60112817</a> (Thread Type)

**Install CIM 1902 CIM upgrade**

### Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**

Relevant CIM case		
CIM case	Task list	SWI
<a href="#">1902</a>	13447	See Doc.Table

Relevant documentation	
Description	DMS No.
SM CIM 1902 (Information on hydraulic oil tank shim instillation and background).	SM <a href="#">0014-2424</a>
Instructions on installing hydraulic oil tank shims. (Solution only applies to the Mk 3-5 V82).	WKI <a href="#">0010-7662</a>

### Pre-charge Accumulators

#### Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**

If oil level is not ok, and no external leakage is found, check pre-charge of accumulators in hub.





Relevant documentation	
Description	DMS No.
Relevant item numbers for tools and nitrogen	<a href="#">941918</a>
Replacement failed accumulators	<a href="#">0001-2871</a>

(Failed accumulators will consume much of the system volume of oil, as the nitrogen is not present in the bladders and cannot push the oil back to tank).

### Replace proportional valve if leaking

Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**

Proportional Valve leakage observed not from the port but at the joints.

Replace the Proportional valve this is the case.

Relevant spare parts	
Description	Item No.
PROP. VALVE D31FHE01C (Parker)	<a href="#">60112621</a>
PROP VAL 4WREE 10R75-2X/G24K31	<a href="#">60078979</a>



Below picture shows damaged O-ring.



**Repair/ Replace the Rotating Union**

**Does this solve the problem?**

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**

Check and repair/ replace Rotating Union, if found oil leakage.







Relevant spare parts	
Description	Item No.
ROTATING UNION 1760-1" K	<a href="#">60065484</a>