

930 - Internal battery low - NM72,NM82,V82 Mk1-5



Replace battery with a new

**Does this solve the problem?**

1] Yes

2] No

3] I don't know

- [Explanation](#)

Replace the existing battery in the TAC Controller with a new battery from inventory.

[60000698](#) BAT LS14500 3.6V 2.25Ah SAFT

This procedure must be performed with the TACII controller powered up. If the battery is removed when the TACII is powered down, stored data in the controller will be lost.


Remove **only** all connectors in the top of the controller:



Unscrew the back panel of the TAC (pay close attention not to touch anything else other than the battery, even it's only 18 Vac):



The backup battery is located in the top right corner as seen from the back of the controller:



930 - Internal battery low - NM72,NM82,V82 Mk1-5



Replace TAC II

**Does this solve the problem?**

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**

If the backup battery is replaced with new, and the alarm persists, double check that the battery polarity is correct.  
If the polarity is correct, replace the TACII controller.