

Replace the cable

Does this solve the problem?

1] Yes

2] No

3] I don't know


- **Explanation**

Check the cable for obvious physical damage.

Check the connection from the sensor switch connector to X15 in hub computer panel AK4.

Check the continuity of the cable. If the cable is found to be damaged, replace the cable.

Relevant spare parts	
Description	Item No.
CABLE W900 FILTER CLOG -B406	60021519



Replace the switch

Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**

Check the switch for obvious physical damage.

Check the ports on the sensor for debris that may be clogging the unit.

Check the connector of the sensor for damage.



Relevant spare parts		
Description	Item No.	
Indicator FPC.T25.VM-NPN	60073370	Obsolete part no - PARKER
FPC.T25.BM Diff. Indic. 125VDC	60067777	New part no. - PARKER
INDICATOR F FLTR PIS3092-5.0	60098798	Bosch Rexroth

Replace the Filter

Does this solve the problem?

1] Yes

2] No


3] I don't know

- **Explanation**

The high pressure filter in the hub is replaced at every service and therefore is not commonly contaminated to the point of setting this fault. If through the process of elimination, it is determined that the filter is clogged, replace the filter.

Relevant spare parts

Description	Item No.
FILTER ELEMENT, 5MY, FC7007.Q005.BK - PARKER	60112661
FILTERELEMENT 0160 DN 006BN/HC – BOSCH REXROTH	60096498



Replace the Hub computer

Does this solve the problem?


1] Yes

2] No

3] I don't know

- **Explanation**

Visually inspect the connector at the hub computer. Inspect for damage, contamination or corrosion. If the connector on the hub computer printed circuit board is damaged beyond repair, replace the hub computer. If there is contamination or corrosion, clean the connector and pins.



Relevant spare parts	
Description	Item No.
SIF HUB COMPUTER CABINET EVOII	51701801