

Replace the defective TAC84 module

Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**
IN THE +AN1 CABINET:

Check the TAC84 module parameters as per instruction:

Settings for TAC 84 Edgewise blade vibrations **DMS: [17000068](#)**

Also refer to the TAC84 User manual **DMS: [5002041](#)**



Perform the test as per commissioning manual :

5.17 Testing Safety Functions **DMS: [0000-9925](#)**



Check the TAC84 module for any loose connections.
If the module is found to be defective, replace with new.

Vibration / Overspeed TAC 84 connections:



Part Number for TAC84 module 2 Filter (U03)

[51701001](#) - TAC 84C VIB GUARD 2 FILTERS

Replace the defect speed sensor

Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**
AT THE GENERATOR:

Check the generator speed sensor for any physical damage or dirt.

Check the RPM value through TAC84 Module.

If found to be defective replace the sensor.

Sensor part number:

[60009270](#) - PROXI SWITCH I1808PPOS1531 Ø18



Adjust the distance between the Inductive sensor and the scanning points as per Instalation and service data
DMS: [5003033](#)