

Perform the blade calibration as per the WKI

Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**
IN THE Nacelle:

Do the blade calibration. Original calibration may be altered during component replacement, such as position sensors (Balluf), cables, proportional valves and hub computer.

Section 5.10.9 'Blade Position Calibration during manual pitching in the Nacelle Mode' of the Commissioning Manual.

| Relevant documentation | |
|---|---------------------------|
| Description | DMS No. |
| Commissioning instruction V82 -1.65-Mk4 | 0000-9925 |
| Blade Pitch System Test | 0002-0467 |

Replace the defective power net

Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**
IN THE HUB:

Check for any loose connections at the power net (Pos: G401).

Check input and output voltage 230/115VAC /24VDC

If defective replace the power net.



Relevant CIM case

| CIM case | Task list | SWI |
|----------------------|-----------|-----|
| 1390 | | |

Relevant spare parts

| Description | Item No. |
|-------------|----------|
|-------------|----------|

PS ADC 5483R-3 10A-27,4 NM PIN

[188453](#)

Check the accumulator pre-charge pressure and recharge the accumulators

Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation
IN THE HUB:**

Check all of the pitch accumulator pre-charge pressures.

If nitrogen pressure in any of the accumulators are low, recharge.

Relevant documentation

| Description | DMS No. |
|-----------------------------------|---------------------------|
| Charging of Nitrogen Accumulators | 941918 |
| Blade Accumulator Exchange | 0001-2871 |

Check accumulator retrofit installation


Relevant CIM case

| CIM case | Task list | SWI |
|----------|-----------|-----|
|----------|-----------|-----|

| | | |
|----------------------|--|---------------------------|
| 1168 | | 0000-9402 |
|----------------------|--|---------------------------|

If the bladder in the accumulator has failed, replace the accumulator.

| Relevant spare parts | |
|--|--------------------------|
| Description | Item No. |
| HYDR ACCU 20 L 115 BAR DUAL (NM72) | 60113096 |
| HYDR ACCU 24.5 L 115 BAR DUAL (V82 other than Australia) | 60113097 |
| HYDR ACCU 24.5 L 115 BAR AS1210 (V82 Australia) | 60113098 |



Replace the defective Pitch position sensor and defective cables

Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation
IN THE HUB :**


Check for any loose connections in the hub computer terminal X19.

Check for any loose connections on the Blade position sensor.






Swap the signal wire to the position transducer (Balluff) on the hub computer. If the fault follows to the new blade then the fault is either in the position transducer or one of the cables.



In the example below, we are swapping the plugs between blades C and B.



Place the cables back to their original position and then swap pitch position sensor from affected blade to another working blade.

If the alarm follows the valve to the other blade, the pitch position sensor is defective.

If it does not, the pitch position sensor is likely not the cause.

Pitch position sensor



Service Module



Check the cable for any or short due to the cable rubbing near the hub casting or friction between the cable and the hydraulic hose.

Replace any defective cables.

| Relevant spare parts | |
|-------------------------------|--------------------------|
| Description | Item No. |
| TRANSDUCER BTL5-E10-M0950-A-S | 60098816 |

| | |
|----------------------------------|--------------------------|
| SERVICEMODUL, BTL5 - E10 | 60102394 |
| Cable W 923 Pos.transducer 1 Std | 60101018 |
| Cable W 924 Pos.transducer 2 Std | 60101148 |
| Cable W 925 Pos.transducer 3 Std | 60101149 |

Check the blade bearing greasing system and replace the failed components

Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**
IN THE HUB:

Manually operate the grease pump from the controller.

Check that the grease reaches all lubrication points on all blades.

| Relevant documentation | |
|---|-------------------------|
| Description | DMS No. |
| SII for Lubrication Unit for Blade Bearings | 1001450 |


Check that the grease flows from all of the ports:



Inspect for any damaged hose fittings, manifold grease blockage or hose damage.

If necessary replace the manifolds and hoses.


Blade bearing greasing system:



Part number details for Blade bearing Greasing system:

| Relevant spare parts | |
|--|--------------------------|
| Description | Item No. |
| GREASE PUMP P203 std.(with Molykote2+ grease) | 60112213 |
| GREASE PUMP P203 ARCTIC (with Fuchs Stabyl LT50 grease) | 60067070 |
| PUMP - BRG. GREASING SYS - STD | 60073006 |

| | |
|--------------------------------|--------------------------|
| WING PL BRG. GREASING SYS –STD | 60094070 |
|--------------------------------|--------------------------|



Part number for Grease pump with main manifold and hoses

(does not include blade hoses& manifolds)




Part number for full set of Slave manifolds (3 EA) with hose and accessories:



Sub - Part number details for hose accessories

| COMPONENT | DESCRIPTION | QUANTITY PER | UM | Remarks |
|-----------|---------------------------------|--------------|----|---|
| 60067073 | METERING DEVICE "PRIMARY" | 1,000 | EA | Distributor Manifold |
| 60080996 | GREASE HOSE ASSEMBLY (1210 MM. | 1,000 | EA | Hoses from pump to Distributor manifold to Slave Manifold |
| 60080997 | GREASE HOSE ASSEMBLY (390MM) | 2,000 | EA | |
| 60080998 | GREASE HOSE ASSEMBLY (7840 MM. | 2,000 | EA | |
| 60080999 | GREASE HOSE ASSEMBLY (6290 MM. | 1,000 | EA | |
| 60111921 | Protective hood /m.strop red | 1,000 | EA | Fittings& Accessories for above hose&Manifold |
| 60111922 | Elbow LL6MMx1/8K | 1,000 | EA | |
| 60112211 | Check valve 1/6, high pressure | 4,000 | EA | |
| 60112212 | Protective cap f. quick fittin | 4,000 | EA | |
| 60067074 | METERING DEVICE "SECONDARY" | 1,000 | EA | Slave Manifold (for 1 blade) |
| 60067085 | HOSE 1/6 x 320MM (CUT LENGTH) | 1,000 | EA | Hoses from Slave manifold to Blade bearing (for 1 blade) |
| 60067086 | HOSE 1/6 x 490MM (CUT LENGTH) S | 1,000 | EA | |
| 60067087 | HOSE 1/6 x 1200MM (CUT LENGTH) | 1,000 | EA | |
| 60067088 | HOSE 1/6 x 1380MM (CUT LENGTH) | 1,000 | EA | |
| 60067089 | HOSE 1/6 x 2080MM (CUT LENGTH) | 1,000 | EA | |
| 60067090 | HOSE 1/6 x 2250MM (CUT LENGTH) | 1,000 | EA | |
| 60112212 | Protective cap f. quick fittin | 6,000 | EA | Fittings& Accessories for above hose&Manifold (for |
| 60112214 | Quick fittings 90 elbow 1/6 | 6,000 | EA | |




Check for blade bearing grease leaks:

Check blade bearings for any grease leak.


Check the hydraulic system for any leaks, isolate and repair any leaks if found.

Check for grease or oil stains on the blades and spinner.



Check the grease collector bottles in all blade roots. If there is a large volume of oil in the hub or evidence that oil has

penetrated into the bearing, perform a manual greasing operation on all of the blades.



| Relevant documentation | |
|---|---------------------------|
| Description | DMS No. |
| Blade Bearing Manual Grease Procedure | 0024-9719 |
| Installation of IMO Retrofit Inner Blade Bearing Seal | 0002-2266 |
| Replacement of Outer IMO Blade Bearing Seal | 0003-1177 |

Check the inner and outer blade bearing seals.

If there is any damage or heavy grease leak replace the seals.



Replace the defect Hub Computer

Does this solve the problem?


- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**
IN THE HUB:

If after the blade calibration, there continue to be any pitch angle deviations, or the angle values show constant when

pitching the blades, the hub computer may be defective.

| Relevant spare parts | |
|--------------------------------|--------------------------|
| Description | Item No. |
| SIF HUB COMPUTER CABINET EVOII | 51701801 |



Perform the blade bearing operation

Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know


- **Explanation**
IN THE HUB:

Check the Blade bearing operation 'Pitching to run' and 'Pitching to stop'.

Check for any blade vibration or any abnormal noise during operation.

Perform the Blade Pitch System Test

| Relevant documentation | |
|-------------------------|---------------------------|
| Description | DMS No. |
| Blade Pitch System Test | 0002-0467 |



If manual greasing does not solve the issue, likely it is the cause of blade bearing failure. Consult the SBU Engineering group to determine course of action and correct item number for the applicable blade bearing.

| Relevant CIM case | | |
|----------------------|-----------|---------------------------|
| CIM case | Task list | SWI |
| 1908 | | 0003-1177 |
| 929 | | 0002-2266 |

| Relevant spare parts | |
|---------------------------------------|--------------------------|
| Description | Item No. |
| BLADE BEAR. STD. IMO -NEW SEAL (NM72) | 60113392 |
| BLADE BEARING STD LAULAGUN | 60104445 |