

## Replace the Pt100 sensor

### Does this solve the problem?

1] Yes

2] No

3] I don't know


- **Explanation**

Check the Pt100 temperature sensor. Use the temperature/resistance chart to verify your readings.

If the temp is  $-40^{\circ}\text{C}$ , there is likely a short in the circuit.

If the temp is  $200^{\circ}\text{C}$ , there is likely an open in the circuit.

Perform a pull test on the wires to ensure any opens are not due to loose connections.



Pt100 resistance/temp chart Doc: [0039-6203](#)

AN1 wiring diagram Doc: [0003-2029](#)

AN12 wiring diagram Doc: [/D6015816](#)

PT100 SENSOR, TOP PSC 1030 JAKE Part: [60066565](#)

## Test/Replace Varistor Box

Does this solve the problem?

1] Yes


2] No

3] I don't know

- Explanation**  
 Check the continuity to earth from the F35 terminals 5 and 6 (verify test pints with wiring diagram specific to turbine

Mk).

If you the multi meter does not display “OL” there is a problem with the varistor and it should be replaced.



AN1 wiring diagram Doc: [0003-2029](#)

F35 Varistor Part: [51706201](#)

### Replace the TOI

Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**

Measure the resistance of the B26 sensor from the AN1:U01 connections 727 and 728 (with wires disconnected).

If the temperature given by the controller doesn't match your readings, then a faulty TOI could be the cause.

Pt100 resistance/temp chart Doc: [0039-6203](#)

AN1 wiring diagram Doc: [0003-2029](#)

AN12 wiring diagram Doc: [/D6015816](#)

TOI-II INTERF EXT Part: [51701601](#)