

## Replace the defect pressure transmitter

Does this solve the problem?

1] Yes


2] No

3] I don't know

- **Explanation**  
**IN THE NACELLE:**

Check the pressure value through the TAC -II controller,

Status→ Pressures→ Pressure shaft brake acc



If the displayed pressure shows as a negative value the pressure transmitter is may be defective and has to be replaced

60104065- PR TRANSDUCER SCP-200-34-06







### Replace the defect Varistor


Does this solve the problem?

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**  
**IN THE AN1 CABINET:**

Varistors (F32 MkIII+ or F30 MkII and below) can be tested individually by placing a multimeter (set to measure  $\Omega$ ) lead on the common (earth) side of the varistors and the other on the individual varistor terminals. The resistance value over the varistor should be  $\infty$  or in the high M $\Omega$  range. If the resistance is lower, the varistor has been damaged

by an over voltage in the circuit and must be replaced







Item Number : 51706201 VARISTOR BOX X8

**Varistor box F32/F30:**

(F32 MkIII+ or F30 MkII and below).

Press clip on top and bottom of varistor box and remove varistor assembly from housing:



The varistor box is made up of eight varistors and has provisions for 16 wire connections (protection for 8 signals)

### **Replace the defect cable**

**Does this solve the problem?**


- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**  
**IN THE Nacelle:**

Check the pressure transmitter cable (W604) connections and connectivity.








#### IN THE AN12 CABINET:

Check the terminal connection if any loose X02- 06



**Replace the defect TOI**

**Does this solve the problem?**

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation**  
**IN THE AN1 CABINET:**

Check the pressure value through TAC-II controller if the value does not showing correct then the cause is likely a faulty Nacelle TOI

Item Number: 51701601- TOI-II INTERF EXT POC

