

## Check the Parameter List and correct if necessary

### Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**

Check the different from factory parameters and verify that the HSS brake related parameters are correct. Refer to the current parameter list for the correct values.

### If turbine has combined hydraulics for yaw- and shaft- brake:

Check that combi hydraulic is enabled.

Relevant documentation	
Description	DMS No.
Parameter list 50Hz Doc	<a href="#">17000193</a>
Parameter list 60Hz Doc	<a href="#">17000169</a>

## Replace the defective pressure sensor

### Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**

Check the Relief Valve setting and ensure its as per I&S data, wrong setting and malfunction will lead to this error.

Relevant spare parts-Parker	
Description	Item No.

VALVE RELIEF RDH-08-2-S-30 69-207 BAR

[60104030](#)


## AT NACELLE

Check the unit pressure with Manometer and TAC computer. If the TAC computer showing the wrong value than manometer replace the pressure Transmitter

## AVN hydraulics

Manometer test connection port pos.18.

Hydraulic pressure transmitter POS. 12




## Relevant spare parts

Description	Item No.
PRESS. TRANSMITTER MBS 33 060G1	<a href="#">60066971</a>

## Parker Hydraulic

Manometer test connection port pos.M3.

Hydraulic pressure transmitter POS. 0.22



Relevant spare parts	
Description	Item No.
PR TRANSDUCER SCP-200-34-06	<a href="#">60104065</a>