

## Replace the defective PT100

### Does this solve the problem?

1] Yes

2] No

3] I don't know

- **Explanation**  
**AT NACELLE**


Check the Loose connection in W524 Cable in F10 varistor Terminals 1 & 2.

Remove the wires from F10 Varistor.

Use a Multimeter set to read ohm value and measure the resistance across the leads of the PT100.

Use a resistance/Temperature conversion chart to determine the actual measured value.

If the value is un real (-40° to 200° Celsius) then the PT 100 is faulty and must be replaced.



Relevant documentation	
Description	DMS No.
PT100 Resistance/Temperature chart	<a href="#">0039-6203</a>

### Relevant spare parts

Description	Item No.
PT100 180-4-2M Ø6x60mm	<a href="#">60009279</a>

### Replace the Varistor F 10

Does this solve the problem?

1] Yes

2] No

3] I don't know

- Explanation**

**AT NACELLE** : Check resistance value before and after the variastors terminal PT100 connected, if the values different change the varistor



Relevant spare parts	
Description	Item No.
VARISTOR BOX X8 (Discontinue)	<a href="#">60015847</a>
VARISTOR BOX X8 (New)	<a href="#">51706201</a>
Mounted PCB VARISTOR BOX X8	<a href="#">60015268</a>

## Replace the faulty TOI


### Does this solve the problem?

1] Yes

2] No

3] I don't know

- Explanation**  
 Check the Loose connection in Nacelle TOI Input terminal U01 Terminal no 303 & 304 for any loose connection and change the TOI



Relevant spare parts

Description

Item No.

TOI-II INTERF EXT POC

[51701601](#)