

## Replace the defective wind vane and defect wind sensor

### Does this solve the problem?

1] Yes


2] No

3] I don't know


- **Explanation**  
**IN THE NACELLE:**

Check that the wind vane is properly fixed to the met frame on top of the cooler.

Relevant documentation	
Description	DMS No.
Wind vane alignment	<a href="#">1001337</a>



Check the wind vane signal in the top TOI Unit,



If the wind vane is defective replace with new wind vane.

Relevant spare parts	
Description	Item No.
WVA HEATED DWS-D-DAC-13 (CG)	<a href="#">60092777</a>
WINDVANE NRG 2 ICEFREE, ARCTIC (NRG)	<a href="#">60009349</a>





Check the FT sensor alignment and working condition.

If found to be defective, replace with new one.



Relevant CIM case		
CIM case	Task list	SWI
<a href="#">2675</a>		

Relevant spare parts	
Description	Item No.
WIND SENSOR US FT702LT V7-10	<a href="#">60111943</a>
WIND SENSOR US FT702LT V22	<a href="#">106510</a>

Relevant documentation	
Description	DMS No.
FT sensor Fault finding Procedure	<a href="#">0010-1892</a>



If replacing the FT sensor, ensure that it meets the firmware requirements mandated in DMS 0028-9335 and 0029-1332

Relevant documentation	
Description	DMS No.

CIM 2675 FT Sensor New Software	<a href="#">0028-9335</a>
Upgrading FT22 Sensor Firmware	<a href="#">0029-1332</a>

**NOTE:** To upgrade the sensor firmware, the sensor will be connected directly to a PC with firmware installed from the Vestas Software Portal.

If the FT sensor does not appear to be shorted, check the F46 varistor box for a failed varistor. Remove the wires from the varistor box and remove it from the housing.

#### **Varistor box F46:**

Both wind sensor 1 (left) and wind sensor 2 (right) use varistor box F46. Terminals 1-4 (top and bottom) are for wind sensor 1 and 5-8 (top and bottom) are for wind sensor 2.

If the cable is mounted tight and it pulls in the sensor connector, it must be connected so that it is not pulling the plug.

Relevant spare parts	
Description	Item No.
VARISTOR BOX X8	<a href="#">51706201</a>

Press clip on top and bottom of varistor box and remove varistor assembly from housing:





The varistor box is made up of eight varistors and has provisions for 16 wire connections (protection for 8 signals)

Cable plug and protective boot:



Proper instillation of protective boot:



Check the connections at the ICP RS485 repeaters (K21 & K22) in the AN1.

Check for loose wires and plugs or corrosion at the repeater.



If there is no communication on one sensor, switch the ICP RS485 repeaters to see if the communication returns. If communication returns when the repeaters are switched, replace the faulty repeater. Item number:

Relevant spare parts	
Description	Item No.
RS485/RS485 REPEATER I-75	<a href="#">60004933</a>

**Replace the defect Nacelle TOI Unit**

**Does this solve the problem?**

1] Yes

2] No

3] I don't know

- **Explanation**  
**IN THE AN1 CABINET:**

Check the indication of nacelle TOI unit during yawing, the LED should be blink and TAC yaw counter value will change.

If the value does not change in the TAC, then the cause is likely a faulty Nacelle TOI.

**Nacelle TOI part Number:**

Relevant spare parts	
Description	Item No.
TOI-II INTERF EXT POC	<a href="#">51701601</a>





**Replace the new Yaw gear unit**

**Does this solve the problem?**

- 1] Yes
- 2] No
- 3] I don't know

- **Explanation  
IN THE NACELLE:**

Check the turbine alarm log for recent yaw errors such as yaw motor "X" overload. If the turbine has a history of yaw related errors, there may be an issue with one or more of the yaw gears that is causing this alarm.

Check the yaw gear which is connected in the yaw system.

Check the teeth in the remaining yaw gear pinion wheels if any damage.

If abnormal sound can be heard in the yaw gear unit it is likely defective.

Relevant documentation	
Description	DMS No.
Replacement of Yaw Gear Unit	<a href="#">0010-5073</a>

Relevant spare parts	
Description	Item No.
Yaw gear Bonfiglioli 709T4F	<a href="#">60103371</a>

