

**CC2420 Errata Note 002, rev. 2.0**

March 18, 2005

For CC2420 devices marked with lot codes ranging from WA8402.00 to WB8341.00 correct operation of the SPI interface is not guaranteed at I/O-voltages below 2.1 V, unless the on-chip voltage regulator is used. This problem is now fixed and operation down to 1.6 V is ensured for devices with lot codes succeeding WB8341.00.

**Description and reason for the problem**

When using I/O-voltages below 2.1 V a limitation in the digital pads has been observed to cause reduced SPI speed and in some cases loss of functionality. This will only occur for I/O pins configured as inputs and at I/O-voltages below 2.1 V.

**Suggested workaround**

Using I/O-voltages at or above 2.1 V will ensure reliable operation and unaffected SPI speed. Designs already utilizing the CC2420 on-chip voltage regulator will comply with this requirement.

**Fix**

Using the CC2420 on-chip regulator or voltages above 2.1 V solves the problem for those devices affected.

**Batches affected**

This errata note applies to all CC2420 devices marked with lot codes ranging from WA8402.00 through WB8341.00. For devices with lot codes succeeding WB8341.00 this problem is resolved.

**CHIPCON,**

Tel. +47-22958544, Fax +47-22958546

[www.chipcon.com](http://www.chipcon.com)

[wireless@chipcon.com](mailto:wireless@chipcon.com)

**Document History**

Revision	Date	Description/Changes
2.0	2005-03-18	Problem fixed on lot codes higher than WB8341.00
1.0	2004-10-18	Initial release