

## Lecture 19 Summary

- unstable pole-zero cancellation BAD
- internal stability  $\Rightarrow$  I.O. stability
- If  $s^n + a_{n-1}s^{n-1} + \dots + a_1s + a_0$  is Hurwitz, then  $a_i > 0$  for all  $i$

## Routh-Hurwitz

- (i)  $\pi(s)$  is Hurwitz  $\iff$  all elements in 1<sup>st</sup> column of Routh table have the same sign
- (ii) If there are no zeros in 1<sup>st</sup> column, then
  - # of sign changes = # of bad roots
  - $\pi$  has no roots on Im axis

e.g. S.3.2  $\pi(s) = a_2s^2 + a_1s + a_0$

$s^2$	$a_2$	$a_0$
$s^1$	$a_1$	0
$s^0$	$\frac{a_1a_0 - a_2 \cdot 0}{a_1}$ $= a_0$	

$\pi$  is Hurwitz if and only if  $a_2, a_1, a_0$  have the same sign.



e.g. 5.3.3  $\pi(s) = 2s^4 + s^3 + 3s^2 + 5s + 10$

$s^4$	2	3	10
$s^3$	1	5	0
$s^2$	-7	10	
$s^1$	45	0	
$s^0$	7		
	10		


(i)  $\pi$  is not Hurwitz

(ii) The list of signs in 1st column:  $\{+, +, -, +, +\}$

$\rightarrow$  2 sign changes

$\Rightarrow$  2 bad roots

e.g. 5.3.4



$$P(s) = \frac{1}{s^4 + 6s^3 + 11s^2 + 6s}$$

Let's see if proportional control will stabilize the loop.

$$C(s) = K_p$$

$$\pi(s) = K_p + s^4 + 6s^3 + 11s^2 + 6s \quad (\text{Necessary: } K_p > 0)$$

$$\begin{array}{r} s^4 \quad 1 \quad 11 \quad K_P \\ s^3 \quad 6 \quad 6 \quad 0 \\ s^2 \quad 10 \quad K_P \\ s^1 \quad 6 - \frac{3}{5}K_P \quad 0 \\ s^0 \quad K_P \end{array}$$

$$6 - \frac{3}{5}K_P > 0$$

$$6 > \frac{3}{5}K_P$$

$$10 > K_P \Leftrightarrow K_P < 10$$

Conclusion:

$0 < K_P < 10$  for a stable loop with prop. controller  $\Delta$

## 5.4 Steady state performance

Typical design specs:

- internal stability (mandatory)
- good transient behaviour (depends, in a complicated way, on pole and zero locations)
- this section: steady state behaviour (tracking and disturbance rejection)

### e.g. 4.5.1

plant: motor speed control  $\dot{w} = -w + u$   
 $w$  - angular velocity of shaft  $u$  - applied voltage



$$P(s) = \frac{1}{s+1} \quad r(t) = r_0 \cdot 1(t)$$

Tracking error:  $e(t) = r(t) - y(t)$

Try an integral controller:  $C(s) = \frac{k_i}{s}$

Take  $k_i = 1$  (valid by Routh-Hurwitz)

$$\pi(s) = s^2 + s + 1 \Rightarrow \text{I.O. stable}$$

-let's compute the s.s. tracking error

$$e_{ss} = \lim_{t \rightarrow \infty} e(t) \stackrel{?}{=} \lim_{s \rightarrow 0} s E(s)$$

$$= \lim_{s \rightarrow 0} s \left( \frac{1}{1+PC} \right) R(s)$$

$$= \lim_{s \rightarrow 0} \cancel{s} \frac{1}{1+PC} \cdot \frac{r_0}{\cancel{s}} = \lim_{s \rightarrow 0} \frac{r_0}{1+PC} = \lim_{s \rightarrow 0} \frac{s(s+1)}{s^2+s+1} r_0$$

$$= 0$$


We get perfect asymptotic step tracking.

Why it works?  $C(s)$  has an "internal model"

of  $R(s)$  (an integrator). This places a zero at  $s=0$  in the TF  $\frac{E(s)}{R(s)}$

Other interpretations on why this works:


(i) Frequency domain



$$\text{Bode of } P(j\omega)C(j\omega) = \frac{1}{j\omega(j\omega+1)}$$

$$\rightarrow \text{As } \omega \rightarrow 0, \frac{E(j\omega)}{R(j\omega)} = \frac{1}{1+P(j\omega)C(j\omega)} \rightarrow 0$$

(ii) Time domain



If system is I.O. stable, constant  $r$  produces, in steady state, constant  $y, e, v$ .

⇒  $e$  must go to 0 to make  $v$  be constant

⇒ Need integral control to track constant signals.