

```
/* SELFTEST FOR PIC18F4550 Automated-Guided Vehicle CONTROLLER  
   Converted on 16 Aug 2009 VER02 from SELFTEST.ASM
```

The SELFTEST Mode depends on the button pressed during RESET
i.e. Press Button first then RESET

1. (no switches pressed) = LED test

2. Switch RB0 = Stepper and DC Motor Test note:

After this, RB1 and RB2 move the DC motor

3. Switch RB1 = LED test

```
/* Program starts here: */
```

```
#include <p18f4550.h>
```

```
#include <delays.h>
```

Defines all PIC-18 labels

Defines all delay functions

```
#define RB0 PORTBbits.RB0 /* labelled on PIC board */
```

```
#define RB1 PORTBbits.RB1
```

```
#define RB2 PORTBbits.RB2
```

```
#define SMEnable PORTEbits.RE0 /* Stepper motor enable bit */
```

```
#define SMReset PORTEbits.RE1 /* Stepper motor reset bit */
```

```
#define DCMEnable PORTEbits.RE2 /* DC motor enable bit */
```

```
#define DCMPhase PORTCbits.RC7 /* DC motor reset bit */
```

```
/* Left-Motor */
```

```
#define SMLDir PORTCbits.RC2 /* Left stepper motor direction */
```

```
#define SMLClk PORTCbits.RC0 /* Left stepper motor clock */
```

```
/* Right-Motor */
```

```
#define SMRDir PORTCbits.RC6 /* Right stepper motor direction */
```

```
#define SMRClk PORTCbits.RC1 /* Right stepper motor clock */
```

Defines the symbol for the string on the right.

(Whenever the program encounters the symbol thereafter, it will be replaced by the string.)

```
#define ONb    0          /* active low */
#define ON     1          /* active high */
#define OFFb   1          /* active low */
#define OFF    0          /* active high */
#define TRUE   1
#define TransistorON  PORTBbits.RB5
#define SensorClk    PORTBbits.RB3
```

Active HIGH: 1=on, 0=off

Active LOW: 0=on, 1=off

```
void      LEDTest();
void      sensortest();
void      motortest();
```

Function Prototypes

Needed if the function is used (e.g. in main)
before being defined.

```

void      main()
{
    /*  ==== Use with SP PIC18f4550 board with USB bootloader ==== */

    ADCON1 = 0x0F;      /* PORTA all digital, use Vcc & Gnd for A/D ref */
    CMCON = 0x07;       /* disable analogue comparator */
    /*  end PIC18F4550  */

    /* Initialise PORTs */

    TRISC = 0xFF;
    TRISD = 0x00;
    TRISB = 0x07;
    
        }
    
    SMEnable = OFF;
    DCMEnable = OFF;

    if (RB0 == ONb)
        motortest();

    if (RB1 == ONb)
        sensortest();

    /* otherwise this is the LED test */
    LEDTest();
}

```

PORTC – all inputs

PORTD – all outputs (to LEDs)

PORTB – bit 0-2: inputs, other bits: outputs

/ Disable DC Motor */*

/ RB0 pressed, do Motor test */*

/ RB1 pressed, do sensor test */*


```

void      sensortest()
{
    unsigned char  LEDData;      /* hold LED data */
    TRISB = 0x00;
    TRISD = 0x00;

```

PORTB – all outputs

PORTD – all outputs (to LEDs)

Repeat
forever:

```
while (TRUE) {
```

Enable the sensors by turning on the IR LEDs.

```
    TransistorON = ON;      /* TURN ON EMITTER */
```

```
    SensorClk = 0;
```

Clock pulse to latch the data for PORTA.

```
    SensorClk = 1;
```

00011111 – Capture only the lower 5 bits, RA0-RA5.

```
    LEDData = PORTA & 0x1f; /* READ IN */
```

Bitwise AND

```
    LEDData = ~LEDData;      /* INVERT DATA */
```

Alternatively:

PORTD = ~(PORTA<<3) & 0b11111000;

```
    LEDData = LEDData << 3; /* using RD3-RD7 to display */
```

```
    PORTD = LEDData;      /* DISPLAY */
```


```
    // STATUS ON LED
```

Shift left by 3 bit.

```
    Delay10KTCYx(100);      /* DELAY */
```

```
}
```

```
}
```



```
/* ROUTINE TO RUN THE TWO STEPPER MOTOR AND DC MOTOR */
```

```
void      motortest()
```

```
{
```

```
    unsigned char    savx;          /* for counting */
```

```
/* Enable and reset L297 */
```

```
    TRISB = 0x07;
```

```
    TRISC = 0x00;
```

```
    TRISE = 0;
```

```
    SMReset = 1;
```

```
    SMEnable = 1;
```

```
    SMReset = 0;
```

```
    SMReset = 1;
```

```
    // RESET PULSE
```

```
/* Reset Stepper Motor driver */
```

```
    SMLDir = 0;
```

```
/* SET DIR-X TO CCW */
```

```
    SMLClk = 0;
```

```
/* SET CLK-X TO LO */
```

```
    SMRDir = 0;
```

```
/* SET DIR-Y TO CCW */
```

```
    SMRClk = 0;
```

```
/* SET CLK-Y TO LO */
```

```
    PORTD = 0;
```

```
/* CLEAR LED */
```

```
    savx = 0;
```

```
/* clear counter */
```

PORTB – bit 0-2: inputs, others: outputs

PORTC – all outputs

PORTE – all outputs

```
/* Start to run motors */
```

Repeat
forever:

```
while (TRUE) {
```

```
/* check switches for DC motor operation first */
```

```
if ((SW2 == ONb) && (SW3 == OFFb)) { /* RB1 on, RB2 off */
```

```
    DCMPhase = ON; /* CW */
```

```
    DCMEnable = ONb;
```

```
}
```

```
if ((SW2 == OFFb) && (SW3 == ONb)) { /* RB1 off, RB2 on */
```

```
    DCMPhase = OFF; /* CCW */
```

```
    DCMEnable = ONb;
```


```
}
```

```
if ((SW2 == OFFb) && (SW3 == OFFb)) { /* RB1 off, RB2 off */
```

```
    DCMPhase = OFF; /* disable motor */
```

```
    DCMEnable = OFFb;
```

```
}
```




```

/* Check for stepper motor */
/* Move left motor 1 step */
SMLEDir = 0; /* CCW */
SMLEClk = 1;
Delay10KTCYx(1); /* 0.833 ms */
SMLEClk = 0;
Delay10KTCYx(1); /* 0.833 ms */

```

Each clock pulse will change pattern ABCD of the stepper motor and rotate it by 1 step.

```

/* Move right motor 1 step */
SMRDir = 0; /* CCW */
SMRClk = 1;
Delay10KTCYx(1);
SMRClk = 0;
Delay10KTCYx(1);

```

```

/* Displays a scrolling pattern on the LEDBAR */
savx++; /* increment */
PORTD = savx; /* and show */

```

```


}

```

```

}

```



To:
Stepper
Motor
(Left)

From:

- RE0 (SMReset)
- RE1 (SMEnable)
- RC2 (SMLDir)
- RC6 (SMRDir)
- RC0 (SMLCik)
- RC1 (SMRCik)

Motor Driver Circuit