



HARDWARE-CNC.NL

HIGH TORQUE HYBRID STEPPING MOTOR Nema 23 - 3 Nm - 8 leads - SS


PHASE	STEP ANGLE	CONNECTION STYLE	CURRENT	RESISTANCE	INDUCTANCE	HOLDING TORQUE	WEIGHT
	DEG/STEP		A	ohms	mH	N.m	Kg
4	1.8°	Parallel	4	0.85	3.8	300	1.5
		Series	2	3.4	15.2		
		Unipolar	2.8	1.7	3.8	210	

● Dimensions:

(unit=mm)



● Wiring Diagram :



● Connection to driver:

Parallel Connection

Red + Blue : A+
Yellow + Black : A-
White + Brown : B+
Orange + Green : B-

Series Connection

Red : A+
Yellow + Blue : Connect to each other,
but not to the driver
Black : A-
White : B+
Orange + Brown : Connect to each other,
but not to the driver
Green : B-

For more information about stepper motor connections, please visit our website: www.impulsecnc.nl/faq/stappenmotoren/connections

General specifications	
Step Angle (°)	1.8
Temperature Rise (°C)	80 Max (rated current, 2 phase on)
Ambient Temperature (°C)	-20 ~ +50
Number of Phase	2
Insulation Resistance (MΩ)	100 Min (500VDC)
Insulation Class	Class B
Max.radial force (N)	75 (20mm from the flange)
Max.axial force (N)	15


Nema 23 - 3 Nm - 8 leads - SS

Impulse CNC

Impulse CNC
www.ImpulseCNC.nl

How to connect the stepper motor to a driver:



Wiringdiagram Parallel connection (recommended):




And this is how it looks like:

Note: Normally the motor would be connected to a 4 lead cable.

To make the connections clear we've connected them directly to the driver.





Wiring diagram Series connection:



And this is how it looks like:

Note: Normally the motor would be connected to a 4 lead cable.

To make the connections clear we've connected them directly to the driver.



Note: Never leave the wiring blank. We did this just to demonstrate the wiring. Solder the ends of the wiring and add heat-shrink tubing.