

<b>Subject</b>	<b>Firmware upgrade (Measure for the false detection displaying the check waste toner box message)</b>		
<b>Model</b>	<b>FS-C5150DN, FS-C5250DN</b>		
<b>Classification</b>	<b>Field measure timing:</b>	<b>Next Visit/Service Call</b>	
	<b>Problem:</b>	<b>Other</b>	
	<b>Type of change:</b>	<b>Firmware and Software</b>	

[Content of change]

No.	Item	Details	FW
1	Measure for the false detection displaying the check waste toner box message	When coming out of sleep mode, inconsistency in the software interruption process may occur. As a result, the state of waste toner box becomes unclear and the check waste toner box message may display even if it is not full yet. This has been corrected. When it occurs, it cannot be reset by pulling out/inserting the waste toner box or by replacing with the new part. Cycle the main switch to reset.	ENGINE

< FS-C5150DN, FS-C5250DN >

Type Gemini Pri	Program No.	VER.	Remark	
MAIN	2KV_3F00005003	005.003		
ENGINE	<a href="#">2KT_1000010001</a>	010.001	FS-C5150DN	← New upgrade
ENGINE	<a href="#">2KV_1000010001</a>	010.001	FS-C5250DN	← New upgrade
LANGUAGE BR	2KV_81BR001010	001.010	Brazilian Portuguese	

KDC sales companies may download firmware through Knowledge Cabi-NET.

When upgrading firmware and/or replacing board, etc., please upgrade each firmware to the latest usable version.

<b>Field measure</b>	If the problem occurs, please upgrade the firmware.
<b>Implement timing</b>	See below.

**Affected Machines Serial Number**

Model	Specification	Item code	Starting S/N
FS-C5150DN	KDA120V	1102KT2US0	No applicable production
	KDA220V	1102KT4US0	N1N4500824
FS-C5250DN	KDA120V	1102KV2US0	No applicable production
	KDA(GSA)	1102KV2US1	Next production
	KDA(GSA)	1102KV2US2	No applicable production
	KDA220V	1102KV4US0	N1P4500177