

Service Bulletin

Ref. No. **2V8-0072(P105)**

<Date> May 12, 2025

Subject:	Firmware upgrade (Upgrade Pack 2VG_V2.19/2V8_V2.22/2VK_V2.20) (Except Russia and Belarus)		
Model:	TASKalfa 6053ci, TASKalfa 5053ci, TASKalfa 4053ci, TASKalfa 3553ci, TASKalfa 3253ci, TASKalfa 2553ci, TASKalfa 6003i, TASKalfa 5003i, TASKalfa 4003i, PF-7120		
Classification:	Field measures timing:	<input type="checkbox"/> At Set Up <input checked="" type="checkbox"/> Next Visit/Service Call	<input type="checkbox"/> Next Periodic Maintenance <input type="checkbox"/> Information only
	Phenomenon:	<input type="checkbox"/> SC/Error <input type="checkbox"/> Image	<input type="checkbox"/> Paper Feeding/Conveying <input type="checkbox"/> Machine operation
	Type of change:	<input type="checkbox"/> Hardware <input checked="" type="checkbox"/> Firmware and Software	<input type="checkbox"/> Information
Remarks:	Supplement for KDEM: Delivery to Russia and Belarus is prohibited by KDC in consideration of the law.		

The PF-7120 firmware is released. Refer to the next page for the content of the change.

[*1: 3253ci/2553ci, *2: 6053ci/5053ci/4053ci/3553ci, *3: 6003i/5003i/4003i]

Type	Program No.	Remarks	Models			
			*1 Low	*2 High	*3 Mono	
Upgrade Pack Ver.		Other than KDCN	2VG_V2.19-S	2V8_V2.22-S	2VK_V2.20-S	New upgrade (Note: KDEM)
		KDCN	2VG_V2.19CN-S	2V8_V2.22CN-S	2VK_V2.20CN-S	New upgrade
CONTROLLER	2VG_S000.002.801		X	-	-	
	2V8_S000.002.801		-	X	-	
	2VK_S000.002.706		-	-	X	
PANEL MAIN	2VG_7200.001.005		X	-	-	
	2V8_7200.001.006		-	X	X	
ENGINE	2VG_1000.005.001		X	-	-	
	2V8_1000.005.001		-	X	-	
	2VK_1000.005.001		-	-	X	
LANGUAGE MLT	2V8_81XM.002.704		X	X	X	
OCR	2V8_L000.001.001		X	X	X	
COPY COLOR TABLE	2VG_KZ00.001.005	For Copy	X	-	-	
	2V8_KZ00.001.005		-	X	-	
MLTCOLORTABLE	2VG_GZ00.001.005	For Printer	X	-	-	
	2V8_GZ00.001.005		-	X	-	
ESPECIAL	ES SKIP.ON		X	X	X	
ENHANCE						
DP-7100	3R7_9500.002.002	RADF	X	X	X	
DP-7120	3RJ_9500.002.002	RADF for 25/32ppm	X	-	-	
DP-7110	3R8_9500.007.301	CIS	X	X	X	
DP-7130	3SR_9500.002.202	CIS/double feed detection	X	X	X	
PF-7100/7110	3RB_9000.002.001	500x2/1500x2	X	X	X	
PF-7120	3RL_9000.003.001	SIDE DECK	X	X	X	New upgrade
DF-7110/7120	3RW_9200.006.002	4K/1K	X	X	X	
DF-7130 MAIN	3SW_9200.004.101	100STP	-	X	X	
DF-7130 DF SUB	3S8_9C00.002.102	100STP	-	X	X	
PH-7A/B/C/D	3NK_9A00.006.001		X	X	X	
BF-730	3ND_9700.007.002		X	X	X	
BF-9100	3SP_9700.005.001		-	X	X	
MT-730(B)	3N0_9800.004.001		X	X	X	
DF-7100	3RD_9200.005.001		X	X	X	
PH-7100/7110/7120/7130	3RF_9A00.002.001		X	X	X	
JS-7100	N/A	Standard for KDA25ppm only	-	-	-	
FAX System 12	3R2_5400.003.012	Other than KDCN *4	X	X	X	(Note: KDEM)
FAX System 12 CHN	3R2_5600.Z03.012	KDCN *5	X	X	X	

(Note: KDEM) Do not distribute to Russia and Belarus.

(Details of the FAX System 12 firmware configuration continue on the next page.)

Field Measure:

When upgrading firmware or replacing PWB, etc., please upgrade each firmware (MAIN, ENGINE, etc.) to the latest version at the same time.

Service Bulletin

Ref. No. **2V8-0072(P105)**

<Date> May 12, 2025

**[FAX System 12/FAX System 12 CHN] Firmware Configuration

*4: (BOOT) 3R2_5000.001.009 / (APL) 3R2_5100.003.012 / (IPL) 3R2_5600.002.002

*5: (BOOT) 3R2_5000.001.009 / (APL) 3R2_5100.Z03.012 / (IPL) 3R2_5600.002.002

[Content of Change]

No	title	Contents	Ctl	FW
1	Support for the lift motor change	<p>Since the supplier of the lift motor has changed, support for the new lift motor is added.</p> <p>*When using the new lift motor with the old firmware, the tray lift drive joint might be damaged.</p> <p>- This item is the change at the upgrade of PF-7120 individual FW (3RL_9000.003.001) released via Service bulletin No.3RL-0003(P046).</p>	2XC-15843	PF-7120

[CVE reference No.] No CVE No. is supported this time.

First implemented timing at factory

Planned in March 2025 production

N00132509