

Référence / Reference : **ICO-ETU-0210-PP**

Révision / Revision : **A**

Titre /Title : **SDK 6.4 release delivery**

Programme / Subject : TELIUM SOFTWARE

Approbation de la révision / Revision Approval : A		
	Nom <i>Name</i>	Fonction <i>Function</i>
Etabli par : <i>Written by:</i>	P. Plasse	SDK project manager
Vérifié ou Approuvé par : <i>Checked or approved by:</i>	C.Barthelemy	Export Product leader
Autorisé par : <i>Authorized by:</i>	C.Barthelemy	Export Product leader

Révision <i>Issue</i>	Date de validité / d'application <i>Validity/application date</i>	Nb de pages <i>Nb of pages</i>	Nb de pages annexes <i>Nb of appendices</i>	Objet et description de la modification <i>Object and description of modification</i>
A	July 2009			Release SDK 6.4

1 DESCRIPTION

This document describes the evolutions between the SDK6.4 preliminary version and this SDK6.4 official version.

2 TERMINALS COMPATIBILITY

The following terminals are compatible with this SDK release:

2.1 TELIUM 1

- EFT30
- EFT SMART
- EFT930
- TWIN
- UCM
- ML30
- CAD30
- SMART2
- MR40
- EFT930 BL2
 - GPRS,
 - GPRS Contactless,
 - GPRS Color,
 - GPRS Contactless Color;
 - Bluetooth,
 - Bluetooth Contactless,
 - Bluetooth Color;
 - EFT930 BCC (Bluetooth Color Contactless) is new in this release.

2.2 TELIUM 2

- ICT220
- ICT250 is managed with extension cards. Only the following are currently managed (only one feature available by option):
 - Card option 1 : SCR2 (=CAM2)
 - Card option 2 : GPRS / μ SD / Contactless
 - Card option 5 : μ SD / 2nd RS232
- SPM

3 TELIUM SYSTEM

Following points are delivered in this release.

3.1 TELIUM GENERIC

- FT4868 Allow to manufacturer application to run VAR-signed scheme
- FT4955 Added fiocctl SYS_FIOCTL_GET_TERMINAL_TYPE
- FT5045 Correction of the Modem Stack overflow en mode V29FC
- FT5073 Correction of the access to null pointer NULL in user_api.c
- FT5079 Decrease of the delay (10ms instead of 1s) between two readings when USB FIFO is full. **MANDATORY WITH BIO TERMINALS**
- FT5199 TMS call failed when RAM used was just below 8 Mo.
- FT5204 Number of forkable tasks is now 64 instead of 41.

3.2 TELIUM 1

- FT4909 It was not possible to load an unsigned component in mock-up

3.3 TELIUM 2

- FT5039 Correction of the problem if contactless is parameterized on serial link
- FT5070 Mismanagement of the resizing of an area previously created by RegisterPowerFailure
- FT5071 Start of the HILO improved for ICT and EFT930S (IO management modified)

3.4 930 S

- FT5071 Start of the HILO improved for ICT and EFT930S (IO management modified)

3.5 HANDHELD TERMINALS

- FT4465 USB symbol didn't appear when the terminal was connected to a peripheral with a consumption over 100 mA
- FT5010 Correction of the problem of unload of battery (printing became slower)

3.6 930 BLUETOOTH

- FT5105 ELC930 didn't work very well with a Bluetooth configuration

3.7 EFT930 BL2

- FT4612 Display latencies with WGUI
- FT5008 Correction of the reset due to the CLess drivers optimisations
- FT4966 SHA256 added in Booster 2 systems
- FT5088 Booster 2 was blocked after battery pulled out
- FT5089 Correction of the problem of Vitale IGEA 340 card
- FT5137 Consumption improved
- FT5138 Function used to know if a terminal is in mockup mode didn't work on EFT930BL2

3.8 MR40

- FT3718 Reset after a EMV APDU command was sent to the BL2 CAM (NACK was only received on InterUc)
- FT5005 MR40 was sometimes blocked after a light sleep
- FT5009 Light sleep counter added
- FT5117 After a deep sleep, the swipe was not read
- FT4814 Correction of the problem when the terminal goes into sleep just after a swipe reading

3.9 PINPAD PPS30 AND P30

- FT4440 Optimisation of the timings performance for P30 Cless
- FT4487 Periodical re-initialisation of the display
- FT4506 A secret area added
- FT4525 / Information Booster1, 2 or 3/Pinpad or Non/Var Identifier provided to the
- FT4526 schemes
- FT4966 SHA256 added
- FT5041 Robustness of USB pinpad improved

3.10 EFT30

- FT5154 Correction of problem when printing on EFT30 with printer older than April 2004

3.11 ICT220

- FT5178 NTP_SoftwareActivateRam didn't work on ICT (problem for French healthcare applications)

3.12 ICT250

- FT4648 Correction of the lost of data in flash (hterm, key files)
- FT5169 Correction of the reset on fioctl CAM

3.13 SPM

- FT5202 Printer driver for SPM added

4 TELIUM MANAGER

Following points are delivered in this release.

4.1 NEW FEATURES

- FT4922 Association of a non Bluetooth terminal on base 2LS
- FT4081 Add the possibility to have a beep when a card is removed
- FT4243 Manage FOOTER to ICT250.
- FT4421 Manager compatibility with SPM products
- FT4535 At startup of M2OS, added display of the security configuration number (only for BOOSTER 2 and upper)
- FT4927 API to enable/disable an external PINpad from application
- FT5092 Manage flash memory available higher than 64Mo (ISC350)
- FT5096 Added sent of PLS event (for French health applications)

4.2 CORRECTIONS

- FT5130 "WELCOME" is not displayed correctly on PP30S
- FT4942 Contactless logo was displayed on SPM
- FT4742 Handset display didn't hang-up when calling in GSM mode
Battery display didn't blink correctly when there was no battery into POS.
- FT3241 Automatic parameterization of TYPE_TMS if GPRS
- FT4867 WGUI display optimisation
- FT4882 Start up delay optimisation
- FT4986 On SPM, only IP proposed for type of network
- FT5069 Update of the field returned by OS_GetIDLecteur for ICT250
- FT5053 When card is removed, coupler number dealt
- FT5069 ICT250 added to the function OS_GetIdlecteur

5 DLL SECURITY

Version is 03.08.

Following points are delivered in this release.

- FT5017 SEC_FreeSecret correction for SDK standard scheme
- FT4862 Optimisation of the time when schemes are searched at start-up.
This is required for UCM
- FT5062 Correction of the data size in ADF file (with out that a reset could occur when is presented to the card)
- No FT Adding SEC_DukptKeyVerify

6 SCHEMES

No evolution: version is 03.06.

7 LINKLAYER

No evolution: TCPIP package delivery is the pack 03.05.

8 AVL (ADDED VALUE LIBRARIES)

Version is 1.04.

Following points are delivered in this release.

- FT5218 The help for AVL is now only in the CHM file

9 SDK

Following points are delivered in this release.

- FT5061 xml_expat.h and xmls.h added to the delivery.
- FT4486 File controle.txt containing traps numbers added to the delivery.
- FT5059 Correction of the compilation compatibility problem between Telium Pass and AVL
- FT4970 Bad version of trace.exe for Telium1 in the SDK
- FT4448 Samples available at the Ingedev format
- FT2000 Include files provided as read-only

10 TOOLS

10.1 SIMULATOR

Following points are delivered in this release.

- FT4806 Version is now 2.03 (corresponding to the version automatically generated by the tool GSIM): no change in the way to use it.

11 MAIN REMAINING POINTS IN THIS RELEASE

Following points are not yet solved in this release.

11.1 930 BCC

- FT5203 Access to the memory card causes a lost of the base
- FT5205 Sometimes terminal lost the base with out any reason
- FT5210 Terminal blocked with out any reason

11.2 ICT250

- FT5100 When a pinpad is plugged on an ICT250 contactless the display is all the time
"Present only one card"