



TELIUM SDK

SDK6.6 Release Note

Reference: ICO-ETU-09-0815-PP

Date: 2009-01-08

From: Pascal PLASSE

To: All SDK users

TABLE OF CONTENTS

1. PURPOSE OF THE DOCUMENT	1
2. TERMINALS COMPATIBILITY	1
2.1 CGUI	1
2.2 TELIUM 1.....	1
2.3 TELIUM 2.....	1
2.4 HANDHELD TERMINALS	1
3. HIGHLIGHTED POINTS.....	2
3.1 ISC350	2
3.2 DIR SYSTEM VERSION DOWNGRADE.....	2
3.3 EFT930BL2 SYSTEM VERSION DOWNGRADE.....	2
3.4 SERVICE NUMBERS.....	2
3.5 DOCUMENTATION	2
3.6 EFT930 WHICH EMBED 8MO OF FLASH	2
4. TELIUM SYSTEM	3
4.1 RKI INGETRUST 930 BL2, SMART2/ML30, PP30S AND P30	3
4.2 ZKA : ICT2XX/SPM, 930 BL2, SMART2/ML30, PP30S AND P30.....	3
CLEAR PINCODE ON TIMEOUT ADDED	3
4.3 ICT2XX	3
4.4 EFT30, SMART AND EFT930	3
4.5 EFT930 BL2.....	3
4.6 ML30/SMART2 BOOSTER 2 SYSTEM	3
4.7 P30 AND PP30S SYSTEMS.....	4
4.8 THUNDER	4
4.9 CAD30 UCR - UCM	5
4.10 HANDHELD TERMINALS / INTELLIGENT BASES	5
4.11 BLUETOOTH HANDHELD TERMINALS	5
5. TELIUM MANAGER.....	5
6. CGUI	6
7. DLL SECURITY	6
8. DLL HARDWARE.....	6
9. SCHEMES	6
10. LINKLAYER	6
11. PACK IP	6
12. FTP.....	6
13. SSL.....	6

14. AVL (ADDED VALUE LIBRARIES)	6
15. SDK.....	6
15.1 FONTS.....	7
15.2 SIMULATOR	7

1. PURPOSE OF THE DOCUMENT

This document describes the evolutions since the SDK6.5.3 which is the previous one.

2. TERMINALS COMPATIBILITY

2.1 CGUI

CGUI (Color and Graphic User Interface) is included in this release.

2.2 TELIUM 1

The following terminals are compatible with this SDK release:

- EFT30
- EFT SMART
- TWIN
- UCM
- ML30
- CAD30
- SMART2

2.3 TELIUM 2

The following terminals are compatible with this SDK release:

- ICT220
- ICT250 is managed with extension cards. Only the following are currently managed (only one feature available by option):
 - Card option 1 : SCR2 (=CAM2)
 - Card option 2 : GPRS / μ SD / Contactless
 - Card option 5 : μ SD / 2nd RS232
- SPM

2.4 HANDHELD TERMINALS

This SDK is compatible with these products:

- EFT930
- EFT930 BL2
 - GPRS,
 - GPRS Contactless,
 - GPRS Color,
 - GPRS Contactless Color;
 - Bluetooth,
 - Bluetooth Contactless,
 - Bluetooth Color;
 - EFT930 BCC (Bluetooth Color Contactless).

3. HIGHLIGHTED POINTS

3.1 ISC350

The ISC350 is not managed by this package. For this terminal you need to use the SDK 7.0 Preliminary 2 for ISC350.

3.2 DIR SYSTEM VERSION DOWNGRADE

It is not possible to downgrade from a system managing directories (catalogue XXX_DIR.mYY) to a system which not manage directories (catalogue XXX.mYY).

3.3 EFT930BL2 SYSTEM VERSION DOWNGRADE

It is not possible to downgrade from the EFT930 BL2 system version embedded in the SDK 6.4.2 (or newer), to an older one. This downgrade is blocked. It is due to a change of the time base (1 s to 125 ms).

3.4 SERVICE NUMBERS

Service numbers from 1 to 100 and from 7680 à 8191 are reserved for Ingenico internal use.

3.5 DOCUMENTATION

The folders under <Your Install Directory>\Document have changed. Now, most part of the documentation is inside the file SDK_TELIUM.chm.

3.6 EFT930 WHICH EMBED 8MO OF FLASH

It is not possible to use this SDK on EFT930 which have only 8 Mo of flash.

4. TELIUM SYSTEM

New version of Telium System: **08.44**.

Following points are delivered in this release.

4.1 RKI INGETRUST 930 BL2, SMART2/ML30, PP30S AND P30

4784 Possibility added to store a TLS key as pin code.

4.2 ZKA : ICT2XX/SPM, 930 BL2, SMART2/ML30, PP30S AND P30

6005, 6029 Clear PinCode on TimeOut added

6006 OS integrity auto test added

6007,6031,6215 Security improved during the OS update

4.3 ICT2XX

5779 Only keys change of state emitted (as it is done for 930)

5986 Flash access improvement if an IT is raised during the operation

6138 Colour display type added to distinguish ISC350 and ICT250

6140 New version of colour driver integrated

6161 Integration of Motorola V34 modem evolution

4.4 EFT30, SMART AND EFT930

4507 In mock-up mode, possibility added to erase all the secret area excepted the pinpad secret

4.5 EFT930 BL2

6114 Mifare4K contactless cards management added

6189 Contactless detection delay improved

4.6 ML30/SMART2 BOOSTER 2 SYSTEM

5255 Fioctl added to check if a smart card is powered on

5294 Fixed display problem in the mock up header : bitmap was sometimes display in the mockup header

5467 InterUC reiteration is now 200 ms

5735 At start up the terminal was stuck when contactless didn't answer or was not present

6114 Mifare4K contactless cards management added

6152 Only keys change of state emitted (as it is done for 930)

6189 Contactless detection period improved

6272 Possibility added to do an automatic IFS request in ISO7816 mode

4.7 P30 AND PP30S SYSTEMS

- 4695 USB performance improved
- 5089 Sesam Vitale card (French healthcare) IGEA 350 reading problem solved
- 6423 P30 CAM with NCN problems fixed

4.8 THUNDER

4.8.1 USB

- 5753 Controls signal managed for keyspan
- 6013 There was sometimes a reset on fclose (COM21)
- 6243 Return of status() after fopen() was wrong
- 6274 For keyspan and FTDI data were not returned to the application after fclose() + fopen()
- 6297 Driver CDC for CAD30-UCI

4.8.2 GPRS

- 6304 Problem of POK management fixed

4.8.3 VFS

- 5822 Data writing improved if there is a reset

4.8.4 Thunder system

- 5212 Back up during a power cut was KO if a garbage collector was in progress
- 5376 Thunder 3 drivers were accepted by Thunder 2
- 5640 CTAP system implementation
- 5820 ML30-WebPOS implementation
- 5821 Diagnostic added to know the active IT during a power cut
- 5824 Flash manager improved
- 5881 Possibility added to define dynamically flash formatting
- 5995 ISO123 reading improved
- 6023 On printer, bold string could have been truncated in the middle of character
- 6082 Correction of RegisterPowerfailure() returns
- 6120 After an empty battery state, 930G was not able to start when a barcode was connected
- 6199 It was not possible to load with LLT a 930G connected to an Ethernet base
- 6218 Ingetrusted locked implemented for Telium
- 6267 Pinpad IPP2XX managed for Telium1 an 2
- 6336 SystemFioctl SYS_FIOCTL_WHERE_IS_CLESS added to know if the contactless is implemented in the Booster or in the Thunder
- 6339 There were sometimes, BC06 GPRS terminals blocked
- 6361 Large files writing on μ SD improved

- 6452 Bluetooth diagnostic ticket simplified
- 6156 For CTAP, security application must include a specific scheme to be accepted by Telium System
- 5991 Possibility to have the backlight if battery is low (configuration file used)
- 1996 Restart of DHCP negotiation added if the Ethernet link is re-plugged
- 6415 ISO3 reading for a specific project
- 6342 IPP3x type detection added
- 6442 Fixed phase 7 error in the activation application
- 6429 Orphan files are now removed in the system disk
- 6430 V29 FC communication problem fixed

4.9 CAD30 UCR - UCM

- 6432 Some bytes were lost during a diagnostic or configuration printing
- 6435 Optimisation of the RAM used by the external printer driver

4.10 HANDHELD TERMINALS / INTELLIGENT BASES

- 6436 Base download problem solved

4.11 BLUETOOTH HANDHELD TERMINALS

- 5120 When there was no system pack in the base, the version uploaded was 99.99
- 5203 Fix to avoid conflicts between Bluetooth and MMC on new Bluetooth (BC06) devices.

5. TELIUM MANAGER

New version of Telium Manager: **55.00**.

Following points are delivered in this release.

- 6344 CAPS ON/OFF was impossible when calling G_Saisie_Etendue
- 6157 Unwanted image was printed by pprintf8859 after the printing of a logo with defprinterpattern
- 6291 Message management didn't work during a remote download
- 6349 Wrong function used by the Manager to determine if embedded class is present or not
- 6444 There was a reset when shortcut F49 was ran
- 6453 Catalogue CGUI MOCKUP created : they have to be used during development if the Ingedev CGUI Preview tool is used
- 6076 Message "No TEL FAI (IP/RTC)" display problem fixed
- 5340 Removed contrast menu on Color Terminals
- 6109 New payment type in the protocol F, POS protocol
- 6335 Value added to define if a manager compliant with CGUI
- 6122 Touch screen management
- 6160 Manager parameter file for ICT250 and ISC350 have now different names

- 4534 Simulation of F1 F2 F3 F4 keys for terminal not having physical F1 F2 F3 F4 keys
- 5308 If CGUI DLL is not in the terminal, the Manager works now like before
- 5480 It is now possible to manage 10 numbers amount
- 5721 IDSA added (IDSA is a identifier sent by the bank server)
- 5743 G_List_Entry() can now manage 99 items
- 5807 There was a crash when printing big bitmap
- 5816 A ML30 can now be connected to a webPOS, ML30 can be used in full IP mode
- 6124 Problem of DLL Crypto re-opening after closing fixed
- 6143 ZKA activation didn't work on 930 Bluetooth
- 6145 Colour display improvement
- 6203 Specific hardware type for ICT GPRS

6. CGUI

New version of CGUI: **01.07**.

CGUI is now provided natively in the SDK.

The Mock-up manager catalogue has to be loaded only to use the Ingedev CGUI Preview tool.

- 5435 Some files were not found in the TAR archives
- 6399 Numbering of the DLLs updated

7. DLL SECURITY

No evolution: version of DLL Security is: **03.10**.

8. DLL HARDWARE

No evolution: version of DLL Hardware is: **02.32**.

9. SCHEMES

No evolution: version is **03.06**.

10. LINKLAYER

No evolution: version of Link Layer is: **03.10**.

11. PACK IP

No evolution: version of Pack IP is: **03.05**.

12. FTP

No evolution: version of FTP is: **01.17**.

13. SSL

No evolution: version of SSL is: **01.48**.

14. AVL (ADDED VALUE LIBRARIES)

No evolution: version of AVL: **01.07**.

15. SDK

15.1 Fonts

No evolution: version of the fonts is: **01.09**.

15.2 Simulator

New version of the Simulator: **02.06**.

[END OF DOCUMENTATION]