

Approbation de la révision / Revision Approval : A		
	Nom <i>Name</i>	Fonction <i>Function</i>
Etabli par : <i>Written by:</i>	P. Plasse	SDK project manager
Vérifié ou Approuvé par : <i>Checked or approved by:</i>	C.Barthelemy	Export Product leader
Autorisé par : <i>Authorized by:</i>	C.Barthelemy	Export Product leader

Révision <i>Issue</i>	Date de validité / d'application <i>Validity/application date</i>	Nb de pages <i>Nb of pages</i>	Nb de pages annexes <i>Nb of appendices</i>	Objet et description de la modification <i>Object and description of modification</i>
A	June 2009			Release SDK 6.3.2

1 INTRODUCTION

This document describes the content of the SDK 6.3.2 delivery and evolutions/corrections from SDK 6.3.1.

2 TELIUM SYSTEM

The Telium System delivery is the pack **07.76**.

2.1 TELIUM GENERIC

- FT4035 Some MMC card didn't work (reset during the mount)
- FT4946 Sometimes MicroSD was blocked
- FT5079 Decrease of the delay (10ms instead of 1s) between two readings when USB FIFO is full. **MANDATORY WITH BIO TERMINALS**

2.2 EFT PORTABLE

- FT5010 Correction of the problem of unload of battery (printing became slower)

2.3 GPRS TELIUM 1 TERMINALS

- FT5071 Start of the HILO improved for ICT and EFT930S (IO management modified)
- FT4705 GSM disconnection delay reduced
- FT4791 Management of the L38 retrofit on EFT930S_GEM
- FT4860 Correction of the SIM id upload on GPRS HiLo
- FT4698 External command requests were lost when too near

2.4 930 BLUETOOTH

- FT5105 Cheque readers didn't work well on 930 Bluetooth

2.5 MR40 / CAD30

- FT3718 Reset after a EMV APDU command was sent to the BL2 CAM (NACK was only received on InterUc)
- FT4811 Reset on CAD30 UPT in *read_dateSys*
- FT4797 Correction of the wrong swipe reading after card staying in the swipe when the terminal goes to light sleep
- FT4814 Correction of the problem when the terminal goes into sleep just after a swipe reading
- FT5005 MR40 was sometimes blocked after a light sleep
- FT5009 Light sleep counter added
- FT5045 Stack overflow en mode V29FC.
- FT5117 After a deep sleep, the swipe was not read

3 TELIUM MANAGER

The Telium Manager delivery is the pack **52.02**.

3.1 NEW IN THE MANAGER

3.1.1 New features

No new feature in this release.

3.1.2 Corrections

FT4363 When AID was to confirm, no message was displayed (blank screen). Correction is in the management of the messages.

3.2 DLL SECURITY

No evolution: The DLL Security is the pack 03.07.

3.3 TCPIP

No evolution: TCPIP package delivery is the pack 03.05.

4 LINKLAYER

No evolution.

5 SCHEMES

No evolution.

6 AVL (ADDED VALUE LIBRARIES)

FT5090 XML module version is now 01.02
TLV Tree module version is now 01.04

FT5118 All AVL is now management as only one package : version is 01.03

7 SDK

FT5061 xml_expat.h and xmls.h added to the delivery.

FT4486 File controle.txt containing traps numbers added to the delivery.

FT5059 Correction of the compilation compatibility problem between Telium Pass and AVL

FT4970 Bad version of trace.exe for Telium1 in the SDK

FT4448 Samples available at the Ingedev format

FT2000 Include files provided as read-only

8 TOOLS

No evolution.