

Intel® 82580EB/82580DB Gigabit Ethernet Controller Specification Update

Networking Division (ND)

Revision 2.7
February 2020



Legal

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

Intel disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade.

This document contains information on products, services and/or processes in development. All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest forecast, schedule, specifications and roadmaps.

The products and services described may contain defects or errors which may cause deviations from published specifications.

Copies of documents which have an order number and are referenced in this document may be obtained by calling 1-800-548-4725 or by visiting www.intel.com/design/literature.htm.

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

* Other names and brands may be claimed as the property of others.

© 2020 Intel Corporation.



Revisions

Date	Revision	Description
12/2009	1.0	Initial public release
01/14/2010	2.0	Updated errata list for PRQ.
02/03/2010	2.1	Added spec. clarification: <ul style="list-style-type: none"> 1. EEPROM Required For Proper Operation of the 82580 Controller Updated errata: <ul style="list-style-type: none"> 3. Possible System Hang During Enable/Disable When Connecting through nVidia* IO55 Slot
03/01/2010	2.2	Updated sections: <ul style="list-style-type: none"> 1.3 Identifying Marks
06/25/2010	2.3	Updated: <ul style="list-style-type: none"> 1.3 Identifying Marks. Added marking information for Engineering samples. Updated or added errata: <ul style="list-style-type: none"> 6. LAN_DIS_N and AUX_PWR Pins Are Driven by the 82580 When Not Used for Strapping. Problem: The Com_MDIO (bit 30) and Destination (bit 31) bits of the MDICNFG register (0x0E04) are not loaded consistently from the EEPROM. In some cases, the hardware default value of 0b is used instead.. 8. Dummy Function Present When All Ports are Disabled.
7/16/2010	2.31	Added: <ul style="list-style-type: none"> 9. PCIe: Link Control 2 Register Contains Incorrect Read Values. Updated: <ul style="list-style-type: none"> 1. TAG Not Reset by Power-on-reset Function. Status changed to Closed. 5. PCIe Links at x1 Instead of x4 When Attached to Certain Chipset Ports.
8/20/2010	2.32	Specification Clarification added: <ul style="list-style-type: none"> 3. Use of Wake on LAN Together with Manageability Software Change added: <ul style="list-style-type: none"> Change: PBA Number Module—Word 0x8-0x9.
9/10/2010	2.33	Specification Change updated: <ul style="list-style-type: none"> Change: PBA Number Module—Word 0x8-0x9. Text updated to address confusion about new number format.
10/19/2010	2.34	Software Clarification updated: <ul style="list-style-type: none"> 1. While In TCP Segmentation Offload, Each Buffer is Limited to 64 KB.
1/6/2011	2.35	Specification Clarification added: <ul style="list-style-type: none"> 5. SerDes: AN_TIMEOUT Only Works When Link Partner Idle. Specification Changes added: <ul style="list-style-type: none"> 2. Updates to PXE/iSCSI EEPROM Words. Errata added or text updated: <ul style="list-style-type: none"> 5. PCIe Links at x1 Instead of x4 When Attached to Certain Chipset Ports. 10. I2C Data Out Hold Time Violation. Software Clarification added: <ul style="list-style-type: none"> 2. EEPROM Checksum Not Set for LAN1, 2, 3.



Date	Revision	Description
2/25/2011	2.36	<p>Document title updated to correctly reflect brand strings.</p> <p>Specification Clarification added:</p> <ul style="list-style-type: none"> 6. LED Modes Based on Link Speed Only work in Copper (Internal PHY) Mode. <p>Specification Change updated:</p> <ul style="list-style-type: none"> 2. Updates to PXE/iSCSI EEPROM Words. <p>Specification Change added:</p> <ul style="list-style-type: none"> 3. Update to Software Compatibility EEPROM Word 0x3. <p>Errata added:</p> <ul style="list-style-type: none"> 11. SGMII: Counters Incorrectly Increment on Collision. Problem: When using Rx L0s in an x1 configuration, the 82580 reports receiver errors at a rate of more than one per minute on some platforms.. 13. TSYNC: Auxiliary Timestamp from SDP is Unreliable. 14. PCIe: N_FTS Value is too Small When Common Clock Configuration is Zero.
4/7/2011	2.37	<p>Tables updated.</p> <ul style="list-style-type: none"> Table 1, Product and Device Identification.
7/20/2011	2.38	<p>Specification Clarifications added:</p> <ul style="list-style-type: none"> 7. PCIe: Completion Timeout Mechanism Compliance. 8. PCIe Timeout Interrupt <p>Errata added:</p> <ul style="list-style-type: none"> 15. NC-SI: Command Interface Non-functional During PCIe Reset Due to Device Power Down State. 16. IEEE Std 802.3™-2008 Tx Distortion Marginality.
8/15/2011	2.39	<p>Specification Clarifications updated:</p> <ul style="list-style-type: none"> 3. Use of Wake on LAN Together with Manageability. Driver-specific information added. 6. LED Modes Based on Link Speed Only work in Copper (Internal PHY) Mode. Error in problem statement corrected. <p>Specification Change updated:</p> <ul style="list-style-type: none"> 4. Updated Definition of SW EEPROM Port Identification LED Blinking (Word 0x4). Updated section for datasheet provided. <p>Software Clarification added:</p> <ul style="list-style-type: none"> 3. Serial Interfaces Programmed By Bit Banging.
8/24/2011	2.40	Addresses production issue.
9/14/2011	2.41	<p>Specification change added:</p> <ul style="list-style-type: none"> 5. Minimum Value for Flow Control Receive Threshold Low. <p>Errata added:</p> <ul style="list-style-type: none"> Problem: The NC-SI Specification, version 1.0.0a defines the Pass-through Tx Packets counter contained in the Get NC-SI Pass-through Statistics Response Packet to be an 8-byte field. The 82580 provides this counter as a 4-byte field..
1/30/2012	2.43	<p>Specification Clarification added:</p> <ul style="list-style-type: none"> 9. Padding on Transmitted SCTP Packets.
5/2/2012	2.44	<p>Errata added:</p> <ul style="list-style-type: none"> 18. PCIe Reset Causes FW Reset When Ports Are Disabled.
9/1/2012	2.45	<p>Specification Change added:</p> <ul style="list-style-type: none"> 6. I2C Timing Parameter Correction. <p>Specification Clarifications:</p> <ul style="list-style-type: none"> 7. PCIe: Completion Timeout Mechanism Compliance. Text updated. See italics. 10. Dynamic LED Modes Can Only Be Used in an Active Low Configuration. Added.



Date	Revision	Description
July 2014	2.5	Added Specification Changes #7 through #9. Added Specification Clarification #11. Added Errata #19 through #22.
August 2015	2.6	Added Errata #23 #24.
February 2020	2.7	Added Specification Clarification #12.



NOTE: *This page intentionally left blank.*



1.1 Introduction

This document is an update to the product datasheet. It is intended for use by system manufacturers and software developers. All product documents are subject to frequent revision. Be sure you have the latest information before finalizing your design.

References to PCIe* in this document refer to PCIe v2.0 (5Gbps).

1.2 Product and Device Identification

Table 1. Product and Device Identification

MM#	Stepping	Top Marking	Spec #	Intel SPEED iPN	Status & Media	Description
905781	A1	NH82580EB	S LH5P	E69716-003	Production, T&R	1 Gbs, 4-port
905782	A1	NH82580EB	S LH5Q	E69716-004	Production, Tray	
905783	A1	NH82580EK	S LH5R	E82069-002	Production, T&R	1 Gbs 4-port SERDES
905784	A1	NH82580EK	S LH5S	E82069-003	Production, Tray	
905785	A1	NH82580DB	S LH5T	E82070-002	Production, T&R	1 Gbs, 2-port
905786	A1	NH82580DB	S LH5U	E82070-003	Production, Tray	
904983	A1	NH82580EB	Q MQR	E69716-002	Engineering, Tray	1 Gbs, 4 port
907335	A1	NH82580EK	Q MQT	E82069-001	Engineering, Tray	1 Gbs, 4-port SERDES
907334	A1	NH82580DB	Q MQS	E82070-001	Engineering, Tray	1 Gbs, 2-port
903315	A0	NH82580EB	Q LSY	E69716-001	Engineering, Tray	1 Gbs, 4-port

1.3 Identifying Marks




Figure 1. Sample Component Diagram Illustrating Identifying Marks

Refer to [Figure 1](#):

Line 1	"intel"
Line 2	Marketing Name
Line 3	Fab Lot Number "XXXXXXXX" (Wafer Lot no. concatenated with Assembler vendor code)
Line 4	Assembly Date Code YYWW; Engineering samples have additional Intel data.
Line 5	Copyright line; includes two number date code and the Pb-free mark (e1)
Line 6	Country of Origin

1.4 Nomenclature Used In This Document

This document uses specific terms, codes, and abbreviations to describe changes, errata, sightings and/or clarifications that apply to a specific silicon stepping. See [Table 2](#) for a description.

Table 2. Nomenclature

Name	Description
Specification Changes	Modifications to the current published specifications. These changes will be incorporated in the next release of the specifications.
Errata	Design defects or errors. Errata may cause device behavior to deviate from published specifications. Hardware and software designed to be used with any given stepping must assume that all errata documented for that stepping are present on all devices.
Sightings	Observed issues that are believed to be errata, but have not been completely confirmed or root caused. The intention of documenting sightings is to pro-actively inform users of behaviors or issues that have been observed. Sightings may evolve to errata or may be removed as non-issues after investigation completes.

**Table 2. Nomenclature**

Specification Clarifications	Greater detail or further highlights concerning a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the specifications.
Software Clarifications	Applies to Intel drivers, EEPROM loads.
Documentation Corrections	Errors, or omissions in current published specifications. These changes are incorporated in the next release of the applicable document and then dropped from the spec update. You may also check for changes in the revision history of specific documents.
A1, B1, etc.	Stepping to which the status applies.
Doc	Document change or update that will be implemented.
Fix	This erratum is intended to be fixed in a future stepping of the component.
Fixed	This erratum has been fixed.
EEPROM/NVM Fix	This indicates the Errata was in the EEPROM/NVM and is fixed in an updated version.
NoFix	There are no plans to fix this erratum.
Eval	Plans to fix this erratum are under evaluation.
Red Change Bar/ or Bold	This Item is either new or modified from the previous version of the document.

1.5 Sightings, Clarifications, Changes, Errata, Software Clarifications

See [Section 1.4](#) above for an explanation of terms, codes, and abbreviations.

Table 3. Summary of Sightings, Clarifications, Changes, Errata, Software Clarifications

Sightings	Status
1. None.	N/A
Specification Clarifications	Status
1. EEPROM Required For Proper Operation of the 82580 Controller	N/A
2. AC JTAG Junction Temperature Limit	N/A
3. Use of Wake on LAN Together with Manageability	N/A
4. SMBus: Illegal STOP Condition	N/A
5. SerDes: AN_TIMEOUT Only Works When Link Partner Idle	N/A
6. LED Modes Based on Link Speed Only work in Copper (Internal PHY) Mode	N/A
7. PCIe: Completion Timeout Mechanism Compliance	N/A
8. PCIe Timeout Interrupt	N/A
9. Padding on Transmitted SCTP Packets	N/A
10. Dynamic LED Modes Can Only Be Used in an Active Low Configuration	N/A
11. TimeSync: Ensure that the Programmed Target Time is in the Future	N/A
12. PCIe Separate Reference Clock with Independent Spread (SRIS) Support	N/A
Specification Changes	Status
Change: PBA Number Module—Word 0x8-0x9	N/A
2. Updates to PXE/iSCSI EEPROM Words	N/A
3. Update to Software Compatibility EEPROM Word 0x3	N/A
4. Updated Definition of SW EEPROM Port Identification LED Blinking (Word 0x4)	N/A



Table 3. Summary of Sightings, Clarifications, Changes, Errata, Software Clarifications

5. Minimum Value for Flow Control Receive Threshold Low	N/A
6. I2C Timing Parameter Correction	N/A
7. PXE VLAN NVM Words	N/A
8. Update to SerDes Loopback Configuration	N/A
9. Device Reset (CTRL.DEV_RST) should not be used	N/A
Errata	
1. TAG Not Reset by Power-on-reset Function	Closed
2. MNG Reset Clears Resource Grant With No Feedback	A1 NoFix
3. Possible System Hang During Enable/Disable When Connecting through nVidia* IO55 Slot	A1 NoFix
4. SMBus: EEPROM Not Written On ARP If the EEPROM Semaphore Is Taken by SW	A1 NoFix
5. PCIe Links at x1 Instead of x4 When Attached to Certain Chipset Ports	A1 NoFix
6. LAN_DIS_N and AUX_PWR Pins Are Driven by the 82580 When Not Used for Strapping	A1 NoFix
7. MDIO: Com_MDIO and Destination Bits of MDICNFG Register Are Not Loaded Consistently from EEPROM	A1 NoFix
8. Dummy Function Present When All Ports are Disabled	A1 NoFix
9. PCIe: Link Control 2 Register Contains Incorrect Read Values	A1 NoFix
10. I2C Data Out Hold Time Violation	A1 NoFix
11. SGMII: Counters Incorrectly Increment on Collision	A1 NoFix
12. PCIe: Correctable Errors Reported When Using Rx L0s in a x1 Configuration	A1 NoFix
13. TSYNC: Auxiliary Timestamp from SDP is Unreliable	A1 NoFix
14. PCIe: N_FTS Value is too Small When Common Clock Configuration is Zero	A1 NoFix
15. NC-SI: Command Interface Non-functional During PCIe Reset Due to Device Power Down State	A1 NoFix
16. IEEE Std 802.3™-2008 Tx Distortion Marginality	A1 NoFix
17. NC-SI: Get NC-SI Pass-through Statistics Response Format	A1 NoFix
18. PCIe Reset Causes FW Reset When Ports Are Disabled	Fixed in EEPROM
19. First Flash Read After Switching Ports Might Be Corrupt	A1 NoFix
20. Update to PXE/iSCSI Word 0x30, 0x34, 0x38, 0x3A bit 5	A1 NoFix
21. NC-SI: Count of Dropped Control Packets Could Be Incorrect	A1 NoFix
22. Common MDIO Failure when Port 0 is Disabled or Powered Down	A1 NoFix
23. NC-SI: Output Signals Have Indeterminate Value After Power Up	A1 NoFix
24. Certain Malformed IPv6 Extension Headers Are Not Processed Correctly By The Device	A1 NoFix
Software Clarifications	
1. While In TCP Segmentation Offload, Each Buffer is Limited to 64 KB	N/A
2. EEPROM Checksum Not Set for LAN1, 2, 3	N/A
3. Serial Interfaces Programmed By Bit Banging	N/A



1.5.1 Sightings

1. None.

1.5.2 Specification Clarifications

1. EEPROM Required For Proper Operation of the 82580 Controller

Clarification: Problems identified in the PCIe logic were resolved by implementing workarounds in EEPROM. Without these workarounds, the PCIe bus may not properly configure and the possibility exists that the controller will not negotiate a PCIe connection. This leaves the 82580 inaccessible.

Workaround: Use an EEPROM with the workarounds (v3.22 or greater) to ensure proper device configuration.

2. AC JTAG Junction Temperature Limit

Specification: IEEE 1149.6: A Boundary-Scan Standard for Advanced Digital Networks

Clarification: AC JTAG (IEEE 1149.6) is supported only up to a junction temperature of 70°C.

Workaround: None. This is a design parameter for the hardware.

3. Use of Wake on LAN Together with Manageability

Clarification: The Wakeup Filter Control Register (WUFC) contains the NoTCO bit, which affects the behavior of the wakeup functionality when manageability is in use. Note that if manageability is not enabled, the value of NoTCO has no effect.

When NoTCO contains the hardware default value of 0b, any received packet that matches the wakeup filters will wake the system. This could cause unintended wakeups in certain situations. For example, if Directed Exact Wakeup is used and the manageability shares the host's MAC address, IPMI packets that are intended for the BMC wakes the system, which might not be the intended behavior.

When NoTCO is set to 1b, any packet that passes the manageability filter, even if it also is copied to the host, is excluded from the wakeup logic. This solves the previous problem since IPMI packets do not wake the system. However, with NoTCO=1b, broadcast packets, including broadcast magic packets, do not wake the system since they pass the manageability filters and are therefore excluded.

Effects of NoTCO Settings WoL	NoTCO	Shared MAC Address	Unicast Packet	Broadcast Packet
Magic Packet	0b	-	OK	OK
Magic Packet	1b	Y	No wake	No wake
Magic Packet	1b	N	OK	No wake
Directed Exact	0b	Y	Wake even if MNG packet. No way to talk to BMC without waking host.	N/A



Effects of NoTCO Settings WoL	NoTCO	Shared MAC Address	Unicast Packet	Broadcast Packet
Directed Exact	0b	N	OK	N/A
Directed Exact	1b	-	OK	N/A

The Intel Windows* drivers set NoTCO by default.

If this is not not desired behavior, the EnableWakeOnManagmentOnTCO registry entry can be used to change this setting starting with Intel LAN driver SW release 15.7. Setting this registry entry to 1b causes the driver to program NoTCO to 0b. A tool to modify the registry entry can be provided.

Contact your Intel representative for access.

4. SMBus: Illegal STOP Condition

Clarification: It is important to prevent illegal STOP conditions on the SMBus interface, even when resetting the MC.

Specifically, a STOP condition should never be generated by the MC during the high clock phase of an ACK cycle while reading packet data from the 82580 as part of a Receive TCO LAN packet transaction.

If this situation occurs, the 82580 replies with a NACK to all future commands until a power cycle. As a result, the SMBus interface becomes inoperable.

Ensure that this illegal sequence does not occur, even during MC reset.

5. SerDes: AN_TIMEOUT Only Works When Link Partner Idle

Clarification: The auto-negotiation timeout mechanism (PCS_LCTL.AN_TIMEOUT_EN) only works if the SerDes partner is sending idle code groups continuously for the duration of the timeout period, which is the usual case.

However, if the partner is transmitting packets, an auto-negotiation timeout will not occur since auto-negotiation is restarted at the beginning of each packet. If the partner has an application that indefinitely transmits data despite the lack of any response, it is possible that a link will not be established.

If this is a concern, the auto-negotiation timeout mechanism may be considered unreliable and an additional software mechanism could be used to disable auto-negotiation if sync is maintained without a link being established (PCS_LSTS.SYNC_OK=1b and PCS_LSTS.LINK_OK=0b) for an extended period of time.

6. LED Modes Based on Link Speed Only work in Copper (Internal PHY) Mode

Clarification: LED modes based on LINK speed work only in copper mode, not in SerDes/SGMII modes. This includes the modes LINK_10/1000, LINK_100/1000, LINK_10, LINK_100, LINK_1000 and COLLISION.

Designs using SerDes and SGMII modes requiring a Link-up indication should use LINK_UP or LINK/ACTIVITY LED modes. Using these modes results in no issues in using the LEDs to properly indicate the link is up.



7. PCIe: Completion Timeout Mechanism Compliance

Clarification: The 82580 Completion Timeout Value[3:0] must be properly set by the system BIOS in the 82580 PCIe Configuration Space Device Control 2 register (0xC8; W). Failure to do so can cause unexpected completion timeouts.

The 82580 complies with the PCIe 2.0 specification for the completion timeout mechanism and programmable timeout values. The PCIe 2.0 specification provides programmable timeout ranges between 50us to 64s with a default time range of 50us—50ms. The 82580 defaults to a range of 16ms—32ms.

The completion timeout value must be programmed correctly in PCIe configuration space (in Device Control 2 register); the value must be set above the expected maximum latency for completions. This ensures that the 82580 receives completions for the requests it sends out. Failure to properly set the completion timeout value can result in the device timing out prior to a completion returning.

The 82580 can be programmed to resend a completion request after a completion timeout (the original completion is assumed lost). But if the original completion arrives after a resend request, two completions may arrive for the same request; this can cause unpredictable behavior. Intel EEPROM images set the resend feature to off. Intel recommends that you do not change this setting.

For details on completion timeout operation, refer to the Datasheet.

8. PCIe Timeout Interrupt

Clarification: The PCIe Timeout Exception (TO) bit in the PCIe Interrupt Cause (PICAUSE) register is set when a timeout occurs on an access to the address space of this port. This includes accesses initiated by the EEPROM auto-load function and manageability firmware, in addition to accesses from the PCIe interface.

This interrupt bit does not necessarily indicate a problem with a PCIe transaction and further analysis would be required to determine the source of problem.

9. Padding on Transmitted SCTP Packets

Clarification: When using the 82580EB/DB to offload the CRC calculation for transmitted SCTP packets, software should not add Ethernet padding bytes to short packets (less than 64 bytes). Instead, the TCTL.PSP bit should be set so that the 82580EB/DB pads the packets after performing the CRC calculation.

10. Dynamic LED Modes Can Only Be Used in an Active Low Configuration

Clarification: In any of the dynamic LED modes (FILTER_ACTIVITY, LINK/ACTIVITY, COLLISION, ACTIVITY, PAUSED), LED blinking should only be enabled if the LED signal is configured as an active low output.

11. TimeSync: Ensure that the Programmed Target Time is in the Future

Clarification: When using the target time feature of the TimeSync logic, software should ensure that the target time being programmed is always in the future. For example, the target time should be larger than the system time except for when the intention is for the target time to be after the system time has wrapped. Unintentionally programming a target time that is smaller than the system time disables the target time functionality until the system time has wrapped.



12. PCIe Separate Reference Clock with Independent Spread (SRIS) Support

Clarification: PCIe Separate Reference Clock with Independent Spread (SRIS) is NOT supported. The device requires a common PCIe reference clock and should be configured with Common Clock: Mode in BIOS. SRIS mode causes PCI bus enumeration to fail.

1.5.3 Specification Changes

1. Update to PBA Number EEPROM Word Format

Change: PBA Number Module—Word 0x8-0x9

The nine-digit Printed Board Assembly (PBA) number used for Intel manufactured Network Interface Cards (NICs) is stored in EEPROM.

Through the course of hardware ECOs, the suffix field is incremented. The purpose of this information is to enable customer support (or any user) to identify the revision level of a product.

Network driver software should not rely on this field to identify the product or its capabilities.

PBA numbers have exceeded the length that can be stored as HEX values in two words. For newer NICs, the high word in the PBA Number Module is a flag (0xFAFA) indicating that the actual PBA is stored in a separate PBA block. The low word is a pointer to the starting word of the PBA block.

The following shows the format of the PBA Number Module field for new products.

PBA Number	Word 0x8	Word 0x9
G23456-003	FAFA	Pointer to PBA Block

The following provides the format of the PBA block; pointed to by word 0x9 above:

Word Offset	Description
0x0	Length in words of the PBA Block (default is 0x6)
0x1 ... 0x5	PBA Number stored in hexadecimal ASCII values.

The new PBA block contains the complete PBA number and includes the dash and the first digit of the 3-digit suffix which were not included previously. Each digit is represented by its hexadecimal-ASCII values.

The following shows an example PBA number (in the new style):

PBA Number	Word Offset 0	Word Offset 1	Word Offset 2	Word Offset 3	Word Offset 4	Word Offset 5
G23456-003	0006	4732	3334	3536	2D30	3033
	Specifies 6 words	G2	34	56	-0	03



Older NICs have PBA numbers starting with [A,B,C,D,E] and are stored directly in words 0x8-0x9. The dash in the PBA number is not stored; nor is the first digit of the 3-digit suffix (the first digit is always 0b for older products).

The following example shows a PBA number stored in the PBA Number Module field (in the old style):

PBA Number	Byte 1	Byte 2	Byte 3	Byte 4
E23456-003	E2	34	56	03

2. Updates to PXE/iSCSI EEPROM Words

Change: Word 0x30, 34, 38, 3A are now defined as follows:

Bit(s)	Value	Port Status	CLP (Combo) Executes	iSCSI Boot Option ROM CTRL-D Menu	FCoE Boot Option ROM CTRL-D Menu
15:6	Same as before.				
5	Bit 5, formerly used to indicate iSCSI enable/disable, is no longer valid and is not checked by software.				
4:3	Same as before.				
2:0	101-111	Reserved			
	100	FCoE	FCoE	Displays port as FCoE. Allows changing port to Boot Disabled, iSCSI Primary or Secondary.	Displays port as FCoE. Allows changing to Boot Disabled.
	011	iSCSI Secondary	iSCSI	Displays port as iSCSI Secondary. Allows changing to Boot Disabled, iSCSI Primary.	Displays port as iSCSI. Allows changing to Boot Disabled, FCoE Enabled.
	010	iSCSI Primary	iSCSI	Displays port as iSCSI Primary. Allows changing to Boot Disabled, iSCSI Secondary.	Displays port as iSCSI. Allows changing to Boot Disabled, FCoE Enabled.
	001	Boot Disabled	NONE	Displays port as Disabled. Allows changing to iSCSI Primary/Secondary.	Displays port as Disabled. Allows changing to FCoE enabled.
	000	PXE	PXE	Displays port as PXE. Allows changing to Boot Disabled, iSCSI Primary or Secondary.	Displays port as PXE. Allows changing to Boot Disabled, FCoE Enabled.

Bit 5 Description:

Bit	Name	Default	Description
5	Disable iSCSI Setup Menu	0x0	<p>This controls iSCSI init message (Ctrl+D menu prompt) when iSCSI is disabled.</p> <ul style="list-style-type: none"> When iSCSI option ROM is disabled and this bit is 1, the init message is not displayed for the port. When iSCSI option ROM is disabled and this bit is 0, the init message is displayed for the port. When iSCSI option ROM is enabled this bit does not matter, as the init message is displayed for the port.



3. Update to Software Compatibility EEPROM Word 0x3

Change: To Software Compatibility EEPROM Word 0x3:

Bit	Name	Default	Description
15	Checksum Flag/Reserved	0	0b: Only the checksum for LAN0 is valid 1b: All 4 LAN checksum are valid.
14:13	Reserved	0	Reserved
12	Reserved	0	Reserved
11	LOM	0	Indicates whether dedicated flash for the option ROM is attached to LAN silicon. Used by option ROM update applications (DMIX). 0b: NIC (A dedicated flash is attached) 1b: LOM (No dedicated flash is attached)
10	Reserved	0	Reserved
9	Client	0	Client/Not a Client NIC 0b = Server. 1b = Client. This bit is used by DMIX to verify the NIC is server or client. A team is required to have server NIC or LOM.
8	Reserved	0	Reserved.
7:5	Reserved	0	Reserved
4	Reserved	0	Reserved
3	Reserved	0	Reserved
2	Reserved	0	Reserved
1:0	Reserved	0	Reserved

4. Updated Definition of SW EEPROM Port Identification LED Blinking (Word 0x4)

Change: Port Identification LED blinking (Word 0x04)

Driver software provides a method to identify an external port on a system through a command that causes the LED's to blink. Based on the setting in word 0x4, the LED drivers should blink between STATE1 and STATE2 when a port identification command is issued.



When word 0x4 is equal to 0xFFFF or 0x0000, the blinking behavior reverts to a default.

Bit	Description
15:12	Control for LED 3 0000b or 1111b: Default LED Blinking operation is used. 0001b = Default in STATE1 + Default in STATE2. 0010b = Default in STATE1 + LED is ON in STATE2. 0011b = Default in STATE1 + LED is OFF in STATE2. 0100b = LED is ON in STATE1 + Default in STATE2. 0101b = LED is ON in STATE1 + LED is ON in STATE2. 0110b = LED is ON in STATE1 + LED is OFF in STATE2. 0111b = LED is OFF in STATE1 + Default in STATE2. 1000b = LED is OFF in STATE1 + LED is ON in STATE2. 1001b = LED is OFF in STATE1 + LED is OFF in STATE2. All other values are Reserved.
11:8	Control for LED 2 – same encoding as for LED 3.
7:4	Control for LED 1 – same encoding as for LED 3.
3:0	Control for LED 0 – same encoding as for LED 3.

5. Minimum Value for Flow Control Receive Threshold Low

Change: If FCRTL0.XONE is 1, the minimum value allowed in FCRTL0.RTL is 3 (48 bytes).

6. I²C Timing Parameter Correction

Change: In the I²C Timing Parameters table, the values of T_{SU:STA} and T_{SU:STO} should be 0.6 μ s (Min).

7. PXE VLAN NVM Words

Change: With Intel SW Release 17.1, TVL SW 2 support was added to the Intel Boot Agent to enable tagging for VLAN and 802.1p priority.

Note that some words are only included in multi-port devices. Single-port devices need only the Port 0 word, Dual-port devices need only the Port 0 & 1 words.

The following EEPROM words are now defined as follows:

Table 4. PXE VLAN Configuration Pointer—(0x003C)

Bits	Field Name	Default	Description
15:0	PXE VLAN Configuration Pointer	0x0	The pointer contains offset of the first NVM word of the PXE VLAN config block.

Table 5. PXE VLAN Configuration Section Summary Table

Word Offset	Field Name	Description
0x0000	VLAN Block Signature	ASCII "V", "L".
0x0001	Version and Size	Contains version and size of structure.



0x0002	Port 0 VLAN Tag	VLAN tag value for first port of the controller. Contains PCP, CFI and VID fields. Value 0 means no VLAN configured for port.
0x0003	Port 1 VLAN Tag	VLAN tag value for second port of the controller. Contains PCP, CFI and VID fields. Value 0 means no VLAN configured for port.
0x0004	Port 2 VLAN Tag	VLAN tag value for third port of the controller. Contains PCP, CFI and VID fields. Value 0 means no VLAN configured for port.
0x0005	Port 3 VLAN Tag	VLAN tag value for fourth port of the controller. Contains PCP, CFI and VID fields. Value 0 means no VLAN configured for port.

Table 6. VLAN Block Signature—0x0000

Bits	Field Name	Default	Description
15:0	PXE VLAN Block Signature	0x4C56	ASCII 'V', 'L'

Table 7. Version and Size—0x0001

Bits	Field Name	Default	Description
15:8	Size		Total size in bytes of section
7:0	Version	0x01	Version of this structure. Should be set to 1.

Table 8. Port 0 VLAN Tag—0x0002

Bits	Field Name	Default	Description
15:13	Priority (0-7)	0x0	Priority 0-7
12	Reserved	0x0	Always 0
11:0	VLAN ID (1-4095)	0x0	VLAN ID (1-4095)

**Table 9. Port 1 VLAN Tag—0x0003**

Bits	Field Name	Default	Description
15:13	Priority (0-7)	0x0	Priority 0-7
12	Reserved	0x0	Always 0
11:0	VLAN ID (1-4095)	0x0	VLAN ID (1-4095)

Table 10. Port 2 VLAN Tag—0x0004

Bits	Field Name	Default	Description
15:13	Priority (0-7)	0x0	Priority 0-7
12	Reserved	0x0	Always 0
11:0	VLAN ID (1-4095)	0x0	VLAN ID (1-4095)

Table 11. Port 3 VLAN Tag—0x0005

Bits	Field Name	Default	Description
15:13	Priority (0-7)	0x0	Priority 0-7
12	Reserved	0x0	Always 0
11:0	VLAN ID (1-4095)	0x0	VLAN ID (1-4095)

8. Update to SerDes Loopback Configuration

Add the following definition to the PCS_CFG register (0x4200):

Bit	Field	Initial Value	Description
IGN_SD	0	0	Ignore Signal Detection 0b = Attempt to establish a link only when a signal is present. 1b = Ignore the signal detection logic and always attempt to establish a link. This bit should be 0b for normal operation. It should be 1b for SerDes loopback operation.

2. Add the following to the procedure for setting SerDes Loopback Mode:

- PCS_CFG.IGN_SD (CSR 0x4200 bit 0) = 1b

Intel LAN drivers and tools implemented the above workaround in Release 17.5

9. Device Reset (CTRL.DEV_RST) should not be used

Problem: The DEV_RST bit in the CTRL register should not be used. This bit should be treated as Reserved and always written as 0b.

Intel LAN drivers remove the use DEV_RST in Release 17.5.

1.5.4 Errata

1. TAG Not Reset by Power-on-reset Function

Note: Not applicable to current products.

Status: Closed

2. MNG Reset Clears Resource Grant With No Feedback

Problem: When accessing the EEPROM (via EEC register) or FLASH (via FLA register), grants may be lost due to deadlock or FW reset. Software will not be notified of the lost grant. A driver in the middle of a bit bang may renew the request and receive the grant without knowing that it is actually starting a new transaction.

Implications:

1. FLA/EEC bit banging transactions may fail.
2. Long transactions may turn into different transactions than expected.

Workaround:

1. SW should not execute bit bang sequences longer than one word at a time.
2. When SW reads the EEC/FLA, it should make sure that it still has the request and grant; if not it should renew it and re-start the transaction (this does not cover all cases but reduces the possibility of a problem).

Status: A1 NoFix

3. Possible System Hang During Enable/Disable When Connecting through nVidia* IO55 Slot

Problem: Once the link is up, when the 82580 tries to connect with the nVidia IO55 chipset, the following may occur:

- The Link layer tries to train but not all lanes work.
- The 82580EB/DB tries retraining with fewer lanes; but during retraining may loop.
- The system hangs.

Implication: The 82580 cannot reliably connect using this configuration.

Workaround: Connecting to a different port on the system.

Status: A1 NoFix

4. SMBus: EEPROM Not Written On ARP If the EEPROM Semaphore Is Taken by SW

Problem: If an SMBus ARP address is stored at the same time the EEPROM is locked by SW, the address is not be saved.

Implication : Wrong SMBus address after firmware reset.

Workaround: Set the SMBus address in the EEPROM (not through ARP).



Status: A1 NoFix

5. PCIe Links at x1 Instead of x4 When Attached to Certain Chipset Ports

Problem: When the 82580 is connected to certain PCIe x4 ports, the PCIe link is x1 instead of x4. The affected ports on Intel devices have a Device ID of 0x2690. These ports can be found on:

- 6311ESB2/6321ESB2 I/O Controller Hub
- INTEL 3100 SCH Port B

Implications: If the PCIe link is x1, the bandwidth is limited and might not be sufficient for all device ports, resulting in a performance bottleneck.

Workaround: Do not attach the 82580 to this chipset port. If such a connection cannot be avoided, please contact your Intel representative for assistance.

Status: A1 NoFix

6. LAN_DIS_N and AUX_PWR Pins Are Driven by the 82580 When Not Used for Strapping

Problem: At other times, these pins become outputs and are driven low.

Implication If these pins are driven high from another device, there could be high current draw.

If the external pull-up resistor used on these pins is not strong enough, the wrong value could be sampled at the beginning of the PCIe reset.

Workaround When driving the LANx_DIS_N and/or AUX_PWR pins from another device, use a series resistor between the devices to reduce the current.

For both external pull-up resistors and series resistors, ensure that the resistor is strong enough to pull up the pin within 40 ns. Assuming relatively short traces between the 82580 and the resistor, a 3.3 K ohm resistor should work well. Larger resistance values should not be used.

Status: A1 NoFix

7. MDIO: Com_MDIO and Destination Bits of MDICNFG Register Are Not Loaded Consistently from EEPROM

Problem: The Com_MDIO (bit 30) and Destination (bit 31) bits of the MDICNFG register (0x0E04) are not loaded consistently from the EEPROM. In some cases, the hardware default value of 0b is used instead.

Implication Software that relies on the EEPROM-loaded value might not be able to initialize an external PHY. When not using an external PHY, there is no issue.

Workaround Software should assume that the initial values of these bits are undefined and should program them before attempting to initialize an external PHY. The EEPROM bits can be used to determine the intended settings.



Status: A1 NoFix

8. Dummy Function Present When All Ports are Disabled

Problem: When all ports are disabled, either by strapping pins or by EEPROM settings, no PCIe functions should be present. However, if the Dummy Function Enable EEPROM bit (word 0x1B, bit 14) is set to 1b, Function 0 becomes a dummy function even if all ports are disabled.

Implication Even with all ports disabled, Function 0 appears in the system PCIe enumeration with a Device ID of 0x10A6, indicating a dummy function. This should not have any effect on the system.

Workaround N/A

Status: A1 NoFix

9. PCIe: Link Control 2 Register Contains Incorrect Read Values

Problem: The Target Link Speed and Transmit Margin fields of the Link Control 2 Register in the PCIe configuration space are described as follows in the PCIe specification:

“For a Multi-Function device associated with an Upstream Port, the field in Function 0 is of type RWS, and only Function 0 controls the component’s Link behavior. In all other Functions of that device, this field is of type RsvdP.”

This means that when reading the Link Control 2 Register on functions other than Function 0, these fields should be 0b. Instead, the 82580 returns the value written to Function 0, behavior which differs from the specification.

Implication: No functional implication since these fields are defined as reserved and ignored by software.

Workaround:N/A

Status: A1 NoFix

10. I²C Data Out Hold Time Violation

Problem: The 82580 should provide a data out hold time of 50 ns on the SFPx_I2C_DATA pins. The actual hold time is about 16 ns.

Implication: Timing specification violation. There have been no reports of failures resulting from this timing. Note that the data input hold time required is zero, so the provided output hold time should be more than enough as long as the I²C CLK and DATA signals are reasonably matched on the board.

Workaround:N/A

Status: A1 NoFix

11. SGMII: Counters Incorrectly Increment on Collision

Problem: In SGMII mode/half duplex, the statistics counters listed below incorrectly increment when a collision occurs:



Name	Definition	Location
RLEC	Length error counter	0X4040
CRCERRS	CRC error counter	0x4000
RFC	receive frame counter	0x40A8

Implication: Error counters may not be accurate.

Workaround: None.

Status: A1 NoFix

12. PCIe: Correctable Errors Reported When Using Rx L0s in a x1 Configuration

Problem: When using Rx L0s in an x1 configuration, the 82580 reports receiver errors at a rate of more than one per minute on some platforms.

Implication: Correctable errors are reported at a higher rate than can be explained by random bit errors. These errors should be ignored by the system.

Workaround: None.

Status: A1 NoFix

13. TSYNC: Auxiliary Timestamp from SDP is Unreliable

Problem: The SDP inputs to the timestamp logic are not properly synchronized. As a result, both the Auxiliary Timestamp Register values and the Auxiliary Timestamp Taken bits in TSAUXC are sometimes loaded incorrectly.

Implication: The auxiliary timestamp feature should be considered unreliable.

Workaround: For applications that use the auxiliary timestamp feature to synchronize to an external clock, it might be acceptable to drop some of the samples. For such applications, software can filter out many of the incorrect timestamp values by comparing them to an approximate expected timestamp and discarding unreasonable values.

In addition, the following method can be used to filter out incorrect values:

- Connect the input signal to two SDP inputs for the same port.
- Using the TSSDP register, assign one of the SDP inputs to AUX0 and the other SDP input to AUX1.
- When reading the TSAUXC register to check for new samples, check that both AUTT0 and AUTT1 are set. Otherwise, discard the sample.
- Read both the AUX0 and AUX1 timestamp values and compare the values. Discard the values if they differ by more than the sampling uncertainty -- 8 ns if the SDP inputs are balanced externally or slightly higher if the external trace lengths differ significantly.

Using this method, along with a SW filter for expected values, almost all errors can be filtered out, with the remaining samples having a very high probability of being correct.

When using Port 0, the following combinations of SDP connections to AUX0 and AUX1 allow the above method to filter out all errors.

AUX0 Connection	AUX1 Connection
SDP0	SDP1
SDP0	SDP3
SDP1	SDP0



SDP1	SDP2
SDP2	SDP0
SDP2	SDP1
SDP2	SDP3
SDP3	SDP2

Status: A1 NoFix

14. PCIe: N_FTS Value is too Small When Common Clock Configuration is Zero

Problem: When the Common Clock Configuration bit in the Link Control Register is 0b, the value of N_FTS advertised by the 82580 is taken from internal configuration registers, with separate values used for Gen1 and Gen2 speeds. The hardware default values are too small to guarantee a clean exit from L0s in all cases.

As a result, link recovery procedures might be performed and Correctable Errors might be reported: Bad TLP, Bad DLLP, and Replay Timer Timeout.

Note that even on platforms where the Common Clock Configuration is set to 1b, this bit is cleared by Hot Reset or D3->D0 transitions, and the previous situation can still occur until the configuration space programming has been restored.

Implications: The Correctable Errors can generally be ignored. The link recovery procedures and replayed packets result in a small reduction of effective bandwidth on the PCIe link.

However, in certain circumstances on some platforms, the repeated loss of packets can lead to a Completion Timeout error, which might cause the application and/or the system to stop working.

Workaround: Disable L0s on the upstream device.

OR

Disable L0s on the upstream device before putting the 82580 in Hot Reset or D3 states.

OR

Upgrade EEPROM image. Fix in EEPROM version 3.29. Contact your Intel representative to obtain updated EEPROM images.

Status: A1 NoFix

15. NC-SI: Command Interface Non-functional During PCIe Reset Due to Device Power Down State

Problem: When the conditions for the Device Power Down State exist during power-up and NC-SI manageability is enabled, the MNG firmware is unable to respond to commands during PCIe reset.

This occurs when all the following are true:

- Power Down Enable EEPROM bit (word 0x1E bit 15) is set.
- PHY Power Down Enable EEPROM bit (offset 0x0F bit 6) is set for all ports using a copper link.
- SerDes Low Power Enable EEPROM bit (offset 0x0F bit 2) is set for all ports using a SerDes link.
- APM Enable EEPROM bit (offset 0x24 bit 10) is clear for all ports.



Implication: The NC-SI interface is non-functional during PCIe reset. Once PCIe reset has been negated and a Clear Initial State command has been executed, the interface functions as expected even if PCIe reset is asserted again.

Workaround: If the DEV_OFF_N input pin is not being used and if manageability is enabled, the Power Down Enable EEPROM bit (word 0x1E, bit 15) should be 0.

If the DEV_OFF_N input pin needs to be functional in the design, do not use the combination of EEPROM settings described above that causes this condition. For example, clear the PHY Power Down Enable bit on at least one port if using an NC-SI image.

Status: A1 NoFix

16. IEEE Std 802.3™-2008 Tx Distortion Marginality

Problem: The 82580 might not meet the IEEE Std 802.3™-2008 specification (40.6.1.2.4) that states that the Tx Distortion must meet the following criteria. "A PHY is considered to pass this test if the peak distortion is below 10 mV for at least 60% of the UI within the eye opening." The 82580 might marginally fail this requirement.

Implication: IEEE conformance is marginal.

The Tx distortion is less than 10 mV during the critical time when the signal is actually sampled therefore no impact on system performance is observed with the 82580 due to this marginality.

Workaround: None

Status: A1 NoFix

17. NC-SI: Get NC-SI Pass-through Statistics Response Format

Problem: The NC-SI Specification, version 1.0.0a defines the Pass-through Tx Packets counter contained in the Get NC-SI Pass-through Statistics Response Packet to be an 8-byte field. The 82580 provides this counter as a 4-byte field.

Implication: A BMC that uses the Get NC-SI Pass-through Statistics command and expects the response format as described in the NC-SI Specification will not parse the response as intended by the 82580 and will obtain inaccurate statistics.

Workaround: The BMC can account for the different format provided by the 82580 and parse the response accordingly.

Status: A1 NoFix

18. PCIe Reset Causes FW Reset When Ports Are Disabled

Problem: If one or more of the ports are disabled by strapping (asserting LANx_DIS_N) or from the EEPROM (by setting the LAN_DIS bit offset 0x20, bit 11), the firmware is reset following a PCIe reset. This applies to the 82580DB (dual-port) device even if neither port is explicitly disabled.

Implication: The manageability configuration is cleared by the PCIe reset and therefore any active session is disconnected.

On some of the ports the PHY is not configured correctly following the negation of the PCIe reset until the driver is loaded and resets the PHY. An incorrectly configured PHY could cause link issues and prevent WoL and/or manageability pass-through from working during this period of time.



Workaround: The Management Controller should re-run the initialization following PCIe reset to restore the configuration.

No workaround is available for the PHY configuration issues; the EEPROM should be updated to avoid this issue.

Status: Fixed in EEPROM

Fixed in EEPROM version 3.29. Contact your Intel representative to obtain updated EEPROM images.

19. First Flash Read After Switching Ports Might Be Corrupt

Problem: The data read from the Flash via a port's BAR0 or EXPROM BAR might be invalid if the previous read access from the Flash was from a different port. This also applies to the first read access after power-up if it is not from Port 0.

Implication: Invalid data read from the Flash could cause the BIOS to determine that there is no valid pre-boot image in the Flash.

Workaround: Do one of the following:
Only access the Flash from Port 0. For example, set the LAN Boot Disable EEPROM bit for Ports 1-3.

Use PCIe Gen1 speed.

A dummy Flash read access should be done before reading from the Flash each time it's possible that the previous Flash read access was from a different port. Single-threaded software could do the dummy read access before reading the Flash from each port. Multi-threaded software might use the SW_FLASH_SM semaphore bit to ensure that no other threads can interrupt a sequence of Flash read accesses. The dummy read could be performed once after acquiring the semaphore.

Status: A1 NoFix

20. Update to PXE/iSCSI Word 0x30, 0x34, 0x38, 0x3A bit 5

Problem: The data read from the Flash via a port's BAR0 or EXPROM BAR might be invalid if the previous read access from the Flash was from a different port. This also applies to the first read access after power-up if it is not from Port 0.

Implication: Invalid data read from the Flash could cause the BIOS to determine that there is no valid pre-boot image in the Flash.

Workaround: Do one of the following:
Only access the Flash from Port 0. For example, set the LAN Boot Disable EEPROM bit for Ports 1-3.

Use PCIe Gen1 speed.

A dummy Flash read access should be done before reading from the Flash each time it's possible that the previous Flash read access was from a different port. Single-threaded software could do the dummy read access before reading the Flash from each port. Multi-threaded software might use the SW_FLASH_SM semaphore bit to ensure that no other threads can interrupt a sequence of Flash read accesses. The dummy read could be performed once after acquiring the semaphore.



Status: A1 NoFix

21. NC-SI: Count of Dropped Control Packets Could Be Incorrect

Problem: The NC-SI Control Packets Dropped counter in the Get NC-SI Statistics Response packet does not include control packets that were dropped due to a checksum error.

Implication: Misleading statistics when debugging.

Workaround: Add the value of the NC-SI Command Checksum Errors counter to the value of the NC-SI Control Packets Dropped counter when processing a Get NC-SI Statistics Response packet.

Status: A1 NoFix

22. Common MDIO Failure when Port 0 is Disabled or Powered Down

Problem: The Common MDIO feature (using one pair of MDC/MDIO signals for multiple ports to access an external PHY) uses the Port 0 internal clock. If Port 0 is disabled (by strapping) or in a low-power state (non-D0a and no WoL and NoMng) the clock is gated off and the common MDIO logic does not operate.

Implication: Ports 1-3 cannot access the external PHY if Port 0 is not operational.

Workaround: For applications where Port 0 might be disabled by strapping, set the PHY_in_LAN_disable EEPROM bit for Port 0 so that the MAC is always operational.

Also, one of the following:

- Enable Wake on LAN for Port 0.
- Use an EEPROM image that has manageability enabled

Status: A1 NoFix

23. NC-SI: Output Signals Have Indeterminate Value After Power Up

Problem: The NC-SI output signals have an indeterminate value after power up until the first rising edge of the NC-SI input clock. The signals could be tri-stated or driven high or low.

Implication: Current leakage through the NC-SI I/O buffers.

Workaround: If the NC-SI input clock is not driven after power up, connect the NC-SI clock input pin so that there is a rising edge after power has stabilized. For example, it could be connected via a resistor to a power-good indication on the board.

Status: A1 NoFix



24. Certain Malformed IPv6 Extension Headers Are Not Processed Correctly By The Device

Problem: Certain malformed IPv6 extension headers are not processed correctly by the device.

Implication: If a packet containing such malformed IPv6 extension headers is received, the device might behave unpredictably.

Workaround: Set bit 16 (IPv6_ExDis) in the RFCTL register to disable the processing of received IPv6 extension headers. Note that with this bit set, checksum calculation and RSS are disabled for IPv6 packets containing extension headers.

This workaround has been implemented in Intel drivers starting from Release 20.2.

Status: A1 NoFix

1.5.5 Software Clarifications

Applies to Intel drivers, EEPROM loads.

1. While In TCP Segmentation Offload, Each Buffer is Limited to 64 KB

Clarification: The 82580 supports 256 KB TCP packets; however, each buffer is limited to 64 KB since the data length field in the transmit descriptor is only 16 bits. This restriction increases driver implementation complexity if the operating system passes down a scatter/gather element greater than 64KB in length. This can be avoided by limiting the offload size to 64 KB.

Investigation has concluded that the increase in data transfer size does not provide any noticeable improvements in LAN performance. As a result, Intel network software drivers limit the data transfer size in all drivers to 64 KB.

Please note that Linux operating systems only support 64 KB data transfers.

For further details about how Intel network software drivers address this issue, refer to Technical Advisory TA-191.

2. EEPROM Checksum Not Set for LAN1, 2, 3

Clarification: Intel provides tools to change EEPROM content: EEUPDATE, LANCONF, and CELO. Prior to SW Release 15.7, these tools changed EEPROM content but did not update or program the EEPROM checksums for LAN1, LAN2, and LAN3. More recent Intel EEPROM tools releases (Release 15.7 and later) fix this issue; they update and set EEPROM checksums for LAN 0,1,2,3.

The more recent tools also set word 0x3 (bit 15) in the EEPROM. This setting indicates that all four EEPROM checksums are valid. If bit 15 is not set, only the LAN 0 checksum is valid.

Note: Word 0x3 (bit 15) in the EEPROM was previously RESERVED in the documentation. The bit is now used for the above purpose and is no longer RESERVED.



3. Serial Interfaces Programmed By Bit Banging

Clarification: When bit-banging on a serial interface (such as SPI, I²C, or MDIO), it is often necessary to perform consecutive register writes with a minimum delay between them. However, simply inserting a software delay between the writes can be unreliable due to hardware delays on the CPU and PCIe interfaces. The delay at the final hardware interface might be less than intended if the first write is delayed by hardware more than the second write. To prevent such problems, a register read should be inserted between the first register write and the software delay, i.e. "write", "read", "software delay", "write".



NOTE: *This page intentionally left blank.*