

Electric Machine Control

Chapter 2

d-q Modelling of Induction and Synchronous Machines

Woei-Luen Chen

2.2 Winding Inductances

✚ Assumptions

- ❑ Uniform air gap induction machine (constant air gap length : g)
- ❑ Stator with sinusoidally wound three phase windings
- ❑ Neglect the slotting effects
 - Neglect harmonic components of flux arising from the placement of the actual conductors in the discrete slot
- ❑ The permeability of the stator and rotor iron is assumed to be Infinite
- ❑ Two poles construction

- ✱ The flux density is sinusoidally distributed spatially in the air gap
 - The induced rotor currents are always sinusoidally distributed spatially
 - Actual winding distribution (an n phase concentrated winding) can be replaced by an equivalent 3Φ sinusoidally distributed winding




Figure 2.1 Placement of conductors of one stator or rotor phase around the air gap of a two pole machine. The details of the slot shape are not shown for clarity.

Winding density distribution




Figure 2.2 Idealized induction machine illustrating sinusoidal distribution of one phase winding

N_x : effective number of the turns

$$\int_0^{\pi} \eta_m \sin \xi d\xi = N_x \quad (2.2-2)$$

$$\eta_m = \frac{N_x}{2} \quad (2.2-3)$$

$$N_x = k_p k_d k_s N_t$$

N_t : actual number of the turns

Ampere's Law

Nt: actual number of the turns


(2.2-3)

$$dN(\xi_o) = \frac{N_x}{2} \sin \xi_o d\xi \quad (2.2-5)$$

$$\oint \vec{H} \cdot d\vec{l} = \int_1^2 \vec{H}_{12} \cdot d\vec{l}_{12} + \int_2^3 \vec{H}_{23} \cdot d\vec{l}_{23} + \int_3^4 \vec{H}_{34} \cdot d\vec{l}_{34} + \int_4^1 \vec{H}_{41} \cdot d\vec{l}_{41} = I_x dN(\xi_o) \quad (2.2-6)$$

$$H_{iron} = \frac{B_{iron}}{\mu_{iron}} \ll H_{air} = \frac{B_{air}}{\mu_{air}}$$

$$H_{12}(\xi_o + \zeta)g + H_{34}(\xi_o - \zeta)g = dN(\xi_o)I_x \quad (2.2-8)$$



$$H(\zeta + \xi_o) = \frac{dN(\xi_o)I_x}{2g} \quad \text{for } 0 < \zeta < \pi \quad (2.2-9)$$


$$H(\zeta + \xi_o) = -\frac{dN(\xi_o)I_x}{2g} \quad \text{for } \pi < \zeta < 2\pi \quad (2.2-10)$$

Figure 2.3 Differential number of winding turns of winding x

Flux (weber)

$$\begin{aligned} d\phi &= \vec{B} \cdot d\vec{A} \\ &= \mu_o \vec{H} \cdot d\vec{A} \quad (2.2-11) \\ &= \mu_o H dl (rd\zeta) \end{aligned}$$

$$\begin{aligned} d\phi &= \mu_o N_x I_x \left(\frac{r}{4g} \right) \sin \xi_o d\xi (d\zeta dl) \\ &\quad \text{for } 0 < \zeta < \pi \quad (2.2-12) \end{aligned}$$



The number of turns linked by a differential packet of flux located at a position ξ relative to ξ_o is

$$N = \int_{\xi_o - \zeta}^{\xi_o + \zeta} \frac{N_x}{2} \sin u du \quad (2.2-13)$$

$$N = N_x \sin \xi_o \sin \zeta \quad (2.2-14)$$

Figure 2.4 Showing winding portion linked by an arbitrary flux packet located at $\zeta + \xi_o$

Flux linkage (weber turns)

The number of turns linked by a differential packed of flux located at a position ξ relative to ξ_o is


$$N = \int_{\xi_o - \xi}^{\xi_o + \xi} \frac{N_x}{2} \sin u du \quad (2.2-13)$$

$$N = N_x \sin \xi_o \sin \xi \quad (2.2-14)$$

The total number of flux linkages linked by all such packets of flux $d\varphi$ is

$$d\lambda_{xm} = \mu_o \frac{N_x I_x}{4g} r \sin^2 \xi_o d\xi \int_0^l dl \int_0^\pi N_x \sin \zeta d\zeta \quad (2.2-15)$$

$$= \mu_o \frac{N_x^2 I_x}{2g} r l \sin^2 \xi_o d\xi \quad (2.2-16)$$



Magnetizing inductance

The total number of flux linkages linked by all such packets of flux $d\varphi$ is

$$d\lambda_{xm} = \mu_o \frac{N_x I_x}{4g} r \sin^2 \xi_o d\xi \int_0^l dl \int_0^\pi N_x \sin \zeta d\zeta \quad (2.2-15)$$

$$= \mu_o \frac{N_x^2 I_x}{2g} r l \sin^2 \xi_o d\xi \quad (2.2-16)$$


The total flux linkages is the sum of the linkages from such differential windings

$$\lambda_{xm} = \int_0^\pi \mu_o \frac{N_x^2 I_x}{2g} (r l) \sin^2 \xi d\xi \quad (2.2-17)$$

$$= \mu_o N_x^2 I_x \left(\frac{r l}{g} \right) \left(\frac{\pi}{4} \right) \quad (2.2-18)$$

The magnetizing inductance associated with this winding is

$$L_m = \frac{\lambda_{xm}}{I_x} = \mu_o N_x^2 \left(\frac{r l}{g} \right) \left(\frac{\pi}{4} \right) \quad (2.2-19)$$



Mutual inductance

The number of turns N linked by the flux $d\varphi$ is given by the modification of eq. (2.2.14)

$$N = N_y \sin(\xi_o - \alpha) \sin \zeta \quad (2.2-20)$$

The number of flux linkages of winding y linked by the flux $d\varphi$ located at $\xi_o + \zeta$ is

$$d\lambda_{xy} = \mu_o \frac{N_x I_x}{4g} r l \sin \xi_o d\xi \int_0^\pi N_y \sin(\xi_o - \alpha) \sin \zeta d\zeta \quad (2.2-21)$$

$$= \mu_o \frac{N_x N_y I_x}{2g} r l \sin \xi_o \sin(\xi_o - \alpha) d\xi \quad (2.2-22)$$

The number of flux linkages of winding y due to a current in winding 'x' is

$$\begin{aligned} \lambda_{xy} &= \int_0^\pi \mu_o \frac{N_x N_y I_x}{2g} r l \sin \xi \sin(\xi - \alpha) d\xi \\ &= \mu_o N_x N_y I_x \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) \cos \alpha \quad (2.2-23) \end{aligned}$$




Figure 2.5 Sinusoidal current sheets for two windings displaced by an angle α

Mutual inductance

$$\begin{aligned} \lambda_{xy} &= \int_0^\pi \mu_o \frac{N_x N_y I_x}{2g} r l \sin \xi \sin(\xi - \alpha) d\xi \\ &= \mu_o N_x N_y I_x \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) \cos \alpha \quad (2.2-23) \end{aligned}$$

The mutual inductance between winding x and winding y

$$L_{xy} = \frac{\lambda_{xy}}{I_x} = \mu_o N_x N_y \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) \cos \alpha \quad (2.2-24)$$

$$L_{yx} = \frac{\lambda_{yx}}{I_y} = L_{xy} \quad (2.2-25)$$

2.3 System Equations in Stationary a,b,c R.F.

The voltage equations describing the stator and rotor circuits can be written conveniently in matrix form as

$$\mathbf{v}_{abcs} = \mathbf{r}_s \mathbf{i}_{abcs} + p \boldsymbol{\lambda}_{abcs} \quad (2.3-1)$$

$$\mathbf{v}_{abcr} = \mathbf{r}_r \mathbf{i}_{abcr} + p \boldsymbol{\lambda}_{abcr} \quad (2.3-2)$$

where p represents the operator d/dt and \mathbf{v}_{abcs} , \mathbf{i}_{abcs} and $\boldsymbol{\lambda}_{abcs}$ are 3x1 vectors defined by

$$\mathbf{v}_{abcs} = \begin{bmatrix} v_{as} \\ v_{bs} \\ v_{cs} \end{bmatrix}; \quad \mathbf{i}_{abcs} = \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix}; \quad \boldsymbol{\lambda}_{abcs} = \begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix} \quad (2.3-3)$$

Coupling

$$\lambda_{abcs} = \lambda_{abcs(s)} + \lambda_{abcs(r)} \quad (2.3-4)$$

$$\lambda_{abcr} = \lambda_{abcr(s)} + \lambda_{abcr(r)} \quad (2.3-5)$$




Figure 2.6 Magnetic axes of a three phase induction machine

Coupling

$$\lambda_{abcs}(s) = \begin{bmatrix} L_{as} & L_{abs} & L_{acs} \\ L_{abs} & L_{bs} & L_{bcs} \\ L_{acs} & L_{bcs} & L_{cs} \end{bmatrix} i_{abcs} \quad (2.3-6)$$

$$\lambda_{abcs}(r) = \begin{bmatrix} L_{as,ar} & L_{as,br} & L_{as,cr} \\ L_{bs,ar} & L_{bs,br} & L_{bs,cr} \\ L_{cs,ar} & L_{cs,br} & L_{cs,cr} \end{bmatrix} i_{abcr} \quad (2.3-7)$$

$$\lambda_{abcr}(s) = \begin{bmatrix} L_{ar,as} & L_{ar,bs} & L_{ar,cs} \\ L_{br,as} & L_{br,bs} & L_{br,cs} \\ L_{cr,as} & L_{cr,bs} & L_{cr,cs} \end{bmatrix} i_{abcs} \quad (2.3-8)$$

$$\lambda_{abcr}(r) = \begin{bmatrix} L_{ar} & L_{abr} & L_{acr} \\ L_{abr} & L_{br} & L_{bcr} \\ L_{acr} & L_{bcr} & L_{cr} \end{bmatrix} i_{abcr} \quad (2.3-9)$$

2.4 Determination of Induction Machine Inductances

The mutual inductance between winding x and winding y

$$L_{xy} = \frac{\lambda_{xy}}{I_x} = \mu_o N_x N_y \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) \cos \alpha \quad (2.2-24)$$

Self inductance

$$L_{as} = L_{ls} + L_{am} \quad (2.4-2)$$

$$L_{am} = \mu_o N_s^2 \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) \quad (2.4-1)$$

magnetizing inductance ($\alpha = 0$, $N_x = N_y$)

leakage inductance: flux lines don not cross the air gap

- ❑ Slot leakage : cross close with the stator slot itself
- ❑ Harmonic leakage : in the air gap
- ❑ End winding leakage

Stator self inductance

$$L_{as} = L_{ls} + L_{am} \quad (2.4-2)$$

$$L_{bs} = L_{ls} + L_{bm} \quad (2.4-3)$$

$$L_{cs} = L_{ls} + L_{cm} \quad (2.4-4)$$

$$L_{ms} = \mu_o N_s^2 \frac{rl}{g} \left(\frac{\pi}{4} \right) \quad (2.4-5)$$

$$L_{as} = L_{bs} = L_{cs} = L_{ls} + L_{ms} \quad (2.4-6)$$

Stator mutual inductance

The mutual inductance between winding x and winding y

$$L_{xy} = \frac{\lambda_{xy}}{I_x} = \mu_o N_x N_y \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) \cos \alpha \quad (2.2-24)$$

mutual inductance ($\alpha = 2\pi/3$, $N_x = N_y = N_s$)

$$L_{abs} = L_{bcs} = L_{cas} = -\mu_o N_s^2 \frac{rl}{g} \left(\frac{\pi}{8} \right) \quad (2.4-7)$$

$$L_{abs} = L_{bcs} = L_{cas} = -\frac{L_{ms}}{2} \quad (2.4-8)$$

Stator flux linkages resulting from stator currents

$$\lambda_{abcs} = \lambda_{abcs(s)} + \lambda_{abcs(r)} \quad (2.3-4)$$

$$\lambda_{abcr} = \lambda_{abcr(s)} + \lambda_{abcr(r)} \quad (2.3-5)$$

$$\lambda_{abcs(s)} = \begin{bmatrix} L_{as} & L_{abs} & L_{acs} \\ L_{abs} & L_{bs} & L_{bcs} \\ L_{acs} & L_{bcs} & L_{cs} \end{bmatrix} i_{abcs} \quad (2.3-6)$$

$$\lambda_{abcs(s)} = \begin{bmatrix} L_{ls} + L_{ms} & -\frac{L_{ms}}{2} & -\frac{L_{ms}}{2} \\ -\frac{L_{ms}}{2} & L_{ls} + L_{ms} & -\frac{L_{ms}}{2} \\ -\frac{L_{ms}}{2} & -\frac{L_{ms}}{2} & L_{ls} + L_{ms} \end{bmatrix} \cdot i_{abcs} \quad (2.4-9)$$

Mutual coupling between the stator and the rotor windings

The mutual inductance between winding x and winding y


$$L_{xy} = \frac{\lambda_{xy}}{I_x} = \mu_o N_x N_y \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) \cos \alpha \quad (2.2-24)$$

• $\alpha = \theta_r$, $N_x = N_s$, $N_y = N_r$

$$\begin{aligned} L_{as,ar} &= L_{bs,br} = L_{cs,cr} = \mu_o N_s N_r \frac{rl}{g} \left(\frac{\pi}{4} \right) \cos \theta_r \\ &= \frac{N_r}{N_s} L_{ms} \cos \theta_r \end{aligned} \quad (2.4-10)$$

$$L_{as,br} = L_{bs,cr} = L_{cs,ar} = \frac{N_r}{N_s} L_{ms} \cos (\theta_r + 2\pi/3) \quad (2.4-11)$$

$$L_{as,cr} = L_{bs,ar} = L_{cs,br} = \frac{N_r}{N_s} L_{ms} \cos (\theta_r - 2\pi/3) \quad (2.4-12)$$



Stator flux linkages resulting from rotor currents

$$\lambda_{abcs} = \lambda_{abcs(s)} + \lambda_{abcs(r)} \quad (2.3-4)$$

$$\lambda_{abcr} = \lambda_{abcr(s)} + \lambda_{abcr(r)} \quad (2.3-5)$$

$$\lambda_{abcs(r)} = \begin{bmatrix} L_{as, ar} & L_{as, br} & L_{as, cr} \\ L_{bs, ar} & L_{bs, br} & L_{bs, cr} \\ L_{cs, ar} & L_{cs, br} & L_{cs, cr} \end{bmatrix} i_{abcr}$$

$$\lambda_{abcs(r)} = \frac{N_r}{N_s} L_{ms} \begin{bmatrix} \cos \theta_r & \cos (\theta_r + 2\pi/3) & \cos (\theta_r - 2\pi/3) \\ \cos (\theta_r - 2\pi/3) & \cos \theta_r & \cos (\theta_r + 2\pi/3) \\ \cos (\theta_r + 2\pi/3) & \cos (\theta_r - 2\pi/3) & \cos \theta_r \end{bmatrix} \begin{bmatrix} i_{ar} \\ i_{br} \\ i_{cr} \end{bmatrix} \quad (2.4-13)$$

Rotor flux linkages resulting from stator currents

$$\lambda_{abcs} = \lambda_{abcs(s)} + \lambda_{abcs(r)} \quad (2.3-4)$$

$$\lambda_{abcr} = \lambda_{abcr(s)} + \lambda_{abcr(r)} \quad (2.3-5)$$

$$\lambda_{abcr(s)} = \begin{bmatrix} L_{ar, as} & L_{ar, bs} & L_{ar, cs} \\ L_{br, as} & L_{br, bs} & L_{br, cs} \\ L_{cr, as} & L_{cr, bs} & L_{cr, cs} \end{bmatrix} i_{abcs}$$

$$\lambda_{abcr(s)} = \frac{N_r}{N_s} L_{ms} \begin{bmatrix} \cos \theta_r & \cos (\theta_r - 2\pi/3) & \cos (\theta_r + 2\pi/3) \\ \cos (\theta_r + 2\pi/3) & \cos \theta_r & \cos (\theta_r - 2\pi/3) \\ \cos (\theta_r - 2\pi/3) & \cos (\theta_r + 2\pi/3) & \cos \theta_r \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} \quad (2.4-16)$$

Rotor self inductance

The mutual inductance between winding x and winding y

$$L_{xy} = \frac{\lambda_{xy}}{I_x} = \mu_o N_x N_y \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) \cos \alpha \quad (2.2-24)$$

Stator magnetizing inductance

$$L_{ms} = \mu_o N_s^2 \frac{rl}{g} \left(\frac{\pi}{4} \right) \quad (2.4-5)$$

magnetizing inductance ($\alpha = 0$, $N_x = N_y$)

Rotor magnetizing inductance

$$L_{am} = \mu_o N_r^2 \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) = \left(\frac{N_r}{N_s} \right)^2 L_{ms}$$

Rotor flux linkages resulting from rotor currents

$$\lambda_{abcs} = \lambda_{abcs(s)} + \lambda_{abcs(r)} \quad (2.3-4)$$

$$\lambda_{abcr} = \lambda_{abcr(s)} + \lambda_{abcr(r)} \quad (2.3-5)$$

$$\lambda_{abcr(r)} = \begin{bmatrix} L_{lr} + \left(\frac{N_r}{N_s} \right)^2 L_{ms} & -\frac{1}{2} \left(\frac{N_r}{N_s} \right)^2 L_{ms} & -\frac{1}{2} \left(\frac{N_r}{N_s} \right)^2 L_{ms} \\ -\frac{1}{2} \left(\frac{N_r}{N_s} \right)^2 L_{ms} & L_{lr} + \left(\frac{N_r}{N_s} \right)^2 L_{ms} & -\frac{1}{2} \left(\frac{N_r}{N_s} \right)^2 L_{ms} \\ -\frac{1}{2} \left(\frac{N_r}{N_s} \right)^2 L_{ms} & -\frac{1}{2} \left(\frac{N_r}{N_s} \right)^2 L_{ms} & L_{lr} + \left(\frac{N_r}{N_s} \right)^2 L_{ms} \end{bmatrix} \begin{bmatrix} i_{ar} \\ i_{br} \\ i_{cr} \end{bmatrix} \quad (2.4-15)$$

2.5 Complex Vector Representation of 3-P Variables

- Consider the equation describing the instantaneous position of the stator air gap MMF


- If phase a is sinusoidally distributed with a max. value located at $\xi = \alpha$, then the MMF in the air gap resulting from current flowing in phase a is

$$F_{as} = \frac{N_s}{2} i_{as} \cos(\beta) \quad (2.5-1)$$

$$\text{where } \beta = \xi - \alpha$$

$$F_{bs} = \frac{N_s}{2} i_{bs} \cos(\beta - 2\pi/3) \quad (2.5-2)$$

$$F_{cs} = \frac{N_s}{2} i_{cs} \cos(\beta + 2\pi/3) \quad (2.5-3)$$



- Total air gap MMF resulting from three phase currents:

$$F_{abcs} = \frac{N_s}{2} [i_{as} \cos \beta + i_{bs} \cos(\beta - 2\pi/3) + i_{cs} \cos(\beta + 2\pi/3)] \quad (2.5-4)$$

Complex vector representation

$$e^{j\theta} = \cos \theta + j \sin \theta \quad (2.5-5)$$

$$\cos \theta = \frac{e^{j\theta} + e^{-j\theta}}{2} \quad (2.5-6)$$

$$\sin \theta = \frac{e^{j\theta} - e^{-j\theta}}{2j} \quad (2.5-7)$$

$$F_{abcs} = \frac{N_s}{2} [i_{as} \cos \beta + i_{bs} \cos(\beta - 2\pi/3) + i_{cs} \cos(\beta + 2\pi/3)] \quad (2.5-4)$$

$$\Rightarrow F_{abcs} = \frac{N_s}{2} \left[i_{as} \frac{(e^{j\beta} + e^{-j\beta})}{2} + i_{bs} \frac{(e^{j(\beta - 2\pi/3)} + e^{-j(\beta - 2\pi/3)})}{2} + i_{cs} \frac{(e^{j(\beta + 2\pi/3)} + e^{-j(\beta + 2\pi/3)})}{2} \right] \quad (2.5-8)$$

Complex vector representation

$$F_{abcs} = \frac{N_s}{2} \left[i_{as} \frac{(e^{j\beta} + e^{-j\beta})}{2} + i_{bs} \frac{(e^{j(\beta-2\pi/3)} + e^{-j(\beta-2\pi/3)})}{2} + i_{cs} \frac{(e^{j(\beta+2\pi/3)} + e^{-j(\beta+2\pi/3)})}{2} \right] \quad (2.5-8)$$

$$\Rightarrow F_{abcs} = \frac{N_s}{4} \{ [i_{as} + i_{bs}e^{-j2\pi/3} + i_{cs}e^{j2\pi/3}] e^{j\beta} + [i_{as} + i_{bs}e^{j2\pi/3} + i_{cs}e^{-j2\pi/3}] e^{-j\beta} \} \quad (2.5-9)$$

Defining $\begin{cases} \underline{a} = e^{j2\pi/3} \\ \underline{a}^2 = \underline{a}^{-1} = e^{j4\pi/3} = e^{-j2\pi/3} = \underline{a}^\dagger \end{cases}$ † denotes the complex conjugate

$$\Rightarrow F_{abcs} = \frac{N_s}{4} \{ [i_{as} + \underline{a}^2 i_{bs} + \underline{a} i_{cs}] e^{j\beta} + [i_{as} + \underline{a} i_{bs} + \underline{a}^2 i_{cs}] e^{-j\beta} \} \quad (2.5-12)$$

Complex vector representation

$$F_{abcs} = \frac{N_s}{4} \{ [i_{as} + \underline{a}^2 i_{bs} + \underline{a} i_{cs}] e^{j\beta} + [i_{as} + \underline{a} i_{bs} + \underline{a}^2 i_{cs}] e^{-j\beta} \} \quad (2.5-12)$$

$$\underline{i}_{abcs}^\dagger = \frac{2}{3} (i_{as} + \underline{a}^2 i_{bs} + \underline{a} i_{cs}) \quad (2.5-14)$$

$$\underline{i}_{abcs} = \frac{2}{3} (i_{as} + \underline{a} i_{bs} + \underline{a}^2 i_{cs}) \quad (2.5-13)$$

complex space vector

$$F_{abcs} = \frac{3N_s}{2 \cdot 4} (\underline{i}_{abcs} e^{-j\beta} + \underline{i}_{abcs}^\dagger e^{j\beta}) \quad (2.5-15)$$

Notation of complex space vector : \underline{f}_{abc}

Complex space vector

$$\begin{cases} \underline{a} = e^{j2\pi/3} = -\frac{1}{2} + j\frac{\sqrt{3}}{2} & 1 - \frac{\underline{a}}{2} - \frac{\underline{a}^2}{2} = \frac{3}{2} \\ \underline{a}^2 = \underline{a}^{-1} = e^{j4\pi/3} = e^{-j2\pi/3} = \underline{a}^\dagger & 1 + \underline{a} + \underline{a}^2 = 0 \end{cases}$$

$$\underline{f}_{abc} = \frac{2}{3} \left(f_a + \underline{a} f_b + \underline{a}^2 f_c \right)$$

$$f_a = \text{Re} \left(\underline{f}_{abc} \right) \quad (2.5-17)$$

$$f_b = \text{Re} \left(\underline{a}^2 \underline{f}_{abc} \right) \quad (2.5-19)$$

$$f_c = \text{Re} \left(\underline{a} \underline{f}_{abc} \right) \quad (2.5-20)$$

2.6 Complex Variables Model of 3-P IM

Stator voltage equations:

$$\underline{v}_{abcs} = r_s \underline{i}_{abcs} + p \underline{\lambda}_{abcs} \quad (2.6-1)$$

where

$$\underline{v}_{abcs} = \frac{2}{3} (v_{as} + \underline{a} v_{bs} + \underline{a}^2 v_{cs}) \quad (2.6-2)$$

$$\underline{v}_{abcr} = r_r \underline{i}_{abcr} + p \underline{\lambda}_{abcr} \quad (2.6-3)$$

Stator flux linkage equations:

$$\begin{aligned} \underline{\lambda}_{abcs}(s) &= \lambda_{as}(s) + \underline{a} \lambda_{bs}(s) + \underline{a}^2 \lambda_{cs}(s) \\ &= \left[L_{ls} + L_{ms} \left(1 - \frac{\underline{a}}{2} - \frac{\underline{a}^2}{2} \right) \right] (i_{as} + \underline{a} i_{bs} + \underline{a}^2 i_{cs}) \end{aligned} \quad (2.6-4)$$

$$= \left(L_{ls} + \frac{3}{2} L_{ms} \right) \underline{i}_{abcs} \quad (2.6-6)$$

Stator flux linkage arises from rotor current

$$\lambda_{abcs(r)} = \frac{N_r}{N_s} L_{ms} \begin{bmatrix} \cos \theta_r & \cos(\theta_r + 2\pi/3) & \cos(\theta_r - 2\pi/3) \\ \cos(\theta_r - 2\pi/3) & \cos \theta_r & \cos(\theta_r + 2\pi/3) \\ \cos(\theta_r + 2\pi/3) & \cos(\theta_r - 2\pi/3) & \cos \theta_r \end{bmatrix} \begin{bmatrix} i_{ar} \\ i_{br} \\ i_{cr} \end{bmatrix}$$

$$\begin{bmatrix} \lambda_{as(r)} \\ \lambda_{bs(r)} \\ \lambda_{cs(r)} \end{bmatrix} = \frac{N_r L_{ms}}{N_s} \frac{1}{2} \left\{ \begin{bmatrix} e^{j\theta_r} & \underline{a}e^{j\theta_r} & \underline{a}^2e^{j\theta_r} \\ \underline{a}^2e^{j\theta_r} & e^{j\theta_r} & \underline{a}e^{j\theta_r} \\ \underline{a}e^{j\theta_r} & \underline{a}^2e^{j\theta_r} & e^{j\theta_r} \end{bmatrix} + \begin{bmatrix} e^{-j\theta_r} & \underline{a}^2e^{-j\theta_r} & \underline{a}e^{-j\theta_r} \\ \underline{a}e^{-j\theta_r} & e^{-j\theta_r} & \underline{a}^2e^{-j\theta_r} \\ \underline{a}^2e^{-j\theta_r} & \underline{a}e^{-j\theta_r} & e^{-j\theta_r} \end{bmatrix} \right\} \cdot \begin{bmatrix} i_{ar} \\ i_{br} \\ i_{cr} \end{bmatrix} \quad (2.6-7)$$

$$\lambda_{abcs(r)} = \frac{2}{3} (\lambda_{as(r)} + \underline{a}\lambda_{bs(r)} + \underline{a}^2\lambda_{cs(r)}) \quad (2.6-11)$$

$$= \frac{N_r 3L_{ms}}{N_s} \frac{1}{2} i_{abcr} e^{j\theta_r} = \frac{N_r L_{ms}}{N_s} \frac{1}{2} [3(i_{ar} + \underline{a}i_{br} + \underline{a}^2i_{cr})e^{j\theta_r} + (1 + \underline{a} + \underline{a}^2)(i_{ar} + i_{br} + i_{cr})e^{-j\theta_r}] \quad (2.6-8)$$

Total flux linkages in complex space vector form

Total stator flux linkages

$$\lambda_{abcs} = \left(L_{ls} + \frac{3}{2} L_{ms} \right) i_{abcs} + \frac{N_r 3L_{ms}}{N_s} \frac{1}{2} i_{abcr} e^{j\theta_r} \quad (2.6-13)$$

$$\lambda_{abcs(s)} = \left(L_{ls} + \frac{3}{2} L_{ms} \right) i_{abcs} \quad (2.6-6)$$

$$\lambda_{abcs(r)} = \frac{N_r 3L_{ms}}{N_s} \frac{1}{2} i_{abcr} e^{j\theta_r} \quad (2.6-10)$$

Total rotor flux linkages

$$\lambda_{abcr} = \left[L_{lr} + \frac{3}{2} \left(\frac{N_r}{N_s} \right)^2 L_{ms} \right] i_{abcr} + \frac{N_r 3L_{ms}}{N_s} \frac{1}{2} i_{abcs} e^{-j\theta_r} \quad (2.6-14)$$

2.7 Turns Ration Transformation

✿ Refer the rotor circuits to the stator

$$\begin{cases} v_{abcr} = r_r i_{abcr} + p \lambda_{abcr} \end{cases} \quad (2.6-3)$$

$$\begin{cases} \left(\frac{N_s}{N_r} \right) v_{abcr} = \left(\frac{N_s}{N_r} \right)^2 r_r \left[\left(\frac{N_r}{N_s} \right) i_{abcr} \right] + p \left[\left(\frac{N_s}{N_r} \right) \lambda_{abcr} \right] \end{cases} \quad (2.7-1)$$

$$\begin{cases} \lambda_{abcr} = \left[L_{lr} + \frac{3}{2} \left(\frac{N_r}{N_s} \right)^2 L_{ms} \right] i_{abcr} + \frac{N_r 3 L_{ms}}{N_s 2} i_{abcs} e^{-j\theta_r} \end{cases} \quad (2.6-14)$$

$$\begin{cases} \left(\frac{N_s}{N_r} \right) \lambda_{abcr} = \left[\left(\frac{N_s}{N_r} \right)^2 L_{lr} + \frac{3}{2} L_{ms} \right] \left[\left(\frac{N_r}{N_s} \right) i_{abcr} \right] + \frac{3 L_{ms}}{2} i_{abcs} e^{-j\theta_r} \end{cases} \quad (2.7-3)$$

$$\begin{cases} \lambda_{abcs} = \left(L_{ls} + \frac{3}{2} L_{ms} \right) i_{abcs} + \frac{N_r 3 L_{ms}}{N_s 2} i_{abcr} e^{j\theta_r} \end{cases} \quad (2.6-13)$$

$$\begin{cases} \lambda_{abcs} = \left(L_{ls} + \frac{3}{2} L_{ms} \right) i_{abcs} + \frac{3 L_{ms}}{2} \left[\frac{N_r}{N_s} i_{abcr} \right] e^{j\theta_r} \end{cases} \quad (2.7-2)$$

Refer the rotor circuits to the stator

$$\begin{cases} \left(\frac{N_s}{N_r} \right) v_{abcr} = v'_{abcr} \end{cases} \quad (2.7-4)$$

$$\begin{cases} \left(\frac{N_s}{N_r} \right) \lambda_{abcr} = \lambda'_{abcr} \end{cases} \quad (2.7-5)$$

$$\begin{cases} \left(\frac{N_r}{N_s} \right) i_{abcr} = i'_{abcr} \end{cases} \quad (2.7-6)$$

$$\begin{cases} \left(\frac{N_s}{N_r} \right)^2 r_r = r'_r \end{cases} \quad (2.7-7)$$

$$\begin{cases} \left(\frac{N_s}{N_r} \right)^2 L_{lr} = L'_{lr} \end{cases} \quad (2.7-8)$$

Refer the rotor circuits to the stator

$$L_m = \frac{3}{2}L_{ms} = \frac{3}{2}N_s^2 \left(\mu_o \frac{rl}{g} \right) \frac{\pi}{4} \quad (2.7-9)$$

$$\begin{cases} v_{abcs} = r_s i_{abcs} + (L_{ls} + L_m) p i_{abcs} + L_m p (i'_{abcr} e^{j\theta_r}) \end{cases} \quad (2.7-10)$$

$$\begin{cases} v_{abcs} = r_s i_{abcs} + (L_{ls} + L_m) p i_{abcs} + L_m (p i'_{abcr}) e^{j\theta_r} + j\omega_r L_m i'_{abcr} e^{j\theta_r} \end{cases} \quad (2.7-12)$$

$$\begin{cases} v'_{abcr} = r'_r i'_{abcr} + (L'_{lr} + L_m) p i'_{abcr} + L_m p (i_{abcs} e^{-j\theta_r}) \end{cases} \quad (2.7-11)$$

$$\begin{cases} v'_{abcr} = r'_r i'_{abcr} + (L'_{lr} + L_m) p i'_{abcr} + L_m (p i_{abcs}) e^{-j\theta_r} - j\omega_r L_m i_{abcs} e^{-j\theta_r} \end{cases} \quad (2.7-13)$$

$$\text{where } \omega_r = p\theta_r = \frac{d\theta_r}{dt}.$$

2.8 Transformation to Rotating Reference Frame




Figure 2.7 Location of rotating d,q axes relative to the magnetic axes of the stator and rotor phases

$$\begin{bmatrix} f_{qs} \\ f_{ds} \\ f_{0s} \end{bmatrix} = \frac{2}{3} \begin{bmatrix} \cos \theta & \cos(\theta - 2\pi/3) & \cos(\theta + 2\pi/3) \\ \sin \theta & \sin(\theta - 2\pi/3) & \sin(\theta + 2\pi/3) \\ 1/2 & 1/2 & 1/2 \end{bmatrix} \begin{bmatrix} f_{as} \\ f_{bs} \\ f_{cs} \end{bmatrix}$$

$$\underline{f}_{qds} = f_{qs} - j \cdot f_{ds}$$

$$\begin{aligned} \underline{f}_{qds} = f_{qs} - j f_{ds} &= \frac{2}{3} [f_{as} e^{-j\theta} + f_{bs} e^{-j(\theta - 2\pi/3)} + f_{cs} e^{-j(\theta + 2\pi/3)}] \\ &= \frac{2}{3} e^{-j\theta} [f_{as} + a f_{bs} + a^2 f_{cs}] \end{aligned} \quad (2.8-4)$$

$$= e^{-j\theta} \underline{f}_{abcs} \quad (2.8-5)$$

Transformation matrix

$$\begin{bmatrix} f_{qs} \\ f_{ds} \\ f_{0s} \end{bmatrix} = \frac{2}{3} \begin{bmatrix} \cos \theta & \cos(\theta - 2\pi/3) & \cos(\theta + 2\pi/3) \\ \sin \theta & \sin(\theta - 2\pi/3) & \sin(\theta + 2\pi/3) \\ 1/2 & 1/2 & 1/2 \end{bmatrix} \begin{bmatrix} f_{as} \\ f_{bs} \\ f_{cs} \end{bmatrix}$$

$$\begin{bmatrix} f_{as} \\ f_{bs} \\ f_{cs} \end{bmatrix} = \begin{bmatrix} \cos \theta & \sin \theta & 1 \\ \cos(\theta - 2\pi/3) & \sin(\theta - 2\pi/3) & 1 \\ \cos(\theta + 2\pi/3) & \sin(\theta + 2\pi/3) & 1 \end{bmatrix} \begin{bmatrix} f_{qs} \\ f_{ds} \\ f_{0s} \end{bmatrix}$$

Rotating Reference Frame


stator variables

$$\begin{aligned} \underline{f}_{qds} &= f_{qs} - jf_{ds} = \frac{2}{3} [f_{as}e^{-j\theta} + f_{bs}e^{-j(\theta - 2\pi/3)} + f_{cs}e^{-j(\theta + 2\pi/3)}] \\ &= \frac{2}{3}e^{-j\theta} [f_{as} + \underline{a}f_{bs} + \underline{a}^2f_{cs}] \end{aligned} \quad (2.8-4)$$

$$= e^{-j\theta} \underline{f}_{abcs} \quad (2.8-5)$$

rotor variables

$$\begin{aligned} \underline{f}_{qdr} &= \frac{2}{3}e^{-j(\theta - \theta_r)} [f_{ar} + \underline{a}f_{br} + \underline{a}^2f_{cr}] \\ &= e^{-j(\theta - \theta_r)} \underline{f}_{abcr} \end{aligned} \quad (2.8-6)$$



Voltage Equations in Rotating Reference Frame

$$e^{-j\theta} v_{abcs} = r_s e^{-j\theta} i_{abcs} + (L_{ls} + L_m) e^{-j\theta} p i_{abcs} + L_m e^{-j\theta} p (i'_{abcr} e^{j\theta_r}) \quad (2.8-7)$$

$$\begin{aligned} &= r_s e^{-j\theta} i_{abcs} + (L_{ls} + L_m) p (e^{-j\theta} i_{abcs}) + L_m p [i'_{abcr} e^{-j(\theta-\theta_r)}] \\ &\quad + j\omega [(L_{ls} + L_m) e^{-j\theta} i_{abcs} + L_m i'_{abcr} e^{-j(\theta-\theta_r)}] \end{aligned} \quad (2.8-8)$$

$$v_{qds} = r_s i_{qds} + (L_{ls} + L_m) p i_{qds} + L_m p i'_{qdr} + j\omega [(L_{ls} + L_m) i_{qds} + L_m i'_{qdr}] \quad (2.8-10)$$

$e^{-j\theta} i_{abcs} \quad i'_{abcr} e^{-j(\theta-\theta_r)} \quad e^{-j\theta} i_{abcs} \quad i'_{abcr} e^{-j(\theta-\theta_r)}$

$$v'_{qdr} = r'_r i'_{qdr} + (L'_{lr} + L_m) p i'_{qdr} + L_m p i_{qds} + j(\omega - \omega_r) [(L'_{lr} + L_m) i'_{qdr} + L_m i_{qds}] \quad (2.8-11)$$

Voltage Equations in Rotating Reference Frame

$$v_{0s} = (r_s + pL_{ls}) i_{0s}$$

$$v_{0s} = (r_s + pL_{ls}) i_{0s} \quad (2.8-12)$$

$$v'_{0r} = (r'_r + pL'_{lr}) i'_{0r} \quad (2.8-13)$$

The zero sequence inductance is typically less than the per phase leakage inductance being roughly 0.8 to 0.95 of the value

Voltage Equations in Rotating Reference Frame

$$\left\{ \begin{array}{l} v_{ds} = r_s i_{ds} + \frac{d\lambda_{ds}}{dt} - \omega \lambda_{qs} \\ v_{qs} = r_s i_{qs} + \frac{d\lambda_{qs}}{dt} + \omega \lambda_{ds} \\ v_{0s} = r_s i_{0s} + \frac{d\lambda_{0s}}{dt} \end{array} \right. \quad \text{where}$$

$$\begin{aligned} \lambda_{ds} &= L_{ls} i_{ds} + L_m (i_{ds} + i'_{dr}) \\ \lambda_{qs} &= L_{ls} i_{qs} + L_m (i_{qs} + i'_{qr}) \\ \lambda_{0s} &= L_{ls} i_{0s} \end{aligned}$$


$$\left\{ \begin{array}{l} v'_{dr} = r'_r i'_{dr} + \frac{d\lambda'_{dr}}{dt} - (\omega - \omega_r) \lambda'_{qr} \\ v'_{qr} = r'_r i'_{qr} + \frac{d\lambda'_{qr}}{dt} + (\omega - \omega_r) \lambda'_{dr} \\ v'_{0r} = r'_r i'_{0r} + \frac{d\lambda'_{0r}}{dt} \end{array} \right. \quad \text{where}$$

$$\begin{aligned} \lambda'_{dr} &= L'_{lr} i'_{dr} + L_m (i_{ds} + i'_{dr}) \\ \lambda'_{qr} &= L'_{lr} i'_{qr} + L_m (i_{qs} + i'_{qr}) \\ \lambda'_{0r} &= L'_{lr} i'_{0r} \end{aligned}$$


Voltage Equations in Rotating Reference Frame

$$\begin{bmatrix} v_{ds} \\ v_{qs} \\ v'_{dr} \\ v'_{qr} \end{bmatrix} = \begin{bmatrix} r_s + L_s p & -\omega L_s & L_m p & -\omega L_m \\ \omega L_s & r_s + L_s p & \omega L_m & L_m p \\ L_m p & -(\omega - \omega_r) L_m & r'_r + L'_r p & -(\omega - \omega_r) L'_r \\ (\omega - \omega_r) L_m & L_m p & (\omega - \omega_r) L'_r & r'_r + L'_r p \end{bmatrix} \begin{bmatrix} i_{ds} \\ i_{qs} \\ i'_{dr} \\ i'_{qr} \end{bmatrix} \quad (2.8-26)$$


where $L'_r = L'_{lr} + L_m$ and $L_s = L_{ls} + L_m$



d-axis equivalent circuit



q-axis equivalent circuit



0-axis equivalent circuit

Figure 2.8 The $d,q,0$ equivalent circuits of three phase induction machine

2.9 Interpretation of Complex Vectors

Complex space vector (abc axes)

$$\underline{f}_{abc} = \frac{2}{3} (\underline{f}_a + \underline{a} \underline{f}_b + \underline{a}^2 \underline{f}_c)$$

$$\underline{f}_a = \text{Re}(\underline{f}_{abc}) \quad (2.5-17)$$

$$\underline{f}_b = \text{Re}(\underline{a}^2 \underline{f}_{abc}) \quad (2.5-19)$$

$$\underline{f}_c = \text{Re}(\underline{a} \underline{f}_{abc}) \quad (2.5-20)$$

Complex space vector (dq axes)

$$\underline{f}_{qds} = \frac{2}{3} e^{-j\theta} (\underline{f}_{as} + \underline{a} \underline{f}_{bs} + \underline{a}^2 \underline{f}_{cs})$$

Stationary reference frame

$$\theta = 0$$

$$\underline{f}_{qds}^s = \frac{2}{3} (\underline{f}_{as} + \underline{a} \underline{f}_{bs} + \underline{a}^2 \underline{f}_{cs}) \quad (2.9-2)$$

Synchronous reference frame

$$\theta = \theta_e = \omega_e t$$

$$\underline{f}_{qds}^e = \underline{f}_{qds}^s e^{-j\theta_e} \quad (2.9-3)$$

Rotor reference frame

$$\theta = \theta_r = \omega_r t$$

$$\underline{f}_{qds}^r = \underline{f}_{qds}^s e^{-j\theta_r} \quad (2.9-12)$$

$$\theta = 0$$

$$\underline{f}_{qds}^s = \frac{2}{3} (f_{as} + \underline{a} f_{bs} + \underline{a}^2 f_{cs}) \quad (2.9-2)$$





Figure 2.9 Transformation from three phase stator to complex vector voltage



$$\theta = \theta_e = \omega_e t$$

$$\underline{f}_{qds}^e = \underline{f}_{qds}^s e^{-j\theta_e} \quad (2.9-3)$$


Figure 2.10 Transformation from d,q variables in a stationary axes to rotating d,q variables, (pure rotation)

Example

$$i_{as} = I_s \cos \omega_e t \quad (2.9-4)$$

$$i_{bs} = I_s \cos \left(\omega_e t - \frac{2\pi}{3} \right) \quad (2.9-5)$$

$$i_{cs} = I_s \cos \left(\omega_e t + \frac{2\pi}{3} \right) \quad (2.9-6)$$



$$\begin{aligned} \underline{i}_{qds}^s &= \frac{2I_s}{3} \left[e^{j\omega_e t} + e^{-j\omega_e t} + \underline{a} (e^{j(\omega_e t - 2\pi/3)} + e^{-j(\omega_e t - 2\pi/3)}) \right. \\ &\quad \left. + \underline{a}^2 (e^{j(\omega_e t + 2\pi/3)} + e^{-j(\omega_e t + 2\pi/3)}) \right] \quad (2.9-7) \end{aligned}$$

$$\begin{aligned} &= \frac{I_s}{3} [3e^{j\omega_e t} + e^{-j\omega_e t} (1 + \underline{a} + \underline{a}^2)] \\ &= I_s e^{j\omega_e t} \quad (2.9-8) \end{aligned}$$

$$\begin{aligned} \theta &= \theta_e = \omega_e t \\ \underline{f}_{qds}^e &= \underline{f}_{qds}^s e^{-j\theta_e} \quad (2.9-3) \end{aligned}$$

Inverse of complex vector quantity

$$\underline{f}_{qdx}^x = \frac{2}{3} [f_{ax} + \underline{a} f_{bx} + \underline{a}^2 f_{cx}]$$

$$\begin{aligned} \underline{f}_{qdx}^x &= \frac{2}{3} \left[f_{ax} + \left(-\frac{1}{2} + j\frac{\sqrt{3}}{2} \right) f_{bx} + \left(-\frac{1}{2} - j\frac{\sqrt{3}}{2} \right) f_{cx} \right] \\ &= \frac{2}{3} \left[\frac{3}{2} f_{ax} - \frac{1}{2} (f_{ax} + f_{bx} + f_{cx}) + j\frac{\sqrt{3}}{2} (f_{bx} - f_{cx}) \right] \quad (2.9-14) \end{aligned}$$



$$f_{ax} = \text{Re} [\underline{f}_{qdx}^x] + f_{0x} \quad (2.9-15)$$

$$f_{bx} = \text{Re} [\underline{a}^2 \underline{f}_{qdx}^x] + f_{0x} \quad (2.9-16)$$

$$f_{cx} = \text{Re} [\underline{a} \underline{f}_{qdx}^x] + f_{0x} \quad (2.9-17)$$

$$f_{ax} = |f| \cos \phi + f_{0x} \quad (2.9-19)$$

$$f_{bx} = |f| \cos \left(\frac{2\pi}{3} - \phi \right) + f_{0x} \quad (2.9-20)$$

$$f_{cx} = |f| \cos \left(\frac{2\pi}{3} + \phi \right) + f_{0x} \quad (2.9-21)$$

Inverse of complex vector quantity




Figure 2.11 Graphical inverse of complex vector quantity

2.10 Power Flow in the d,q Equivalent Circuit

$$\begin{aligned}
 \underline{v}_{abcs} \underline{i}_{abcs}^\dagger &= \frac{2}{3} (v_{as} + a v_{bs} + a^2 v_{cs}) \left[\frac{2}{3} (i_{as} + a^2 i_{bs} + a i_{cs}) \right] \text{conjugate} \\
 &= \frac{4}{9} [v_{as} i_{as} + a (v_{bs} i_{as} + v_{as} i_{cs}) + a^2 (v_{as} i_{bs} + v_{cs} i_{as} + v_{bs} i_{cs}) \\
 &\quad + a^3 (v_{bs} i_{bs} + v_{cs} i_{cs}) + a^4 (v_{cs} i_{bs})] \\
 &= \frac{4}{9} [v_{as} i_{as} + v_{bs} i_{bs} + v_{cs} i_{cs} + a (v_{bs} i_{as} + v_{as} i_{cs} + v_{cs} i_{bs}) \\
 &\quad + a^2 (v_{as} i_{bs} + v_{cs} i_{as} + v_{bs} i_{cs})] \\
 \text{Re}[\underline{v}_{abcs} \underline{i}_{abcs}^\dagger] &= \frac{4}{9} \{ v_{as} i_{as} + v_{bs} i_{bs} + v_{cs} i_{cs} \\
 &\quad - \frac{1}{2} [v_{as} (i_{bs} + i_{cs}) + v_{bs} (i_{as} + i_{cs}) + v_{cs} (i_{as} + i_{bs})] \}
 \end{aligned}$$

Assume $i_a + i_b + i_c = 0$

$$= \frac{2}{3} \{ v_{as} i_{as} + v_{bs} i_{bs} + v_{cs} i_{cs} \} \quad (2.10-2)$$

rms, phase voltage

Real power representation in dq plane

Assume three phase machine without a neutral return
($i_a + i_b + i_c = 0$)

$$P_e = \frac{3}{2} \{ \text{Re} [v_{abcs} i_{abcs}^\dagger] + \text{Re} [v'_{abcr} i_{abcr}'^\dagger] \} \quad (2.10-3)$$

$$\underline{f}_{abcs} = e^{j\theta} \underline{f}_{qds} \quad (2.10-5)$$

$$\underline{f}'_{abcr} = e^{j(\theta - \theta_r)} \underline{f}'_{qdr} \quad (2.10-6)$$

$$P_e = \frac{3}{2} \text{Re} [(e^{j\theta} v_{qds}) (e^{-j\theta} i_{qds}^\dagger) + (e^{j(\theta - \theta_r)} v'_{qdr}) (e^{-j(\theta - \theta_r)} i_{qdr}'^\dagger)] \quad (2.10-7)$$

$$P_e = \frac{3}{2} \text{Re} [v_{qds} i_{qds}^\dagger + v'_{qdr} i_{qdr}'^\dagger] \quad (2.10-8)$$

In scalar
form:

$$P_e = \frac{3}{2} (v_{ds} i_{ds} + v_{qs} i_{qs} + v'_{dr} i'_{dr} + v'_{qr} i'_{qr}) \quad (2.10-9)$$

2.11 Example: Stator abc and rotor dq model


$$\begin{bmatrix} v_{ds}^s \\ v_{qs}^s \\ v_{dr}^s \\ v_{qr}^s \end{bmatrix} = \begin{bmatrix} r_s + L_s p & -\omega L_s & L_m p & -\omega L_m \\ \omega L_s & r_s + L_s p & \omega L_m & L_m p \\ L_m p & (\omega - \omega_r) L_m & r_r + L_r p & -(\omega - \omega_r) L_r \\ (\omega - \omega_r) L_m & L_m p & (\omega - \omega_r) L_r & r_r + L_r p \end{bmatrix} \begin{bmatrix} i_{ds}^s \\ i_{qs}^s \\ i_{dr}^s \\ i_{qr}^s \end{bmatrix}$$

$$\begin{bmatrix} v_{as} \\ v_{bs} \\ v_{cs} \\ v_{qr}^s \\ v_{dr}^s \end{bmatrix} = \begin{bmatrix} \text{[Matrix]} \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \\ i_{qr}^s \\ i_{dr}^s \end{bmatrix}$$

$\begin{bmatrix} r_r + L_r p & -(\omega - \omega_r) L_r \\ (\omega - \omega_r) L_r & r_r + L_r p \end{bmatrix}$

$$v_{qs}^s = \text{Re}(\underline{v}_{qds}^s) = \text{Re}\left[\frac{2}{3}(v_{as} + \underline{a}v_{bs} + \underline{a}^2v_{cs})\right]$$

$$= \frac{2}{3}v_{as} - \frac{1}{3}v_{bs} - \frac{1}{3}v_{cs} = v_{as} - \frac{1}{3}(v_{as} + v_{bs} + v_{cs})$$

$$= v_{as} - v_{0s}$$


Assume q and a axes are aligned

$$v_{as} = v_{qs}^s + v_{0s} = (r_s + L_s p) i_{qs}^s + L_m p i_{qr}^s + v_{0s}$$

$$i_{qs}^s = i_{as} - i_{0s}$$

$$v_{as} = (r_s + L_s p) i_{as} + L_m p i_{qr}^s + v_{0s} - (r_s + L_s p) i_{0s}$$

$$v_{0s} = [r_s + (L_s - L_m) p] i_{0s} \quad i_{0s} = \frac{1}{3}(i_{as} + i_{bs} + i_{cs})$$

$$v_{as} = \left[r_s + \left(L_s - \frac{L_m}{3}\right)p\right] i_{as} - \frac{L_m}{3} p i_{bs} - \frac{L_m}{3} p i_{cs} + L_m p i_{qr}^s$$

Stator voltage equations

$$v_{as} = \left[r_s + \left(L_s - \frac{L_m}{3}\right)p\right] i_{as} - \frac{L_m}{3} p i_{bs} - \frac{L_m}{3} p i_{cs} + L_m p i_{qr}^s$$

$$v_{bs} = \left[r_s + \left(L_s - \frac{L_m}{3}\right)p\right] i_{bs} - \frac{L_m}{3} p i_{as} - \frac{L_m}{3} p i_{cs} - \frac{L_m}{2} p i_{qr}^s - \frac{\sqrt{3}}{2} L_m p i_{dr}^s$$

$$v_{cs} = \left[r_s + \left(L_s - \frac{L_m}{3}\right)p\right] i_{cs} - \frac{L_m}{3} p i_{as} - \frac{L_m}{3} p i_{bs} - \frac{L_m}{2} p i_{qr}^s + \frac{\sqrt{3}}{2} L_m p i_{dr}^s$$

Rotor voltage equations

$$v_{qdr}^s = (r_r + L_r(p - j\omega_r)) i_{qdr}^s + L_m(p - j\omega_r) i_{qds}^s$$

$$\begin{aligned} i_{qds}^s &= \frac{2}{3} (i_{as} + a i_{bs} + a^2 i_{cs}) \\ &= \frac{2}{3} i_{as} - \frac{1}{3} i_{bs} - \frac{1}{3} i_{cs} + j \frac{1}{\sqrt{3}} (i_{bs} - i_{cs}) \end{aligned}$$

$$v_{qdr}^s = [r_r + L_r(p - j\omega_r)] i_{qdr}^s + L_m(p - j\omega_r) \left[\frac{2}{3} i_{as} - \frac{1}{3} i_{bs} - \frac{1}{3} i_{cs} + j \frac{1}{\sqrt{3}} (i_{bs} - i_{cs}) \right]$$

re. part

$$v_{qr}^s = (r_r + L_r p) i_{qr}^s - \omega_r L_r i_{dr}^s + L_m p \left(\frac{2}{3} i_{as} - \frac{1}{3} i_{bs} - \frac{1}{3} i_{cs} \right) + \frac{\omega_r L_m}{\sqrt{3}} (i_{bs} - i_{cs})$$

Im. part

$$v_{dr}^s = (r_r + L_r p) i_{dr}^s + \omega_r L_r i_{qr}^s + L_m p \frac{1}{\sqrt{3}} (i_{cs} - i_{bs}) + \omega_r L_m \left(\frac{2}{3} i_{as} - \frac{1}{3} i_{bs} - \frac{1}{3} i_{cs} \right)$$

$$v_{qr}^s = (r_r + L_r p) i_{qr}^s - \omega_r L_r i_{dr}^s + L_m p \left(\frac{2}{3} i_{as} - \frac{1}{3} i_{bs} - \frac{1}{3} i_{cs} \right) + \frac{\omega_r L_m}{\sqrt{3}} (i_{bs} - i_{cs})$$

$$v_{dr}^s = (r_r + L_r p) i_{dr}^s + \omega_r L_r i_{qr}^s + L_m p \frac{1}{\sqrt{3}} (i_{cs} - i_{bs}) + \omega_r L_m \left(\frac{2}{3} i_{as} - \frac{1}{3} i_{bs} - \frac{1}{3} i_{cs} \right)$$

$$\begin{bmatrix} v_{as} \\ v_{bs} \\ v_{cs} \\ v_{qr}^s \\ v_{dr}^s \end{bmatrix} = \begin{bmatrix} r_s + \left(L_s - \frac{1}{3} L_m \right) p & -\frac{1}{3} L_m p & -\frac{1}{3} L_m p & L_m p & 0 \\ -\frac{1}{3} L_m p & r_s + \left(L_s - \frac{1}{3} L_m \right) p & -\frac{1}{3} L_m p & -\frac{1}{2} L_m p & -\frac{\sqrt{3}}{2} L_m p \\ -\frac{1}{3} L_m p & -\frac{1}{3} L_m p & r_s + \left(L_s - \frac{1}{3} L_m \right) p & -\frac{1}{2} L_m p & \frac{\sqrt{3}}{2} L_m p \\ \frac{2}{3} L_m p & -\frac{L_m}{3} (p - \sqrt{3} \omega_r) & -\frac{L_m}{3} (p + \sqrt{3} \omega_r) & r_r + L_r p & -\omega_r L_r \\ \frac{2}{3} L_m \omega_r & -\frac{L_m}{3} (\omega_r + \sqrt{3} p) & -\frac{L_m}{3} (\omega_r - \sqrt{3} p) & \omega_r L_r & r_r + L_r p \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \\ i_{qr}^s \\ i_{dr}^s \end{bmatrix} \quad (2.11-1)$$

$$L_{0s} = L_s - L_m = L_{ls}, \text{ and } L_m = \frac{3}{2} L_{ms}$$

$$L_s - \frac{1}{3} L_m = \frac{2}{3} L_m + L_{ls} = L_{ms} + L_{ls}$$

2.12 The Electromagnetic Torque

$$P_e = \frac{3}{2} \text{Re} [v_{qds} \dot{i}_{qds}^\dagger + v'_{qdr} \dot{i}'_{qdr}{}^\dagger] \quad (2.10-8)$$

$$P_e = \frac{3}{2} \text{Re} \left\{ \underbrace{r_s \dot{i}_{qds} + (L_{ls} + L_m) p \dot{i}_{qds} + L_m p \dot{i}'_{qdr}}_{\text{Power lost in Conductors}} + j\omega [(L_{ls} + L_m) \dot{i}_{qds} + L_m \dot{i}'_{qdr}] \dot{i}_{qds}^\dagger \right\} \quad (2.12-1)$$

$$+ \frac{3}{2} \text{Re} \left\{ \underbrace{r'_r \dot{i}'_{qdr} + (L'_{lr} + L_m) p \dot{i}'_{qdr} + L_m p \dot{i}_{qds}}_{\text{Time Rate of Change of Stored Energy}} + j(\omega - \omega_r) [(L'_{lr} + L_m) \dot{i}'_{qdr} + L_m \dot{i}_{qds}] \dot{i}'_{qdr}{}^\dagger \right\}$$

$$= \text{Re} [(L_{ls} + L_m) \dot{i}_{qds} \cdot p \dot{i}_{qds}]$$

$$= \text{Re} [(L_{ls} + L_m) \cdot (i_{qs} + j i_{ds}) \cdot (p i_{qs} - j p i_{ds})]$$

$$= \text{Re} [(L_{ls} + L_m) \cdot (i_{qs} \cdot p i_{qs} + i_{ds} \cdot p i_{ds})]$$

$$= \frac{1}{2} \text{Re} [(L_{ls} + L_m) \cdot p (i_{qs}^2 + i_{ds}^2)]$$

$$= \frac{1}{2} \text{Re} [(L_{ls} + L_m) \cdot p (\dot{i}_{qds})^2]$$

$$P_e = \underbrace{\frac{3}{2} r_s |\dot{i}_{qds}|^2 + \frac{3}{2} r'_r |\dot{i}'_{qdr}|^2}_{\text{Power lost in Conductors}} + \underbrace{\frac{3}{2} p \left[\frac{L_{ls}}{2} |\dot{i}_{qds}|^2 + \frac{L'_{lr}}{2} |\dot{i}'_{qdr}|^2 + L_m |\dot{i}_{qds} + \dot{i}'_{qdr}|^2 \right]}_{\text{Time Rate of Change of Stored Energy}}$$

$$+ \underbrace{\frac{3}{2} \text{Re} \{ j\omega [(L_{ls} + L_m) |\dot{i}_{qds}|^2 + L_m \dot{i}'_{qdr} \dot{i}_{qds}^\dagger] + j(\omega - \omega_r) [(L'_{lr} + L_m) |\dot{i}'_{qdr}|^2 + L_m \dot{i}_{qds} \dot{i}'_{qdr}{}^\dagger] \}}_{\text{Energy Conversion Term}}$$

Power transfer to mechanical load

$$P_e = \underbrace{\frac{3}{2} r_s |\dot{i}_{qds}|^2 + \frac{3}{2} r'_r |\dot{i}'_{qdr}|^2}_{\text{Power lost in Conductors}} + \underbrace{\frac{3}{2} p \left[\frac{L_{ls}}{2} |\dot{i}_{qds}|^2 + \frac{L'_{lr}}{2} |\dot{i}'_{qdr}|^2 + L_m |\dot{i}_{qds} + \dot{i}'_{qdr}|^2 \right]}_{\text{Time Rate of Change of Stored Energy}}$$

$$+ \underbrace{\frac{3}{2} \text{Re} \{ j\omega [(L_{ls} + L_m) |\dot{i}_{qds}|^2 + L_m \dot{i}'_{qdr} \dot{i}_{qds}^\dagger] + j(\omega - \omega_r) [(L'_{lr} + L_m) |\dot{i}'_{qdr}|^2 + L_m \dot{i}_{qds} \dot{i}'_{qdr}{}^\dagger] \}}_{\text{Energy Conversion Term}}$$

$$P_{em} = \frac{3}{2} \text{Re} \{ j\omega L_m \dot{i}'_{qdr} \dot{i}_{qds}^\dagger + j(\omega - \omega_r) L_m \dot{i}_{qds} \dot{i}'_{qdr}{}^\dagger \} \quad (2.12-2)$$

$$= \frac{3}{2} \text{Re} \{ j\omega L_m (\dot{i}'_{qdr} \dot{i}_{qds}^\dagger + \dot{i}_{qds} \dot{i}'_{qdr}{}^\dagger) - j\omega_r L_m \dot{i}_{qds} \dot{i}'_{qdr}{}^\dagger \}$$

$$\underline{a} \underline{b}^\dagger + \underline{a}^\dagger \underline{b} = 2(a_r b_r + a_i b_i) \quad \dots \text{pure real number}$$

$$= -\frac{3}{2} \text{Re} \{ j\omega_r L_m \dot{i}_{qds} \dot{i}'_{qdr}{}^\dagger \} \quad (2.12-3)$$

Electromagnetic torque

$$P_{em} = -\frac{3}{2} \text{Re} \{ j \omega_r L_m i_{qds} i_{qdr}'^\dagger \} \quad (2.12-3)$$

$$P_{em} = \frac{3}{2} \text{Im} \{ \omega_r L_m i_{qds} i_{qdr}'^\dagger \} \quad (2.12-4)$$

$$P_{em} = \frac{3}{2} \omega_r L_m (i_{qs} i_{dr}' - i_{ds} i_{qr}') \quad (2.12-5)$$

$$\omega_r = \frac{P}{2} \omega_{rm}$$

Type-I

$$\begin{aligned} T_e &= \frac{3P}{2} L_m \text{Im} \{ i_{qds} i_{qdr}'^\dagger \} \\ &= \frac{3P}{2} L_m (i_{qs} i_{dr}' - i_{ds} i_{qr}') \end{aligned} \quad (2.12-7)$$

Electromagnetic torque

Type-I

$$T_e = \frac{3P}{2} L_m \text{Im} \{ i_{qds} i_{qdr}'^\dagger \} \quad (2.12-7)$$

$$\lambda_{qds} = (L_{ls} + L_m) i_{qds} + L_m i_{qdr}' \quad (2.12-9)$$

$$T_e = \frac{3P}{2} \text{Im} [- (L_{ls} + L_m) i_{qds} i_{qds}^\dagger + i_{qds} \lambda_{qds}^\dagger] \quad (2.12-10)$$

Type-II

$$T_e = \frac{3P}{2} \text{Im} (i_{qds} \cdot \lambda_{qds}^\dagger) \quad (2.12-11)$$

$$= \frac{3P}{2} (\lambda_{ds} i_{qs} - \lambda_{qs} i_{ds}) \quad (2.12-12)$$

Electromagnetic torque

Type-I

$$T_e = \frac{3P}{2} L_m \text{Im} \{ i_{qds} i_{qdr}'^\dagger \} \quad (2.12-7)$$

$$\lambda'_{qdr} = (L'_{lr} + L_m) i'_{qdr} + L_m i_{qds}$$

Type-III

$$T_e = \frac{3P}{2} \text{Im} (\lambda'_{qdr} i_{qdr}'^\dagger) \quad (2.12-14)$$

Electromagnetic torque

Type-I

$$T_e = \frac{3P}{2} L_m \text{Im} \{ i_{qds} i_{qdr}'^\dagger \} \quad (2.12-7)$$

$$\lambda_{qdm} = L_m (i_{qds} + i_{qdr}') \quad (2.12-15)$$

Type-IV

$$T_e = \frac{3P}{2} \text{Im} (i_{qds} \lambda_{qdm}^\dagger) \quad (2.12-16)$$

Electromagnetic torque

Type-I

$$T_e = \frac{3P}{2} L_m \text{Im} \{ i_{qds} i_{qdr}^* \} \quad (2.12-7)$$

$$\begin{cases} \lambda'_{dr} = L'_{lr} i'_{dr} + L_m (i_{ds} + i'_{dr}) & (2.8-23) \\ \lambda'_{qr} = L'_{lr} i'_{qr} + L_m (i_{qs} + i'_{qr}) & (2.8-24) \end{cases}$$

$$i'_{qdr} = \frac{1}{L'_{lr} + L_m} \lambda'_{qdr} - \frac{L_m}{L'_{lr} + L_m} i_{qds} \quad (2.12-17)$$

Type-V

$$T_e = \frac{3P L_m}{2 L'_r} \text{Im} (i_{qds} \lambda_{qdr}^*) \quad (2.12-18)$$

where $L'_r = L'_{lr} + L_m$

$$\lambda_{qds} = (L_{ls} + L_m) i_{qds} + L_m i'_{qdr} \quad (2.12-9)$$

$$\lambda_{qdm} = L_m (i_{qds} + i'_{qdr}) \quad (2.12-15)$$

$$\lambda'_{qdr} = (L'_{lr} + L_m) i'_{qdr} + L_m i_{qds}$$




Figure 2.12 Illustrating torque production by vectors on the d,q plane

TABLE 2.1 Complex Vector Expressions for Electromagnetic Torque. ‡ denotes variable used to calculate torque

	i_{qds}	i'_{qdr}	λ_{qds}	λ'_{qdr}	λ_{qdm}	Torque Expression
1	‡	‡				$T_e = \frac{3}{2} \frac{P}{2} L_m \text{Im} \{ i_{qdr}' i_{qds} \}$
2	‡				‡	$T_e = \frac{3}{2} \frac{P}{2} \text{Im} \{ \lambda_{qdm}' i_{qds} \}$
3	‡		‡			$T_e = \frac{3}{2} \frac{P}{2} \text{Im} \{ \lambda_{qds}' i_{qds} \}$
4	‡			‡		$T_e = \frac{3}{2} \frac{P}{2} \frac{L_m}{L_r'} \text{Im} \{ i_{qds} \lambda_{qdr}' \}$
5		‡			‡	$T_e = \frac{3}{2} \frac{P}{2} \text{Im} \{ i_{qdr}' \lambda_{qdm} \}$
6		‡		‡		$T_e = \frac{3}{2} \frac{P}{2} \text{Im} \{ i_{qdr}' \lambda_{qdr}' \}$
7		‡	‡			$T_e = \frac{3}{2} \frac{P}{2} \frac{L_m}{L_s} \text{Im} \{ i_{qdr}' \lambda_{qds} \}$
8			‡	‡		$T_e = \frac{3}{2} \frac{P}{2} \frac{L_m}{\sigma L_s L_r'} \text{Im} \{ \lambda_{qdr}' \lambda_{qds} \}$

$$\sigma = 1 - L_m^2 / L_r' L_s$$

Electromagnetic torque

$$T_e = J \frac{d\omega_{rm}}{dt} + T_l \quad (2.12-20)$$

$$T_e = \frac{2J}{P} \frac{d\omega_r}{dt} + T_l \quad (2.12-21)$$

where $\omega_r = 2\omega_{rm}/P$.

2.13 Analysis of IM Starting Performance Using d,q,0 Variables

System parameters

$$\begin{aligned} r_s &= 0.531 \, \Omega & r_r' &= 0.408 \, \Omega & J &= 0.1 \, \text{kg-m}^2 \\ L_{ls} = L_{lr}' &= 2.52 \, \text{mH} & L_m &= 84.7 \, \text{mH} \end{aligned}$$

Source voltages

$$v_{as} = \sqrt{\frac{2}{3}} 230 \cos(377t) \quad (2.13-1)$$

$$v_{bs} = \sqrt{\frac{2}{3}} 230 \cos(377t - 2\pi/3) \quad (2.13-2)$$

$$v_{cs} = \sqrt{\frac{2}{3}} 230 \cos(377t + 2\pi/3) \quad (2.13-3)$$

Motor is modelled in abc axes




Figure 2.13 Starting performance of 220 V, 5 hp squirrel cage induction motor with a balanced sinusoidal supply showing physical variables. After reaching rated speed the motor is loaded to 0.83 times rated torque. Traces from top to bottom: v_{as} , phase a line to neutral voltage, i_{as} , line current of stator phase as , i_{ar}' , phase current of rotor phase ar (referred to stator turns), T_e , electromagnetic torque, T_l , load torque, rotor speed in RPM; time axis 0.1 s/div.

Motor is modelled in stationary reference frame

$$v_{ds}^s = -\frac{2}{3} \text{Im} [v_{as} + \underline{a}v_{bs} + \underline{a}^2v_{cs}] \quad v_{0s} = 0 \quad (2.13-6)$$

$$\begin{aligned} &= -\frac{2\sqrt{3}}{3} \frac{1}{2} (v_{bs} - v_{cs}) \\ &= \frac{\sqrt{2}}{\sqrt{3}} \cdot \frac{\sqrt{3}}{2} \left[\frac{\sqrt{2}}{\sqrt{3}} 220 \cos(377t + 2\pi/3) - \frac{\sqrt{2}}{\sqrt{3}} 220 \cos(377t - 2\pi/3) \right] \\ &= -\frac{\sqrt{2}}{\sqrt{3}} 230 \sin(377t) \end{aligned} \quad (2.13-4)$$

$$\begin{aligned} v_{qs}^s &= \frac{2}{3} \text{Re} [v_{as} + \underline{a}v_{bs} + \underline{a}^2v_{cs}] \\ &= \frac{2}{3} \left[\frac{\sqrt{2}}{\sqrt{3}} 220 \cos(377t) - \frac{1}{2} \frac{\sqrt{2}}{\sqrt{3}} 220 \cos(377t - 2\pi/3) \right. \\ &\quad \left. - \frac{1}{2} \frac{\sqrt{2}}{\sqrt{3}} \cos(377t + 2\pi/3) \right] \\ &= \frac{\sqrt{2}}{\sqrt{3}} 220 \cos(377t) \end{aligned} \quad (2.13-5)$$

Motor is modelled in stationary reference frame




Figure 2.14 Starting performance and subsequent loading of 220 V, 5 hp squirrel cage induction motor with a balanced 60 Hz sinusoidal supply. Motor is modelled in stationary d,q axes. (Stationary reference frame). Traces from top to bottom – v_{ds}^s , v_{qs}^s , i_{ds}^s , i_{qs}^s , i_{dr}^s , i_{qr}^s , rotor speed in RPM, T_e ; time axis 0.1 s/div.

Motor is modelled in rotor reference frame




Figure 2.15 Starting performance and subsequent loading of 220 V, 5 hp squirrel cage induction motor with a balanced sinusoidal supply. Motor is modelled in d,q axes rotating at rotor speed. (Rotor reference frame). Traces from top to bottom – $v_{ds}^r, v_{qs}^r, i_{ds}^r, i_{qs}^r, i_{dr}^r, i_{qr}^r$, rotor speed in RPM, torque T_e ; time axis 0.1 s/div.

Motor is modelled in synchronous reference frame

$$\omega = 377 \text{ rad/s} \quad (2.13-10)$$

$$\theta(0) = 0 \quad (2.13-11)$$


$$v_{ds}^{sv} = 0 \quad (2.13-12)$$

$$v_{qs}^{sv} = \sqrt{\frac{2}{3}} 220 \text{ V} \quad (2.13-13)$$

$$v_{0s}^{sv} = 0 \quad (2.13-14)$$

Stator voltage (synch.) reference frame

Motor is modelled in synchronous reference frame



2.16 Starting performance and subsequent loading of 5 hp, 220 V squirrel cage induction motor with a balanced sinusoidal supply. Motor is modelled in d,q axes synchronously rotating with the applied voltage vector. (Synchronous reference frame). Traces from the top: v_{ds}^{sv} , v_{qs}^{sv} , i_{ds}^{sv} , i_{qs}^{sv} , i'_{ds}^{sv} , i'_{qs}^{sv} , rotor speed in RPM, electromagnetic torque T_e ; time axis 0.1 s/div.

Motor is modelled in rotor flux reference frame

$$v_{ds}^{rf} = -\sqrt{\frac{2}{3}} 220 \sin(377t - \theta_{rf}) \quad (2.13-15)$$

$$v_{qs}^{rf} = \sqrt{\frac{2}{3}} 220 \cos(377t - \theta_{rf}) \quad (2.13-16)$$

$$v_{0s}^{rf} = 0 \quad (2.13-17)$$

θ_{rf} is the instantaneous position of the rotor flux vector

➤ d-axis is continuously aligned with the rotor flux vector so that the q-axis rotor flux component is always identically zero.

$$T_e = \frac{3PL_m}{22L_r} \text{Im}(i_{qds} \lambda_{qdr}^*) \quad (2.12-18) \quad \Rightarrow \quad T_e = \frac{3PL_m}{22L_r} \lambda_{dr}^{rf} i_{qs}^{rf} \quad (2.13-18)$$

Motor is modelled in rotor flux reference frame




Figure 2.17 Starting performance and subsequent loading of 220 V, 5 hp squirrel cage induction motor with a balanced sinusoidal supply. Motor is modelled in d,q axes rotating synchronously with the rotor flux. (Rotor flux reference frame). Traces from the top: v_{ds}^{rf} , v_{qs}^{rf} , i_{ds}^{rf} , i_{qs}^{rf} , i_{dr}^{rf} , i_{qr}^{rf} , rotor speed in RPM, electromagnetic torque T_e ; time axis 0.1 s/div.

2.14 Extension of d,q,0 Theory to Analysis of Salient Pole Synchronous Machines

Salient pole synchronous machines

- Non-uniform air gap between stator and rotor
 - Stator self inductances vary with rotor position

- Self inductance of any winding must pulsate once each time the rotor moves one pole pitch
- There exists a second harmonic component in addition to the constant component represented by (2.4-5)

□ Self inductance of phase a is

$$L_{as,as} = L_{ls} + L_{0s} - L_{2s} \cos 2\theta_r$$

(2.14-1)




Figure 2.18 Magnetic axes of a salient pole synchronous machine

□ Self inductance of phase a is

$$L_{as,as} = L_{ls} + L_{0s} - L_{2s} \cos 2\theta_r \quad (2.14-1)$$

$$L_{0s} = \mu_0 r l N_s^2 \left(\frac{\pi}{8} \right) \left(\frac{1}{g_{min}} + \frac{1}{g_{max}} \right) \quad (2.14-2)$$

$$L_{2s} = \mu_0 r l N_s^2 \left(\frac{\pi}{8} \right) \left(\frac{1}{g_{min}} - \frac{1}{g_{max}} \right) \quad (2.14-3)$$

□ Self inductance of phase b and c is


$$L_{bs,bs} = L_{ls} + L_{0s} - L_{2s} \cos (2\theta_r + 2\pi/3)$$

$$L_{cs,cs} = L_{ls} + L_{0s} - L_{2s} \cos (2\theta_r - 2\pi/3)$$

$$\theta_r = 0^\circ$$

smallest

$$L_{as,as}$$




$$L_{as,as} = L_{ls} + \mu_0 r l N_s^2 \left(\frac{\pi}{8} \right) \frac{2}{g_{max}}$$

$$\theta_r = 90^\circ$$

largest

$$L_{as,as}$$




$$L_{as,as} = L_{ls} + \mu_0 r l N_s^2 \left(\frac{\pi}{8} \right) \frac{2}{g_{min}}$$

Mutual inductances between stator phases

$$L_{as,bs} = L_{bs,as} = -\frac{1}{2}L_{0s} - L_{2s} \cos (2\theta_r - 2\pi/3) \quad (2.14-6)$$

$$L_{as,cs} = L_{cs,as} = -\frac{1}{2}L_{0s} - L_{2s} \cos (2\theta_r + 2\pi/3) \quad (2.14-7)$$

$$L_{bs,cs} = L_{cs,bs} = -\frac{1}{2}L_{0s} - L_{2s} \cos 2\theta_r \quad (2.14-8)$$



Mutual inductances between field winding and stator phases


$$L_{as,fd} = L_{fd,as} = L_{sfd} \cos \theta_r \quad (2.14-9)$$

$$L_{bs,fd} = L_{fd,bs} = L_{sfd} \cos (\theta_r - 2\pi/3) \quad (2.14-10)$$

$$L_{cs,fd} = L_{fd,cs} = L_{sfd} \cos (\theta_r + 2\pi/3) \quad (2.14-11)$$

where

$$L_{sfd} = \mu_0 r l N_s N_{fd} \left(\frac{\pi}{4} \right) \frac{1}{g_{min}} \quad (2.14-12)$$



$$L_{xy} = \frac{\lambda_{xy}}{I_x} = \mu_0 N_x N_y \left(\frac{rl}{g} \right) \left(\frac{\pi}{4} \right) \cos \alpha \quad (2.2-24)$$

Mutual inductances between d-axis damper winding and stator phases


$$L_{as,kd} = L_{kd,as} = L_{skd} \cos \theta_r \quad (2.14-13)$$

$$L_{bs,kd} = L_{kd,bs} = L_{skd} \cos (\theta_r - 2\pi/3) \quad (2.14-14)$$

$$L_{cs,kd} = L_{kd,cs} = L_{skd} \cos (\theta_r + 2\pi/3) \quad (2.14-15)$$

where

$$L_{skd} = \mu_0 r l N_s N_{kd} \left(\frac{\pi}{4} \right) \frac{1}{g_{min}} \quad (2.14-16)$$



Mutual inductances between q-axis damper winding and stator phases


$$L_{as,kq} = L_{kq,as} = -L_{skq} \sin \theta_r \quad (2.14-17)$$

$$L_{bs,kq} = L_{kq,bs} = -L_{skq} \sin (\theta_r - 2\pi/3) \quad (2.14-18)$$

$$L_{cs,kq} = L_{kq,cs} = -L_{skq} \sin (\theta_r + 2\pi/3) \quad (2.14-19)$$

where

$$L_{skq} = \mu_0 r l N_s N_{kq} \left(\frac{\pi}{4} \right) \frac{1}{g_{max}} \quad (2.14-20)$$



Stator voltage equations

$$\begin{bmatrix} v_{as} \\ v_{bs} \\ v_{cs} \end{bmatrix} = r_s \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} + p \begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix} \quad (2.14-21)$$

$$\begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix} = \begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix} + \begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix} \cdot \begin{bmatrix} i_{fd} \\ i_{kd} \\ i_{kq} \end{bmatrix} \quad (2.14-22)$$

Voltage equation for field, d-axis damper and q-axis damper windings

$$v_{fd} = r_{fd} i_{fd} + p \lambda_{fd} \quad (2.14-23)$$

$$v_{kd} = r_{kd} i_{kd} + p \lambda_{kd} \quad (2.14-24)$$

$$v_{kq} = r_{kq} i_{kq} + p \lambda_{kq} \quad (2.14-25)$$

$$\begin{bmatrix} \lambda_{fd} \\ \lambda_{kd} \\ \lambda_{kq} \end{bmatrix} = \begin{bmatrix} \\ \\ \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} + \begin{bmatrix} \\ \\ \end{bmatrix} \begin{bmatrix} i_{fd} \\ i_{kd} \\ i_{kq} \end{bmatrix}$$

Voltage equation for field, d-axis damper and q-axis damper windings

$$\begin{bmatrix} \lambda_{fd} \\ \lambda_{kd} \\ \lambda_{kq} \end{bmatrix} = \begin{bmatrix} \\ \\ \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} + \begin{bmatrix} 0 \\ 0 \\ 0 \ 0 \ X \end{bmatrix} \begin{bmatrix} i_{fd} \\ i_{kd} \\ i_{kq} \end{bmatrix}$$

$$\lambda_{fd} = (L_{lfd} + L_{mfd}) i_{fd} + L_{fkd} i_{kd} + L_{sfd} [i_{as} \cos \theta_r + i_{bs} \cos (\theta_r - 2\pi/3) + i_{cs} \cos (\theta_r + 2\pi/3)] \quad (2.14-26)$$

$$\lambda_{kd} = (L_{lkd} + L_{mkd}) i_{kd} + L_{fkd} i_{fd} + L_{skd} [i_{as} \cos \theta_r + i_{bs} \cos (\theta_r - 2\pi/3) + i_{cs} \cos (\theta_r + 2\pi/3)] \quad (2.14-27)$$

$$\lambda_{kq} = (L_{lkq} + L_{mkq}) i_{kq} - L_{skq} [i_{as} \sin \theta_r + i_{bs} \sin (\theta_r - 2\pi/3) + i_{cs} \sin (\theta_r + 2\pi/3)] \quad (2.14-28)$$

Voltage equation for field, d-axis damper and q-axis damper windings

$$L_{mfd} = \mu_0 r l N_f^2 \left(\frac{\pi}{4} \right) \frac{1}{g_{min}} \quad (2.14-29)$$

$$L_{kfd} = \mu_0 r l N_f N_{kd} \left(\frac{\pi}{4} \right) \frac{1}{g_{min}} \quad (2.14-30)$$

$$L_{mkd} = \mu_0 r l N_{kd}^2 \left(\frac{\pi}{4} \right) \frac{1}{g_{min}} \quad (2.14-31)$$

$$L_{mkq} = \mu_0 r l N_{kq}^2 \left(\frac{\pi}{4} \right) \frac{1}{g_{max}} \quad (2.14-32)$$

Stator voltage in space vector form

$$\begin{bmatrix} v_{as} \\ v_{bs} \\ v_{cs} \end{bmatrix} = r_s \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} + p \begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix} \Rightarrow \begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix} = \begin{bmatrix} L_{ls} + L_{0s} & -\frac{1}{2}L_{0s} & -\frac{1}{2}L_{0s} \\ -\frac{1}{2}L_{0s} & L_{ls} + L_{0s} & -\frac{1}{2}L_{0s} \\ -\frac{1}{2}L_{0s} & -\frac{1}{2}L_{0s} & L_{ls} + L_{0s} \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} + \begin{bmatrix} L_{sfd} \cos \theta_r & L_{skd} \cos \theta_r & -L_{skq} \sin \theta_r \\ L_{sfd} \cos (\theta_r - 2\pi/3) & L_{skd} \cos (\theta_r - 2\pi/3) & -L_{skq} \sin (\theta_r - 2\pi/3) \\ L_{sfd} \cos (\theta_r + 2\pi/3) & L_{skd} \cos (\theta_r + 2\pi/3) & -L_{skq} \sin (\theta_r + 2\pi/3) \end{bmatrix} \begin{bmatrix} i_{fd} \\ i_{kd} \\ i_{kq} \end{bmatrix}$$

$$\begin{bmatrix} L_{ls} + L_{0s} & -\frac{1}{2}L_{0s} & -\frac{1}{2}L_{0s} \\ -\frac{1}{2}L_{0s} & L_{ls} + L_{0s} & -\frac{1}{2}L_{0s} \\ -\frac{1}{2}L_{0s} & -\frac{1}{2}L_{0s} & L_{ls} + L_{0s} \end{bmatrix} - \begin{bmatrix} L_{2s} \cos 2\theta_r & L_{2s} \cos (2\theta_r - 2\pi/3) & L_{2s} \cos (2\theta_r + 2\pi/3) \\ L_{2s} \cos (2\theta_r - 2\pi/3) & L_{2s} \cos (2\theta_r + 2\pi/3) & L_{2s} \cos 2\theta_r \\ L_{2s} \cos (2\theta_r + 2\pi/3) & L_{2s} \cos 2\theta_r & L_{2s} \cos (2\theta_r - 2\pi/3) \end{bmatrix}$$

$$+ \begin{bmatrix} L_{sfd} \cos \theta_r & L_{skd} \cos \theta_r & -L_{skq} \sin \theta_r \\ L_{sfd} \cos (\theta_r - 2\pi/3) & L_{skd} \cos (\theta_r - 2\pi/3) & -L_{skq} \sin (\theta_r - 2\pi/3) \\ L_{sfd} \cos (\theta_r + 2\pi/3) & L_{skd} \cos (\theta_r + 2\pi/3) & -L_{skq} \sin (\theta_r + 2\pi/3) \end{bmatrix}$$

Stator voltage in space vector form

$$\begin{aligned}
 \begin{bmatrix} \lambda_{as} \\ \lambda_{bs} \\ \lambda_{cs} \end{bmatrix} &= \begin{bmatrix} L_{ls} + L_{0s} & -\frac{1}{2}L_{0s} & -\frac{1}{2}L_{0s} \\ -\frac{1}{2}L_{0s} & L_{ls} + L_{0s} & -\frac{1}{2}L_{0s} \\ -\frac{1}{2}L_{0s} & -\frac{1}{2}L_{0s} & L_{ls} + L_{0s} \end{bmatrix} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} \\
 &= \frac{L_{2s}}{2} \left\{ \begin{bmatrix} e^{2j\theta_r} & a^2 e^{2j\theta_r} & a e^{2j\theta_r} \\ a^2 e^{2j\theta_r} & a e^{2j\theta_r} & e^{2j\theta_r} \\ a e^{2j\theta_r} & e^{2j\theta_r} & a^2 e^{2j\theta_r} \end{bmatrix} + \begin{bmatrix} e^{-2j\theta_r} & a e^{-2j\theta_r} & a^2 e^{-2j\theta_r} \\ a e^{-2j\theta_r} & a^2 e^{-2j\theta_r} & e^{-2j\theta_r} \\ a^2 e^{-2j\theta_r} & e^{-2j\theta_r} & a e^{-2j\theta_r} \end{bmatrix} \right\} \begin{bmatrix} i_{as} \\ i_{bs} \\ i_{cs} \end{bmatrix} \\
 &\quad + \frac{L_{sfd}}{2} \left\{ \begin{bmatrix} e^{j\theta_r} \\ a^2 e^{j\theta_r} \\ a e^{j\theta_r} \end{bmatrix} + \begin{bmatrix} e^{-j\theta_r} \\ a e^{-j\theta_r} \\ a^2 e^{-j\theta_r} \end{bmatrix} \right\} i_{fd} + \frac{L_{skd}}{2} \left\{ \begin{bmatrix} e^{j\theta_r} \\ a^2 e^{j\theta_r} \\ a e^{j\theta_r} \end{bmatrix} + \begin{bmatrix} e^{-j\theta_r} \\ a e^{-j\theta_r} \\ a^2 e^{-j\theta_r} \end{bmatrix} \right\} i_{kd} \\
 &\quad - \frac{L_{skq}}{2j} \left\{ \begin{bmatrix} e^{j\theta_r} \\ a^2 e^{j\theta_r} \\ a e^{j\theta_r} \end{bmatrix} - \begin{bmatrix} e^{-j\theta_r} \\ a e^{-j\theta_r} \\ a^2 e^{-j\theta_r} \end{bmatrix} \right\} i_{kq} \quad (2.14-34)
 \end{aligned}$$

Stator voltage in space vector form

$$\begin{aligned}
 \lambda_{as} + a\lambda_{bs} + a^2\lambda_{cs} &= \left(L_{ls} + \frac{3}{2}L_{0s} \right) (i_{as} + ai_{bs} + a^2i_{cs}) \\
 &\quad - \frac{3}{2}L_{2s} (i_{as} + a^2i_{bs} + ai_{cs}) e^{j2\theta_r} \\
 &\quad + \frac{3}{2}L_{sfd}i_{fd}e^{j\theta_r} + \frac{3}{2}L_{skd}i_{kd}e^{j\theta_r} - \frac{3}{2}L_{skq}i_{kq}e^{j\left(\theta_r - \frac{\pi}{2}\right)} \quad (2.14-35)
 \end{aligned}$$



$$\begin{aligned}
 \lambda_{abcs} &= \left(L_{ls} + \frac{3}{2}L_{0s} \right) i_{abcs} - \frac{3}{2}L_{2s} i_{abcs}^* e^{j2\theta_r} + \frac{3}{2}L_{sfd}i_{fd}e^{j\theta_r} \\
 &\quad + \frac{3}{2}L_{skd}i_{kd}e^{j\theta_r} - \frac{3}{2}L_{skq}i_{kq}e^{j\left(\theta_r - \frac{\pi}{2}\right)} \quad (2.14-36)
 \end{aligned}$$



$$v_{abcs} = r_s i_{abcs} + p \lambda_{abcs} \quad (2.14-37)$$

Transform the complex vector eqs. to the rotor reference frame

$$v_{abcs} = r_s i_{abcs} + p \lambda_{abcs} \quad (2.14-37)$$

$$v_{abcs} e^{-j\theta_r} = r_s i_{abcs} e^{-j\theta_r} + e^{-j\theta_r} p \lambda_{abcs} \quad (2.14-38)$$

$$\begin{aligned} \lambda_{abcs} e^{-j\theta_r} &= \left(L_{ls} + \frac{3}{2} L_{0s} \right) i_{abcs} e^{-j\theta_r} \\ &\quad - \frac{3}{2} L_{2s} i_{abcs}^{\dagger} e^{j\theta_r} + \frac{3}{2} L_{sfd} i_{fd} + \frac{3}{2} L_{skd} i_{kd} - \frac{3}{2} L_{skq} i_{kq} e^{-j\frac{\pi}{2}} \quad (2.14-39) \\ &= \frac{2}{3} \lambda_{abcs} e^{-j\theta_r} \end{aligned}$$

$$\lambda_{qds}^r = \left(L_{ls} + \frac{3}{2} L_{0s} \right) i_{qds}^r - \frac{3}{2} L_{2s} (i_{qds}^r)^{\dagger} + L_{sfd} i_{fd} + L_{skd} i_{kd} + j L_{skq} i_{kq} \quad (2.14-44)$$

Transform the complex vector eqs. to the rotor reference frame

$$v_{abcs} = r_s i_{abcs} + p \lambda_{abcs} \quad (2.14-37)$$

$$v_{qds}^r = r_s i_{qds}^r + p \lambda_{qds}^r + j \omega_r \lambda_{qds}^r \quad (2.14-43)$$

$$v_{abcs} e^{-j\theta_r} = r_s i_{abcs} e^{-j\theta_r} + e^{-j\theta_r} p \lambda_{abcs} \quad (2.14-38)$$

$$v_{qds}^r = v_{qs}^r - j v_{ds}^r = \frac{2}{3} v_{abcs} e^{-j\theta_r} \quad (2.14-40)$$

$$\lambda_{qds}^r = \lambda_{qs}^r - j \lambda_{ds}^r = \frac{2}{3} \lambda_{abcs} e^{-j\theta_r} \quad (2.14-41)$$

$$i_{qds}^r = i_{qs}^r - j i_{ds}^r = \frac{2}{3} i_{abcs} e^{-j\theta_r} \quad (2.14-42)$$

Direct axis and quadrature axis inductance

--- specify that the rotor is not symmetrical

$$\lambda_{qds}^r = \left(L_{ls} + \frac{3}{2} L_{0s} \right) i_{qds}^r - \frac{3}{2} L_{2s} (i_{qds}^r)^\dagger + L_{sfd} i_{fd} + L_{skd} i_{kd} + j L_{skq} i_{kq} \quad (2.14-44)$$



$$\lambda_{qds}^r = \left(L_{ls} + \frac{L_{md} + L_{mq}}{2} \right) i_{qds}^r + \frac{2}{3} L_{md} (i_{fd}' + i_{kd}') - \left(\frac{L_{md} - L_{mq}}{2} \right) (i_{qds}^r)^\dagger + \frac{2}{3} j L_{mq} i_{kq}' \quad (2.14-47)$$

where

$$\text{direct axis ind.} \quad L_{md} = \frac{3}{2} (L_{0s} + L_{2s}) = \frac{3}{2} \frac{N_s}{N_{fd}} L_{sfd} = \frac{3}{2} \frac{N_s}{N_{kd}} L_{skd} \quad (2.14-45)$$

$$\text{quad. axis ind.} \quad L_{mq} = \frac{3}{2} (L_{0s} - L_{2s}) = \frac{3}{2} \frac{N_s}{N_{kq}} L_{skq} \quad (2.14-46)$$

Direct axis and quadrature axis inductance

--- transform rotor var. to stator

$$\lambda_{fd} = (L_{lfd} + L_{mfd}) i_{fd} + L_{fkd} i_{kd} + \frac{3L_{sfd}}{4} [i_{qds}^r + (i_{qds}^r)^\dagger] \quad (2.14-48)$$

$$\lambda_{kd} = (L_{lkd} + L_{mkd}) i_{kd} + L_{fkd} i_{fd} + \frac{3L_{skd}}{4} [i_{qds}^r + (i_{qds}^r)^\dagger] \quad (2.14-49)$$

$$\lambda_{kq} = (L_{lkq} + L_{mkq}) i_{kq} - j \frac{3L_{skq}}{4} [i_{qds}^r - (i_{qds}^r)^\dagger] \quad (2.14-50)$$

$$\lambda_{fd}' = L_{lfd}' i_{fd}' + L_{md} \{ i_{fd}' + i_{kd}' + \frac{1}{2} [i_{qds}^r + (i_{qds}^r)^\dagger] \} \quad (2.14-53)$$

$$\lambda_{kd}' = L_{lkd}' i_{kd}' + L_{md} \{ i_{kd}' + i_{fd}' + \frac{1}{2} [i_{qds}^r + (i_{qds}^r)^\dagger] \} \quad (2.14-54)$$

$$\lambda_{kq}' = L_{lkq}' i_{kq}' + L_{mq} \{ i_{kq}' - j \frac{1}{2} [i_{qds}^r - (i_{qds}^r)^\dagger] \} \quad (2.14-55)$$

Direct axis and quadrature axis inductance

--- transform rotor var. to stator

$$L_{md} = \frac{3}{2} (L_{0s} + L_{2s}) = \frac{3}{2} \frac{N_s^2}{N_{fd}^2} L_{mfd} = \frac{3}{2} \frac{N_s^2}{N_{kd}^2} L_{mkd} = \frac{3}{2} \frac{N_s^2}{N_{fd} N_{kd}} L_{fkd}$$

$$= \frac{3}{2} \frac{N_s}{N_{kd}} L_{skd} = \frac{3}{2} \frac{N_s}{N_{fd}} L_{sfd} \quad (2.14-51)$$

$$L_{mq} = \frac{3}{2} (L_{0s} - L_{2s}) = \frac{3}{2} \frac{N_s^2}{N_{fq}^2} L_{mfq} = \frac{3}{2} \frac{N_s}{N_{kq}} L_{skq} \quad (2.14-52)$$

$$i'_{kd} = \frac{2}{3} \frac{N_{kd}}{N_s} i_{kd} \quad (2.14-56)$$

$$L'_{lfd} = \frac{3}{2} L_{lfd} \frac{N_s^2}{N_{fd}^2} \quad (2.14-59)$$

$$\lambda'_{kd} = \frac{N_s}{N_{kd}} \lambda_{kd} \quad (2.14-62)$$

$$i'_{fd} = \frac{2}{3} \frac{N_{fd}}{N_s} i_{fd} \quad (2.14-57)$$

$$L'_{lkd} = \frac{3}{2} L_{lkd} \frac{N_s^2}{N_{kd}^2} \quad (2.14-60)$$

$$\lambda'_{fd} = \frac{N_s}{N_{fd}} \lambda_{fd} \quad (2.14-63)$$

$$i'_{kq} = \frac{2}{3} \frac{N_{kq}}{N_s} i_{kq} \quad (2.14-58)$$

$$L'_{lkq} = \frac{3}{2} L_{lkq} \frac{N_s^2}{N_{kq}^2} \quad (2.14-61)$$

$$\lambda'_{kq} = \frac{N_s}{N_{kq}} \lambda_{kq} \quad (2.14-64)$$

Direct axis and quadrature axis inductance

--- transform rotor var. to stator

$$v_{ds}^r = r_s i_{ds}^r + p \lambda_{ds}^r - \omega_r \lambda_{qs}^r \quad (2.14-65)$$

$$\lambda_{ds}^r = L_{ls} i_{ds}^r + L_{md} (i_{ds}^r + i'_{fd} + i'_{kd}) \quad (2.14-70)$$

$$v_{qs}^r = r_s i_{qs}^r + p \lambda_{qs}^r + \omega_r \lambda_{ds}^r \quad (2.14-66)$$

$$\lambda_{qs}^r = L_{ls} i_{qs}^r + L_{mq} (i_{qs}^r + i'_{kq}) \quad (2.14-71)$$

$$v'_{fd} = r'_{fd} i'_{fd} + p \lambda'_{fd} \quad (2.14-67)$$

$$\lambda'_{fd} = L'_{lfd} i'_{fd} + L_{md} (i'_{fd} + i'_{kd} + i_{ds}^r) \quad (2.14-72)$$

$$v'_{kd} = r'_{kd} i'_{kd} + p \lambda'_{kd} \quad (2.14-68)$$

$$\lambda'_{kd} = L'_{lkd} i'_{kd} + L_{md} (i'_{kd} + i'_{fd} + i_{ds}^r) \quad (2.14-73)$$

$$v'_{kq} = r'_{kq} i'_{kq} + p \lambda'_{kq} \quad (2.14-69)$$

$$\lambda'_{kq} = L'_{lkq} i'_{kq} + L_{mq} (i'_{kq} + i_{qs}^r) \quad (2.14-74)$$

=0

$$r'_{kd} = \frac{2}{3} r_{kd} ; r'_{kq} = \frac{2}{3} r_{kq} ; \text{ and } r'_{fd} = \frac{2}{3} r_{fd}$$

Power input and torque output equations

$$P_e = \frac{3}{2} [v_{ds}^r i_{ds}^r + v_{qs}^r i_{qs}^r + v_{fd}' i_{fd}'] \quad (2.14-75)$$

$$T_e = \frac{3P}{22} [\lambda_{ds}^r i_{qs}^r - \lambda_{qs}^r i_{ds}^r] \quad (2.14-76)$$

$$T_e = \frac{3P}{22} [\underbrace{(L_{ds} - L_{qs}) i_{qs}^r i_{ds}^r}_{\text{Saliency torque}} + \underbrace{L_{md} i_{fd}' i_{qs}^r + L_{md} i_{kd}' i_{qs}^r}_{\text{Excitation torque}} - \underbrace{L_{mq} i_{kd}' i_{ds}^r}_{\text{Damping torque or induction motor torque}}] \quad (2.14-77)$$

Motor is modelled in rotor reference frame --- a trace of acceleration of a SM




Figure 2.19 Acceleration of a 20 kVA, 230 V salient pole synchronous machine from rest with a shorted field winding. Traces from the top: i_{as} , i_{qs}^r , i_{ds}^r , i_{kq} , i_{kd} , i_{fd}' , T_{em} , rotor speed in rpm; time axis – 0.1 s/div.

2.14 Extension of d,q,0 Theory to Analysis of Permanent Magnet Motor

✿ Assume constant field current

$$\Lambda'_{mf} = L'_{md} i'_{fd} \quad (2.15-1)$$

$$v_{ds}^r = r_s i_{ds}^r + p \lambda_{ds}^r - \omega_r \lambda_{qs}^r \quad (2.15-2)$$

$$v_{qs}^r = r_s i_{qs}^r + p \lambda_{qs}^r + \omega_r \lambda_{ds}^r \quad (2.15-3)$$

$$v'_{kd} = r'_{kd} i'_{kd} + p \lambda'_{kd} \quad (2.15-4)$$

$$v'_{kq} = r'_{kq} i'_{kq} + p \lambda'_{kq} \quad (2.15-5) \quad \lambda_{ds}^r = L_{ls} i_{ds}^r + L_{md} (i_{ds}^r + i'_{kd}) + \Lambda'_{mf} \quad (2.15-6)$$

$$\lambda_{qs}^r = L_{ls} i_{qs}^r + L_{mq} (i_{qs}^r + i'_{kq}) \quad (2.15-7)$$

$$\lambda'_{kd} = L'_{lkd} i'_{kd} + L_{md} (i'_{kd} + i_{ds}^r) + \Lambda'_{mf} \quad (2.15-8)$$

$$\lambda'_{kq} = L'_{lkq} i'_{kq} + L_{mq} (i'_{kq} + i_{qs}^r) \quad (2.15-9)$$

