


ALARM ADDRESS	A27.4	ALARM NO.	1304
OP. MESSAGE	NO CONFIRM OF APC POS.2		
Related Signal	Input: X16.3 (154APC) °		
CAUSE	<p>Pallet 2 in position not reached</p> 		
ACTION	<p>P2 sensor X16.3 not detected after pallet swing finish.</p> <ol style="list-style-type: none"> 1.check X16.3 signal. 2.hydraulic pressure. 3.adjust sensor detect distance. 		