

## M051 Series CMSIS BSP Revision History

---

### Version 2.01.002 (Released 2012-08-10)

---

1. Fixed the \_TIMER\_RESET definition.
2. Fixed the SYSCLK\_CLKSEL1\_PWM23\_HCLK definition.
3. Removed the IARv6 directory and supported only IAR v6.21 and higher versions.
4. Modified PLL enable procedure to avoid unstable condition caused by PLL frequency changes.

### Version 2.01.001 (Released 2012-04-24)

---

1. Provided a new driver for faster performance with smaller code size.
2. Created a new directory hierarchy.

### Version 1.02.003 (Released 2012-03-12)

---

1. Fixed the UART driver bug.

### Version 1.02.002 (Released 2011-08-26)

---

1. Added the NuvotonPlatform\_IARv6 directory to support IAR tool v6.10 and later.
2. Supported semihosted input by IAR.

### Version 1.02.001 (Released 2011-07-08)

---

1. Updated the header to support 32-bit word access for control registers.

### Version 1.01.005 (Released 2011-06-20)

---

1. Fixed the bug about wrong clock source of timer driver.

### Version 1.01.004 (Released 2011-06-08)

---

1. Fixed the \_PORT\_DOUT definition of GPIO header.
2. Fixed the GPIO example in the Driver Reference Guide.

### Version 1.01.003 (Released 2011-05-31)

---

1. Added new sample code of learning board in KEIL environment: SmpI\_I2C\_SW, SmpI\_I2C\_SW\_I, SmpI\_Idle.
2. Fixed driver bugs.

3. Updated the clock diagram in the Driver Reference Guide.

## Version 1.01.002 (Released 2011-01-05)

---

1. Fixed bugs and added more samples.
2. Added sample code for the learning board.

## Version 1.01.001 (Released 2010-12-01)

---

1. Fixed bugs and added more samples.
2. Defaulted the NMI\_SEL to 0x31 (assigned NMI to reserved IRQ).
3. Updated the clock diagram in the Driver Reference Guide for the PLL source.
4. Removed the second parameter (E\_ADC\_INPUT\_MODE) from DrvADC\_SetADCChannel().
5. Removed multi-function pin configurations from SPI driver (DrvSPI\_Open()).
6. Removed multi-function pin configurations from ADC driver [ DrvADC\_Open( ) & DrvADC\_SetADCChannel( ) ]. Users need to control the multi-function I/O by GPIO driver before they can use the I/O of ADC or SPI.
7. Added sample code for M051-LB\_004 (Learning Board).
8. Fixed the gau32ClkSrcTbl setting to avoid wrong system clock calculation.
9. Fixed the bug about EINT0, EINT1 handler cleaning status.
10. Removed unused register definitions in startup\_M051Series.s.
11. Fixed the GCR\_INT\_T definition in M051Series.h.
12. Fixed the wrong definition of DRVUART\_STOPBITS\_1\_5 and DRVUART\_STOPBITS\_2.

## Version 1.00.001 (Released 2010-08-20)

---

1. Primary release version.

## Important Notice

Nuvoton Products are neither intended nor warranted for usage in systems or equipment, any malfunction or failure of which may cause loss of human life, bodily injury or severe property damage. Such applications are deemed, "Insecure Usage".

Insecure usage includes, but is not limited to: equipment for surgical implementation, atomic energy control instruments, airplane or spaceship instruments, the control or operation of dynamic, brake or safety systems designed for vehicular use, traffic signal instruments, all types of safety devices, and other applications intended to support or sustain life.

All Insecure Usage shall be made at customer's risk, and in the event that third parties lay claims to Nuvoton as a result of customer's Insecure Usage, customer shall indemnify the damages and liabilities thus incurred by Nuvoton.

---

*Please note that all data and specifications are subject to change without notice.  
All the trademarks of products and companies mentioned in this datasheet belong to their respective owners.*