

**Fan motor failure after a longer operating time****Models:       Refrigerators and Freezers with fan blade 6299 905-02**

Unit Designation
BGPv 55.., 65.., 84..;
BKPv 65.., 84..;
BKv 40..
CASS 11..
CASSP 11..
CNes 62..
ECN 62..
ECNes 62..
FKAv 29.., 41..;
FKDv 10.., 34.., 37.., 43..
FKDv 902
FKSBv 36..
FKv 26.., 36.., 41.., 43.., 54..;
FKv 302
FKvsl 26.., 36.., 41.., 54..;
FT 29..
FTI 29..
GGPv 55.., 65.., 84.., 14..;
GKPv 65.. 14..;
GKS 14.., 55.., 65.., 84..;
GKv 43.., 57.., 64..;
GTE 10.., 14.., 30.., 36.., 37.., 43.., 49.., 50.., 55.., 61..;
GTI 18.., 24.., 30.., 37.., 43.., 50..;
GTIC 4..
GTL 30.., 49..;
GTV 35..
GWK 64..
JKv 64..
KS 36.., 37..;
KSv 37..
LCv 40..
LGPv 65.., 14..;
LKexv 18.., 36.., 39..;

Unit Designation
LKPv 65.., 14..;
LKv 18.., 36.., 39..;
RC 34..
TGS 52..
TGSD 37..
UGK 40.., 41.., 57.., 64..;
UGS 14.., 55.., 65..;
UKB 55.., 84..;
UKS 18.., 26.., 35.., 36.., 43.., 49.., 50.., 57..;
UKSD 43.., 37..;
UKU 18..
UTB 55.., 84..;
UTSD 37..
WK 18.., 29.., 41.., 46.., 57.., 64..;
WKA 41..
WKb 18.., 24.., 29.., 32.., 57..;
WKes 32.., 41.., 46..;
WKR 18.., 24.., 29.., 32.., 41.., 46.., 57..;
WKrs 32..
WKS 32..
WKS 32.., 47..;
WKSb 18.., 24.., 32.., 47.., 57..;
WKsl 29.., 41.., 46..;
WKSr 18.., 24.., 32.., 47.., 57..;
WKSw 18.., 24.., 32.., 57..;
WKsw 29.., 41.., 47..;
WKUes 18..
WKw 18.., 24.., 32..;

**Cause:** The defect of the fan motor (e.g. bracket defect) can be effected by an imbalanced fan blade.

**To correct:** Check the fan blade in addition to the replacement of the fan motor.  
(See next page)

Fan blade **not** okay:




Fig. 1.0: Art.No. 6299 905-02

Fan blade okay:




Fig. 1.1: Art.No. 6299 905-03

If there is no material increase obviously (like in Fig. 1.0), change the fan blade to the new one.

Spare part	Until now	<b>NEW</b>
Fan blade	6299 905-02	<b>6299 905-03</b>

**Note:** Previous fan blade must not be used anymore.

**Comment:** If “Fans complete” are in the warehouse (see list below), they must be checked too according Fig. 1.0/1.1. If necessary, even there the fan blade must be replaced.

<b>Affected „Fans complete“</b>	
9870 687 Fan complete	9870 104 Fan complete
9870 695 Fan complete	9870 621 Fan complete
9870 697 Fan complete	9870 635 Fan complete
9870 707 Fan complete	9870 653 Fan complete
9870 711 Fan complete	9870 659 Fan complete
9870 719 Fan complete	9870 667 Fan complete
9870 731 Fan complete	9870 673 Fan complete
9870 753 Fan complete	9870 757 Fan complete
9870 755 Fan complete	9870 759 Fan complete