

Loud fan noise**Models: FAN BLADE Part.No. 6299 905-02**Built into the following groups of appliances: (Concerns all versions)

Models
BGPv 55.., 65.., 84..;
BKPv 65.., 84..;
BKv 40..
CASS 11..
CASSP 11..
CNes 62..
ECN 62..
ECNes 62..
FKAv 29.., 41..;
FKDv 10.., 34.., 37.., 43..
FKDv 902
FKSBv 36..
FKv 26.., 36.., 41.., 43.., 54..;
FKv 302
FKvsl 26.., 36.., 41.., 54..;
FT 29..
FTI 29..
GGPv 55.., 65.., 84.., 14..;
GKPv 65.. 14..;
GKS 14.., 55.., 65.., 84..;
GKv 43.., 57.., 64..;
GTE 10.., 14.., 30.., 36.., 37.., 43.., 49.., 50.., 55.., 61..;
GTI 18.., 24.., 30.., 37.., 43.., 50..;
GTIC 4..
GTL 30.., 49..;
GTV 35..
GWK 64..
JKv 64..
KS 36.., 37..;
KSv 37..
LCv 40..
LGPv 65.., 14..;
LKexv 18.., 36.., 39..;

Models
LKPv 65.., 14..;
LKv 18.., 36.., 39..;
RC 34..
TGS 52..
TGSD 37..
UGK 40.., 41.., 57.., 64..;
UGS 14.., 55.., 65..;
UKB 55.., 84..;
UKS 18.., 26.., 35.., 36.., 43.., 49.., 50.., 57..;
UKSD 43.., 37..;
UKU 18..
UTB 55.., 84..;
UTSD 37..
WK 18.., 29.., 41.., 46.., 57.., 64..;
WKA 41..
WKb 18.., 24.., 29.., 32.., 57..;
WKes 32.., 41.., 46..;
WKr 18.., 24.., 29.., 32.., 41.., 46.., 57..;
WKrs 32..
WKS 32..
WKS 32.., 47..;
WKSb 18.., 24.., 32.., 47.., 57..;
WKsl 29.., 41.., 46..;
WKSr 18.., 24.., 32.., 47.., 57..;
WKSw 18.., 24.., 32.., 57..;
WKsw 29.., 41.., 47..;
WKUes 18..
WKw 18.., 24.., 32..;

Fault profile: Loud fan noises are caused by fan blade.

Cause: The inclusion of the fan blade to the motor shaft is not centered, so the fan is unbalanced.

To correct: Built in optimized fan blade:

Spare part	Until now	NEW
Fan blade	6299 905-02	6299 905-03

Detection of the optical difference: see next page.

Fan blade until now:




Fig. 1.0: Part.No. 6299 905-02

Fan blade NEW:




Fig. 1.1: Part.No. 6299 905-03

Note: Previous fan blade must not used anymore.