

Healthcare Performance Improvement

www.mareksturek.com | [@mareksturek](https://twitter.com/mareksturek) | [mareksturek.github.io](https://github.com/mareksturek)

Marek Šturek



Agenda

- ❖ My journey into healthcare
- ❖ A brief overview of my healthcare work
- ❖ Connection b/w mind & heart, body & soul
- ❖ Some practical examples
- ❖ What can I do today




Crossroad



Spojená škola Tvrdošín

"Neučíme sa pre školu, ale pre život."



Timeline



YKHC
Bethel, Alaska



HNŠP Trstená
Trstená, Slovakia



UPOL
Olomouc, Czechia

2007

Medtronic
Fort Worth, Texas



2014

YVFWC
Yakima, Washington



2015

2019


2020

SWHR
Dallas, Texas



2021

Holistic Approach



Reactive work assignments | 1/2

Supplier Quality > Nonconformance Communication


Medtronic NONCONFORMANCE REPORT NCR No. 11-1375

Item	Qty	Part Number	Product Description	Quantity	Lot	Lot Date	Lot Location	Lot Status	Lot Remarks
1	1	120-089-3	Rev A clean and free of defects	1	1	10/11/06	10/11/06	10/11/06	10/11/06

Description:
PIN 120-089-3 Rev A clean and free of defects


NCR 11-1393

Conforming sample



Description:
PIN 120-089-3 Rev A clean and free of defects

Non-conforming sample



Description:
PIN 120-089-3 Rev A with marks/stains on surface

Medtronic NONCONFORMANCE REPORT NCR No. 11-1351

Item	Qty	Part Number	Product Description	Quantity	Lot	Lot Date	Lot Location	Lot Status	Lot Remarks
1	1	120-089-3	Rev A clean and free of defects	1	1	10/11/06	10/11/06	10/11/06	10/11/06

Description:
PIN 120-089-3 Rev A clean and free of defects

ZEISS Calypso

Measurement Plan
Date: 10/11/06
Operator: [Signature]
Part Number: 120-089-3
Process Plan: [Signature]
Lot Number: 10/11/06

Feature	Actual	Normal	Upper Tol	Lower Tol	Deviation
#1 OD 1.270	1.271252	1.270000	0.002000	-0.002000	0.001252
#2 ID 1.270	1.269848	1.270000	0.000000	-0.000000	-0.000152
#3 ID 1.270	1.269848	1.270000	0.000000	-0.000000	-0.000152
#4 ID 1.270	1.269848	1.270000	0.000000	-0.000000	-0.000152
#5 ID 1.270	1.269848	1.270000	0.000000	-0.000000	-0.000152
#6 ID 1.270	1.269848	1.270000	0.000000	-0.000000	-0.000152
#7 ID 1.270	1.269848	1.270000	0.000000	-0.000000	-0.000152
#8 ID 1.270	1.269848	1.270000	0.000000	-0.000000	-0.000152
#9 ID 1.270	1.269848	1.270000	0.000000	-0.000000	-0.000152
#10 ID 1.270	1.269848	1.270000	0.000000	-0.000000	-0.000152


Medtronic NONCONFORMANCE REPORT NCR No. 11-1372

Item	Qty	Part Number	Product Description	Quantity	Lot	Lot Date	Lot Location	Lot Status	Lot Remarks
1	1	120-089-3	Rev A clean and free of defects	1	1	10/11/06	10/11/06	10/11/06	10/11/06

Description:
PIN 120-089-3 Rev A clean and free of defects


NCR 11-1372

Conforming sample




Description:
PIN 120-089-3 Rev A clean and free of defects

Non-conforming sample



Description:
PIN 120-089-3 Rev A with marks/stains on surface



CORRECTIVE ACTION REPORT (CAR) FORM

CAR No.: CAR 06-0092

☒ CA ☐ PA

Initiation/Background Information (CAPA Coordinator / Owner)

Product Description / Quality System Microtec Process Capability (Length Dimension) for Part #100-580-4	CAR Initiation Date 10/11/06
---	--

CAR Source

☐ Management Review Meeting
☒ Quality Review Board (QRB)
☐ Complaint No.
☐ NCR No.

Initial Risk Assessment

☐ CAPA System Review
☐ Investigation (Inv. No.)
☐ Department Management
☐ Other:

RAW #: NA-
(Attach copy of risk assessment)

☐ R1
☐ R2
☐ R3
☐ R4

Root or Probable Cause (If CAR source is not an investigation)

☐ N/A (If CAR source is an investigation)

CAR #06-0012 was issued to Microtec after MPSS received two lots of Part #100-580-4 and one lot failed incoming inspection because the overall length on 17 parts fell below the lower specification limit of .314". The initial implementation plan to perform 100% inspection on all subsequent parts for this dimension was not successful. The capability of Microtec's manufacturing process to provide parts with a proper length has not been determined or required by Medtronic.

CAR Owner
Chris Fussell

Responsible Department
Quality Assurance

CAR Implementation Plan (Owner)

Description of Corrective/Preventive Action to be Implemented:

☐ OR Attach a CAR Plan if the activities required are complex.

Microtec will begin capturing the data that is currently obtained during their in-process inspection procedures for the length dimension on the 100-580-4 part. The capability of the process will be determined from the data and appropriate actions will be taken to improve the capability as necessary. The current MPSS inventory levels for the 100-580-4 part will be sufficient for 3 to 4 months of production. Once Microtec begins manufacturing the 100-580-4 parts again, they will be required by MPSS Supplier Quality to provide in-process inspection data and capability measures for the length dimension of the 100-580-4 part.

Implementation Due Date
05/31/07
(Provide date to CAPA Coordinator within 14 days of CAR Initiation)

☐ CAR Implementation Due Date Extended
(Attach Form 4141104 for each extension)

Additional Team Members Requested? ☐ Yes ☒ No
(The Addition of Team Members Requires QRB Approval)

Name	Department

Proposed Criteria to Determine CAR Effectiveness

The in-process inspection data and process capability for the length dimension must be provided by Microtec for each of the next three production lots of the 100-580-4 parts that are manufactured for MPSS. The next three production lots must not fail for a non-conforming length dimension.

Initial Plan Approval (Owner, Owner's Supervisor, & CAPA Coordinator unless resources added)

Signature	Date
Owner	10/25/2006
R&D	
Manufacturing	
Quality	10/25/06
Other	
RA *	
CAPA Coordinator	10/25/06

Provide Original to CAPA Coordinator After Approval

Reactive work assignments | 2/2


Project Charter Date: 31-January-2011		Project Name/QTRAK Number: LSPR00020375	
Problem Statement		Project Y	Path Y's (if needed)
Diamond coating yields at diamond coater, Di-Coat Corp., are below 96% causing shortages, affecting MPSS' ability to meet customer demands		Production yield (PY>97%)	Rolled Throughput Yield
Project Goal		Scope	
Increase diamond coating yields at Di-Coat Corp. to greater than 97 % by August 2011		Scope includes: Diamond coating process through receiving inspection at Medtronic Scope excludes: Transit, stem material, Medtronic packaging Do not harm: Dimension of the product, durability of diamond coating	
Resources		Business Impact and Benefits	
Project Team <ul style="list-style-type: none"> Julie Mouzakis Richard Castellanos Glenn Nolley Marek Sturek 		Schedule: <ul style="list-style-type: none"> Project start date: January, 2011 Estimated project completion date: August, 2011 Estimated date when benefits will begin: June, 2011 Benefits: <ul style="list-style-type: none"> Hard savings: Estimated MPSS's scrap cost of \$41K, Di-Coat's cost \$31K. NCR scrap cost of \$5K. Soft savings: Reduce non-conformances, reduce rework Other benefits: Strengthen partnership, Documented process controls 	
Support Team: <ul style="list-style-type: none"> Kristin Hughes (MBB) Ross Smith (PO, SSBB) Stakeholders: <ul style="list-style-type: none"> Tony Knight (CH) Dan Robinson (VSM) Dan Cleary (F) Humacao PR (C.S) Di-Coat Corp. (S) 			

LEAN SIGMA SOLUTIONS™



Lean Six Sigma Di-Coat Corp. Production Project					
I. NCR Reduction	1	January-May 2011 (Prior Improve Phase)		June - August 2011 (Current State)	
		Quantity (No.)	Cost (\$)	Quantity (No.)	Cost (\$)
		4	3485	0	0
II. Scrap Reduction	2	January-May 2011 (Prior Improve Phase)		June - August 2011 (Current State)	
		Quantity (pcs)	Average Scrap (%)	Quantity (pcs)	Average Scrap (%)
		1868	4.684	1305	2.087%
III. Component Quantity	3	January-May 2011 (Prior Improve Phase)		June - August 2011 (Current State)	
		Quantity (pcs)	Average monthly receipts (pcs)	Quantity (pcs)	Average monthly receipts (pcs)
		43327	9865	61284	20428
IV. Savings	4	Di-Coat Corp. Savings		Medtronic Inc. Saving	
		400 pcs X \$6 = \$2400 per month		400 pcs X \$10 = \$4000 per month	
V. Other	-	-		-	
> MPSS Inspection time	5	Receiving inspection for curve burrs the same		Receiving inspection for curve burrs improved (Ultrasonic cleaning process removed)	
> Di-Coat Corp. Rework process	6	AVG Feb-May 2011 (Overplated, Spase) 9.08%		AVG June-August 2011 (Overplated, Spase) 2.47%	
> Inspection method variation	7	No visual methods of inspection established between MPSS & Di-Coat		Visual methods of inspection established & aligned	
> Di-Coat Corp. Operational & process metrics	8	Operational & process metrics the same		Weekly meetings / Data collection / Data analysis established	
What's next?		Complete drawing revisions	Drive excellence to improve Op. 40	Continue focus on XOMED curve burrs	Complete transfer to Plant No. 3

$1/2$


Work instructions are provided for operator at every work station, but human error



Proactive work assignments | 2/2



Preventive work assignments | 1/2



Preventive work assignments | 2/2

Task	Job	Standard Work	Department	Date
R1	Acute Patient	YMDC Reception	Quality	12/04/2017

Task Elements Owner: Front Office Supervisor

	Description	☑ If Critical	Key Points	Visual Cue(s)
1.	Greet the patient	☑	Ask for D.O.B, First and Last Name, Introduce yourself. Let patient know who they are seeing and what time is appointment.	
2.	Demographics	☑	<p>Click on Appointment Desk Registration Demographics Patient Demographics General Information</p>	

HFMEA Subprocess Step Title and Number													
HFMEA Step 4 - Hazard Analysis													
Failure Mode: First Evaluate failure mode before determining potential causes	Potential Causes		Scoring		Decision Tree Analysis			Action Type (Control (Control, Accept, Eliminate))	Actions or Rationale for Stopping		Outcome Measure	Person Responsible	Management Concurrence
			Severity	Probability	Haz Score	Single Point Weakness?	Existing Control Measure?						
Bed availability (Inpatient 3 beds, ER 2 beds)	→		Major	Frequent	12	N	N	N	Y				
	1	Gender, Age in same room	Moderate	Frequent	8	Y	N	N	Y	N/A	State and Joint Commission regulations		
	2	High volume of patient	Moderate	Frequent	8	N	N	N	Y	Control	Review staffing plan for North Wing and ER in order to establish more effective patient service	Effective patient service measured by Patient Satisfaction, Decreased length of stay	Carrino, Richelle, Jeff
	3	Staffing	Moderate	Frequent	8	N	N	N	Y	Control	› Create guidelines for admission › Review staffing plan on North Wing › Training status		Barbara, Rag
	4	Lack of guards	Minor	Occasional	3	N	N	N	N	Accept			
	5	Intoxication (High acuity)	Major	Frequent	12	N	N	N	Y	Accept			
	6	Insufficient # of room	Major	Frequent	12	N	N	N	Y	Control			
	7	Mechanical issue	Moderate	Uncommon	4	N	N	N	Y	Control			
	8	Standardization	Moderate	Occasional	6	N	N	N	Y	Control			
	9	Waiting Judge, API Response, BH clinical	Moderate	Frequent	8	N	N	N	Y	Accept			

Today not tomorrow

8 steps
according to
JOHN KOTTER

- ❖ Urgency of change
- ❖ Coalition supporting change
- ❖ Clear vision
- ❖ Communication of vision
- ❖ Stronger employee engagement
- ❖ Short wins
- ❖ Support of next change
- ❖ Hardwiring change

Thank you & Questions

