
ee9 V6 ERRATA

- **The timing of some magnetic tape operations is underestimated.**

SIGNIFICANCE: NONE: HAS NO EFFECT ON CORRECT EXECUTION OF PROBLEM PROGRAMS.

V6.1A CORRECTS THIS ERROR IN V6.0A.

- **Drum I/O mistakenly uses zero bytes as the sector filler rather than spaces (KDF9 0 characters). Fortuitously, this has no effect on data read from the drum, as the zero bytes are translated back into KDF9 spaces.**

SIGNIFICANCE: NONE: HAS NO EFFECT ON CORRECT EXECUTION OF PROBLEM PROGRAMS.

V6.2A CORRECTS THIS ERROR IN V6.1A.