

Power Issues & Fixes

1. Incorrect Fuse Footprint

- Issue: Ordered fuse footprint is too large.
- To-Do: Update footprint to match ordered fuse size.

2. Barrel Jack Polarity Reversed

- Issue: Pin 1 (VCC) and Pin 2 (GND) are swapped.
- To-Do: Correct polarity in the schematic.

3. TPS5433 Symbol Incorrect

- Issue: Incorrect pin mapping in the schematic.
- To-Do:
 - Update symbol with correct pin mapping:
 - **PH** → Pin 3 → Pin 8
 - **GND** → Pin 4 → Pin 7
 - **EN** → Pin 7 → Pin 3
 - **SS** → Pin 8 → Pin 4

4. DC-DC Feedback Network Adjustment

- Issue: Current resistor network needs optimization.
- To-Do: Replace the feedback network with a single **1.91k Ω** and **3.24k Ω** resistor.

5. Power Rail Sourcing

- Issue: 5V and 3.3V should source from 12V instead of sequential rails.
- To-Do: Update schematic power distribution to ensure both 5V and 3.3V are derived from the 12V supply.

Connector Issues & Fixes

1. Screw Terminal Footprint Mismatch

- Issue: Ordered screw terminal product is **P2.54**, but PCB footprint is **P5.08**.
- To-Do: Update the component selection to match **P5.08**. These need to be sourced.