

1. Overview

This project analyzes aircraft accidents and incidents from 1948 to 2022. It is part of the initial phase of the FlatIron Data Science bootcamp, with the requirement to investigate the provided dataset. The goal is to derive three business recommendations for strategic investments in the aircraft industry. The business problem is to identify low-risk aircraft for a company looking to expand into commercial and private aviation.

2. Business Understanding

The main objective is to discern which aircraft present the lowest risk for the company's venture into aviation. This expansion requires a thorough risk assessment to make informed decisions on aircraft acquisition. The findings will be translated into actionable insights for the head of the new aviation division to guide purchase decisions. The investigation centers on assessing the risk profiles of various aircraft, with the aim of providing three informed business recommendations. These recommendations will specifically address which types of aircraft the company should consider for investment based on historical safety data. The ultimate goal is to guide the company towards aircraft options that minimize risk and potential liability, thereby supporting safe and sound investment decisions in the aviation sector.

Our primary stakeholders are the board members of the company as they are the ones to decide whether to carry out the investment or not.

3. Data Understanding

3.1 Data Description

For the project, the data source is drawn from Kaggle, which encompasses a comprehensive collection of aircraft accidents and incidents. The timeline of this dataset spans an extensive period, covering events from the year 1948 through to 2022.

The dataset has undergone a meticulous cleaning procedure to ensure the quality and relevance of the data. This process included a filter to retain only those incidents and accidents that occurred within the United States. Additionally, the data was refined by filtering out events to include only those that resulted in fatal injuries or serious injuries, thus focusing on the most severe occurrences.

Now let's dive into the data to better understand it and arrive to the business recommendations.

3.2 SetUp

3.3 Import necessary libraries

```
In [2]: import pandas as pd
import numpy as np
import matplotlib.pyplot as plt
%matplotlib inline
import seaborn as sns
```

```
In [3]: pd.set_option('display.max_columns', 500)
```

3.4 Define global variables

```
In [4]: INPUT_PATH = "../Data_Project_Phase1/AviationData.csv"
```

```
In [5]: !pwd
```

```
/c/Users/Usuario/Desktop/FlatIron/DataScience_FlatIron_Curso/Phase_1/Phase1-Project/Aircraft_safety_analysis/notebooks
```

3.5 Functions

```
In [6]: def categorize_data(column):
        """
        Function: This function will return the string 'zero' if the value of the argument
        'one or more' if the value of 'column' is not zero

        Argument (data series): The column to evaluate

        Result (string): The category label for the value

        """
        if column==0:
            return 'Zero'
        elif pd.isna(column):
            return 'Unknown'
        else:
            return 'One or More'
```

```
In [7]: def plot_bar_graph_for_columns(columns):  
  
    """  
    Function: This function creates a bar graph for a column.  
  
    Argument (data series): The columns to evaluate.  
  
    Returns: Bar plot for the column  
  
    """  
  
    plt.figure()  
    df[columns].value_counts().plot(kind='bar')  
    plt.xlabel(columns)  
    plt.ylabel('Frequency')  
    plt.xticks(rotation=90)  
    plt.title(f'Bar Graph of {columns}')
```

```
In [8]: def plot_column_data(df, column, kind_of_graph):  
  
    """  
    Function: This function creates a value_counts and the desired graph for a column  
  
    Argument (data series): The data frame, the column and the kind of graph wished  
  
    Returns: Value_counts of the column and the desired graph representation  
    """  
  
    # Print the normalized value counts including NaN values  
    value_counts = df[column].value_counts(normalize=True, dropna=False)  
    print(value_counts)  
    print()  
  
    # Plot the graph  
    if kind_of_graph == 'bar':  
        plt.figure()  
        value_counts.plot(kind='bar')  
    elif kind_of_graph == 'pie':  
        plt.figure()  
        value_counts.plot(kind='pie')  
    elif kind_of_graph == 'line':  
        plt.figure()  
        value_counts.plot(kind='line')  
  
    # Show the plot  
    plt.title(f'Graph of {column}')  
    plt.ylabel('Frequency')  
    plt.xlabel(column)  
    plt.xticks(rotation=90)  
    plt.show();
```

```
In [9]: def plot_feature(df: pd.DataFrame,
                    column_name: str,
                    column_type: str,
                    variable_target1: str,
                    variable_target2: str):
    """
    Visualize a variable with faceting on two target variables.

    Parameters:
        df (pd.DataFrame): The dataframe containing the data.
        column_name (str): The name of the column to be visualized.
        column_type (str): The type of the column ('continuous' or 'categorical').
        variable_target1 (str): The name of the first target variable for faceting.
        variable_target2 (str): The name of the second target variable for faceting.
    """
    f, (ax1, ax2, ax3) = plt.subplots(nrows=1, ncols=3, figsize=(18,6), dpi=90)

    # Plot without target variables
    if column_type == 'continuous':
        sns.distplot(df.loc[df[column_name].notnull()], column_name, kde=False, ax=ax1)
    else:
        categories_to_consider = list(df[column_name].value_counts().index[:15])
        df = df[df[column_name].isin(categories_to_consider)]
        sns.countplot(x=df[column_name], order=sorted(categories_to_consider),
                      color='#5975A4', saturation=1, ax=ax1)
    ax1.set_xlabel(column_name)
    ax1.set_ylabel('Count')
    ax1.set_title(f"Distribution of {column_name}")
    ax1.tick_params(axis='x', rotation=90)

    # Plot with the first target variable
    if column_type == "continuous":
        sns.boxplot(x=column_name, y=variable_target1, data=df, ax=ax2)
    else:
        data = df.groupby(column_name)[variable_target1].value_counts(normalize=True)
        data.plot(kind='bar', stacked=True, ax=ax2)
    ax2.set_ylabel(f"Proportion of {variable_target1}")
    ax2.set_title(f"{column_name} by {variable_target1}")
    ax2.tick_params(axis='x', rotation=90)

    # Plot with the second target variable
    if column_type == "continuous":
        sns.boxplot(x=column_name, y=variable_target2, data=df, ax=ax3)
    else:
        data = df.groupby(column_name)[variable_target2].value_counts(normalize=True)
        data.plot(kind='bar', stacked=True, ax=ax3)
    ax3.set_ylabel(f"Proportion of {variable_target2}")
    ax3.set_title(f"{column_name} by {variable_target2}")
    ax3.tick_params(axis='x', rotation=90)

    plt.tight_layout()
    plt.show()
```

3.6 Code

```
In [10]: df = pd.read_csv(INPUT_PATH, encoding="latin-1")
df
```

C:\Users\Usuario\AppData\Local\Temp\ipykernel_22212\281516245.py:1: DtypeWarning: Columns (6,7,28) have mixed types. Specify dtype option on import or set low_memory=False.

```
df = pd.read_csv(INPUT_PATH, encoding="latin-1")
```

```
Out[10]:
```

	Event.Id	Investigation.Type	Accident.Number	Event.Date	Location	Country	Le
0	20001218X45444	Accident	SEA87LA080	1948-10-24	MOOSE CREEK, ID	United States	
1	20001218X45447	Accident	LAX94LA336	1962-07-19	BRIDGEPORT, CA	United States	
2	20061025X01555	Accident	NYC07LA005	1974-08-30	Saltville, VA	United States	36.5
3	20001218X45448	Accident	LAX96LA321	1977-06-19	EUREKA, CA	United States	
4	20041105X01764	Accident	CHI79FA064	1979-08-02	Canton, OH	United States	
...
88884	20221227106491	Accident	ERA23LA093	2022-12-26	Annapolis, MD	United States	
88885	20221227106494	Accident	ERA23LA095	2022-12-26	Hampton, NH	United States	
88886	20221227106497	Accident	WPR23LA075	2022-12-26	Payson, AZ	United States	34
88887	20221227106498	Accident	WPR23LA076	2022-12-26	Morgan, UT	United States	
88888	20221230106513	Accident	ERA23LA097	2022-12-29	Athens, GA	United States	

88889 rows × 31 columns

```
In [11]: print(f"This dataset has {df.shape[0]} rows and {df.shape[1]} columns")
```

This dataset has 88889 rows and 31 columns

```
In [12]: df.info()
```

```
<class 'pandas.core.frame.DataFrame'>
RangeIndex: 88889 entries, 0 to 88888
Data columns (total 31 columns):
#   Column                Non-Null Count  Dtype  
---  -
0   Event.Id              88889 non-null  object  
1   Investigation.Type     88889 non-null  object  
2   Accident.Number       88889 non-null  object  
3   Event.Date            88889 non-null  object  
4   Location              88837 non-null  object
```

```
5   Country                88663 non-null object
6   Latitude               34382 non-null object
7   Longitude              34373 non-null object
8   Airport.Code           50132 non-null object
9   Airport.Name           52704 non-null object
10  Injury.Severity         87889 non-null object
11  Aircraft.damage         85695 non-null object
12  Aircraft.Category       32287 non-null object
13  Registration.Number     87507 non-null object
14  Make                   88826 non-null object
15  Model                  88797 non-null object
16  Amateur.Built          88787 non-null object
17  Number.of.Engines       82805 non-null float64
18  Engine.Type            81793 non-null object
19  FAR.Description         32023 non-null object
20  Schedule                12582 non-null object
21  Purpose.of.flight       82697 non-null object
22  Air.carrier            16648 non-null object
23  Total.Fatal.Injuries    77488 non-null float64
24  Total.Serious.Injuries  76379 non-null float64
25  Total.Minor.Injuries    76956 non-null float64
26  Total.Uninjured         82977 non-null float64
27  Weather.Condition       84397 non-null object
28  Broad.phase.of.flight   61724 non-null object
29  Report.Status           82505 non-null object
30  Publication.Date        75118 non-null object
dtypes: float64(5), object(26)
memory usage: 21.0+ MB
```

Now, I am going to clean the column names by making them be in lower case and using an underscore

```
In [13]: df.columns = df.columns.str.lower().str.replace('.', '_')
df.columns
```

```
Out[13]: Index(['event_id', 'investigation_type', 'accident_number', 'event_date',
               'location', 'country', 'latitude', 'longitude', 'airport_code',
               'airport_name', 'injury_severity', 'aircraft_damage',
               'aircraft_category', 'registration_number', 'make', 'model',
               'amateur_built', 'number_of_engines', 'engine_type', 'far_description',
               'schedule', 'purpose_of_flight', 'air_carrier', 'total_fatal_injuries',
               'total_serious_injuries', 'total_minor_injuries', 'total_uninjured',
               'weather_condition', 'broad_phase_of_flight', 'report_status',
               'publication_date'],
              dtype='object')
```

```
In [14]: df
```

```
Out[14]:
```

	event_id	investigation_type	accident_number	event_date	location	country	lat
0	20001218X45444	Accident	SEA87LA080	1948-10-24	MOOSE CREEK, ID	United States	
1	20001218X45447	Accident	LAX94LA336	1962-07-19	BRIDGEPORT, CA	United States	
2	20061025X01555	Accident	NYC07LA005	1974-08-30	Saltville, VA	United States	36.9
3	20001218X45448	Accident	LAX96LA321	1977-06-19	EUREKA, CA	United States	

	event_id	investigation_type	accident_number	event_date	location	country	lat
4	20041105X01764	Accident	CHI79FA064	1979-08-02	Canton, OH	United States	
...	
88884	20221227106491	Accident	ERA23LA093	2022-12-26	Annapolis, MD	United States	
88885	20221227106494	Accident	ERA23LA095	2022-12-26	Hampton, NH	United States	
88886	20221227106497	Accident	WPR23LA075	2022-12-26	Payson, AZ	United States	34°
88887	20221227106498	Accident	WPR23LA076	2022-12-26	Morgan, UT	United States	
88888	20221230106513	Accident	ERA23LA097	2022-12-29	Athens, GA	United States	

3.6.1 Descriptive Statistics

In [15]: `df.describe()`

Out[15]:

	number_of_engines	total_fatal_injuries	total_serious_injuries	total_minor_injuries	total_uninjured
count	82805.000000	77488.000000	76379.000000	76956.000000	82977.000000
mean	1.146585	0.647855	0.279881	0.357061	5.325400
std	0.446510	5.485960	1.544084	2.235625	27.913600
min	0.000000	0.000000	0.000000	0.000000	0.000000
25%	1.000000	0.000000	0.000000	0.000000	0.000000
50%	1.000000	0.000000	0.000000	0.000000	1.000000
75%	1.000000	0.000000	0.000000	0.000000	2.000000
max	8.000000	349.000000	161.000000	380.000000	699.000000

Even though Number of Engines is continuous, it could be considered as discrete because it doesn't make much sense to talk about a mean of 1.14 of number of engines.

Other noticeable things are that there is a mean of almost 1 total fatal injury for all the accidents, and data seems to be coherent because there aren't negative values.

3.6.2 Making a primary key

In [16]: `df['event_id'].value_counts()`

Out[16]:

event_id	
20001212X19172	3
20001214X45071	3

```
20220730105623    2
20051213X01965    2
20001212X16765    2
..
20001211X14216    1
20001211X14239    1
20001211X14207    1
20001211X14204    1
20221230106513    1
```

```
In [17]: df['accident_number'].value_counts()
```

```
Out[17]: accident_number
CEN22LA149    2
WPR23LA041    2
WPR23LA045    2
DCA22WA214    2
DCA22WA089    2
..
LAX92FA065    1
ANC92T#A12    1
MIA92LA049    1
NYC92LA048    1
ERA23LA097    1
Name: count, Length: 88863, dtype: int64
```

```
In [18]: df['registration_number'].value_counts()
```

```
Out[18]: registration_number
NONE          344
UNREG         126
UNK           13
USAF           9
N20752         8
...
N93478         1
N519UA         1
N8840W         1
N21040         1
N9026P         1
Name: count, Length: 79104, dtype: int64
```

```
In [19]: df[df['accident_number']=='CEN22LA149']
```

```
Out[19]:
```

	event_id	investigation_type	accident_number	event_date	location	country	latitud
87548	20220323104818	Accident	CEN22LA149	2022-03-18	Grapevine, TX	United States	032530
87549	20220323104818	Accident	CEN22LA149	2022-03-18	Grapevine, TX	United States	032530

```
In [20]: df['primary_key'] = df['accident_number'] + '_' + df['registration_number']
df
```

```
Out[20]:
```

	event_id	investigation_type	accident_number	event_date	location	country	lat
--	----------	--------------------	-----------------	------------	----------	---------	-----

	event_id	investigation_type	accident_number	event_date	location	country	lat
0	20001218X45444	Accident	SEA87LA080	1948-10-24	MOOSE CREEK, ID	United States	36.9
1	20001218X45447	Accident	LAX94LA336	1962-07-19	BRIDGEPORT, CA	United States	
2	20061025X01555	Accident	NYC07LA005	1974-08-30	Saltville, VA	United States	
3	20001218X45448	Accident	LAX96LA321	1977-06-19	EUREKA, CA	United States	
4	20041105X01764	Accident	CHI79FA064	1979-08-02	Canton, OH	United States	
...	
88884	20221227106491	Accident	ERA23LA093	2022-12-26	Annapolis, MD	United States	34
88885	20221227106494	Accident	ERA23LA095	2022-12-26	Hampton, NH	United States	
88886	20221227106497	Accident	WPR23LA075	2022-12-26	Payson, AZ	United States	
88887	20221227106498	Accident	WPR23LA076	2022-12-26	Morgan, UT	United States	
88888	20221230106513	Accident	ERA23LA097	2022-12-29	Athens, GA	United States	

In [21]: `df['primary_key'].value_counts()`

```
Out[21]: primary_key
SEA87LA080_NC6404      1
SEA05CA166_N2094K      1
CHI05CA172_N7446       1
DEN05CA122_N2584B      1
DEN05LA121_N5754S      1
..
MIA91LA225_N2983U      1
ATL91LA180_N62108      1
ATL91LA181A_N26004     1
ATL91LA181B_N67174     1
ERA23LA097_N9026P      1
Name: count, Length: 87507, dtype: int64
```

We haven't found a primary key, but I have created one by combining 2 columns:
accident_number and registration_number

3.6.3 Duplicates study

Checking for duplicates

In [22]: `df.duplicated().sum()`

Out[22]: 0

3.6.4 Null-values analysis

Checking for null values

```
In [23]: df.isnull().sum()/len(df)*100
```

```
Out[23]: event_id                0.000000
investigation_type              0.000000
accident_number                0.000000
event_date                     0.000000
location                       0.058500
country                        0.254250
latitude                       61.320298
longitude                      61.330423
airport_code                   43.601570
airport_name                   40.708074
injury_severity                1.124999
aircraft_damage                3.593246
aircraft_category              63.677170
registration_number            1.554748
make                           0.070875
model                          0.103500
amateur_built                  0.114750
number_of_engines              6.844491
engine_type                    7.982990
far_description                63.974170
schedule                       85.845268
purpose_of_flight              6.965991
air_carrier                    81.271023
total_fatal_injuries           12.826109
total_serious_injuries         14.073732
total_minor_injuries           13.424608
total_uninjured                6.650992
weather_condition              5.053494
broad_phase_of_flight          30.560587
report_status                  7.181991
publication_date               15.492356
primary_key                    1.554748
dtype: float64
```

I will proceed to create a list to drop certain columns that have too many null values and that I perceive not to be useful for the analysis.

Latitude, Longitude, airport_code, airport_name, and publication_date I decide to drop mainly because they are not useful for the case study. Schedule and air_carrier I decide to drop because they have more than 80% of null values


```
In [24]: drop_columns = ['latitude', 'longitude', 'airport_code', 'airport_name', 'schedule', 'air_
```

Now I will study other columns that have a high percent of null values to determine whether they still can give good insights. These columns are: aircraft_category, far_description, and broad_phase_of_flight

Aircraft_category

```
In [25]: plot_column_data(df, 'aircraft_category', 'bar')
```

```
aircraft_category
NaN                0.636772
Airplane           0.310691
Helicopter         0.038700
Glider             0.005715
Balloon            0.002599
Gyrocraft          0.001946
Weight-Shift       0.001811
Powered Parachute  0.001024
Ultralight         0.000337
Unknown            0.000157
WSFT               0.000101
Powered-Lift       0.000056
Blimp              0.000045
UNK                0.000022
Rocket             0.000011
ULTR               0.000011
Name: proportion, dtype: float64
```



It's observable that only the airplanes and the helicopters have considerable numbers of registrations in the aircraft category. Moreover, as can be seen most of the aircrafts are airplanes.

Given that there 64% of NaN values, I will drop this column too

```
In [26]: drop_columns.append('aircraft_category')
```


3.6.5 Further study of the rest of the columns

Far Description column

```
In [27]: plot_column_data(df, 'far_description', 'bar')
```

far_description	
NaN	0.639742
091	0.204986
Part 91: General Aviation	0.072967
NUSN	0.017820
NUSC	0.011396
137	0.011362
135	0.008392
121	0.007639
Part 137: Agricultural	0.004916
UNK	0.004174
Part 135: Air Taxi & Commuter	0.003352
PUBU	0.002846
129	0.002767
Part 121: Air Carrier	0.001856
133	0.001204
Part 129: Foreign	0.001125
Non-U.S., Non-Commercial	0.001091
Non-U.S., Commercial	0.001046
Part 133: Rotorcraft Ext. Load	0.000360
Unknown	0.000247
Public Use	0.000214
091K	0.000157
ARMF	0.000090
Part 125: 20+ Pax,6000+ lbs	0.000056
125	0.000056
107	0.000045
103	0.000022
Public Aircraft	0.000022
Part 91 Subpart K: Fractional	0.000011
Part 91F: Special Flt Ops.	0.000011
437	0.000011
Armed Forces	0.000011

Name: proportion, dtype: float64



I interpret that the 091 and Part 91: General Aviation are the same norm of aviation. Basing myself in these research:

<https://www.risingup.com/fars/info/>

Subchapter F – Air Traffic and General Operating Rules

- **Part 91 - GENERAL OPERATING AND FLIGHT RULES**
- [Part 93 - SPECIAL AIR TRAFFIC RULES](#)
- [Part 95 - IFR ALTITUDES](#)
- [Part 97 - STANDARD INSTRUMENT APPROACH PROCEDURES](#)
- [Part 99 - SECURITY CONTROL OF AIR TRAFFIC](#)
- [Part 101 - MOORED BALLOONS, KITES, UNMANNED ROCKETS AND UNMANNED FREE BALLOONS](#)
- [Part 103 - ULTRALIGHT VEHICLES](#)
- [Part 105 - PARACHUTE OPERATIONS](#)


I will proceed to join both of these values and print the result

```
In [28]: df['far_description'] = df['far_description'].map(lambda x: 'Part 91 - General Aviation' if x == '091' else x)
          plot_column_data(df, 'far_description', 'bar')
```

```
far_description
NaN                0.639742
Part 91 - General Aviation  0.278133
NUSN                0.017820
NUSC                0.011396
137                 0.011362
135                 0.008392
121                 0.007639
Part 137: Agricultural  0.004916
UNK                 0.004174
Part 135: Air Taxi & Commuter  0.003352
```

PUBU	0.002846
129	0.002767
Part 121: Air Carrier	0.001856
133	0.001204
Part 129: Foreign	0.001125
Non-U.S., Non-Commercial	0.001091
Non-U.S., Commercial	0.001046
Part 133: Rotorcraft Ext. Load	0.000360
Unknown	0.000247
Public Use	0.000214
ARMF	0.000090
125	0.000056
Part 125: 20+ Pax,6000+ lbs	0.000056
107	0.000045
103	0.000022
Public Aircraft	0.000022
Armed Forces	0.000011
437	0.000011

Name: proportion, dtype: float64




As is visible, the aircrafts under 91 regulations encompass the most part of the dataset about aviation accidents. Given that the far description has 64% of null values, I will add this column to the drop list

```
In [29]: drop_columns.append('far_description')
```

Broad Phase of Flight

```
In [30]: plot_column_data(df, 'broad_phase_of_flight', 'bar')
```

```
broad_phase_of_flight
NaN          0.305606
Landing      0.173565
Takeoff      0.140546
Cruise       0.115526
Maneuvering  0.091620
Approach     0.073642
Climb        0.022882
Taxi         0.022027
Descent      0.021229
Go-around    0.015221
Standing     0.010631
Unknown      0.006165
Other        0.001339
Name: proportion, dtype: float64
```



The most important causes of accidents happened either during: landing, takeoff, cruise, maneuvering or approach. I consider 30% of null values to not be too excessive and believe that the 5 phases mentioned before could be of use. I will not drop these columns

```
In [31]: df['broad_phase_of_flight'].fillna('Unknown', inplace=True)
```

The study of the columns in question have been done and I will now proceed to drop said

columns. I will also append to the drop columns the previous id columns that are now unnecessary with the new primary_key column

```
In [32]: drop_columns = drop_columns + ['accident_number', 'registration_number', 'event_id']  
  
df = df.drop(drop_columns, axis=1)
```


```
In [33]: df.isnull().sum()/len(df)*100
```

```
Out[33]: investigation_type      0.000000  
event_date      0.000000  
location      0.058500  
country      0.254250  
injury_severity      1.124999  
aircraft_damage      3.593246  
make      0.070875  
model      0.103500  
amateur_built      0.114750  
number_of_engines      6.844491  
engine_type      7.982990  
purpose_of_flight      6.965991  
total_fatal_injuries      12.826109  
total_serious_injuries      14.073732  
total_minor_injuries      13.424608  
total_uninjured      6.650992  
weather_condition      5.053494  
broad_phase_of_flight      0.000000  
report_status      7.181991  
primary_key      1.554748  
dtype: float64
```

Investigation type

```
In [34]: plot_column_data(df, 'investigation_type', 'bar')
```

```
investigation_type  
Accident      0.956418  
Incident      0.043582  
Name: proportion, dtype: float64
```



After doing some reasearch, we have noticed that an accident is a unintentional event that results in harm whereas an incident although it might be unintentional doesn't necessarily result in harm

Moreover, we can see that all of the registrations in the dataset are all accidents (in 96% of it's totality)

Event Date

```
In [35]: df['event_date'].min()
```

```
Out[35]: '1948-10-24'
```

```
In [36]: df['event_date'].max()
```

```
Out[36]: '2022-12-29'
```

```
In [37]: df['event_date'].value_counts(normalize=True, dropna=False)
```

```
Out[37]: event_date
1984-06-30    0.000281
1982-05-16    0.000281
2000-07-08    0.000281
1983-08-05    0.000270
1984-08-25    0.000270
...
2014-03-16    0.000011
2014-03-15    0.000011
2014-03-12    0.000011
2014-03-10    0.000011
2022-12-29    0.000011
Name: proportion, Length: 14782, dtype: float64
```

```
In [38]: df['event_date'].isna().any()
```

```
Out[38]: False
```

We have realized that we have accidents or incidents from 1948 to 2022

```
In [39]: df['event_date'] = df['event_date'].astype('object')
```

I would like to investigate the number of accidents per year and month


```
In [40]: df['year'] = df['event_date'].map(lambda x:int(x[:4]))
df['year']
```

```
Out[40]: 0      1948
         1      1962
         2      1974
         3      1977
         4      1979
         ...
        88884    2022
        88885    2022
        88886    2022
        88887    2022
        88888    2022
        Name: year, Length: 88889, dtype: int64
```

```
In [41]: df.groupby('year')['investigation_type'].count().plot(kind='line')

plt.title('Number of accidents and incidents per year')
plt.xlabel('Year')
plt.ylabel('Accidents and incidents')

plt.show()
```



```
In [42]: df[df['year'] < 1982]
```

```
Out[42]:
```

	investigation_type	event_date	location	country	injury_severity	aircraft_damage	make
0	Accident	1948-10-24	MOOSE CREEK, ID	United States	Fatal(2)	Destroyed	Stinson
1	Accident	1962-07-19	BRIDGEPORT, CA	United States	Fatal(4)	Destroyed	Piper

	investigation_type	event_date	location	country	injury_severity	aircraft_damage	make
2	Accident	1974-08-30	Saltville, VA	United States	Fatal(3)	Destroyed	Cessna
3	Accident	1977-06-19	EUREKA, CA	United States	Fatal(2)	Destroyed	Rockwell
4	Accident	1979-08-02	Canton, OH	United States	Fatal(1)	Destroyed	Cessna
5	Accident	1979-09-17	BOSTON, MA	United States	Non-Fatal	Substantial	Mcdonnell Douglas
			COTTON, United				


As can be seen there is only 7 rows of data before 1983. I will proceed to eliminate these rows

```
In [43]: df = df[df['year']>1982]
```

```
In [44]: df.groupby('year')['investigation_type'].count().plot(kind='line', marker='o')

plt.title('Number of accidents and incidents per year')
plt.xlabel('Year')
plt.ylabel('Accidents and incidents')

plt.show()
```



In the passing of time, it is visible that the number of accidents have reduced gradually. In 2020, there is a noticeable drop in the number of accidents, possible due to the Covid-19 restrictions period

I will now study the number of accidents per month


```
In [45]: df['month'] = df['event_date'].map(lambda x:x[5:7])
df['month']
```

```
Out[45]: 3600    01
3601    01
3602    01
3603    01
3604    01
..
88884   12
88885   12
88886   12
88887   12
88888   12
Name: month, Length: 85289, dtype: object
```

```
In [46]: df.groupby('month')['investigation_type'].count().plot(kind='line', marker='o')

plt.title('Number of accidents and incidents per month')
plt.xlabel('Month')
plt.ylabel('Accidents and incidents')

plt.show()
```



The information shows that there are more accidents and incidents during the summer period which is normal as there tends to be more flights during that period as can be seen in the following studies:

There's also typically an increase of passengers escaping cold weather in northern cities for warm weather locales in late winter and early spring. Air travel also increases during the summer months, generally from around Memorial Day through Labor Day. Feb 28, 2017



USA Today

<https://www.usatoday.com> › travel › flights › 2017/02/28


Ask Air Traffic Control: Busiest times of year to fly - USA Today

Country

```
In [47]: plot_column_data(df, 'country', 'bar')
```

country	
United States	0.922475
Brazil	0.004385
Canada	0.004209
Mexico	0.004197
United Kingdom	0.004033
...	
Seychelles	0.000012
Palau	0.000012
Libya	0.000012
Saint Vincent and the Grenadines	0.000012
Turks and Caicos Islands	0.000012

Name: proportion, Length: 220, dtype: float64



The majority of the events occur in USA. I will delete the rows where the country is not USA

```
In [48]: df = df[df['country']=='United States']
```

Injury severity

```
In [49]: df['injury_severity'].value_counts(normalize=True, dropna=False)
```

```
Out[49]: injury_severity
Non-Fatal      0.788896
Fatal(1)       0.070656
Fatal          0.045197
Fatal(2)       0.041334
Incident       0.022294
Fatal(3)       0.012024
Fatal(4)       0.008262
Minor          0.002580
Fatal(5)       0.002110
Serious        0.001945
NaN            0.001373
Fatal(6)       0.001335
Fatal(7)       0.000432
Fatal(8)       0.000280
Fatal(10)      0.000216
Unavailable    0.000191
Fatal(9)       0.000102
Fatal(14)      0.000064
Fatal(11)      0.000064
Fatal(12)      0.000051
Fatal(17)      0.000038
Fatal(13)      0.000038
Fatal(18)      0.000038
Fatal(25)      0.000038
Fatal(82)      0.000025
Fatal(23)      0.000025
Fatal(20)      0.000025
Fatal(34)      0.000025
Fatal(31)      0.000013
Fatal(65)      0.000013
Fatal(19)      0.000013
Fatal(44)      0.000013
Fatal(64)      0.000013
Fatal(21)      0.000013
Fatal(92)      0.000013
Fatal(265)     0.000013
Fatal(228)     0.000013
Fatal(49)      0.000013
```

```
Fatal(70)      0.000013
Fatal(88)      0.000013
Fatal(15)      0.000013
Fatal(29)      0.000013
Fatal(230)     0.000013
Fatal(110)     0.000013
Fatal(68)      0.000013
Fatal(132)     0.000013
Fatal(37)      0.000013
Fatal(16)      0.000013
Fatal(135)     0.000013
Fatal(73)      0.000013
Fatal(111)     0.000013
Fatal(43)      0.000013
Fatal(28)      0.000013
Fatal(156)     0.000013
Fatal(27)      0.000013
```

```
In [50]: df['injury_severity'] = df['injury_severity'].astype('category')
```

I am going to group all the Fatal injuries. First I'll change the type of the column to categorical

```
In [51]: df['injury_severity'] = df['injury_severity'].map(lambda x: 'Fatal' if isinstance(x,
```

```
In [52]: plot_column_data(df, 'injury_severity', 'bar')
```

```
injury_severity
Fatal          0.971618
Incident       0.022294
Minor          0.002580
Serious        0.001945
NaN            0.001373
Unavailable    0.000191
Name: proportion, dtype: float64
```


Graph of injury_severity



'total_fatal_injuries', 'total_serious_injuries', 'total_minor_injuries', 'total_uninjured' looking at their frequencies


```
In [53]: columns_of_injuries = ['total_fatal_injuries', 'total_serious_injuries', 'total_minor_injuries', 'total_uninjured']

for columns in columns_of_injuries:
    # First, I am going to call categorize_data function to categorize the values in
    df[columns] = df[columns].map(categorize_data)

    # Second, I will represent the results of all the columns in bar graphs and their
    plot_column_data(df, columns, 'bar')
```


```
total_fatal_injuries
Zero          0.682220
One or More   0.182684
Unknown       0.135097
Name: proportion, dtype: float64
```

Graph of total_fatal_injuries




```
total_serious_injuries
```


```
Zero          0.705009
One or More   0.150781
Unknown       0.144210
Name: proportion, dtype: float64
```



```
total_minor_injuries
Zero          0.685639
One or More   0.178349
Unknown       0.136012
Name: proportion, dtype: float64
```



```
total_uninjured
One or More    0.615707
Zero          0.320793
Unknown        0.063500
Name: proportion, dtype: float64
```



The graphs above give a view of the injuries. In particular, in the value counts one can see that around 30% of the accidents in the dataset have had injuries

I will eliminate the rows where injury_severity has 'Fatal' but don't have a number in the

corresponding value of total_fatal_injuries

```
In [54]: df = df[~((df['injury_severity']=='Fatal') & (df['total_fatal_injuries']=='Zero'))]
```

I will eliminate the rows where injury_severity has 'Non-Fatal' but have a number in the corresponding value of total_fatal_injuries


```
In [55]: df = df[~((df['injury_severity']=='Non-Fatal') & (df['total_fatal_injuries']!='Zero'))]
```

Given that it is of my interest to study the fatal injuries above all, I will categorize injury_severity to either fatal or non-fatal.

```
In [56]: df['injury_severity'] = df['injury_severity'].map(lambda x: 'Non-fatal' if x is not  
plot_column_data(df, 'injury_severity', 'bar')
```

```
injury_severity  
Fatal          0.916747  
Non-fatal      0.083253  
Name: proportion, dtype: float64
```

```
<>:1: SyntaxWarning: "is not" with 'str' literal. Did you mean "!="?  
<>:1: SyntaxWarning: "is not" with 'str' literal. Did you mean "!="?  
C:\Users\Usuario\AppData\Local\Temp\ipykernel_22212\588282316.py:1: SyntaxWarning: "i  
s not" with 'str' literal. Did you mean "!="?  
df['injury_severity'] = df['injury_severity'].map(lambda x: 'Non-fatal' if x is not  
'Fatal' else x)
```



I decide to select the registrations of total fatal injuries and of total serious injuries that are 'One or More' and study those from now onwards. We don't consider minor injuries because they might be negligible

```
In [57]: df = df[(df['total_fatal_injuries']=='One or More') | (df['total_serious_injuries']=='One or More')]
```

```
In [58]: df = df.reset_index(drop=True)
df
```

```
Out[58]:
```


	investigation_type	event_date	location	country	injury_severity	aircraft_damage	n
0	Accident	1983-01-02	GENOA CITY, WI	United States	Fatal	Destroyed	N Amer
1	Accident	1983-01-02	BEAUFORT, SC	United States	Fatal	Destroyed	F
2	Accident	1983-01-02	HANCOCK, MD	United States	Fatal	Substantial	Ce
3	Accident	1983-01-03	WILLARD, WA	United States	Fatal	Destroyed	Ce
4	Accident	1983-01-03	AVALON, CA	United States	Fatal	Destroyed	F
...
16048	Accident	2022-12-17	Cottonwood, CA	United States	Non-fatal	NaN	RC RAL
16049	Accident	2022-12-21	Auburn Hills, MI	United States	Non-fatal	NaN	CES
16050	Accident	2022-12-21	Reserve, LA	United States	Non-fatal	NaN	GRUMM AMERI AVN. C
16051	Accident	2022-12-26	Annapolis, MD	United States	Non-fatal	NaN	P
16052	Accident	2022-12-29	Athens, GA	United States	Non-fatal	NaN	P

16053 rows × 22 columns

Aircraft Damage

```
In [59]: plot_column_data(df, 'aircraft_damage', 'bar')
```

```
aircraft_damage
Destroyed      0.652900
Substantial    0.317635
NaN            0.019934
Minor          0.008846
Unknown        0.000685
Name: proportion, dtype: float64
```



```
In [60]: df['aircraft_damage'].fillna('Unknown', inplace=True)
```

As we can see the majority of the damages are substantial and destroyed. I will proceed with further investigations

Make

```
In [61]: df['make'].value_counts(normalize=True, dropna=False)
```

```
Out[61]: make
Cessna          0.211985
Piper           0.148695
Beech           0.073133
CESSNA          0.040304
PIPER           0.027970
...
Bensen Aircraft Corp. 0.000062
Boykin B J         0.000062
Motley Vans        0.000062
Madsen            0.000062
ROYSE RALPH L      0.000062
Name: proportion, Length: 2846, dtype: float64
```

```
In [62]: df['make'].isna().sum()
```

```
Out[62]: 3
```

```
In [63]: # Replace null values with 'Unknown'
df['make'].fillna('Unknown', inplace=True)
```

I will change the values of the make column to lower case letters and ensure they're all grouped correctly

```
In [64]: df['make'] = df['make'].str.capitalize()
```

I am going to joint Douglas with McDonnell douglas because they're the same aircraft company

```
In [65]: df['make'] = df['make'].map(lambda x: 'Douglas' if x in ['McDonnell douglas', 'Douglas'])
```


I will proceed to create a list of the top 10 makers with accidents

```
In [66]: top_10_make = df['make'].value_counts(normalize=True, dropna=False).head(10)*100
top_10_make
```

```
Out[66]: make
Cessna          25.228929
Piper           17.666480
Beech           8.851928
Bell            2.578957
Mooney          2.230113
Bellanca        1.345543
Robinson        1.002928
Boeing          0.822276
Hughes          0.797359
North american  0.735065
Name: proportion, dtype: float64
```

```
In [67]: plt.figure()
top_10_make.plot(kind='bar')
plt.xlabel('Top 10 makers')
plt.ylabel('Percentage of Accidents')
plt.xticks(rotation=90)
plt.title('Top 10 Markers per Percentage of Accidents')
```

```
Out[67]: Text(0.5, 1.0, 'Top 10 Markers per Percentage of Accidents')
```



The above markers are the ones with the highest number of accidents. It's noticeable that Cessna, Piper and Beech are the highest of all

Model

```
In [68]: df['model'].value_counts(normalize=True, dropna=False)
```

```
Out[68]: model
152          0.014764
172N         0.011774
PA-28-140    0.011026
A36          0.009095
172          0.008908
...
LJ-60        0.000062
172 F        0.000062
DN-1         0.000062
L-39CT       0.000062
EC 130 T2    0.000062
Name: proportion, Length: 4448, dtype: float64
```

```
In [69]: df['model'].isna().sum()
```

```
Out[69]: 7
```

I don't believe to be able to extract much information from the model column

Amateur Built

```
In [70]: df['amateur_built'].value_counts(normalize=True, dropna=False)
```

```
Out[70]: amateur_built
No      0.846633
Yes     0.152869
NaN     0.000498
Name: proportion, dtype: float64
```

As can be seen most of the accident cases were commercial trips

Number of engines

```
In [71]: df['number_of_engines'].value_counts(normalize=True, dropna=False)
```


```
Out[71]: number_of_engines
1.0      0.798854
```



```
2.0    0.160780
NaN     0.022488
0.0     0.013269
4.0     0.002990
3.0     0.001620
..      ..      ..
```

```
In [72]: # I will proceed to replace the null values with the mode
df['number_of_engines'].fillna(df['number_of_engines'].mode()[0], inplace=True)
```

```
In [73]: plot_bar_graph_for_columns('number_of_engines')
```




As is clearly visible, the majority of the accidents (in an 80% of the cases) happened with aircrafts that only had one engine

Engine type

```
In [74]: plot_column_data(df, 'engine_type', 'bar')
```

```
engine_type
Reciprocating    0.814365
NaN              0.056687
Turbo Prop       0.048278
Turbo Shaft      0.046596
Turbo Fan        0.015511
Unknown          0.009282
Turbo Jet        0.009095
Electric         0.000125
Hybrid Rocket    0.000062
Name: proportion, dtype: float64
```




```
In [75]: # Replace unknown values with 'Unknown' and replace na with 'Unknown'
```

```
df['engine_type'] = df['engine_type'].replace('UNK', 'Unknown')  
df['engine_type'].fillna('Unknown', inplace=True)
```

```
In [76]: plot_column_data(df, 'engine_type', 'bar')
```

```
engine_type  
Reciprocating    0.814365  
Unknown          0.065969  
Turbo Prop       0.048278  
Turbo Shaft      0.046596  
Turbo Fan        0.015511  
Turbo Jet        0.009095  
Electric         0.000125  
Hybrid Rocket    0.000062  
Name: proportion, dtype: float64
```



An overwhelming majority of the accidents (ie in 81% of the cases) the engine type of the aircraft was reciprocating

Purpose of Flight

```
In [77]: df['purpose_of_flight'].value_counts(normalize=True, dropna=False)
```

```
Out[77]: purpose_of_flight
Personal                0.649100
Instructional           0.066343
Unknown                0.063041
Business               0.058556
Aerial Application     0.031770
NaN                    0.029029
Positioning            0.025042
Other Work Use         0.017068
Aerial Observation     0.011462
Public Aircraft        0.010901
Ferry                  0.007787
Executive/corporate    0.007413
Flight Test            0.006292
Skydiving              0.003800
Air Race/show          0.002741
External Load          0.001931
Air Race show          0.001557
Banner Tow             0.001308
Public Aircraft - Federal 0.001308
Glider Tow             0.000997
Public Aircraft - State 0.000872
Public Aircraft - Local 0.000685
Firefighting           0.000623
ASHO                   0.000311
Air Drop               0.000062
Name: proportion, dtype: float64
```


```
In [78]: # Let's fill null values with unknown  
  
df['purpose_of_flight'].fillna('Unknown', inplace=True)
```

I am going to look at the top 10 of the instances

```
In [79]: top_10_purpose_of_flight = df['purpose_of_flight'].value_counts(normalize=True, dropna=False).sort_values(ascending=False).head(10)
```

```
Out[79]: purpose_of_flight  
Personal          64.909986  
Unknown           9.207002  
Instructional      6.634274  
Business          5.855603  
Aerial Application 3.176976  
Positioning        2.504205  
Other Work Use     1.706846  
Aerial Observation 1.146203  
Public Aircraft    1.090139  
Ferry              0.778671  
Name: proportion, dtype: float64
```

```
In [80]: plt.figure()  
top_10_purpose_of_flight.plot(kind='bar')  
plt.xlabel('Top 10 purpose's of flight')  
plt.ylabel('Percentage of Accidents')  
plt.xticks(rotation=90)  
plt.title('Top 10 Purpose's of flight per Percentage of Accidents');
```



The majority of the accidents happened under personal reasons apparently. This doesn't give much insight to our study

Weather condition


```
In [81]: df['weather_condition'].value_counts(normalize=True, dropna=False)
```

```
Out[81]: weather_condition
VMC      0.779044
IMC      0.192550
UNK      0.017006
NaN      0.008534
Unk      0.002866
Name: proportion, dtype: float64
```

```
In [82]: # Let's replace Unk to UNK and all the null values let's call them: UNK (this means

df['weather_condition'] = df['weather_condition'].replace('Unk', 'UNK')
df['weather_condition'].fillna('UNK', inplace=True)
```

```
In [83]: plot_bar_graph_for_columns('weather_condition')
```



The dataset contains in its majority VMC weather conditions (ie more than 91% of the data) which says that the flight conditions are good enough for pilots to fly using only visual cues. There is a remaining 7% of flights that were IMC and that are weather conditions that are so poor that pilots cannot safely fly using only visual cues.

Report Status

```
In [84]: df['report_status'].value_counts(normalize=True, dropna=False)
```

```
Out[84]: report_status
Probable Cause
0.764219
NaN
0.051019
Factual
0.000934
An in-flight loss of control for undetermined reasons.
0.000249
A loss of control for undetermined reasons.
0.000249

...
The pilots inadvertent pulling of the mixture control lever on takeoff, which shut do
wn the engine.
0.000062
The pilot's loss of airplane control during cruise flight.
0.000062
The pilots intentional low-altitude maneuvering and failure to maintain clearance fro
m terrain due to distraction.\r
```

0.000062

The pilot did not maintain adequate airspeed while maneuvering at low altitude, which resulted in an aerodynamic stall.

0.000062

The pilots failure to secure the magneto switch before attempting to hand rotate the engine which resulted in an inadvertent engine start, a runaway airplane, and subsequent impact with parked airplanes. Contributing to the accident was the failure to properly secure the airplane with chocks.

Name: proportion Length: 2916 dtype: float64

```
In [85]: # df['report_status'].unique()
```

```
In [86]: (df['report_status'].isnull().sum()/len(df['report_status']))*100
```

```
Out[86]: 5.101850121472622
```

I'm going to create a new category that groups pilot's faults

```
In [87]: df['report_status'] = df['report_status'].map(lambda x: 'pilot failure' if isinstance(x, str) else x)
```

```
In [88]: df['report_status'].unique()
```

```
Out[88]: array(['Probable Cause', 'Factual', 'Preliminary', 'Foreign',
                'pilot failure',
                'An in-flight loss of control and an uncontrolled descent into terrain for undetermined reasons.',
                'The flight instructor's failure to maintain control of the airplane, which resulted in an inadvertent stall while maneuvering.',
                'The loss of pitch control during cruise flight resulting from the separation of the stabilator trim actuator due to inadequate maintenance.',
                'The improper installation of the fuel pump, leading to a fatigue failure of the pump's lever arm and subsequent loss of engine power. Contributing to the accident was the lack of suitable terrain for a forced landing.',
                'Airplane wing-structure damage sustained during impact with one or more large birds (American white pelicans), which resulted in a loss of control of the airplane.',
                'The flight instructor's failure to maintain aircraft control while maneuvering during a simulated engine failure. Contributing to the accident was the flight instructor's lack of total experience as a multiengine flight instructor.',
                'The in-flight failure of the left wing for undetermined reasons.',
                'An in-flight overtorque of the engine-to-transmission driveshaft resulting in disconnection of the main transmission from the engine. The overtorque likely occurred due to an in-flight main rotor blade contact with snow-covered terrain, precluding significant main rotor blade damage and ground scarring. Contributing to the severity of the surviving occupant's injuries was the helicopter operator's failure to properly monitor their satellite flight-following system and to immediately institute a search once the system reported that the helicopter was overdue.',
                'A loss of engine power during initial climb for undetermined reasons.',
                'The certified flight instructor's failure to maintain airspeed during a steep turn.',
                'Loss of control for undetermined reasons.',
                'A fuel system configuration that was not in accordance with the engine manufacturer's published guidance, which resulted in a complete loss of engine power due to fuel starvation.',
                'A loss of control for undetermined reasons.',
                'Controlled flight into water for undetermined reasons.',
                'The loss of aircraft control due to an undetermined rudder malfunction.',
                'The partial loss of engine power for undetermined reasons.',
                'The loss of control during cruise flight in instrument conditions due to spatial disorientation.',
                'The flight instructor's failure to maintain airspeed which resulted in an inadvertent stall while maneuvering at low altitude, which resulted in an aerodynamic stall.'],
              dtype=object)
```

divertent stall.",
'An in-flight loss of control for undetermined reasons.',
'Loss of engine power during approach for landing due to a fatigue fracture of a power turbine blade.',
'An in-flight collision with terrain for undetermined reasons.',
'The in-flight collision with mountainous terrain for undetermined reasons.\r\n\r\n*This report was modified on December 10, 2009.',
'The improper installation of spark plugs during the annual inspection which resulted in a loss of engine power shortly after takeoff. Contributing to the accident was the lack of suitable terrain during the forced landing.',
'A total loss of engine power due to a loss of engine oil as a result of the installation of the wrong oil adapter O-ring seal.',
"The parachutist's failure to follow procedures/directives by not waiting to jump until the green jump light was illuminated, resulting in his collision with the airplane's tail. Contributing to the accident was the parachutist's impairment by the use of marijuana prior to performing a parachute jump.",
'An inadvertent stall during the initial climb.',
"The flight instructor's failure to initiate a go-around during a high approach, and his inadequate remedial action during an attempted touch-and-go.",
'Undetermined.',
'A partial loss of engine power for undetermined reasons which led to a forced landing in unsuitable terrain.',
'A loss of engine power for undetermined reasons.',
'A loss of control in flight due to undetermined reasons.',
"A partial loss of engine power during initial climb due to the detachment of the engine supercharger drive belt. The detachment resulted from the owner/builder's inadequate installation of the supercharger system and belt-tensioning adjustment.",
'A loss of engine power due to fuel exhaustion.',
'Loss of control inflight for undetermined reason.',
"The in-flight separation of a main rotor blade due to a fatigue failure of the blade spar, rendering the helicopter uncontrollable, and the manufacturer's production of main rotor blades with latent manufacturing defects, which precipitated the fatigue failure of the blade spar.",
'The improper (reverse) rigging of the elevator trim cables by company maintenance personnel, and their subsequent failure to discover the misrigging during required post-maintenance checks. Contributing to the accident was the captain's inadequate post-maintenance preflight check and the flight crew's improper response to the trim problem.',
"The failure of the flight crew to maintain airspeed above in-flight minimum control speed (Vmca) after losing power in the left jet engine during initial climb after takeoff. Contributing to the accident was the crew's inadequate cockpit resource management procedures, the failure of the captain to assume command of the airplane during the emergency, the flight crew's failure to carry out the jet engine fire emergency procedure, and the failure of the crew to jettison the retardant load.",
"The movement of the airplane's modified horizontal stabilizer trim system during an intentional high speed aerobatic maneuver that resulted in exceedance of the design stress limits of the airplane and an in-flight structural failure. Contributing to the accident was that the builder's deviation from the airplane designer's original trim system.",
'The operator's inadequate maintenance of the airplane's tires, which resulted in multiple tire failures during takeoff roll due to severe underinflation, and the captain's execution of a rejected takeoff (RTO) after V1, which was inconsistent with her training and standard operating procedures. \r\n\r\nContributing to the accident were (1) deficiencies in Learjet's design of and the Federal Aviation Administration's (FAA) certification of the Learjet Model 60's thrust reverser system, which permitted the failure of critical systems in the wheel well area to result in an uncommanded forward thrust that increased the severity of the accident; (2) the inadequacy of Learjet's safety analysis and the FAA's review of it, which failed to detect and correct the thrust reverser and wheel well design deficiencies after a 2001 uncommanded forward thrust accident; (3) inadequate industry training standards for flight crews in tire failure scenarios; and (4) the flight crew's poor crew resource management (CRM).',

'A loss of aircraft control for undetermined reasons.',
'A loss of aircraft control due to spatial disorientation.',
"The crews' failure to maintain adequate airspeed, which resulted in an aerodynamic stall close to the ground.",
"The paramedic's failure to monitor and maintain clearance from the rotating main rotor blades after exiting the helicopter.",
'A loss of engine power due to a fractured crankshaft.',
'The partial loss of engine power while maneuvering for undetermined reasons.',
"The flight's encounter with adverse tailwinds and downdrafts in mountainous terrain that exceeded the airplane's climb capability.",
'The loss of engine power while in climb to cruise flight for undetermined reasons.',
'(1) the sudden loss of power to both engines that resulted from impact with a bird (red-tailed hawk), which fractured the windshield and interfered with engine fuel controls, and (2) the subsequent disorientation of the flight crewmembers, which left them unable to recover from the loss of power. Contributing to the accident were (1) the lack of Federal Aviation Administration regulations and guidance, at the time the helicopter was certificated, requiring helicopter windshields to be resistant to bird strikes; (2) the lack of protections that would prevent the T handles from inadvertently dislodging out of their detents; and (3) the lack of a master warning light and audible system to alert the flight crew of a low-rotor-speed condition.',
'A loss of control in flight for undetermined reasons.',
'A loss of aircraft control during the landing approach for undetermined reasons.',
'An in-flight break-up while maneuvering as a result of the main rotor blades diverging from the normal plane of rotation and severing the tailboom. The underlying reason for the main rotor divergence could not be determined.',
"The captain's inappropriate response to the activation of the stick shaker, which led to an aerodynamic stall from which the airplane did not recover. Contributing to the accident were (1) the flight crew's failure to monitor airspeed in relation to the rising position of the low-speed cue, (2) the flight crew failure to adhere to sterile cockpit procedures, (3) the captain's failure to effectively manage the flight, and (4) Colgan Air's inadequate procedures for airspeed selection and management during approaches in icing conditions.",
"The flight instructor's failure to verify that the helicopter's skid was clear of an obstruction while demonstrating a one-skid and toe-in landing maneuver. Contributing to the accident was the flight instructor's decision to practice this maneuver at an unauthorized landing site.",
'The passenger's inadvertent activation of the engine throttle.',
'The in-flight failure of both wings due to aileron flutter. The aileron flutter was the result of inadequate wing stiffness and the lack of aileron counterbalance.',
'A loss of engine power due to contamination and clogging of the fuel system by a post-assembly fuel tank sealant.',
'Inflight collision with terrain for undetermined reasons.',
'An in-flight loss of aircraft control for an undetermined reason.',
'An in-flight fire for undetermined reasons.',
'The in-flight separation of the elevator control torque tube rod end bearing from the elevator torque tube as a result of incorrectly tightened rod end bearing lock nuts.',
"The flight crew's failure to maintain terrain clearance during low altitude flight in low ceiling and visibility conditions. Contributing to the accident was the flight crew's failure to adequately monitor their location with respect to the rising terrain environment ahead, and, their lack of crew resource management communication as a crew.",
'The in-flight separation of the left wing due to failure of one of the inboard attachments to the fuselage.',
'A total loss of engine power due to disengagement of the idler gear support pin as a result of improper maintenance.',
'The separation of the main rotor head during cruise flight as a result of cyclic fatigue of the main rotor head spindle. The fatigue crack was due to an inadequate

e manufacturing process.',
'The loss of aircraft control for undetermined reasons.',
"A total loss of engine power due to fuel starvation as a result of the flight crew's improper fuel management.",
"A loss of engine power due to oil exhaustion from the fracture of the nipple for the engine oil cooler return line. Contributing to the accident was the mechanic's signoff and release of the airplane without performing the required engine run-up following an annual inspection.",
"The flight instructor's failure to ensure that the airplane was properly configured for a short field takeoff, and his decision to not abort the takeoff.",
'A loss of airplane control for undetermined reasons.',
'The cause of this accident is unknown; the airplane is missing.',
'A loss of aircraft control for an undetermined reason.',
'The glider departed controlled flight for undetermined reasons.',
'The in-flight collision with terrain for undetermined reasons.',
'Flight into terrain for undetermined reasons.',
'The airplane's impact with water for undetermined reasons.',
"The rappeller's failure to properly latch the rappelling harness to the rappelling assembly before exiting the helicopter.",
'A total loss of engine power during cruise flight due to the fatigue failure of the number 4 cylinder connecting rod.',
'The reason for this accident was not determined.',
"The inadvertent deployment of the instructor's reserve parachute.",
"A loss of torque to the gearbox engine-side coupling flange bolts, which resulted in separation of the gearbox and propeller from the engine and the subsequent severing of the airplane's tail structure.",
'The improper assembly of both carburetors, resulting in an excessively rich fuel to air ratio and subsequent partial loss of engine power.',
'A loss of airplane control during approach for undetermined reasons.',
"Structural failure of the right wing during the landing approach due to the separation of the wing's fabric covering.",
'The flight crew's failure to maintain adequate main rotor speed while maneuvering, which resulted in a main rotor blade stall and an uncontrolled descent into terrain.',
'An aerodynamic stall shortly after takeoff for undetermined reasons.',
'A total loss of engine power during a night approach for undetermined reasons.',
'The loss of engine power for an undetermined reason.',
'The in-flight separation of both wings due to aileron flutter. The aileron flutter was the result of inadequate wing stiffness and strength and the lack of aileron counterbalances.',
"The flight's descent for undetermined reasons, resulting in the in-flight collision with terrain.",
'Failure of the exhaust band V-clamp during cruise flight, which resulted in an in-flight fire and a subsequent forced landing.',
'A total loss of engine power due to a delamination of the No. 3 connecting rod bearing. Contributing to the accident was the inadequate maintenance inspection of the engine oil system.',
'Airspeed was not maintained, which resulted in a loss of control and the airplane entering into a stall/spin to the ground. Contributing to the accident was a loss of engine power due to carburetor icing.',
"The loss of engine power due to the chaffing and grounding of the single magnet's ignition lead.",
'An in-flight loss of control for an undetermined reason, which resulted in an uncontrolled descent.',
'A loss of aircraft control while maneuvering for undetermined reasons.',
'The failure of both engines for undetermined reasons.',
'The failure of maintenance personnel to properly secure a fitting cap on the throttle and metering assembly inlet after conducting a fuel system pressure check, which resulted in a loss of engine power due to fuel starvation. Contributing to the accident was the decision by the Director of Maintenance to return the airplane to service without verifying with the assigned inspector that all annual inspection items had

ad been completed.',
 'A malfunction of the flight controls for undetermined reasons.',
 'Impact with the runway pavement for unknown reasons.',
 'The complete loss of engine power due to fuel starvation.',
 'Pilot incapacitation due to the combined effect of multiple unreported medical conditions.',
 "The airplane's impact with terrain for undetermined reasons.",
 "The FAA inspector's rapid reduction of power which resulted in a loss of engine power and his decision to initiate a turn during the autorotation without sufficient altitude to clear obstacles. Contributing to the accident was the FAA's lack of comprehensive currency requirements in the make and model helicopter and the inspector's specific limited recent flight experience related to this make and model helicopter.",
 'The loss of control for undetermined reasons.',
 'The opening of the cockpit canopy in-flight due to improper latching, which resulted in a loss of control and impact with terrain.',
 'The fracture of a swashplate drive pin as a result of hydrogen embrittlement due to an unknown source, which resulted in an in-flight breakup of the main rotor system during cruise flight.',
 'The flight instructor's initiation of a simulated single engine scenario at or below the airplane's minimum single engine control speed, resulting in a loss of airplane control. Contributing to the accident was the flight instructor's failure to set full engine power during the takeoff roll and the flight instructor's lack of recent experience in the airplane make and model.',
 'The collision of two counter-rotating main rotor blades for undetermined reasons, which resulted in a loss of control.',
 "The total loss of engine power resulting from the fatigue failure of the engine's number 2 cylinder exhaust valve. The fatigue failure was due to valve guide wear that led to excessive clearance between the valve and valve guide. Contributing to the accident was the contract operator's lack of compliance with its own maintenance procedures, which, if followed, would have prevented the accident.",
 "The glider's encounter with insufficient atmospheric lift to maintain soaring flight.",
 'The total loss of engine power due to fuel starvation as a result of accumulated debris in the fuel system from an undetermined source. Also causal was the inadequate annual maintenance inspection that did not include inspection of the firewall fuel strainer and the fuel inlet screen.',
 'The total loss of engine power due to a high-cycle fatigue fracture of a first-stage compressor blade. The reason for the fracture could not be determined during postaccident examination.',
 'A partial loss of engine power due to the owner's inadequate fuel system maintenance, which resulted in a collision with trees and subsequent impact with the ground.',
 "The manufacturer's inadequate quality control and improper manufacture of the fuel servo diaphragm assembly, which resulted in fatigue cracking of the hub stud and subsequent loss of engine power due to fuel starvation.",
 "The flight instructor's decision to exit the airplane on the taxiway with the engine still operating, and his failure to avoid the rotating propeller.",
 "In-flight impact of a passenger's metal clipboard with the helicopter's tail rotor, which resulted in destruction of the tail rotor and subsequent loss of control of the helicopter. The original location of the clipboard and how it became free could not be determined.",
 'A loss of helicopter control for undetermined reasons.',
 'A partial loss of engine power during approach for reasons that could not be determined because postaccident examination did not reveal any anomalies that would have precluded normal operation.',
 'Inadequate maintenance performed on the airplane, which resulted in a loss of engine power due to fuel starvation. Contributing to the accident was the corrosion within the carburetor.',
 'A loss of engine power during a low approach for undetermined reasons.',
 'The separation of the fuselage-mounted wing strut attachment fitting for an undetermined reason, which resulted in the separation of the left wing of the airplane.

e.',

'A total loss of engine power due to a cracked carburetor float and resulting carburetor malfunction.'

'A total loss of engine power due to the fatigue failure of the crankshaft, which resulted from improper tightening of the cylinder hold-down nuts.'

'Controlled flight into terrain, while on an instrument approach in instrument meteorological conditions, for undetermined reasons.'

'A loss of engine power due to the magneto failure for undetermined reasons.'

'The in-flight collision with a tree while returning to land for undetermined reasons.'

"The engine's loss of power during takeoff for reasons that could not be determined because no engine anomalies were discovered during the postaccident examination."

'The magneto clamps were not securely fastened to the mount, which led to a partial loss of engine power and a subsequent forced landing on unsuitable terrain.'

'The flight instructor did not maintain aircraft control while maneuvering at low altitude. Contributing to the accident was the inadvertent application of the choke, which resulted in a momentary interruption of engine power.'

'A total loss of engine power for undetermined reasons.'

'An inadvertent encounter with localized instrument meteorological conditions, which resulted in spatial disorientation and a loss of control.'

'The National Transportation Safety Board determines the probable cause(s) of this accident as follows: \r\n\r\nan aerodynamic stall and subsequent uncommanded roll during a one engine-inoperative takeoff flight test, which were the result of (1) Gulfstream's failure to properly develop and validate takeoff speeds for the flight tests and recognize and correct the takeoff safety speed (V2) error during previous G650 flight tests, (2) the G650 flight test team's persistent and increasingly aggressive attempts to achieve V2 speeds that were erroneously low, and (3) Gulfstream's inadequate investigation of previous G650 uncommanded roll events, which indicated that the company's estimated stall angle of attack while the airplane was in ground effect was too high. Contributing to the accident was Gulfstream's failure to effectively manage the G650 flight test program by pursuing an aggressive program schedule without ensuring that the roles and responsibilities of team members had been appropriately defined and implemented, engineering processes had received sufficient technical planning and oversight, potential hazards had been fully identified, and appropriate risk controls had been implemented and were functioning as intended.'

'Pilot incapacitation shortly after takeoff for unknown reasons.'

'The loss of aircraft control and subsequent impact with terrain for undetermined reasons.'

'An in-flight fire that mostly likely occurred in the right front cockpit area behind the instrument panel and below the glare shield; the origin of the fire could not be determined because of the extensive fire damage.'

'A total loss of engine power during approach due to inadequate torque on the No. 3 cylinder hold-down nuts.'

'Collision with the ground while maneuvering at low altitude for reasons that could not be determined because postaccident examination did not reveal any anomalies that would have precluded normal operation. \r'

"The total loss of engine power during the initial climb due to a cold seizure as a result of a broken fan V-belt. Contributing to the accident was the passenger's interference with the flight controls during the forced landing."

'The loss of engine power for reasons that could not be determined because postaccident examination of the airplane's engine and ignition system did not reveal any anomalies that would have precluded normal operation, and extensive postaccident fire damage precluded evaluation of the airplane's fuel system components.'

'The total loss of engine power for reasons that could not be determined because postimpact fire damage precluded a thorough examination of the engine.'

'To be determined by the government of Burma.'

'An in-flight loss of control for reasons that could not be determined during postaccident examinations.'

'A loss of airplane control for undetermined reasons as the autopsy was unable to reveal any definitive conditions that would have led to the loss of control.'

'The flight crew's failure to maintain airplane control following a partial

loss of engine thrust during cruise flight. Contributing to the accident was the failed weld as a result of incomplete welding on the left propeller shaft, which led to the partial loss of engine thrust.',

'A collision into water during initial climb after takeoff for undetermined reasons.',

"The passenger's accidental fall while turning the propeller by hand to start the engine.",

"The flight instructor's improper decision to attempt a visual descent into instrument meteorological conditions while approaching the destination airport, which resulted in an in-flight collision with trees and terrain.",

'The wing walker's decision to release his grip of the airplane during an attempted aerial transfer from airplane to helicopter before both aircraft achieved the proper relative positioning for the transfer.',

'The failure of the propeller power speed reduction unit, which resulted in a loss of engine power at low altitude.',

'The in-flight separation of the main rotor mast following a mast bumping event. The reason for the mast bumping event could not be determined due to postaccident damage.',

'Maintenance personnel's improper installation of the No. 2 cylinder's connecting rod, which resulted in the disconnection of the rod and a subsequent loss of engine power.',

'The in-flight failure of the aircraft's Y-tail attachment structure during maneuvering flight due to overload. Contributing to the accident was, the kit manufacturer's use of 14 CFR Part 23, Appendix A design guidelines intended for a conventional tail airplane without a V- (or Y-) tail.',

"The flight instructor's failure to maintain airspeed in changing wind conditions during a steep climb after takeoff, which resulted in an aerodynamic stall. Contributing to the accident was the flight instructor's ostentatious display close to the ground.",

'The loss of power to the rear engine due to fuel starvation during takeoff, which resulted from the fuel selector valve being inadvertently moved to the 'OFF' position, and resulted in the airplane's inability to climb.',

"The helicopter's sudden yaw and subsequent impact with the water for reasons that could not be determined during postaccident examination of the helicopter and its systems.",

'The failure of the No. 2 rod end cap bolt, which resulted in a total loss of engine power.',

'Sundance Helicopters' inadequate maintenance of the helicopter, including (1) the improper reuse of a degraded self-locking nut, (2) the improper or lack of installation of a split pin, and (3) inadequate postmaintenance inspections, which resulted in the in-flight separation of the servo control input rod from the fore/aft servo and rendered the helicopter uncontrollable. Contributing to the improper or lack of installation of the split pin was the mechanic's fatigue and the lack of clearly delineated maintenance task steps to follow. Contributing to the inadequate postmaintenance inspection was the inspector's fatigue and the lack of clearly delineated inspection steps to follow.',

'The total loss of engine power for reasons that could not be determined because postaccident examination of the airframe and engine did not reveal evidence of preaccident mechanical malfunctions or failures that would have precluded normal operation.',

'An electrical or engine electronic problem, which resulted in a loss of engine power, followed by a low-altitude stall.',

'The flight crew's loss of airplane control.',

'An in-flight loss of control in instrument meteorological conditions.',

'A loss of engine power due to fuel starvation for reasons that could not be determined because the postaccident examination of the airframe and engine did not reveal any anomalies that would have precluded normal operation.',

'A loss of airplane control for reasons that could not be determined because postaccident examination of the airplane and engine did not reveal any anomalies that would have precluded normal operation.',

"the flight crew's failure to maintain adequate airspeed after shutting down the right engine due to an in-flight fire in one of the right augmentors. The failure

to maintain airspeed resulted in either an aerodynamic stall or a loss of directional control.",

'An in-flight emergency followed by a collision with terrain for reasons that could not be determined because postaccident examination of the airframe, engine, and forward and aft canopies revealed no evidence of mechanical malfunctions or failures that would have precluded normal operation.',

nan,

"The flight crew's misjudgment of terrain clearance while maneuvering for an aerial application run, which resulted in controlled flight into terrain. Contributing to the accident was the flight crew's failure to follow the lead airplane's track and to effectively compensate for the tailwind condition while maneuvering.",

'An inadvertent aerodynamic stall while maneuvering at a low altitude.',

'Undetermined because the airplane was not found.',

'The in-flight failure of the left wing spar, which resulted in the in-flight separation of the left wing.',

'A fatigue failure of the No. 3 piston skirt, which resulted in a total loss of engine power and the subsequent ditching in the ocean.',

'The in-flight fire for a reason that could not be determined due to extensive damage from the fire.',

'Pilot incapacitation of unknown origin, which resulted in the airplane's loss of control and an inadvertent aerodynamic stall/spin. \r',

'The cause of the accident is undetermined as the airplane has not been located and remains missing.',

'A total loss of engine power for reasons that could not be determined during the postaccident investigation and testing.',

'The flight instructor's delayed remedial action and inadequate supervision during practice traffic pattern work. Contributing to the accident was the flight instructor's use of sedating medication on the day of the accident and airplane's high angle of attack at a low altitude during the traffic pattern turn, which prevented recovery during an aerodynamic stall.',

'The loss of airplane control for reasons that could not be determined because postaccident examination did not reveal any anomalies that would have precluded operation.',

'Disconnection of the upper rod end from the fore/aft servo due to severely worn threads, which resulted in a loss of control and separation of a main rotor blade during cruise flight. Contributing to the accident were incorrect maintenance procedures and inadequate maintenance inspections performed by the operator, and insufficient inspection criteria provided by the helicopter manufacturer.',

"The loss of engine power during takeoff due to fuel contamination. Contributing to the accident was maintenance personnel's failure to adequately correct the water contamination effects. Contributing to the severity of the occupants' injuries was the lack of shoulder restraints.",

'The total loss of engine power as a result of a fractured compressor turbine blade due to high-cycle fatigue.',

'The total loss of engine power, the specific cause of which could not be identified during the postaccident examination, and the airplane's subsequent impact with trees.',

'Mast bumping for reasons that could not be determined because one main rotor blade was not recovered.',

'The descent and overstress of the airplane during the descent, which resulted in the in-flight breakup of the airplane.',

'An in-flight loss of control and impact with terrain for reasons that could not be determined because postaccident examination did not reveal any anomalies that would have precluded normal operation.',

"The airplane's impact with terrain for reasons that could not be determined during examination of the available evidence because of extensive impact damage and postimpact fire.",

'An in-flight encounter with icing conditions during descent, which resulted in the airplane exceeding its critical angle-of-attack and experiencing an aerodynamic stall followed by an in-flight breakup.\r',

"The airplane's impact with a turkey vulture in cruise flight, which resulted in the structural failure of the right wing and the subsequent loss of control.",

'Fracture of the red tail rotor blade spar, which resulted in the separation and departure of the red tail rotor blade from the helicopter and subsequent compromised tail gearbox. The red tail rotor blade was not recovered, thus the cause of the initial fracture could not be determined.\r\n\r',

'The manufacture and installation of a nonstandard part by unknown maintenance personnel to compensate for a bent, misaligned crankshaft propeller flange, which resulted in the improper clearance of the bearings on the crankshaft journal, a loss of oil pressure, overheating of the bearings, and the failure of a connecting rod during cruise flight.\r',

'A total loss of engine power due to oil starvation for reasons that could not be determined due to extensive postcrash fire and heat damage to the engine component s.\r\n\r',

"The flight instructor's inadequate preflight planning and his decision to take off with the airplane at a high gross weight in high temperature conditions that degraded the engine's available power and his subsequent failure to maintain airspeed while attempting to return to the departure airport, which resulted in the airplane exceeding its critical angle-of-attack and experiencing an aerodynamic stall.",

'The loss of helicopter control for reasons that could not be determined because an examination of the helicopter and its systems revealed no malfunctions or failures that would have precluded normal operation.\r\n\r',

'The premature release of the towline from the glider and the glider's subsequent right banking turn at low altitude for reasons that could not be determined because postaccident airframe examination did not reveal any evidence of a mechanical malfunction or failure that would have precluded normal operation. \r',

"The operator's failure to determine the actual cargo weight, leading to the loading and operation of the airplane outside of the weight and center of gravity limits contained in the airplane flight manual, which resulted in an aerodynamic stall. Contributing to the accident was the Federal Aviation Administration's failure to require weight and balance documentation for each flight in 14 Code of Federal Regulations Part 135 single-engine operations.",

"The airplane's unexpected encounter with a dust devil, which resulted in the loss of airplane control.",

'The premature hoisting operation and the inadvertent disengagement of the hoist hook on the rescuer's harness in dark night conditions. Contributing to the accident was a lack of direct audio communication between the rescuer and the hoist operator.\r',

'Slippage in the engine clutch and gear reduction module and a resultant uncommanded movement of the propeller blades into reverse thrust.',

'The loss of engine power for reasons that could not be determined during postaccident examinations due to postcrash fire damage.\r',

"the flight crew's continuation of an unstabilized approach and their failure to monitor the aircraft's altitude during the approach, which led to an inadvertent descent below the minimum approach altitude and subsequently into terrain. Contributing to the accident were (1) the flight crew's failure to properly configure and verify the flight management computer for the profile approach; (2) the captain's failure to communicate his intentions to the first officer once it became apparent the vertical profile was not captured; (3) the flight crew's expectation that they would break out of the clouds at 1,000 feet above ground level due to incomplete weather information; (4) the first officer's failure to make the required minimums callouts; (5) the captain's performance deficiencies likely due to factors including, but not limited to, fatigue, distraction, or confusion, consistent with performance deficiencies exhibited during training; and (6) the first officer's fatigue due to acute sleep loss resulting from her ineffective off-duty time management and circadian factors.",

'The improper routing of the seatbelt, which resulted in the inadvertent deployment of the reserve parachute, and the open jump door, which allowed the passenger to be pulled from the airplane.',

'An impairing medical event of undetermined origin that led to a loss of control during takeoff.',

'The in-flight failure of the left elevator control torque tube. Contributing to the accident was the improper assembly of the elevator control torque tubes. \r',

'The fatigue failure of the upper two tailboom attachment points, which resulted in the tailboom separating from the fuselage during logging operations. Contributing

ng to the accident was poor maintenance throughout the helicopter's operational life. \r',

'Undetermined because the wreckage was not recovered.',

'A total loss of engine power due to the liberation of a second stage turbine blade near the blade root due to a high-cycle fatigue crack and subsequent overload. Although extensive testing and materials analysis was performed, the reason for crack initiation could not be determined.\r\n\r',

'Controlled flight into terrain for reasons that could not be determined from the available evidence.\r',

'The parachutist's low altitude departure from the right wing before the planned altitude and his delayed opening of his parachute canopy, which resulted in impact with a tree and then the ground before the parachute fully opened.',

"The flight instructor's failure to maintain airspeed following a partial loss of engine power for reasons that could not be determined during postaccident examination, which resulted in an aerodynamic stall and subsequent loss of airplane control.",

"The flight crew's excessive elevator input during a rapid descent under night lighting conditions, which resulted in the overstress and breakup of the airplane. Contributing to the accident was an initial loss of airplane control for reasons that could not be determined because postaccident examination revealed no mechanical anomalies that would have precluded normal operation.",

'The loss of engine power due to the fracture of multiple blades on the compressor turbine wheel, which resulted in a ditching. The reason for the blade failures could not be determined due to secondary thermal damage to the blades.\r',

"The flight crew's failure to maintain airplane control during landing following an unstabilized approach. Contributing to the accident were the flight crew's decision to land with a tailwind above the airplane's operating limitations and their failure not to conduct a go-around when the approach became unstabilized.",

'The in-flight separation of a wing for reasons that could not be determined because the wreckage was not recovered from the ocean.\r',

'The loss of helicopter control due to a loss of hydraulic boost to the tail rotor pedal controls at takeoff, followed by a loss of hydraulic boost to the main rotor controls after takeoff. The reason for the loss of hydraulic boost to the main and tail rotor controls could not be determined because of fire damage to hydraulic system components and the lack of a flight recording device.',

"The check airman's delayed remedial action and initiation of a recovery procedure after a simulated pitch trim excursion, which resulted in a loss of airplane control.",

'The flight instructor's failure to arrest the airplane's descent and maintain clearance from mountainous terrain while maneuvering at a low altitude.\r',

"The flight crewmembers' failure to perform the flight control check before takeoff, their attempt to take off with the gust lock system engaged, and their delayed execution of a rejected takeoff after they became aware that the controls were locked. Contributing to the accident were the flight crew's habitual noncompliance with checklists, Gulfstream Aerospace Corporation's failure to ensure that the G-IV gust lock/throttle lever interlock system would prevent an attempted takeoff with the gust lock engaged, and the Federal Aviation Administration's failure to detect this inadequacy during the G-IV's certification.",

'The loss of engine power during takeoff initial climb for reasons that could not be determined during a postaccident examination of the airplane. \r',

"The flight crew's inability to maintain airplane control during initial climb following deployment of the right thrust reverser for reasons that could not be determined because postaccident examination of the airframe and engine thrust reverser system did not reveal any anomalies. Contributing to the accident was the excessive thrust from the right engine with the thrust reverser deployed for reasons that could not be determined during postaccident examinations and testing.",

'An in-flight fire of unknown origin for reasons that could not be determined because of impact damage and postimpact fire damage. \r\n\r',

"Maintenance personnel's application of sealant to the engine case halves during engine overhaul, contrary to manufacturer's instructions, which resulted in internal failure of the engine due to the loss of case bolt torque.",

'An in-flight loss of airplane control for reasons that could not be determine

d during postaccident examinations or based on the available evidence.\r',

'The airplane's vertical descent into water for reasons that could not be determined because postaccident airplane examinations revealed no mechanical anomalies. \r',

'A loss of engine power due to an inoperative magneto and possible carburetor ice, which resulted in a forced landing into unsuitable terrain. Contributing to the accident was an inadequate magneto overhaul by unknown personnel and the modification to the carburetor heat system. \r',

'An in-flight fire for reasons that could not be determined due to the extent of impact and fire damage.\r',

'The fatigue fracture of an engine connecting rod, which resulted in a catastrophic engine failure and a forced landing in unsuitable terrain.\r\n\r\n\r\n\r',

'The partial loss of engine power for reasons that could not be determined because thermal damage to the engine prevented a complete examination. \r',

'An inadvertent collision with a utility wire for reasons that could not be determined from recorded data and examination of the helicopter and accident site.',

'The inadequate torque of the propeller mounting bolts and inspection of the propeller, which resulted in the fatigue fracture of the bolts and a subsequent in-flight separation of the propeller assembly.',

'The failure of the right wing under normal race loads due to an improper repair of the right wing spar that reduced its structural strength following a previous landing accident.\r',

'A loss of engine power for reasons that could not be determined because postaccident examination of the airframe and engine did not reveal any anomalies that would have precluded normal operation.\r\n\r\n\r\n\r',

'An in-flight fire for reasons that could not be determined because the examination of the airplane did not reveal the source of the fire.\r\n\r',

'The failure of the flight control rod bearing due to an undetected preexisting corrosion-induced crack, which resulted in the main rotor blades going to full pitch and the rotor mast folding; this allowed the pusher propeller to strike and sever the tail. \r',

'A total loss of engine power during cruise flight for reasons that could not be determined due to the postaccident condition of the engine and its associated fuel and ignition systems.',

'The partial loss of engine power due to the undetected blockage of the inlet and outlet ports of the manifold valve by an organic compound of an unknown source.\r',

'An in-flight loss of control for reasons that could not be determined based on the available evidence.\r',

'The loss of engine power during cruise flight due to a fatigue fracture of the crankshaft, which resulted in a forced landing on unsuitable terrain.\r\n\r',

'The loss of airplane control for reasons that could not be determined by the postaccident examination, which was limited due to impact damage and postcrash fire.',

'A total loss of engine power for reasons that could not be determined, because the post accident examination did not reveal any mechanical malfunctions or anomalies that would have precluded normal operation.',

'The flight instructor's decision to conduct a night training flight in mountainous terrain without conducting or allowing the student to conduct appropriate preflight planning and his lack of situational awareness of the surrounding terrain altitude, which resulted in controlled flight into terrain.',

"The airplane's collision with water for reasons that could not be determined because the wreckage was not located.",

'A loss of engine power for reasons that could not be determined due to extensive damage sustained during the collision and postaccident water immersion. \r',

'A loss of airplane control for reasons that could not be determined based on available evidence.',

'A main rotor stall due to low rotor rpm, which resulted in an uncontrolled descent into terrain. Contributing to the accident was the flight instructor's delayed remedial action. \r',

'The flight instructor's failure to maintain airspeed during an approach with a simulated engine failure, which resulted in an exceedance of the wing's critical

cal angle-of-attack and a subsequent aerodynamic stall/spin.\r',

'An in-flight separation of the helicopter's horizontal stabilizer due to undetected fatigue cracking of the stabilizer spar, which resulted in a loss of control.\r',

'An in-flight loss of control for reasons that could not be determined based on available information.',

'An in-flight loss of control for reasons that could not be determined during postaccident investigation; the loss of control likely occurred during a simulated loss of power in the right engine during an instructional flight.',

"The flight instructor's decision to initiate flight into forecasted icing conditions in an airplane that was not certified or equipped for flight into icing conditions, which resulted in significant structural ice accumulation to the extent that the airplane was unable to maintain altitude.\r\n\r",

'A loss of airplane control for reasons that could not be determined because the airplane impacted water, and the majority of the wreckage was not recovered. \r',

"An in-flight failure of the helicopter's #2 main rotor spindle due to undetected fatigue cracking, which resulted in an in-flight breakup. Contributing to failure were the nonconforming thread root radius of the spindle and the manufacturer's failure to include a bending moment within the spindle threads when performing the fatigue analysis during initial design of the spindle.",

"A total loss of engine power after takeoff due to fuel starvation as a result of excessive wear of the fuel selector valve. Also causal was the owner/operator and maintenance personnel's inadequate maintenance, and inadequate postmaintenance inspection.",

"The left engine propeller's uncommanded travel to the feathered position during takeoff for reasons that could not be determined due to impact damage. Contributing to the accident was the flight crew's failure to establish a coordinated climb once the left engine was shut down and the left propeller was in the feathered position. \r\n\r",

'The inadequate maintenance and inspection of the fuel system, which resulted in partial blockage of a fuel filter, a partial loss of engine power, and subsequent ditching.\r\n\r',

'A partial loss of engine power for reasons that could not be determined based on the available evidence. \r',

'An in-flight loss of control for reasons that could not be determined based on the available evidence.',

'An inflight loss of control due to the likely detachment of the forward left servo control tube upper rod end attachment bolt.',

'A loss of engine power for reasons that could not be determined due to postaccident fire damage.\r\n\r',

'A rapid onset of smoke and/or fire inflight for reasons that could not be determined due to the postimpact fire and the condition of the wreckage.',

'The helicopter rescue specialist was not properly attached to the hoist system, which resulted in a fall during a night hoist operation.\r\n\r',

'A partial loss of engine power due to contamination in the fuel manifold, which resulted in a collision with terrain shortly after takeoff.',

'Undetermined because the airplane was not located.',

'An in-flight impact with terrain for reasons that could not be determined based on available evidence. \r\n\r',

'A loss of control for reasons that could not be determined, because examination of the airframe and engine revealed no anomalies that would have precluded normal operation.',

'A loss of glider control for reasons that could not be determined based on the available evidence and the glider's severe fragmentation.',

'The partial loss of engine power during takeoff due to debris within the fuel servo, which restricted fuel flow throughout the engine fuel system and resulted in a partial loss of engine power.',

"The powered-lift aircraft's departure from controlled flight for reasons that could not be determined from the available information.",

'The loss of translation/rotational power between the engine and the transmission due to the severe wear of the forward spline portion of the lower coupling drive shaft. The reason for the severe wear of the forward spline could not be definitively

determined due to fire damage and the loss of associated components, which were not located during the investigation.',

'Undetermined because examination of the airplane wreckage did not reveal any anomalies that would have precluded normal operation.',

"A partial loss of engine power due to oil starvation. Contributing was the flight instructor's failure to maintain control of the airplane during an aborted emergency landing, and his delayed decision to deploy the airplane's parachute system.",

'A loss of engine power due to three of the engine valve adjustment mechanisms backing out, which resulted from improper maintenance.\r',

'Oil starvation that led to the failure of the No. 5 connecting rod and a subsequent loss of engine power.',

'The loss of engine power for reasons that could not be determined because postaccident examination of the airframe and engine did not reveal any mechanical malfunctions or failures that would have precluded normal operation.',

'A partial loss of engine power during takeoff. The reason for the partial loss of power could not be determined due to the extensive fire and impact damage to the engine.',

'Failure of the No. 6 cylinder connecting rod, due to improper rotation of the propeller during a previous hydraulic lock. \r\n\r',

"The flight instructor's loss of airplane control while departing in gusting wind conditions that were conducive to low-level wind shear.",

'The total loss of engine power for reasons that could not be determined based on postaccident examination and testing.\r\n\r',

"The in-flight failure of the left wing lower forward attach point under normal loading conditions due to corrosion and fatigue cracking in the center section hinge brackets. Contributing to the accident was the operator's inadequate maintenance and overweight operation of the airplane, and the manufacturer's inadequate guidance to detect and prevent corrosion and fatigue cracking.",

'An in-flight loss of airplane control for reasons that could not be determined because postaccident examination of the airframe and engine revealed no preimpact mechanical malfunctions or failures that would have precluded normal operation.',

'Separation of the vertical and horizontal stabilizers from the fuselage due to a fracture that initiated at the bond between the left horizontal stabilizer and the flange that attached the horizontal stabilizer to the fuselage skin. The failure was likely caused by construction techniques that produced poor bond strength in a critical area and the high loads on the horizontal stabilizer from a single or multiple aerobatic maneuver(s).',

'The partial loss of engine power for reasons that could not be determined based on the available evidence.\r\n\r\n\x0b\r',

"Improper engine assembly by unknown maintenance personnel, which resulted in the failure of the No. 6 connecting rod due to oil starvation from the shifting of the crankshaft's No. 4 main bearing.",

'The separation of the attachment hardware connecting the elevator trim tab pushrod to the elevator trim actuator, which resulted in the elevator trim tab jamming in a position outside the limits of normal travel and a subsequent loss of airplane control.',

'A loss of control for reasons that could not be determined based on the available information.',

'An in-flight structural failure due to a severely corroded wing strut, which resulted in a loss of airplane control.',

"The flight crew's mismanagement of the approach and multiple deviations from company standard operating procedures, which placed the airplane in an unsafe situation and led to an unstabilized approach, a descent below minimum descent altitude without visual contact with the runway environment, and an aerodynamic stall. Contributing to the accident were Execuflight's casual attitude toward compliance with standards; its inadequate hiring, training, and operational oversight of the flight crew; the company's lack of a formal safety program; and the Federal Aviation Administration's insufficient oversight of the company's training program and flight operations.",

"The airplane's impact with trees and terrain during an off-airport forced landing in dark night conditions following a partial loss of engine power. The reason for the partial loss of engine power could not be determined because postaccident examination did not reveal any mechanical anomalies that would have precluded normal operation."

tion.",

'A loss of airplane control for reasons that could not be determined because examination of the wreckage revealed no mechanical deficiencies. \r',

'A total loss of engine power on takeoff, which resulted from a sudden over-temperature condition due to an improperly adjusted fuel control unit and the deteriorated condition of the fuel nozzles.',

'A total loss of engine power for reasons that could not be determined because the examination of the wreckage did not reveal any mechanical anomalies that would have precluded normal operation.',

'Failure of the left wing in flight due to compression loading from wing loads combined with preexisting damage.',

"The failure of the prerotator belt, which impeded the engine's timing belt and resulted in a loss of engine power at low altitude.",

'The in-flight failure of the engine-to-transmission drive shaft due to improper maintenance, which resulted in low main rotor rpm and a subsequent hard landing to water.',

"The flight instructor's inadequate preflight fuel planning, which resulted in a total loss of engine power due to fuel exhaustion.",

"The intentional low altitude maneuvering during takeoff in response to a near-miss with an airplane departing from a converging runway, which resulted in an exceedance of the airplane's critical angle of attack and a subsequent aerodynamic stall.",

"The flight instructor's failure to ensure that her seat was properly secured before initiating the takeoff, which resulted in a subsequent loss of control. Contributing was the lack of an installed secondary seat stop.",

'An inflight loss of engine power due to a failure of the engine fuel pump, which resulted in a collision with trees and terrain during the subsequent autorotation. The failure of the engine fuel pump resulted from the absence of adequate grease leading to accelerated spline wear within the fuel pump.',

"The flight instructor's inability to move the control stick after takeoff for undetermined reasons, which resulted in an exceedance of the airplane's critical angle of attack and inadvertent aerodynamic stall. The reason for the inability to move the control stick could not be determined, because postaccident examination revealed no evidence of flight control malfunctions or anomalies that would have precluded normal operation.",

'A loss of control while maneuvering for reasons that could not be determined because postaccident examination did not reveal any mechanical malfunctions or anomalies with the airplane.',

'The in-flight collision with one or more large birds (Bald Eagle), which resulted in a loss of airplane control.',

'An in-flight collision with trees and terrain for reasons that could not be determined because no anomalies consistent with a preimpact failure or malfunction were observed during the examination.',

"The failure of the power turbine governor's dual-spool bearing due to a lack of lubrication, which resulted in a complete loss of engine power and subsequent impact with terrain.",

"The mechanic's failure to properly secure the bolt connecting the throttle cable to the carburetor during the installation of the carburetor, which resulted in a loss of engine power.",

'A preexisting stress rupture that initiated at a spot weld in the turbocharger v-band exhaust clamp, which resulted in the failure of the clamp and separation of the exhaust tailpipe, an in-flight fire, and subsequent impact with terrain.',

'A total loss of engine power due to fatigue failure of the camshaft drive gear teeth.',

'The steep descent to ground impact for reasons that could not be determined based on the available evidence.',

'A loss of engine power during cruise flight for reasons that could not be determined because a test run of the engine did not reveal any mechanical malfunctions or anomalies that would have precluded normal operation. Contributing to the accident were the tree stumps at the forced landing site.',

"\r\nThe failure of the right wing due to a fatigue fracture of the right outboard wing forward spar lower fitting. Contributing to the accident was the routine op

eration of the airplane over its certificated maximum gross weight and the operator's improper or inadequate maintenance practices, which failed to apply a service life factor to the airplane to account for its overweight operation and also failed to detect the extensive corrosion throughout the airplane.",

'An encounter with turbulence due to updrafts and/or dust devils that resulted in mast bumping and an in-flight break-up.',

"A severe vibration of the helicopter that led to the crew's inability to maintain sufficient rotor rotation speed (Nr), leading to excessive main rotor blade flapping, subsequent main rotor blade contact with the tail boom, and the resultant in-flight breakup. Contributing to the severity and sustainment of the vibration, which was not predicted during development, were (1) the collective biomechanical feedback and (2) the attitude and heading reference system response, both of which occurred due to the lack of protections in the flight control laws against the sustainment and growth of adverse feedback loops when the 6-hertz airframe vibration initiated. Contributing to the crew's inability to maintain sufficient Nr in the severe vibration environment were (1) the lack of an automated safeguard in the modified one-engine-inoperative software used during flight testing to exit at a critical Nr threshold and (2) the lack of distinct and unambiguous cues for low Nr.",

"The emergency response team's failure to ensure that the system operator was secured to the helicopter, which resulted in his fall during the recurrent rescue hoist training operation.",

"Company maintenance personnel's inappropriate removal without replacement of the safety wires on the collective lever pin screws during a recent maintenance inspection, which resulted in the screws backing out and led to a loss of collective control in flight.",

'The loss of aircraft control for reasons that could not be determined because postaccident examination did not reveal any anomalies that would have precluded normal operation.',

'Improper installation of a fuel line by unknown personnel, which resulted in a total loss of engine power during initial climb due to fuel starvation.',

'An inflight fire in the floor area near the main bus tie circuit breaker panel that resulted from chafing between an electrical wire and a hydraulic line and/or a airplane structure.',

'A departure flight path that consisted of several unexplained turns during the initial climbout, and terminated in a high-speed descent and ground impact. The reason(s) for the turns and descent could not be determined due to lack of definitive evidence.',

'Impact with terrain for reasons that could not be determined based on the available information.',

"The improper execution of an autorotation following the loss of engine power, which resulted in an uncontrolled descent into terrain. Contributing to the accident was the flight instructor's lack of remedial action during the autorotation.",

'The sudden right turn on approach to landing for reasons that could not be determined because postaccident examination did not reveal any anomalies that would have precluded normal operation.',

"The airplane's departure from cruise flight for reasons that could not be determined based on the available information.",

"The flight crew's decision to continue the visual flight rules flight into deteriorating visibility and their failure to perform an immediate escape maneuver after entry into instrument meteorological conditions, which resulted in controlled flight into terrain (CFIT). Contributing to the accident were (1) Hageland's allowance of routine use of the terrain inhibit switch for inhibiting the terrain awareness and warning system alerts and inadequate guidance for uninhibiting the alerts, which reduced the margin of safety, particularly in deteriorating visibility; (2) Hageland's inadequate crew resource management (CRM) training; (3) the Federal Aviation Administration's failure to ensure that Hageland's approved CRM training contained all the required elements of Title 14 Code of Federal Regulations 135.330; and (4) Hageland's CFIT avoidance ground training, which was not tailored to the company's operations and did not address current CFIT-avoidance technologies.",

"The flight instructor's loss of control during an aerodynamic stall demonstration, which resulted in an inadvertent spin from which he was unable to recover. Contributing to the accident was the flight instructor's lack of familiarity with the air

plane's stall characteristics.",

'The separation of the main rotor assembly due to mast bumping.',

'The NTSB did not determine the probable cause of this event and does not plan to issue a report or open a public docket. The investigation of this event is being conducted under the jurisdiction of the Federal Bureau of Investigation.',

"The jumpmaster's failure to guard the reserve parachute ripcord, which caused an inadvertent deployment of his reserve parachute.",

'A loss of airplane control for reasons that could not be determined due to the extensive impact and fire damage to the airplane.',

'An abrupt pitch-up maneuver following a descent, which resulted in the in-flight separation of the right wing due to the overload failure of both the forward and aft right wing attachment brackets.',

'The in-flight failure of the propeller due to excessive engine vibration loads and the use of an incorrectly-sized propeller, which resulted in a fatigue crack of the leading edge strip. Contributing to the accident was the inadequate repair of the propeller following a previous crack.',

'A loss of engine power to the left engine for reasons that could not be determined due to the extensive fire and impact damage to the airplane.',

'The loose fuel fitting on the combustion heater that leaked a lean fuel-air mixture into the nose baggage compartment. The mixture was most likely ignited by the combustion heater, blowing off the nose baggage compartment doors and starting an in-flight fire.',

'Undetermined due to a lack of physical evidence.',

'A loss of control in flight for reasons that could not be determined because no anomalies consistent with a preimpact failure or malfunction were identified during the investigation.',

'A total loss of engine power during takeoff due to fuel starvation as a result of a failure of internal components of the fuel servo.',

"The flight instructor's failure to ensure that adequate clearance from terrain was maintained after performance of a simulated engine failure maneuver, which resulted in controlled flight into terrain.",

'The failure of maintenance personnel to ensure that the throttle and fuel metering unit AN "B" nut was secured, which resulted in a total loss of engine power in flight and a subsequent collision with trees while attempting to land after sunset.',

"The flight instructor's inadequate preflight planning and operation of the airplane outside its center of gravity envelope, which resulted in a loss of control while maneuvering.",

"The failure of the fuel selector valve in a position that restricted fuel flow to the engine, resulting in a total loss of engine power during initial climb due to fuel starvation. Also causal was the operator's failure to effectively detect and resolve the wear and progressive binding of the fuel selector valve before it failed due to excessive rotational force being applied. Contributing was the flight instructor's exceedance of the airplane's critical angle of attack during an emergency return to the airport, which resulted in an aerodynamic stall/spin.",

"The flight instructor's exceedance of the critical angle of attack during a go-around, which resulted in an aerodynamic stall/spin. Contributing to the accident was the flight instructor's failure to familiarize himself with the flight characteristics of the unfamiliar airplane before conducting the flight review.",

'The failure of unknown personnel to properly safety an elevator control cable turnbuckle, which disconnected in flight resulting in loss of pitch control. Contributing to the accident was the inadequate design of the experimental airplane, which did not provide a mechanism for accessing the entire flight control system during routine inspections.',

'An impact with terrain during final approach for reasons that could not be determined because no evidence of an in-flight failure or malfunction was observed.',

"The flight instructor's decision to continue the takeoff in gusting tailwind and high density altitude conditions, which significantly reduced airplane performance, and his subsequent exceedance of the airplane's critical angle of attack during the initial climb, which resulted in an aerodynamic stall at low altitude.",

"The in-flight failure of the left wing due to the owner's use of improper hardware and his improper assembly of the airplane, which reduced the strength of the left wing and resulted in its subsequent failure following a sharp pullup maneuver.",

'A partial loss of engine power during initial climb for reasons that could not be determined because extensive fire damage precluded thorough examination of the engine and its associated systems.'

'A loss of control and subsequent in-flight breakup for reasons that could not be determined based on the available information.'

"The flight instructor's failure to maintain control of the aircraft while demonstrating a spiral dive, which resulted in a loss of control. Contributing to the accident was the instructor's decision to demonstrate a spiral dive maneuver at an altitude that was too low for recovery."

'Controlled descent into terrain due to engine issues, the reason for which could not be determined because examination of the engine revealed no evidence of malfunctions or failures that would have precluded normal operation.'

"The flight instructor's decision to conduct a low-altitude flight into a box canyon in high density altitude conditions and his failure to maintain airspeed while maneuvering to escape the canyon, which resulted in an exceedance of the airplane's critical angle of attack and an aerodynamic stall."

'A loss of control in flight for reasons that could not be determined based on the available information, which resulted in an in-flight breakup.'

'The loss of airplane control while maneuvering at low altitude for reasons that could not be determined.'

'A loss of control during takeoff for reasons that could not be determined.'

'A loss of engine power for reasons that could not be determined based on available evidence.'

"The flight instructor's failure to ensure that the wing flaps were properly configured for takeoff, which resulted in an aerodynamic stall and loss of control during the initial climb."

'A loss of control for reasons that could not be determined because of the extensive thermal damage from the postcrash fire.'

"The total loss of engine power due to oil starvation to the No. 1 connecting rod, which resulted from the improper torque of the No. 1 cylinder hold-down bolts and through-studs at the time of the cylinder's installation, which resulted in the failure of the connecting rod due to oil starvation. Contributing to the accident was the omission, from the air traffic control display map data, of a closer alternate airport for the emergency landing."

'An in-flight loss of control and collision with terrain for reasons that could not be determined based on the available information.'

'The loss of directional control during takeoff and impact with a steel culvert.'

'Controlled flight into terrain in dark night conditions.'

'A descent and subsequent impact with open ocean waters for reasons that could not be determined based on the available information.'

'An in-flight loss of control due to a bird strike.'

'Failure of the left aileron control cable that resulted in a loss of aircraft control during takeoff. Contributing to the accident was inadequate maintenance inspections to the aileron cable connections.'

"The loss of engine power due to fuel starvation, which resulted from the unporting of the fuel during a right turn due to the auxiliary fuel tanks' improper configuration."

'An in-flight loss of control due to bird strikes.'

'Impact with trees and terrain for reasons that could not be determined based on available evidence.'

'A total loss of engine power for reasons that could not be determined based on the available information.'

'A loss of engine power due to snow or ice ingestion at an altitude that was insufficient to allow for engine re-ignition. Contributing to the accident were conditions, including altitude and flat light conditions, that precluded a successful autorotation to the field.'

"A loss of control following the gunner's failure to ensure that the net maintained clearance from the tail rotor."

'A loss of control for reasons that could not be determined based on the available information.'

'The driveshaft fracture due to overstress loading and rotational bending as a

'The inflight separation of the upper transmission due to the thread failure o

'An in-flight fire of undetermined origin. Contributing to the accident were the severe icing conditions encountered during the final minutes of the flight, which led to a loss of airplane control.'

'Pilot incapacitation due to carbon monoxide poisoning as a result of an undetected crack in an engine exhaust muffler, which permitted entry of exhaust gasses into the cabin via the cabin heat system. \r',

'The loss of engine power due to fatigue failure of the crankshaft.',

'The loss of airplane control after an engine flameout and auto-feather system interruption during the takeoff climb, which resulted in an impact with terrain.',

'A loss of control for reasons that could not be determined based on the available information.\r',

"A total loss of left engine power for reasons that could not be determined, and the instructor's failure to maintain airspeed while maneuvering for a forced landing, which resulted in a loss of control. Contributing to the accident was the instructor's decision to conduct a simulated engine failure at low altitude.",

"The flight instructor's failure to maintain airplane control during initial climb after a touch-and-go landing, which resulted in an exceedance of the airplane's critical angle of attack and an aerodynamic stall.",

"A partial loss of engine power for reasons that could not be determined, and the flight instructor's exceedance of the airplane's critical angle of attack while maneuvering for a forced landing, which resulted in an aerodynamic stall and subsequent loss of control.",

'The airplane's unairworthy thrust reverser (T/R) system due to inadequate maintenance that resulted in an asymmetric T/R deployment during an approach to the airport and the subsequent loss of airplane control.\r',

"The flight instructor's failure to maintain adequate airspeed during the initial climb after takeoff, which resulted in an exceedance of the airplane's critical angle of attack, an aerodynamic stall, and loss of control. \r",

"The exceedance of the airplane's critical angle of attack during a steep climb after takeoff, which resulted in an aerodynamic stall and spin into terrain.\r",

'A loss of control and impact with terrain while maneuvering.\r',

'The helicopter's encounter with a strong downdraft or outflow boundary while operating at a higher than recommended airspeed in turbulence which resulted in a low-G condition, excessive main rotor flapping, and an in-flight breakup when the main rotor contacted the cabin area. \r',

"A partial loss of engine power due to a stuck exhaust valve and the flight instructor's exceedance of the airplane's critical angle of attack following the loss of power, which resulted in an aerodynamic stall at low altitude.",

'A loss of control due to an inflight right engine fire due to the loose fuel hose between the engine-driven fuel pump and the flow transducer.',

'Impact with water for reasons that could not be determined based on the available information.',

'A loss of control while conducting low-altitude, high-speed maneuvers. \r',

'Impact with the ocean for reasons that could not be determined because the airplane was not located.',

'A total loss of engine power due to fuel starvation.\r',

"The airplane's floats impact with an ocean wave or swell, which exceeded the design load specifications of the flying wire assemblies and resulted in a partial separation of the float assemblies.\r",

'The improper installation of the engine's metal intake screen, which allowed the filter element to become displaced and subsequently lodge in the intake, blocking intake air and causing the total loss of engine power, at low altitude and low airspeed resulting in the airplane impacting terrain.\r',

'Impact with terrain for reasons that could not be determined based on the available information.\r\n\r\n\r\n\r',

'A total loss of engine power due to the failure of the engine's Nos. 3 and 4 bearings and the power turbine pinion gear, and subsequent loss of main rotor rpm, which resulted in a loss of control and impact with the water.\r',

'The loss of engine power due to fuel starvation.\r',

'The mechanic's failure to clean the oil suction screen during the most recent maintenance, which resulted in oil starvation and subsequent total loss of engine power. \r',

'A loss of control during landing due to the loose and uneven landing surface. \r',

'The flight instructor's failure to maintain directional control with a qua

```

rtering tailwind.\r',
    'The flight instructor\x92s delayed remedial action during an unstabilized app
roach, which resulted in an impact with powerlines and a subsequent loss of control\r
',
    'A collision with water following a loss of visual reference to the water surf
ace due to sun glare.\r',
    'A loss of engine power for reasons that could not be determined due to a lack

```

I'm going to create a new category that groups collisions

```
In [89]: df['report_status'] = df['report_status'].map(lambda x: 'Collision' if isinstance(x,
```

```
In [90]: df['report_status'].nunique()
```

```
Out[90]: 418
```

There are still 4358 unique cases in the report_status column and the majority of the explanations are not very clear

3.7 Results

First business recommendation: Invest in aircrafts with more than one engine. The dataset shows that 82% of the accidents happened with aircrafts that had only 1 engine.


This implies that aircraft with more than one engine may have a better safety record and could represent a safer investment.

```
In [91]: plot_feature(df, 'number_of_engines', 'bar', 'total_fatal_injuries', 'total_serious_:
```

```

C:\Users\Usuario\anaconda3\envs\aircraft_env\Lib\site-packages\seaborn\_oldcore.py:14
98: FutureWarning: is_categorical_dtype is deprecated and will be removed in a future
version. Use isinstance(dtype, CategoricalDtype) instead
    if pd.api.types.is_categorical_dtype(vector):
C:\Users\Usuario\anaconda3\envs\aircraft_env\Lib\site-packages\seaborn\_oldcore.py:14
98: FutureWarning: is_categorical_dtype is deprecated and will be removed in a future
version. Use isinstance(dtype, CategoricalDtype) instead
    if pd.api.types.is_categorical_dtype(vector):

```




```
In [92]: plot_column_data(df, 'number_of_engines', 'bar')
```

```

number_of_engines
1.0    0.821342
2.0    0.160780
0.0    0.013269
4.0    0.002990

```

```
3.0    0.001620  
Name: proportion, dtype: float64
```




Second business recommendation: Do not invest in aircrafts with a reciprocating engine type. The dataset shows that 81.4% of the accidents happened with aircrafts that had this type of engine.

Investing in aircraft with alternative engine types might reduce risk exposure.


```
In [93]: plot_column_data(df, 'engine_type', 'bar')
```

```
engine_type  
Reciprocating    0.814365  
Unknown          0.065969  
Turbo Prop       0.048278  
Turbo Shaft      0.046596  
Turbo Fan        0.015511  
Turbo Jet        0.009095  
Electric         0.000125  
Hybrid Rocket    0.000062  
Name: proportion, dtype: float64
```



Third business recommendation: Be weary of investing in certain aircraft makers. Be very carefull in investing on 'Cessna', 'Piper' and 'Beech' as their aircrafts combined have had around 50% of the fatal and serious accidents. In particular, 'Cessna' has 25%, 'Piper' 17.7%, and 'Beech' 8.8%. The rest of the makers are involved in less than 2.6% of the fatal and serious accidents.

```
In [94]: plt.figure()
top_10_make.plot(kind='bar')
plt.xlabel('Top 10 makers')
plt.ylabel('Percentage of Accidents')
plt.xticks(rotation=90)
plt.title('Top 10 Markers per Percentage of Accidents');
```



A prudent investment strategy might be to diversify into manufacturers with lower accident rates or to further scrutinize the causes of these accidents to determine if they are related to maintenance practices, specific models, or flight circumstances that could be mitigated.

Considering the above recommendations, this would be the resulting dataset to consider for aircraft investment

```
In [95]: df_filtered = df[(df['number_of_engines']!=1) & (df['engine_type']!='Reciprocating')
df_filtered.reset_index(drop=True, inplace=True)
```

```
In [96]: df_filtered.columns
```


```
Out[96]: Index(['investigation_type', 'event_date', 'location', 'country',
               'injury_severity', 'aircraft_damage', 'make', 'model', 'amateur_built',
               'number_of_engines', 'engine_type', 'purpose_of_flight',
               'total_fatal_injuries', 'total_serious_injuries',
               'total_minor_injuries', 'total_uninjured', 'weather_condition',
               'broad_phase_of_flight', 'report_status', 'primary_key', 'year',
               'month'],
              dtype='object')
```

```
In [97]: plot_feature(df_filtered, 'make', 'categorical', 'total_fatal_injuries', 'total_serious_injuries')
```

```

C:\Users\Usuario\anaconda3\envs\aircraft_env\Lib\site-packages\seaborn\_oldcore.py:14
98: FutureWarning: is_categorical_dtype is deprecated and will be removed in a future
version. Use isinstance(dtype, CategoricalDtype) instead
    if pd.api.types.is_categorical_dtype(vector):
C:\Users\Usuario\anaconda3\envs\aircraft_env\Lib\site-packages\seaborn\_oldcore.py:14
98: FutureWarning: is_categorical_dtype is deprecated and will be removed in a future
version. Use isinstance(dtype, CategoricalDtype) instead
    if pd.api.types.is_categorical_dtype(vector):

```



Looking at the results, I would recommend to invest in aircrafts made by Schweizer because they're the ones with the lowest numbers of total fatal injuries and are thus, a priori, more reliable

3.8 Write the Results

I will export the dataframe to an excel

```
In [98]: df_filtered.to_csv("../results_data/aircraft_safety_final_dataset.csv", index=False)
```