



ME338 – Manufacturing Process II

Lecture 3 : Chip formation & Tool geometry




Pradeep Dixit

Department of Mechanical Engineering,
Indian Institute of Technology Bombay

Continuous chips




- The lower boundary is below the machined surface, subjecting the machined surface to distortion, as depicted by the distorted vertical lines.
- This situation occurs particularly in machining soft metals at higher speeds and high rake angles (sharp edge).
- Although they generally produce good surface finish, CCs are not always desirable. Safety risks




Factors:

- Ductile material
- High cutting speed
- Low depth of cut
- Large rake angle


Different types of chips




Continuous chip (ductile materials, high speed)



Discontinuous chip (brittle material)



Continuous chip with BUE



low thermal conductivity materials

ME338 – Pradeep Dixit


2

Discontinuous Chips (DC)




- DCs consist of segments that may be firmly or loosely attached to each other DCs usually form under the following conditions:
- Factors that encourage DC chips:
 - Very low or very high cutting speeds/ Large depths of cut/ Low rake angles.
 - Brittle material / Lack of an effective cutting fluid.
- Because of the discontinuous nature of chip formation, forces continually vary during cutting.

Continuous chips with Buildup edge



Hardness distribution with a built-up edge in the cutting zone (material, 3115 steel).



Continuous chip with BUE

- Ductile material
- Stronger adhesion between chip and tool face
- High depth of cut
- Small rake angle


ME338 – Pradeep Dixit

5



Serrated Chips



- Serrated chips: semi-continuous chips with zones of low and high shear strain
- Metals with low thermal conductivity and strength that decreases sharply with temperature, such as titanium, exhibit this behavior.
- The chips have a saw-tooth-like appearance.



Segmented chip



low thermal conductivity materials

ME338 – Pradeep Dixit

7

Continuous chips with Buildup edge



- BUE, consisting of layers of material from the workpiece that are gradually deposited on the tool, may form at the tip of the tool during cutting.
 - As it becomes larger, BUE becomes unstable and eventually breads up.
 - Part of BUE material is carried away by the tool side of the chip; the rest is deposited randomly on the workpiece surface.
 - Because of work hardening and deposition of successive layers of material, the hardness of BUE increases significantly.
- The tendency for a BUE to form is reduced by any of the following practices:
 1. Increase the cutting speeds,
 2. Decreasing depth of cut
 3. Increasing the rake angle, Using a sharp tool
 4. Using an effective cutting fluid
 5. Use a cutting tool that has lower chemical affinity for the workpiece material.





ME338 – Pradeep Dixit

6

Chip control/chip breaker (CB)




- Chip produced during high speed machining of ductile materials are very long & curly that are undesirable
 - Safety concern for workers
 - May entangled with cutting tool, workpiece
- Higher speed > higher temperature > chip with bluish color, long coils
- Chip breaker to break continuous chips
 - Obstruction type / Groove type
- CBs increase the effective rake angle of the tool and, consequently, increase the shear angle.



ME338 – Pradeep Dixit

Video : Single point cutting tool



www.LearnEngineering.org
A YouTube PARTNER...


ME338 – Pradeep Dixit

9


Tool nomenclature systems



- Cutting tool have 6 important angles: each with major/minor edges
 - Rake angle, relief (clearance), cutting edge angles
 - Combination of 6 angles, and 1 nose radius – tool signature
- Various tool standards exists to define tool geometry are available
- ISO System : Orthogonal (ORS)/ Normal Reference System (NRS)
- American Standards Association (ASA) system is popular




Single Point (edge) Tool Geometry




- Cutting tool have 2 cutting edges : Major (Principal) and minor (Auxiliary)
 - Their meeting point is termed as 'nose'
- Tool surface where chip flow is 'Rake surface'
- Surface closer to the 'machined' finished is known as 'Flank'

Reference Planes – ASA system




Tool Angles – ASA System



θ = Plain approach angle
 ψ_s = Side cutting edge angle
 ψ_e = End cutting edge angle
 $\phi = 90^\circ - \psi_s$

Side cutting edge angle is also known as 'Lead' angle

Cutting tool geometry : ASA Nomenclature




Tool Geometry : ASA Nomenclature




- Cutting tool have 6 important angles: each with major/minor edges
- American system
- Cutting tool signature (American system)
 - Back rake angle (α_b) ($^\circ$)
 - Side rake angle (α_s) ($^\circ$)
 - Front (end) clearance (relief) angle (δ_e) ($^\circ$)
 - Side clearance (relief) angle (δ_b) ($^\circ$)
 - Front (end) cutting edge angle (ψ_e) ($^\circ$)
 - Side cutting edge angle (ψ_s) ($^\circ$)
 - Nose radius (r) (mm)
- Tool signature Example : $6^\circ-10^\circ-7^\circ-7^\circ-10^\circ-20^\circ-0.5$

Cutting tool geometry : Various angles



$$\text{Approach angle} = 90^\circ - \text{side cutting edge angle}$$

Effect of rake angle




- Rake angle is cutting edge angle that has a large effect on cutting resistance, chip disposal, cutting temperature and tool life.
- Increasing rake angle in the positive (+) direction improves:
 - Tool Sharpness. Thumb rule : Increasing rake angle by 1° in the positive (+) direction decreases cutting power by about 1%.
 - Lowers cutting edge strength and in the negative (-) direction increases cutting resistance.
- Negative rake angle: hard workpiece, When cutting edge strength is required such as uncut surface
- Positive rake angle: soft workpieces, workpiece is easily machined

ME338 – Pradeep Dixit


17

Positive/ Negative rake angle



Positive rake angle

- Tool sharp and pointed edge
- Relatively weak
- Reduces cutting forces
- Low/moderate cutting speeds
- Good for softer work material




Negative rake angle

- Increases cutting edge strength
- Higher, compressive cutting forces
- High speed cutting
- Brittle tool materials like carbide, ceramics
- Good for harder work materials

ME338 – Pradeep Dixit

18

Relief/Flank/Clearance angle



- Flank angle prevents friction between flank face and finished workpiece surface resulting in smooth surface finish.
- Increasing flank angle decreases flank wear occurrence and lowers the cutting edge strength.
- Reduced flank angle is used for harder material, when higher cutting edge strength is needed
- Higher flank angle is used for softer workpiece


ME338 – Pradeep Dixit

19

Effect of cutting edge angles




$$\begin{aligned} \theta &= \text{Plain approach angle} \\ \psi_s &= \text{Side cutting edge angle} \\ \psi_e &= \text{End cutting edge angle} \\ \theta &= 90^\circ - \psi_s \end{aligned}$$



$$\begin{aligned} t_0 &= f \cos \psi_s \\ w &= d / \cos \psi_s \end{aligned}$$

Effect of Side cutting edge angle (lead angle)



- The side cutting edge angle reduces the impact load and affects the amount of feed force, back force and chip thickness
- Increasing the side cutting edge angle:
 - Increases the chip contact length
 - Decreases chip thickness and increases chip width. Thus, breaking chips is difficult.


http://www.mitsubishicarbide.com/en/technical_information/tec_turning_tools/tec_hsk-t/tec_hsk-t_technical/tec_turning_cutting_edge

ME338 – Pradeep Dixit

21

Effects of End Cutting Edge Angle

- The end cutting edge angle avoids interference between the machined surface and the tool (end cutting edge).
- Usually 5° – 15° .
- Decreasing the end cutting edge angle results into:
 - increases cutting edge strength, but it also increases cutting edge temperature.
 - increases the back force and can result in chattering and vibration while machining.
- Small end cutting edge angle used for roughing and large angle for finishing are recommended.




ME338 – Pradeep Dixit

23

Effects of Side Cutting Edge Angle



- At the same feed rate, increasing the side cutting edge angle increases the chip contact length and decreases chip thickness.
 - As a result, the cutting force is dispersed on a longer cutting edge and tool life is prolonged.
- When to reduce Side cutting edge angle
 - Finishing with small depth of cut
 - thin long workpiece
 - when machine has poor rigidity
- When to increase Side cutting edge angle
 - hard workpiece which produce high cutting temperature
 - when roughing a workpiece with larger diameter
 - when the machine has high rigidity



ME338 – Pradeep Dixit

22

Nose radius of cutting tool



- Radius effects the cutting edge strength and finished surface.
- In general, a corner radius 2–3 times the feed is recommended.

ME338 – Pradeep Dixit

24

Effect of Tool corner radius



- Increasing the corner radius:
 - Improves the surface finish.
 - Improves cutting edge strength.
 - Increases the cutting resistance and causes chattering.
 - Decreases flank and rake wear.
 - Results in poor chip control.

