

IBONG TIRIRIT (MDSP 5)

The hacksaw blade should be placed in the frame with:

- A. the teeth pointing forward
- B. the teeth pointing backward
- C. one end looser than the other end
- D. the teeth facing in any direction

answer: A

When cutting a long thin piece of metal:

- A. turn the blade upside down the frame
- B. turn the blade at right angles to the frame
- C. use a blade with fewer teeth per inch
- D. set the blade in the frame with the teeth facing you

answer: B

A hacksaw blade with 18 teeth per inch is best suited for cutting:

- A. solid stock
- B. cast iron
- C. aluminum
- D. any of the above

answer: D

A coclant is usually used when cutting material in a power hacksaw to

- A. absorb the heat of friction
- B. prevent the blade from overheating
- C. prevent the blade from losing its temper
- D. all of the above

answer: D

A hacksaw blade with 32 TPI is suited for cutting:

- A. small tubing
- B. conduct
- C. sheet metal under 18 gage
- D. any of the above

answer: D

For filing lead or Babbitt, use a:

- A. vixen file
- B. mill file
- C. sheet metal under 18 gage
- D. any of the above

answer: D

It moves on the lathe bed with cutting tool according to the rotation of lead screw or by hand traversing wheel

- A. apron
- B. compound rest
- C. mandrel
- D. saddle

answer: D

It acts the carriage or compound rest through the mechanism lifted inside the apron

- A. apron
- B. compound
- C. mandrel
- D. saddle

answer: A

It gives the cutting tool longitudinal feed, cross feed or carriers

- A. angular feed
- B. apron
- C. compound rest
- D. saddle

answer: C

The center, which is fitted in head stock spindle, called

- A. above center
- B. below center
- C. dead center
- D. live center

answer: D

A center, which is fitted in tail stock spindle called

- A. above center
- B. below center
- C. dead center
- D. live center

answer: C

Which of the following gives shearing action?

- A. front clearance
- B. side clearance
- C. slide rake
- D. top rake

answer: D

Which of the ff. information is necessary when ordering a file?

- A. size (length)
- B. shape
- C. type of teeth
- D. all of the above

answer: D

Never use a file:

- A. that is dirty
- B. w/o a handle
- C. w/o oiling
- D. with a tang

answer: B

The best file to use when finishing sharp corners or slots and grooves is the:

- A. mill file

- B. square
- C. knife file
- D. jewelers file

answer: C

On a lathe the dead center is used after:

- A. boring
- B. center-drilling
- C. drilling
- D. reaming

answer: B

Eleven - sixteenths of an inch expressed as a decimal is:

- A. .6785
- B. .7685
- C. .6875
- D. .6578

answer: C

The markings on a micrometer barrel are:

- A. .025" apart
- B. .250" apart
- C. .0025" apart
- D. 2.5" apart

answer: A

It measures the slope of the top surface of the tool to the side in a direction perpendicular to the longitudinal axis

- A. end relief angle
- B. side cutting edge angle
- C. side rake angle
- D. side relief edge angle

answer: C

It is used for holding straight shank drills in the spindle to the machine when drilling

- A. chuck key
- B. drill chuck
- C. floating holder
- D. magic chuck

answer: B

A reamer is used to correct the

- A. finish and depth of a drilled hole
- B. finish and position of a drilled hole
- C. size and position of a drilled hole
- D. size and roundness of a drilled hole

answer: D

Twist drills are usually considered suitable machining holes having a length less than

- A. two times their diameter
- B. five times their diameter
- C. ten times their diameter
- D. twenty times their diameter

answer: B

In quick return mechanism of shaping machine the ram stroke length is proportional to

- A. crank length
- B. ram length
- C. slotter arm length
- D. stroke

answer: A

Type and number of bearings to be used for spindles of machine tool depend on

- A. type of spindle
- B. type of machine tool
- C. load on spindle
- D. load on the bearing

answer: D

When the dial on the cross-feed is turned .010", you remove from diameter of the stock being cut:

- A. .010
- B. .020
- C. .005
- D. .015

answer: A

The flexible type hacksaw blade is best suited for work on:

- A. channel iron
- B. tubing
- C. aluminum
- D. any of the above

answer: D

A flexible back hacksaw blade is one that has:

- A. only the teeth
- B. flexible ends
- C. a movable back
- D. any of the above

answer: D

A hacksaw blade with 24 TPI is best suitable for cutting:

- A. tubing
- B. sheet metal over 18 gage
- C. brass and copper
- D. any of the above

answer: D

An all hard hacksaw blade is one that:

- A. has a hard back and flexible teeth
- B. has a flexible back and hard teeth
- C. has the entire blade hardened
- D. will only fit a solid frame hacksaw

answer: C

A hacksaw blade can be placed in a frame in:

- A. two positions
- B. four positions
- C. one position
- D. three positions

answer: B

what should be the top rake angle to cut brass?

- A. 0
- B. 15
- C. 30
- D. 45

answer: A

It is a long, tapered punch used for loosening straight pins, taper pins, rivets and other small parts being disassembled

- A. center punch
- B. drift punch
- C. drive-pin punch
- D. hand punch

answer: B

A tool used for turning nuts or bolts

- A. c-clamps
- B. long nose
- C. plier
- D. wrench

answer: D

Used to permit lever shift for vertical travel of rail

- A. ball crank
- B. clamp plates
- C. plumb bob
- D. plunger knob

answer: D

It is mounted on the top of the column and is guided in perfect alignment by the machined dovetailed surface

- A. arbor
- B. over arm
- C. saddle
- D. spindle

answer: B

Name of mechanism, which a welding operator holds during gas welding and at the end of which the gases are burred to perform the various gas welding operation.

- A. hose
- B. gage
- C. switch
- D. torch

answer: D

A scribe is made from:

- A. carbon steel
- B. cold-rolled steel
- C. tool steel
- D. hot-rolled steel

answer: C

Before applying layout blue on a piece of metal, it must be:

- A. roughened
- B. heated
- C. cleaned
- D. cold

answer: C

A drill bit has :

- A. 4 flutes
- B. 3 flutes
- C. 2 flutes
- D. no flutes

answer: C

The alignment of coupling faces can be checked by:

- A. using an inside micrometer
- B. inserting a thermocouple
- C. inserting a feeler gage between the coupling faces at various points around the circumference
- D. rotating and measuring to nearest permanent fitting

answer: C

A piece of cast iron held against an emery wheel will give off:

- A. dull yellow sparks
- B. bright shiny sparks
- C. red sparks
- D. no sparks

answer: A

When cutting material in a lathe, the softer the material being cut, the tool bit should have:

- A. more top rake
- B. less top rake
- C. double top rake
- D. any of the above

answer: D

After grinding a tool bit, the cutting edge should be:

- A. case-hardened
- B. rubbed with emery cloth
- C. stoned with an oilstone
- D. rubbed with crocus cloth

answer: C

It is a hole revolving cutter or grinding wheel for mounting it on an arbor.

- A. arbor hole
- B. hole saw
- C. star drill
- D. star saw

answer: A

A machine in which materials are pulverized between the two toothed metal disk rotating in opposite directions.

- A. attrition mill
- B. ball mill
- C. beater mill
- D. tumbling mill

answer: A

A press in which mechanical feeding of the work is synchronized with the press action

- A. automatic press
- B. dial press
- C. manual press
- D. punch press

answer: A

A supporting member that carries a wheel and either rotates with the wheel to transmit mechanical power to or from it, or allows the wheel to rotate freely on it called

- A. axle
- B. bushing
- C. coupling
- D. shaft

answer: A

A file whose edges are parallel is known as

- A. blunt file
- B. crochet file
- C. cross cut file
- D. equaling file

answer: A

Straight muriatic acid is often used as a flux on:

- A. galvanized iron
- B. cast sheet
- C. sheet steel
- D. any of the above

answer: D

Special solders used for aluminum usually require:

- A. more heat
- B. less heat
- C. the same heat as copper wire
- D. the same heat as sheet metal

answer: A

Copper is annealed by heating to a cherry red color and:

- A. dousing in cold water
- B. cooling slowly in air
- C. dousing in oil
- D. dousing in hot water

answer: B

A piece of mild steel held against an emery wheel will give off:

- A. bright shiny sparks
- B. light straw colored sparks
- C. no sparks
- D. green sparks

answer: B

A gear wheel making 156 rpm has 56 teeth. It drives another gear at 91 rpm. The number of teeth on the second gear is:

- A. 65
- B. 90
- C. 50
- D. 96

answer: D

Tool steel can be hardened by:

- A. heating red hot and plunging into water
- B. heating red hot and cooling in a blast of dry air
- C. heating red hot and plunging into linseed or cottonseed oil
- D. any of the above, depending on type and use

answer: D

A scriber is made from:

- A. carbon steel
- B. cold-rolled steel
- C. tool steel
- D. hot-rolled steel

answer: C

After grinding a tool bit, the cutting edge should be

- A. case hardened
- B. rubbed with emery cloth
- C. rubbed with crocus clothe
- D. stoned with an oilstone

answer: D

When cutting material in a lathe, the softer the material being cut, the tool bit should have

- A. any of these
- B. double top rake
- C. less top rake
- D. more top rake

answer: C

A piece of cast iron held against an emery wheel will give off

- A. bright shiny sparks
- B. dull yellow sparks

- C. no sparks
- D. red sparks

answer: B

Which of the following is not a common term relating to the classification of fits

- A. bound
- B. medium force fit
- C. snug
- D. tunking

answer: A

An oversize hole is produced by a drill if

- A. cutting speed is too high
- B. feed is too high
- C. insufficient coolant is used
- D. lips of drill are of unequal length

answer: D

The studs used as a coolant in general machine shop consist of

- A. a chemical solution
- B. an emulsion of oil and water
- C. a solution of detergent and water
- D. a straight mineral

answer: B

Sometimes used for soldering bright tin

- A. rosin
- B. sal ammoniac
- C. tallow
- D. tinning

answer: A

A very effective flux for soldering galvanized iron and zinc

- A. cut acid
- B. muriatic acid
- C. soldering pastes
- D. zinc chloride

answer: B

The process of checking the surface of a piece by rolling depressions into the surface

- A. honing
- B. knurling
- C. reaming
- D. snagging

answer: B

The process of cutting internal threads by means of a cutting tool.

- A. chamfering
- B. honing
- C. reaming
- D. tapping

answer: D

The surface below the cutting edge

- A. face

- B. flank
- C. nose
- D. side relief

answer: B

Which one is the hardest material?

- A. brass
- B. bronze
- C. diamond
- D. steel

answer: C

The movement of belt upon the face of rim or outer of the driver and driven pulleys within the area of arc of contact is called

- A. creep
- B. crowning
- C. dressing
- D. slip

answer: A

It is a device, which hold the job family

- A. clamp
- B. fixture
- C. grip
- D. jig

answer: B

It is the outer surface of face or rim of the pulley is made in convex form to keep the belt in center when it is in motion

- A. creep
- B. crowning
- C. dressing
- D. slip

answer: B

It is used to transmit motion at high speed without producing noise.

- A. bevel gear
- B. helical gears
- C. hypoid gears
- D. worm gears

answer: B

It is used to transmit motion at high speed with heavy load without producing noise

- A. bevel gear
- B. herring bone gear
- C. spur gear
- D. worm gear

answer: B

It connect the shafts with soft materials such as rubber, leather and canvass

- A. flexible coupling
- B. Oldham coupling
- C. rigid coupling
- D. universal coupling

answer: A

One of the most important factors that is often overlooked when soldering is the fact that:

- A. the surface to be soldered must be clean
- B. the two metals to be soldered must not be the same
- C. the two metals to be soldered must be the same
- D. all surfaces should be dipped in acid first

answer: A

A surface should be prepared for soldering by

- A. filing the surfaces
- B. scraping the surfaces
- C. acid-cleaning the surfaces
- D. any of the above

answer: D

The hand tool used for cutting threads on round stock is the:

- A. stock and die
- B. die wrench
- C. stock
- D. stock cutter

answer: A

A hand tool used for cutting threads on round stock is the:

- A. stock and die
- B. die wrench
- C. stock
- D. stock cutter

answer: A

A tapered piece of stock is 2" long, 1-1/8" diameter at one end and 1/2" diameter at the other end. The taper per foot is:

- A. 2"
- B. 2-1/2"
- C. 2-1/4"
- D. 2-1/16"

answer: C

Sweating is the process of:

- A. soldering two different kinds of metal together
- B. separating two pieces of metal that have been soldered together
- C. tinning two surfaces, applying, flux between them, holding the two together and heating
- D. none of the above

answer: C

If muriatic acid is used as a flux, the soldered area must be cleaned thoroughly afterwards to prevent:

- A. anyone touching it from getting burned
- B. remaining acid from eating the metal
- C. the acid from evaporating the solder disintegrating
- D. none of the above

answer: B

It cannot be forged because it will break if heated and beaten by hammer.

- A. Carbon steel
- B. Cast iron
- C. High speed steel 1
- D. Tool steel

answer: B

Shaper tools are made of what type of material?

- A. Babbitt
- B. Brass
- C. Bronze
- D. High speed steel

answer: D

It is the operation of beveling the mouth of a hole.

- A. Counter boring
- B. Counter broaching
- C. Counter sinking
- D. Spot facing

Answer: C

The size of abrasive grains produced by crushing process is called

- A.
- B.
- C. Grit
- D.

Answer: C

It is the combination of iron, carbon and other alloying elements.

- A. Alloy steel
- B. Brass
- C. Carbon steel
- D. Cast iron

Answer: A

It is the process to divide the periphery of the job in degrees.

- A. Angular indexing
- B. Differential indexing
- C. Direct indexing
- D. Plain indexing

Answer: A

It consists of surface irregularities, which result from the various manufacturing process.

- A. Flaws
- B. Lay
- C. Roughness
- D. Waiveness

Answer: C

A piece of tool steel held against an emery wheel will give off:

- A. White sparks with stars on the ends
- B. Yellow sparks
- C. No sparks
- D. Green sparks

Answer: A

Grinding wheels have a range of soft to hard abrasive materials depending on the use. Most manufacturers latter their wheels from A to Z. The hardest is marked:

- A. E
- B. A
- C. Z
- D. El

Answer: C

The main difference between a planer and shaper is that:

- A. The planer has an offset table and the shaper has a horizontal table.
- B. The shaper has a rotating table and the planer has a horizontal table.
- C. The table of planer has a reciprocating motion past the tool head while the table of the shaper is stationary and the tool head has a reciprocating motion.
- D. One is larger than the other

Answer: C

One of the factors involved in the choice of a grinding wheel is:

- A. The kind of material to be ground
- B. The amount of stock to be removed
- C. The kind of finish required
- D. All of the above

Answer: D

The "tang" of a file is the part that:

- A. Does the cutting
- B. Fits into the handle
- C. has no teeth
- D. is opposite the handle

Answer: B

The best method of avoiding accident is by observing _____ related to job, machine and work piece.

- A. Cleanliness
- B. Emery
- C. Opponent
- D. Safety precautions

Answer: D

The size of try square is measured from the inner edge of stock to the end of its

- A. Base
- B. Blade
- C. Body
- D. Edge

Answer: B

Angle of center punch is

- A. 30°
- B. 45°
- C. 60°
- D. 90°

Answer: D

Staggering of hacksaw blade teeth on both sides alternatively is called

- A. Arrangement of teeth
- B. Positioning of teeth
- C. Setting of teeth
- D. None of the above

Answer: C

It is the distance measured parallel to the axis from a point on a screw thread to the corresponding point on the next thread.

- A. Chord
- B. Lead
- C. Linear
- D. Pitch

Answer: D

Solder is an alloy of

- A. Lead and antimony
- B. Lead and tin
- C. Lead and tungsten
- D. Lead and zinc

Answer: B

It's a square key with the bottom two corners are beveled.

- A. Saddle key
- B. Barth key
- C. Woodruff key
- D. Gib head key

Answer: B

Change in metal structure by which the surface structure recover from its unstable condition

- A. annealing
- B. normalizing
- C. aging
- D. tempering

Answer: C

A tapered square key is known as

- A. Gib head
- B. Woodruff
- C. Kennedy
- D. Barth

Answer: C

The process of welding two dissimilar metals is known as

- A. Friction welding
- B. Flash welding
- C. Oxyacetylene welding
- D. Cold welding

Answer: D

A nonmetal considered as undesirable impurity in steel is

- A. lead
- B. sulfur
- C. phosphorous
- D. cyanide

Answer: B

An alloying element which improves the tensile strength of steel and make it harder

- A. vanadium
- B. carbon
- C. cobalt
- D. chromium

Answer: D

An alloying element which reduces deformation of configuration and sulfuric brittleness.

- A. molybdenum
- B. manganese
- C. nickel
- D. chromium

Answer: B

What is the lip clearance angle of twist drill for generated work?

- A. 3 - 6°
- B. 8 - 10°
- C. 12 - 15°
- D. 18 - 22°

Answer: C

It is a milling method in which parts are placed in a row parallel to the axis of the cutting tool end are milled simultaneously.

- A. Abreast milling
- B. Angular milling

- C. Helical milling
- D. Straddle milling

Answer: A

A core drill with hardened steel shot pellets that revolve under the rim of the rotating tube, employed in rotary drilling in very hard ground.

- A. Adamantive drill
- B. Automatic drill
- C. Double core barrel drill
- D. Flat drill

Answer: A

A grinding mill of large diameter with either lumps of ore pebbles or steel balls as crushing bodies the dry lead is air swept remove mesh material.

- A. Aerial speed
- B. Aero fall mill
- C. Aero motor
- D. Ball mill

Answer: B

A tool - steel cutter used for - finishing surfaces of angles greater than or less than 90° with its axis of rotation called:

- A. Angle cutter
- B. Asphalt cutter
- C. Circular cutter
- D. Helical cutter

Answer: A

When installing a new grinding wheel, always use:

- A. Blotting paper gaskets on each side of the wheel
- B. Copper gasket on each side of the wheel
- C. Only the steel washers provided with the machine
- D. None of the above

Answer: A

The operation of "truing" a grinding wheel is known as:

- A. centering
- B. dressing
- C. sizing
- D. rounding

Answer: B

The tool used to check external pipe threads is called a:

- A. plug gage
- B. thread gage
- C. pitch gage
- D. ring gage

Answer: D

The tool used to check internal pipe threads is called a:

- A. plug gage
- B. thread gage
- C. pitch angle
- D. ring gage

Answer: A

The tool used to cut gears is called a:

- A. gear cutter
- B. gear hob
- C. gear center
- D. gear threader

Answer: B

If use a dry grinding wheel for sharpening tool bits, dip the end of the bit in water frequently to prevent-

- A. burning your fingers
- B. annealing the cutting edge of the bit
- C. hardening of the tip
- D. the tip from crysallizing

Answer: B

CNC in machine shop means

- A. Communication Network Control
- B. Computer Network Center
- C. Computer Number Control
- D. Computer Numerical Control

Answer: D

It is the time lost due to breakdowns, waiting for tools, minor accidents etc.

- A. Down time
- B. Handling time
- C. Machining time
- D. Set up time

Answer: A

Refers to the process of separating or removing the burning or combustible material from the neighborhood of the fire.

- A. Blanketing
- B. Combustion
- C. Cooling
- D. Starvation

Answer: D

What is the necessity of giving tolerance?

- A. It saves the labor charges
- B. Its saves the material from wastage
- C. It saves the time
- D. All of the above

Answer: D

It is done then and there by adjusting or repairing the faults come in notice during work.

- A. Corrective maintenance
- B. Predictive maintenance
- C. Preventive maintenance
- D. Routine maintenance

Answer: D

Which statement does NOT belong to the function of bearings?

- A. To give free rotation to the shaft
- B. To guide the shaft
- C. To support the shaft
- D. To transmit power

Answer: D

A "pillar" file has:

- A. One safe edge
- B. Three safe edges
- C. Two safe edges
- D. A or C

Answer: D

In general, files are divided into two classes called:

- A. Single - cut and double - cut
- B. Fine and coarse
- C. Rough and smooth
- D. Heel and sizes

Answer: A

The length of a file is measured from:

- A. End to end
- B. Point to heel
- C. Point to end
- D. Heel to end

Answer: B

A "pillar" file is used for:

- A. Filling slots
- B. Filling keyways
- C. Filling against a shoulder
- D. Any of the above

Answer: D

A flexible hacksaw blade has a tendency to:

- A. Snap easily
- B. Buckle or run out of line when too much pressure is applied
- C. Cut too fast
- D. Cut on a slant

Answer: B

Soldering is the process of:

- A. Holding two metals together by heating
- B. Joining two metals by third soft metal that is applied in a molten state
- C. Holding two different kinds of metals together by heating

D. Joining two metals together by heating

Answer: B

When soldering, flux is used to;

- A. Keep the solder from running off the metal
- B. Keep the metal from getting too hot
- C. Keep the tip of the soldering iron clean
- D. Remove and prevent oxidation of the metals

Answer: D

What is used to connect the shaft whose axes are intersecting?

- A. Flexible coupling
- B. Oldham coupling
- C. Rigid coupling
- D. Universal coupling

Answer: D

It is generally used on high speed with light load because it has point contact.

- A. Ball bearing
- B. Metal bearing
- C. Roller bearing
- D. Wood bearing

Answer: A

It is generally used on high speed with heavy load because it has line contact.

- A. Ball bearing
- B. Metal bearing
- C. Plastic bearing
- D. Roller bearing

Answer: D

It is a process of enlarging and smoothening the punched hole by means of tapered drifts of various sizes and shape.

- A. Drawing out
- B. Drifting
- C. Jumping
- D. Upsetting

Answer: B

It is a set of gears fitted in different position on a plate which are controlled by a lever.

- A. Differential gear
- B. Gear train
- C. Stud gear
- D. Tumbler gear

Answer: D

An instrument for determining the relative hardness of material by a drop and rebound method.

- A. Brinell hardness tester
- B. Rockwell hardness tester
- C. Scleroscope

D. Universal testing machine

Answer: C

An instrument for measuring the degree of surface roughness in micro inches.

- A. Caliper
- B. Micrometer
- C. Profilometer
- D. Scleroscope

Answer: C

These spindle of the grinding machine on which the wheel is mounted.

- A. Arbor
- B. Bearing
- C. Bushing
- D. Fluting

Answer: A

A device for holding grinding wheels of special shape or the working piece - being grounded.

- A. Chuck
- B. Fixtures
- C. Head stock
- D. Jigs

Answer: A

Grinding the grooves of a twist drill or tap.

- A. Flaring
- B. Fluting
- C. Honing
- D. Lapping

Answer: B

The dulling of the cutting particles of a grinding wheel resulting in a decreased rate of cutting is called

- A. fluting
- B. glazing
- C. grinding
- D. lapping

Answer: B

The process of lengthening a piece of stock while the cross-sectional area is being reduced

- A. Drawing
- B. Honing
- C. Tapping
- D. Upsetting

Answer: A

The major factors, which determined the rpm on milling cutter, are the material being cut and

- A. depth of the cutter

- B. diameter of cutter
- C. number of teeth in cutter
- D. time allowed to complete the job

Answer: D

Electron beam machining process is quite suitable for a material having

- A. high melting point and high thermal conductivity
- B. high melting point and low thermal conductivity
- C. low melting point and low thermal conductivity
- D. low melting point and high thermal conductivity

Answer: B

Grinding is what type of operation?

- A. Metal finishing operation
- B. Metal fusing operation
- C. Metal powdering operation
- D. metal surfacing operation

Answer: A

Grinding is done wherever

- A. a large amount of material is to be removed
- B. a small amount of material is to be removed
- C. high accuracy is required
- D. other machining operations can not be carried out

Answer: C

Laser beam machining process is used to machine

- A. heavier materials
- B. lighter materials
- C. thicker materials
- D. thinner materials

Answer: D

A hard grade-grinding wheel is suitable for grinding

- A. both hard and soft materials
- B. hard materials
- C. smooth materials
- D. soft materials

Answer: D

The usual ratio of forward and return stroke, in quick mechanism of shaping machine is

- A. 3:1
- B. 3:2
- C. 5:2
- D. 6:8

Answer: B

Solder will not unite with metal surface that has:

- A. grease on it
- B. dirt on it

- C. oxidation on it
- D. any of the above

Answer: D

Prepared soldered paste flux is most popular but if you did not have any, you should use:

- A. hydrochloric acid
- B. sulphuric acid
- C. nitric acid
- D. any of the above

Answer: A

Another name for hydrochloric acid is:

- A. sulphuric acid
- B. muriatic acid
- C. nitric acid
- D. acetic acid

Answer: B

Hard solder is made of:

- A. copper and zinc
- B. tin and zinc
- C. tin and copper
- D. tin and lead

Answer: A

Soft solder is made of:

- A. copper and zinc
- B. tin and lead
- C. tin and copper
- D. tin and zinc

Answer: B

Soft solder melts at approximately:

- A. 250 deg.
- B. 350 deg.
- C. 450 deg.
- D. 550 deg.

Answer: B

The flux usually used for hard solder is:

- A. rosin
- B. borax
- C. barium
- D. alum

Answer: B

Which of the following is a boring machine tool used particularly for large work place, types are horizontal and vertical?

- A. Boring mill
- B. Burrstone mill
- C. Cage mill
- D. Chile mill

Answer: A

A tap with a chamfer 1 - 1 ½ threads in length

- A. Bottom tap
- B. Center tap

- C. Plug tap
- D. Taper tap

Answer: A

A small portable hand drill customarily used by hand setters to drill the holes in breast called

- A. spiral drill
- B. diamond drill
- C. churn drill
- D. breast drill

Answer: D

A job, which is fixed away from the table, can be machined by

- A. running head
- B. moving head
- C. static head
- D. traveling head

Answer: D

Shaper tools are made of

- A. cast iron
- B. high speed steel
- C. mild steel
- D. wrought iron

Answer: B

Refers to the unit can be moved longitudinally along the swivel table and is clamped in position by two bolts one on either side of the base

- A. Cross stock
- B. Foot stock
- C. Head stock
- D. Tail Stock

Answer: C

When a lathe is put into back gear, it will go:

- A. at the same speed backwards
- B. slower
- C. faster
- D. at a slower speed backwards

Answer: B

When using a drill press, the work should be held with

- A. the hand
- B. a pair of pliers
- C. a vise or clamp
- D. gloves on

Answers: C

When drilling a hole in a piece of work held in a lathe chuck, and would use the:

- A. compound rest
- B. cross-feed
- C. tailstock and drill chuck
- D. headstock

Answer: C

Copper is annealed by heating to a cherry red color and:

- A. dousing in cold water
- B. cooling slowly in air
- C. dousing with oil
- D. dousing in hot water

Answer: B

The purpose of "annealing" is to make a metal:

- A. harder
- B. medium - hard
- C. softer
- D. shiny

Answer: C

The purpose of "tempering" is to make a metal:

- A. harder
- B. softer
- C. less brittle
- D. more brittle

Answer: C

The minimum diameter of a piece of round stock necessary to make a square key $\frac{3}{4}$ " on a side is:

- A. 1.5"
- B. 1.06"
- C. 1.0"
- D. .75"

Answer: B

A fine grained, salty silica rock used for sharpening edge tools

- A. Oilstone
- B. Peeblestone
- C. Surface grinder
- D. Rocky oil

Answer: A

A hand tool used to measure tension on bolts

- A. Hammer
- B. Plier
- C. Screw driver
- D. Torque range

Answer: D

A hand tool used to measure engine crank web deflection

- A. compound gage
- B. dial gage
- C. distortion gage
- D. feeler gage

Answer: C

A kind of chuck, which has reversible jaws, which could be adjusted separately

- A. Combination chuck
- B. Independent chuck
- C. Magnetic chuck
- D. Universal chuck

Answer: B

A method whereby a gear is run with another gear that has abrasive surface material

- A. hobbing
- B. honing
- C. lapping
- D. milling

Answer: C

Is the process of cold works where a limited amount of material, resulted to a higher strength and it leaves a surface under compressive stress

- A. surface finishing
- B. smoothing
- C. surfacing
- D. surface rolling

Answer: D

Is largely used for low strength application such as elevator ropes not used for hoisting and for stationary guy ropes

- A. steel rope
- B. cast steel rope
- C. nylon rope
- D. iron wire rope

Answer: D

Nitriding process of surface treatment for steel tools is used for tools taking

- A. heavy cuts
- B. light cuts
- C. medium cuts
- D. straight cuts

Answer: B

At a very low cutting speeds the tool wear is due to

- A. hardness
- B. material
- C. plowing action
- D. transfer

Answer: C

They are mixtures of lard, cottonseed or rapeseed oils and mineral oils are called

- A. Cooling oils
- B. Cutting oils

- C. Heating oils
- D. Emulsions

Answer: B

How is the height of a bench vice adjusted?

- A. By using a wooden plate form
- B. By using a wooden packing piece under the vice base
- C. By using a vice adjusting fixture
- D. All of the above

Answer: D

Why hacksaw blade teeth get dullness?

- A. Coarse pitched blade is used on hard metal
- B. Pressure is not released in return stroke
- C. Too much speed and pressure
- D. Any of the above

Answer: D

Files are classified according to

- A. grade and cut
- B. shape
- C. size and length
- D. all of the above

Answer: D

How are rivets made?

- A. Cold pressing
- B. Drawing
- C. Hot rolling
- D. Rolling

Answer: A

What support the top rake?

- A. Front clearance
- B. Side clearance
- C. Side rake
- D. Top rake

Answer: A

Which of the following reduces the rubbing action?

- A. Front clearance
- B. Side Clearance
- C. Side rake
- D. Top rake

Answer: A

Which of the following is used for all general purposes?

- A. Forging
- B. Production slotter
- C. Puncher slotter
- D. Tool room slotter

Answer: C

It is an operation of milling the complex surfaces with the help of a group of cutters mounted on the same arbor

- A. Climb milling
- B. Down milling
- C. Gang milling
- D. Straddle milling

Answer: D

It is an operation to divide the periphery of the job into number of equal parts

- A. Dividing head
- B. Indexing
- C. Protractor
- D. Slotting

Answer: B

The angle formed between the face of a tool and the work surface or the tangent to the work piece at the point of contact with the tool called

- A. clearance angle
- B. cutting angle
- C. rake angle
- D. wedge angle

Answer: B