

INFORMATION DISPLAY DIVISION

IDD MAINTENANCE AGREEMENT PROMOTION SERVICE PLAN 12/14/79

Reference: Field Service Folder

The IDD Maintenance Agreement Promotion Field Service Folder has a Tek part number which is orderable via normal channels. When you order the folder, you should state the quantity and part number, AX-4816. If you want the folders stuffed with the Stan Kouba letter, Field Service Program Brochure and Tek Field Office location sheets, state the word "Stuffed" after the part number of the folder.

--Jim Tiano
63/503, ext. 3701

4052/4054 MISLABLED IC'S ON MAS BOARD

Some 4052/4054 MAS Boards may contain a mislabeled IC in 7 locations. The chip is actually a 74LS645 which is labeled 74LS245, the date code of the mislabeled chip is 8022.

Check the following locations on the MAS Board and replace any chips with a 8022 lot date.

U495, U270, U395, U165, U170, U185, U195.

The MAS Boards with mislabeled IC's may be operational for a short time, some failures this problem will cause are parity errors, and when performing the long RAM test (64K) with the diagnostic ROM Pak the terminal will lock up when the test is complete by continually paging the screen and displaying test done.

--Frank Lees
63/503, ext. 3929