

Chapter -5 (10 marks)

- a) Describe the working principle of three phase induction generator. Also explain how voltage build up in it. [4+4]

Derive torque developed by a 3-phase induction motor at running condition. Draw a Torque-slip characteristic and deduce the condition for maximum torque? [5+3]

Draw the equivalent circuit diagram of three phase induction motor. Explain how the torque is produced in three phase induction motor. [8]

- 1) Define slip. Why does the induction motor operates only in the linear portion of torque-slip characteristics? [4]
2) A three phase 6 pole, 50 Hz induction motor

- a) Explain the T-S characteristic of 3-phase induction motor. Explain the effect of rotor resistance on T-S characteristic. [8]

- a) Explain the operating principle of three phase induction motor with neat sketches. Why rotor speed is always less than synchronous speed. Justify. [8]
b) An alternator on open circuit generates 260V at 60 Hz. [6+2]

Explain the torque-slip characteristics of a three phase induction motor. Starting with the expression for torque as a function of slip, show that the value of maximum torque is independent of rotor resistance. [6]

- a) Explain the torque-slip characteristics of an induction motor. Show the condition for which the maximum torque develops in the induction motor. [5+3]

- b) Explain torque-slip characteristics of 3 phase induction. Deduce the condition for which maximum torque. Discuss the effect of variation of rotor resistance on this maximum torque.

Draw equivalent circuit of 3 phase induction motor at stand still and running conditions. Derive the expression for starting torque and running torque.

What will be the condition for maximum torque and explain torque slip characteristics of 3-phase induction motor. [6]

[8]


- a) Explain the torque-slip characteristics of 3 phase induction motor. Show the condition for which the maximum torque develops in the induction motor. Discuss the effect of variation of rotor resistance on this maximum torque.

[8]

3-phase induction machine

Construction → not asked

Operating of 3 ϕ induction motor (IOE)



- 3 ϕ ac voltage is supplied to 3 ϕ stator winding
- 3 ϕ ac current flows through it and they generate a rotational magnetic field (RMF)
- The synchronous speed (N_s) of this field is determined by the supply frequency (f) and the no of poles (P)

$$N_s = \frac{120f}{P} \text{ (in RPM)}$$

- This rotating stator field cuts across the rotor conductors, inducing an emf (Faraday's law). And current flows through the rotor conductor.
- Now, the current carrying rotor conductors are lying in the magnetic field so force will develop on the rotor conductor. ——— It produces a torque (Lorentz force) causing the rotor to spin in the direction of RMF.

→ This rotor cannot reach synchronous speed (N_s) because there would be no relative motion to induce currents. The difference between N_s and rotor speed (N_r) is called slip (s).

$$s = \frac{N_s - N_r}{N_s}$$

→ slip is for torque production, at standstill (startup) slip is 1 (max), decreasing as the rotor accelerates.

→ Under the action of the produced torque the rotor conductor will rotate with speed N_r .

$$(N_r < N_s)$$

→ This is the basic operating principle of 3 ϕ induction motor.

* Torque Equation (TOE)

→ The circuit at 3 ϕ induction motor is same as at 3 ϕ transformer.

$$p = r \cdot O$$

(active com.)


Torque developed at standstill is :

$$T_s \propto \phi_{av} I_2 \cos \phi_2$$

$$T_s \propto V_2 I_2 \cos \phi_2$$

$$T_s \propto E_2 I_2 \cos \phi_2$$

$$\therefore \boxed{T_s = k E_2 I_2 \cos \phi_2} \quad \text{--- (ii)}$$



from (i) and (ii)

$$T_s = k E_2 \left(\frac{I_2}{\sqrt{R_2^2 + X_2^2}} \right) \left(\frac{R_2}{\sqrt{R_2^2 + X_2^2}} \right) \quad \leftarrow \begin{matrix} R_2 \cos \phi_2 \\ = \frac{R_2}{Z_2} \end{matrix}$$

$$\boxed{T_s = \frac{k R_2 E_2^2}{(R_2)^2 + (X_2)^2}}$$

→ torque developed at initial (stand still) condition

At running condition mainly changes occurs in E_2 , f and X_2

in rotor

$$\text{so, } E_R = s E_2, \quad f_R = s f, \quad X_R = s X_2$$


Now,

kvl

$$I_2 = \frac{SE_2}{R_2 + j(sX_2)} = \frac{SE_2}{\sqrt{R_2^2 + (sX_2)^2}} \quad \text{--- (i)}$$

$$\phi_R = \tan^{-1} \left[\frac{SE_2}{R_2} \right] \quad \left(I_2 \text{ lags } SE_2 \text{ by } \phi_R \right)$$

Torque developed by rotor at running condition



$$T_R \propto \phi_{air} \cdot I_2 \cos \phi_R$$

$$T_R = k E_2 I_2 \cos \phi_R$$

$$T_R = k E_2 \cdot \left[\frac{SE_2}{\sqrt{(R_2)^2 + (sX_2)^2}} \right] \cdot \frac{R_2}{\sqrt{(R_2)^2 + (sX_2)^2}}$$

$$= \frac{k \cdot s \cdot R_2 \cdot E_2^2}{(R_2)^2 + (sX_2)^2}$$

At startup $N_s \rightarrow 0$

$$s = \frac{N_s - N_r}{N_s} = 1$$

$$T_s = \frac{k E_2^2 R_2}{(R_2)^2 + (X_2)^2}$$

Torque - Slip characteristics (JOE) V Imp

→ Torque developed by the rotor during running condition is :

$$T_R = \frac{s R_2 k E_2^2}{(R_2)^2 + s^2 X_2^2} \quad \text{--- (i)}$$

$$s = \frac{N_s - N_r}{N_s} \quad \begin{array}{l} \text{rotor speed} \\ \text{speed of rotation mag flux} \end{array}$$

$$N_r < N_s$$

at normal operating range

Slip (s) is very small

$$s^2 = \text{very small}$$

$$s^2 X_2^2 \ll R_2^2$$

So,

$$T_R = \frac{s R_2 k E_2^2}{(R_2)^2} = \frac{k s E_2^2}{R_2}$$

∴ $T_R \propto s$ (Slip decreases as torque decreases and increases as torque increases)

At overload condition,

Slip (s) will not be small

s^2 will be significant

$$\text{So, } R_2^2 \ll s^2 X_2^2$$

eqn (i) become

$$T_R = \frac{k s E_2^2 R_2}{s^2 X_2^2} = \frac{k E_2^2 R_2}{s X_2^2}$$

$$T_R \propto \frac{1}{s}$$

as slip decreases, torque increases



Condition at max torque (ToK)

→ At a particular value of slip (s_m) the rotor will develop max torque (T_{max})

$$\text{Let } V = \frac{1}{T_R} = \frac{1}{\frac{s R_2 k E_2^2}{R_2^2 + s^2 X_2^2}} = \frac{R_2^2 + s^2 X_2^2}{s R_2 k E_2^2}$$

$$QV_1 \quad Y = \frac{R_1^2}{s R_2 k E_2^2} + \frac{\frac{1}{2} x_2^2}{s R_2 k E_2^2}$$

As $\frac{dY}{ds} = 0$, Tr will be max, There $\Rightarrow sm$

$$\frac{dY}{ds} = \frac{R_1^2}{R_2 k E_2^2} \cdot \frac{d[s]}{ds} + \frac{x_2^2}{R_2 k E_2^2} \frac{ds}{ds}$$

$$0 = \frac{R_1}{k E_2^2} (-1) \cdot sm^{-2} + \frac{x_2^2}{R_2 k E_2^2}$$

$$QV_1 \quad 0 = - \frac{R_1}{k E_2^2 sm^2} + \frac{x_2^2}{R_2 k E_2^2}$$

$$QV_1 \quad \frac{R_1}{k E_2^2 sm^2} = \frac{x_2^2}{R_2 k E_2^2}$$

$$QV_1 \quad \left(\frac{R_1}{x_2} \right)^2 = (sm)^2$$

\therefore $\boxed{sm = \frac{R_1}{x_2}}$ at this sm , torque will be max

$$T_{max} = \frac{sm R_2 k E_2^2}{(R_1)^2 + (sm x_2)^2} = \frac{\frac{R_1}{x_2} R_2 k E_2^2}{R_1^2 + \left(\frac{R_1 \cdot x_2}{x_2} \right)^2}$$

$$T_{max} = \frac{(\cancel{R_2})^2 \cdot k \cdot E_2^2}{X_2^2}$$

$$= \frac{k E_2^2}{2 X_2}$$

$$\therefore T_{max} = \frac{k E_2^2}{2 X_2} \quad \text{at } s = s_m = \frac{R_2}{X_2}$$

Effect of Rotor resistance on torque-slip (TSE)

→ If R_2 is increased $R_2(\text{new}) > R_2(\text{old})$

<p>at operating</p> $T_R = \frac{k s E_2^2}{R_2(\text{new})}$	<p>previous both area</p>	<p>at maximum</p> $T_R = \frac{k E_2^2 R_2(\text{new})}{s X_2}$
---	-------------------------------	---


$R_2(\text{new}) \uparrow \quad T_R \downarrow$

$R_2 \uparrow \quad T_R \uparrow$

$$\uparrow s_m = \frac{R_2(\text{new})}{X_2} \uparrow$$


→ starting torque increases

→ running torque decreases



Testing (not main priority)


① No-load test (iron loss)



$$W_0 = W_1 + W_2 = \sqrt{3} V_p I_0 \cos \phi_0$$

$$\cos \phi_0 = \frac{W_0}{\sqrt{3} V I_0}$$


$$\phi_0 = ?$$



$$R_0 = \frac{V_p}{I_w}$$

$$X_0 = \frac{V_p}{I_w}$$

cii) Blocked Rotor test \rightarrow SC test of transformer



$$Z_{01} = \frac{V_p}{I_{sc}} = \frac{V_{sc}}{\sqrt{3} I_{sc}}$$

$$R_{01} = \frac{W_0}{I_{sc}^2}$$

$$X_{01} = \sqrt{Z_{01}^2 - R_{01}^2}$$

$$\text{cu-loss} = I_{sc}^2 \times R_{01}$$

#1 η at 3 ϕ induction motor

$$\text{i/p power to rotor} = T_R \times \frac{2\pi N_s}{60}$$

$$\text{o/p power by rotor} = T_R \times \frac{2\pi N_r}{60}$$

Rotor Cu-loss = $S \times$ input power to rotor


$$\eta_r = \frac{\text{Power developed by rotor}}{\text{Input power to rotor}}$$

$$\eta_r = \frac{N_r}{N_s}$$

$$\text{Output } \eta_o = \frac{\text{Power developed by shaft}}{\text{Input power to starter}}$$

3 ϕ induction generator

#1 Working (SOF) \rightarrow (motor is main source turn over occasion may arise)



- A turbine provides mech power to the rotor
- The rotor starts rotating at speed higher than synchronous speed ($N_r > N_s$).

- In normal induction motor, slip (s) is positive

$$s = \frac{N_s - N_r}{N_s}$$

- In generator mode, the rotor moves faster than the synchronous speed, making slip negative.

$$s = \frac{N_s - N_r}{N_s} < 0$$

- This negative slip reverse the power flow, converting mechanical into electrical energy.

- The rotor has a rotating magnetic field due to residual mag flux

- as the rotor spins faster, it cuts the stator windings, inducing an opposite direction emf in stator coils.

- The induced voltage in the stator windings causes current flow, producing a three-phase ac output.

- This is the basic operation of 3 ϕ induction generator

Voltage Build up - process for 3 ϕ induction generator (sometimes) (TOE)

- The rotor has a small amount of leftover mag field from previous operation.
- A turbine spins the rotor at high speed.
- As the rotor spins, its residual magnetic field moves past the stator windings, inducing a small emf in it.
- Capacitors are connected in stator terminals allowing a leading current to flow due to small emf.
- The stronger mag field induces an even higher emf in the stator windings.
- This process repeats in a positive feedback loop - higher the emf leads to more current which increases the magnetic field further until the magnetic core sat saturates, stabilizing the voltage.
- Once stabilized, the generator produces a steady 3-phase AC voltage at the stator terminals, ready to power a load.