

Summary report

Wellbore: 15/9-19 ST2

Period: 1993-04-12 00:00 - 1993-04-13 00:00

Status:	normal
Report creation time:	2018-05-03 13:53
Report number:	148
Days Ahead/Behind (+/-):	
Operator:	Statoil
Rig Name:	TREASURE PROSPECT
Drilling contractor:	UNKNOWN
Spud Date:	1992-09-15 01:00
Wellbore type:	
Elevation RKB-MSL (m):	22
Water depth MSL (m):	84
Tight well:	Y
HPHT:	Y
Temperature ():	
Pressure ():	
Date Well Complete:	1993-01-28

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia ():	
Pressure Test Type:	
Formation strength ():	
Dia Last Casing ():	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMd:	-999.99
Depth mTVD:	
Plug Back Depth mMD:	
Depth at formation strength mMD:	
Depth At Formation Strength mTVD:	
Depth At Last Casing mMD:	4640
Depth At Last Casing mTVD:	

Summary of activities (24 Hours)

*CHANGED OUT DAMAGED SEALS ON SHEAR RAM UPPER SEAL SEAT.
*PRESSURE TESTED BOP. CHANGED OUT 2 SPM VALVES. REMOVED LOOSE RUBBER LIP FROM LAP-ELEMENT.

Summary of planned activities (24 Hours)

*RE-RUN BOP. PRESSURE TEST WELLHEAD CONNECTOR AND K/C-LINES.
FUNCTION TEST BOP.
*CHANGE OUT SEAL ASSEMBLY TO METAL-TO-METAL SEAL.
*RE-RUN DST STRING.

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	06:00	0	interruption -- repair	ok	CONT. INVESTIGATING LEAK. OPENED RAM DOORS TO CHECK SEALS. CHECKED RAM OPERATION. FOUND O-RINGS EXTRUDED OUT OF UPPER SEAL SEAT. PREPARED TO REMOVE UPPER SEAL SEAT TO CHANGE OUT O-RINGS.
06:00	15:30	0	interruption -- repair	ok	REMOVED SHEAR RAM UPPER SEAL SEAT. CHANGED OUT O-RINGS AND BACK-UP RING, RE-INSTALLED SEAL SEAT. CLOSED RAM DOORS.
15:30	19:00	0	interruption -- repair	ok	PREPARED TO TEST STACK. ATTEMPTED PRESSURE TESTING SHEAR RAM TWICE, NEGATIVE. PRESSURE TESTED SHEAR RAM OK ON THIRD ATTEMPT TO 20/345 BAR, 5/10 MINS.
19:00	21:30	0	interruption -- repair	ok	FILLED STACK. INSTALLED TEST TOOL. ATTEMPTED PRESSURE TESTING LAP TO 20/345 BAR, NEGATIVE, LEAKED 1 BAR/MIN ON HP-TEST. FUNCTIONED LAP TWICE. SPM-VALVE FAILED.
21:30	22:30	0	interruption -- repair	fail	CHANGED OUT 2 EA SPM VALVES FOR LAP, ON YELLOW POD.
22:30	00:00	0	interruption -- repair	ok	OPERATED LAP SEVERAL TIMES. ATTEMPTED PRESSURE TESTING, NEGATIVE.

Drilling Fluid

Sample Time	23:00
Sample Point	
Sample Depth mMD	-999.99
Fluid Type	BRINE
Fluid Density (g/cm3)	1.15
Funnel Visc (s)	-999.99
Mf ()	
Pm ()	
Pm filtrate ()	
Chloride ()	
Calcium ()	
Magnesium ()	
Ph	
Excess Lime ()	
Solids	
Sand ()	
Water ()	
Oil ()	
Solids ()	
Corrected solids ()	
High gravity solids ()	
Low gravity solids ()	
Viscometer tests	
Plastic visc. (mPa.s)	-999.99
Yield point (Pa)	-999.99
Filtration tests	
Pm filtrate ()	
Filtrate Lthp ()	
Filtrate Hthp ()	
Cake thickn API ()	

Cake thickn HPHT ()	
Test Temp HPHT ()	
Comment	