

Summary report

Wellbore: 15/9-F-15

Period: 2008-11-22 00:00 - 2008-11-23 00:00

Status:	normal
Report creation time:	2018-05-03 13:52
Report number:	49
Days Ahead/Behind (+/-):	
Operator:	StatoilHydro
Rig Name:	MÆRSK INSPIRER
Drilling contractor:	Maersk Drilling
Spud Date:	2008-10-24 00:00
Wellbore type:	
Elevation RKB-MSL (m):	54.9
Water depth MSL (m):	91
Tight well:	Y
HPHT:	Y
Temperature (I):	
Pressure (I):	
Date Well Complete:	2008-12-11

Dist Drilled (m):	-999.99
Penetration rate (m/h):	-999.99
Hole Dia (in):	8.5
Pressure Test Type:	formation integrity test
Formation strength (g/cm3):	1.5
Dia Last Casing (I):	

Depth at Kick Off mMD:	
Depth at Kick Off mTVD:	
Depth mMd:	3670
Depth mTVD:	2910
Plug Back Depth mMD:	
Depth at formation strength mMD:	1381
Depth At Formation Strength mTVD:	1349
Depth At Last Casing mMD:	2534
Depth At Last Casing mTVD:	2348.8

Summary of activities (24 Hours)

None

Summary of planned activities (24 Hours)

None

Operations

Start time	End time	End Depth mMD	Main - Sub Activity	State	Remark
00:00	03:15	0	drilling -- bop activities	ok	Picked up jet sub. Ran in and jet washed the BOP. Picked up the test plug. RIH and jet washed the WH. Landed of test plug.
03:15	04:00	0	drilling -- bop activities	ok	Held tool box talk prior to perform BOP test. Made up pup jnt and swadge to TDS.
04:00	06:00	0	drilling -- bop activities	ok	Started pressure testing of the BOP 345 bars.
06:00	11:15	0	drilling -- bop activities	ok	Continued to pressure test BOPs as per procedure, 30/345 bars 5/ 10 mins. Meanwhile pressure tested upper lower IBOPs & Kelly hose.
11:15	12:15	0	drilling -- wait	ok	Left drill floor due to exhaust (CO levels @ 60 ppm), monitor area until clear reading on sensors.
12:15	14:00	0	drilling -- bop activities	ok	Held tool box talk and broke test assembly from TDS, laid out same.
14:00	14:30	0	interruption -- maintain	ok	Checked dies on PRS, cleaned & cleared drill floor prior to pick up BHA #2. BX elevator not operating probably.
14:30	15:00	0	interruption -- repair	ok	Changed out BX elevators due to latching problem, back up set would not work, installed original elevator & investigated problem with latch.
15:00	17:30	0	drilling -- trip	ok	Held tool box talk and started to pick up 8½" BHA.
17:30	18:15	0	drilling -- trip	ok	Held tool box talk and loaded the radio active source to Ecoscope assembly.
18:15	20:45	180	drilling -- trip	ok	Changed BX inserts to 5" DP. Continued to RIH with 8½" BHA to 180m.
20:45	21:00	180	drilling -- trip	ok	Changed out master bushing to PS 21 slips.
21:00	23:00	992	drilling -- drill	ok	Continued to RIH with 8½" BHA on 5" DP from 180m to 992m.
23:00	00:00	992	drilling -- survey	ok	Made up X-over to 5½". Filled the DP, Staged up pumps until static active volume was established, prior to test of MWD.