


Chapter 3: Sheet Metal Processing [Shearing, Blanking & Punching] (Lecture 8)



Deformation Processes  
>> Starting workpart is shaped by application of forces that exceed the yield stress of the material  
>> Examples: (a) forging and (b) extrusion



Stress-Strain Relationships  
>> Types of Static Stresses:  
1. Tensile – stretching (pull) the material  
2. Shear - causing adjacent portions of the material to slide against each other (apply forces in opposite direction)  
3. Compressive – squeezing the material

Tensile Test  
Engineering stress:  
 $\sigma_e = \frac{F}{A_0}$   
Engineering strain:  
 $e = \frac{L - L_0}{L_0}$

Tensile Test Sequence  
>> (1) No load; (2) uniform elongation; (3) Maximum load; (4) necking; (5) fracture; (6) putting pieces back together to measure final length



Strain/Work Hardening  
>> What is happening between Y and TS on the curve  
>> defined as metal becoming stronger as strain increases


Shear Stress  
>>  $F$  = applied force;  
 $A$  = area where force is applied  
 $\tau = \frac{F}{A}$

Shear Strain  
>>  $\delta$  = deflection of the element;  
 $b$  = distance over which deflection occurs  
 $\gamma = \frac{\delta}{b}$

Shear Stress  
>> Shear stress at fracture = shear strength  $S$   
>> Shear strength can be estimated from tensile strength:  $S \approx 0.7(TS)$  (use when only tensile strength is given)

Basic Types of Metal Forming Processes  
>> Bulk deformation – start with a block of material and apply compression force or some tension force  
→ Compression forces: Rolling, Forging, Extrusion  
→ Tension force: Wire and bar drawing  
>> Sheet metalworking  
→ Bending operations, deep or cup drawing, shearing processes

Bulk Deformation Processes  
>> (a) Rolling, (b) forging, (c) extrusion and (d) wire and bar drawing




Sheet Metalworking  
>> Cutting and forming operations performed on relatively thin sheets of metal  
>> Thickness of sheet metal = 0.4 mm to 6 mm (if thickness > 6 mm → plate)  
>> Operations usually performed as cold working i.e. operating temperature below 30% of melting point of the metal (Kelvin)  
>> Most commonly used metals: low carbon steel (0.06 to 0.15% carbon), aluminum and titanium

Advantages of Sheet Metal Parts  
>> High strength; Good dimensional accuracy; Good surface finish; Relatively low cost; Economical mass production for large quantities


Sheet Metalworking Terminology  
>> Punch-and-die = tooling to perform cutting, bending, and drawing  
>> Stamping press = machine tool that performs most sheet metal operations  
>> Stampings = sheet metal products

Shearing  
>> Cutting material without producing chips (unlike machining)

Sheet Metal Cutting  
(1) Just before the punch contacts the workpiece; (2) the punch pushes into the workpiece, causing plastic deformation; (3) the punch penetrates into the workpiece causing a smooth cut surface; and (4) fracture is initiated at opposing cutting edges to separate the sheet




Characteristics of Shear Edges  
Rollover - Depression made by the punch prior to cutting  
Burnish - Smooth region resulting from penetration of the punch prior to fracture  
Fracture zone - Relatively rough surface caused by the fracture of the metal as the punch goes down  
Burr - Sharp corner edge caused by the elongation of the metal during the final stage of separation



Shearing, Blanking and Punching  
>> Shearing to separate large sheets  
>> Blanking to cut part perimeters out of sheet metal  
>> Punching to make holes in sheet metal  
\* ALL are shearing processes, all cutting metal by shear stress if material

Blanking and Punching  
>> Blanking (a) - sheet metal cutting to separate a piece of metal (called a blank) from the surrounding sheet  
>> Punching (b) - similar to blanking except that the cut piece is scrap, called a slug




Punch and Die Sizes  
For both punching and blanking:  
Die size = Punch size + 2 x clearance  
clearance  $c$  = allowance  $a$  x thickness  $t$   
For punching: hole size = Punch size  
For blanking: blank size = Die size  
For a round blank of diameter  $D_p$ :  
• Blanking punch diameter =  $D_b - 2c$   
• Blanking die diameter =  $D_b$   
where  $c$  = clearance  
For a round hole of diameter  $D_h$ :  
• Hole punch diameter =  $D_h$   
• Hole die diameter =  $D_h + 2c$   
where  $c$  = clearance

Clearance  
>> Distance between punch cutting edge and die cutting edge  
>> Typical values range between 4% and 8% of sheet thickness:  
→ Clearance too small: cause non-optimal fracture and too large forces  
→ Clearance too big: causes oversized burr

Clearance in Sheet Metal Cutting  
>>  $c$  = clearance;  $a$  = allowance; and  $t$  = sheet thickness  
>> Allowance  $a$  is determined according to the type of metal (softer metal, deforms more, smaller allowance)

| Metal Group  | Allowance $a$ |
|--|---------------|
| 1100S and 5052S aluminum alloys, all tempers   | 0.045         |
| 2024ST and 6061ST aluminum alloys; brass, soft cold rolled steel, soft stainless steel | 0.060         |
| Cold rolled steel, half hard; stainless steel, half hard and full hard                 | 0.075         |

Angular Clearance  
>> Purpose: allows slug or blank to drop through the die  
>> Typical values: 0.25° to 1.5° on each side



Important Points  
>> SHEARING, BLANKING, & PUNCHING  
→ Determine the die and punch sizes; Clearance; Force of operation required  
>> BENDING  
→ Determine the starting blank length; Meaning of Bend allowance,  $k$  factor, neutral axis; Bending force required for certain operation  
>> DEEP DRAWING  
→ Determine starting blank size; Whether the operating is feasible; Reasons for defects


Chapter 3: Sheet Metalworking [Bending Operations] (Lecture 9)

Cutting Forces Calculation

Important for estimating the press size (tonnage)


$F = S t L = 0.7(TS) t L$

where  $S$  = shear strength of metal,  $t$  = sheet thickness, and  $L$  = length of cut edge (perimeter of the shape that is cut).




>> Assumptions:  
Neglect minor effect of clearance in calculating  $L$  (perimeter)  
Entire length is made at the same time (maximum cutting force calculated)


Shear Angles  
>> Advantages: reduces the cutting force; reduces shock on the press; cutting gradually over a longer stroke



Other Cutting Operations




Fine Blanking  
>> shearing process which produces very highly precise workpieces with completely smooth, tear-free sheared surfaces  
>> more precise, costly and complex  
>> triple action press – control cracks & clearance 1% of sheet thickness




Bending  
>> forming of solid parts, where angled or ring-shaped workpieces are produced from sheet or strip metal


Sheet Metal Bending  
>> (a) Straining of sheet metal around a straight axis to take a permanent bend  
(b) Metal on the inside of the neutral plane is compressed, while the metal on the outside of the neutral plane is stretched






Types of Sheet Metal Bending – V-bending  
>> performed with V-shaped die  
>> Low production quantity  
>> V-dies are simple & inexpensive




Types of Sheet Metal Bending – Edge bending  
bending  
>> performed with a wiping die  
>> High production quantity  
>> Dies are more complicated and costly (especially if angle > 90°)




Stretching during Bending  
>> If the bend radius  $R$  is small relative to the sheet thickness, the metal tends to stretch during bending.  
>> Important to estimate amt of stretching, so final part length = specified dimension  
>> Problem: to determine length of neutral axis of part before bending → blank size




>>  $A_b$  is the length of the neutral axis within the bended portion  
>> Neutral axis is at plane where the length before & after bending remains the same; has 0 net stress; no deformation there  
>> For bending with little stretch: (bend on big material)  
 $R \geq 2t$ ,  $K_{ba} = 0.50$   
>> For bending with large stretch: (bend on small material)  
If  $R < 2t$ ,  $K_{ba} = 0.33$



Springback  
>> Increase in the included angle of the bent part relative to the included angle of the forming tool after the tool is removed  
>> Reason: When the bending pressure is removed, the elastic energy remains in the bent part, causing it to recover partially toward its original shape  
>> seen as a decrease in bend angle and an increase in bend radius:  
(1) during bending, the workpiece is forced to take the radius  $R_t$  and angle  $\alpha_b$  of the bending tool;  
(2) after the punch is removed, the workpiece springs back to  $R$  and  $\alpha'$



Springback Compensation  
>> Methods of reducing or eliminating springback in bending operations:  
→ Overbending: bend more than required to allow for springback; e.g. included angle after bending < 90°, after springback, angle = 90°  
→ high compressive pressure causes plastic deformation at the bend area



Bending Forces

Maximum bending force is estimated as follows:


$$F = \frac{K_{bf}(TS)wt^2}{D}$$

where  $F$  = bending force;  $TS$  = tensile strength of the sheet metal;  $w$  = part width in the direction of the bend axis;  $D$  = die opening; and  $t$  = sheet thickness.

For V-bending,  $K_{bf} = 1.33$ ; for edge bending,  $K_{bf} = 0.33$ .

Die Opening Dimensions


Die opening dimension  $D$  for (a) V-die, (b) wiping die:



Chapter 3: Sheet Metalworking [Drawing Operations] (Lecture 10)




Drawing  
>> Sheet metal forming to make cup-shaped, box-shaped, or other complex-curved, hollow-shaped parts  
>> Sheet metal blank is positioned over the die cavity & then the punch pushes metal into the opening  
>> Products: beverage cans, ammunition shells, automobile body panels  
>> aka deep drawing (to distinguish it from wire and bar drawing)

Deep Drawing of a Cup  
>> (left) before the punch contacts the workpiece; (right) near end of the stroke



Clearance in Drawing  
>> Sides of punch and die separated by a clearance c given by:  
$$c = 1.1 t$$
  
where t = sheet thickness  
→ clearance ~10% greater than sheet thickness

- Drawing Sequence
- (1) Punch makes initial contact with the workpiece (blank)
  - (2) Downwards movement of the punch, metal bends along the die
  - (3) Straightening to form the cup wall, tensile stress on the cup wall
  - (4) Friction and compression; compressive stress on the flange
  - (5) Final cup shape showing effects of thinning in the cup walls



Effect of Blankholder Force  
>>  $F_h$  too low: Causes wrinkles  
>>  $F_h$  too high: prevents metal from flowing into die cavity; may cause tearing due to stretching of metal (more tension)


Tests of Drawing Feasibility  
>> Three criteria are used to test for drawability: Drawing ratio, Reduction, Thickness-to-diameter ratio

Drawing Ratio DR  
Most easily defined for cylindrical shape (e.g. cup)  
$$DR = \frac{D_b}{D_p}$$
  
where  $D_b$  = blank diameter; and  $D_p$  = punch diameter  
Indicates severity of a given drawing operation  
• Upper limit:  $DR \leq 2.0$ ; i.e. if  $DR > 2.0$ , the operation is not feasible.

Reduction R  
Defined for cylindrical shape:  
$$r = \frac{D_b - D_p}{D_b}$$
  
Value of r should be  $\leq 0.50$ .

Thickness-to-Diameter Ratio T/D<sub>b</sub>  
>> Thickness t of starting blank divided by blank diameter: Desirable for t/D<sub>b</sub> ratio to be greater than 1%; As t/D<sub>b</sub> decreases, tendency for wrinkling increases


Tests of Drawing Feasibility  
>> Conditions for drawability  
→  $DR \leq 2.0$   
→  $r \leq 0.50$   
→  $t/D_b > 1\%$   
>> If the limits on DR, r and t/D<sub>b</sub> are not respected, then the operation is not feasible in one step, redrawing is required  
A blank can be drawn in 2 steps or more with annealing between the steps (reduce stress in material; recover ductility)



Blank Size Determination  
>> After checking tests of drawing feasibility  
>> Starting sheet metal blank >= final product volume; Assume negligible thinning of part wall; Neglect die and punch radii

Drawing Force  
• Calculation of drawing force is required to determine the tonnage of the press:  
$$F = \pi D_p t (TS) \left( \frac{D_b}{D_p} - 0.7 \right)$$
  
F = maximum drawing force (N)  
 $D_p$  = punch diameter (mm)  
 $D_b$  = starting blank diameter (mm)  
t = original sheet thickness (mm)  
TS = tensile strength (MPa)  
0.7 = correction factor to account for friction

Blankholder Force or Holding Force  
• Holding pressure  $\approx 0.015 \times$  yield strength  
• Holding force  $\approx$  holding pressure x starting area of the blank held by blankholder  
$$F_h = \frac{0.015 Y \pi}{4} [D_b^2 - (D_p + 2.2t + 2R_d)^2]$$
  
 $F_h$  = blankholder force (N)  
 $D_p$  = punch diameter (mm)  
 $D_b$  = starting blank diameter (mm)  
t = original sheet thickness (mm)  
Y = yield strength of sheet metal (MPa)  
 $R_d$  = die corner radius (mm)



Reason for Earing  
>> Anisotropy of starting sheet causes earring  
Sheet metal produced by rolling

