

Use Aspire to create ShopBot tool path

HTMAA 2021, Harvard Shop



Startup Tasks

- Create a new file
- Open an existing file

Recently opened files ...

- ShopbotCut_03_threechairs.dxf
- ShopbotCut_01.dxf
- 0924CUT_05.dxf
- 0924CUT_04.dxf

Video Tutorials

- Tutorial Video Browser...

Online Resources


- Vectric Web Site
- Support Web Site
- Vectric Forum
- Vectric on Facebook
- Vectric on Twitter

Clipart & Projects

- Design & Make

2) Open an existing file


*Note : Before using Aspire, please prepare your cut design file and export in dxf file format. The sample file in this document includes three layers- 1) profile for 2mm depth engraving 2) profile for holes, and 3) profile for outmost edge of each parts.



3) Open your dxf file.




1) Launch Aspire software, the program is installed in a computer besides ShopBot and an Alienware besides electronics.




MATERIAL SETUP

Job Setup

Job Type


1  ☒ Single Sided
☐ Double Sided
☐ Rotary

Job Size


 Width (X): 1179.2 mm
Height (Y): 1185.65 mm
Thickness (Z): 12.0 mm

Units ☐ inches ☒ mm

Z Zero Position

 ☒ Material Surface
☐ Machine Bed


XY Datum Position

 ☒ Use Offset
X: 20
Y: 16.755



Design Scaling

☐ Scale design with job size

Modeling Resolution

 Standard (fastest)
1 million points

Appearance

 Solid Color
Solid Color: 



OK **Cancel**


1) Review the job size. Make sure that your design's width and height fit in your material (OSB board). Set thickness as same as thickness of your board. I checked my board is 0.465inch (11.811mm), so I set thickness as 12mm.

2) Set Z zero position as material surface

3) Set X and Y offset from left bottom corner. If you set X0 and Y0 at the left bottom end of your material in machine, your tool path will be generated offset your X Y set values. I set 16mm & 20mm offset to make sure machine does not cut edge of my board where I will place nails.

4) Press OK





MATERIAL SETUP

- Layers List
- 0
 - CUT_OUT
 - CUT_HALF
 - CUT_IN

1) Check thickness, offset, Z-Zero set up.

Material Setup

Thickness 12.0 mm

XY Datum ☒ Use Offset
X: 20.0
Y: 16.755

☒ Show detailed summary on toolpath tab

Z-Zero
☒ Material Surface
☐ Machine Bed

Model Position in Material

☒ Gap Above Model
0.0 mm
☐ Gap Below Model
12.0 mm

Model Thickness 0.0 mm
Modeling Plane Z 0.0 mm

Set...

Rapid Z Gaps above Material

Z1 Clearance (Z1) 5.08 mm
Plunge (Z2) 5.08 mm

Home / Start Position
X: 0.0 Y: 0.0

Z Gap above Material 20.32

OK

2) Press OK if everything looks fine.

POCKET CUT

[ShopbotCut_03_threeChair_Final]

3D View CUT_HALF



Toolpaths



Layers List



- 0
- CUT_OUT
- CUT_HALF**
- CUT_IN

2) Right click on the first layer you want to cut or make a pocket. Select all vector.

4) Click Pocket Cut
In this case, I do not want to cut all the way through the material. I want to cut certain depth all area inside.

Toolpath Operations



Toolpaths



No Toolpaths Created Yet

1) Click Layer


Layers

3) You will see selected vector highlighted as dashed line.

Ready

POCKET CUT

- Layers List
- 0
 - CUT_OUT
 - CUT_HALF
 - CUT_IN



1) Make sure that you are in right function, in this case Pocket Toolpath.

2) Set up Cut depth as you wish. The number must be smaller than your material thickness.

3) For tool, click select

dit Tool

Tool Info

Name: 1/8" Downcut (64-012)

Tool Type: End Mill

Notes:

Geometry

Diameter (D): 0.125 inches

Cutting Parameters

Pass Depth: 0.125 inches

Stepover: 0.06 inches 48.0 %

Feeds and Speeds

Spindle Speed: 18000 r.p.m

Feed Rate: 2.0 inches/sec

Plunge Rate: 2.0 inches/sec

Tool Number: 4

OK Cancel

Tool Database

Tool List

- Imperial Tools
 - End Mill (1.25 inches)
 - End Mill (0.0625 inches)
 - End Mill (0.0313 inches)
 - End Mills
 - End Mill (0.125 inch)
 - End Mill (0.25 inch)
 - End Mill (0.5 inch)
 - Ball Nose
 - Ball Nose (0.0625 inch)
 - Ball Nose (0.125 inch)
 - Ball Nose (0.25 inch)
 - V-Bits
 - V-Bit (60 deg 0.25")
 - V-Bit (90 deg 0.5")
 - V-Bit (90 deg 1.25")
 - Form Tools
 - Ogee - 1/4" Rads 1 1/4" Dia 1
 - Roundover - 3/8" Rad 1" Dia
 - Engraving
 - Engrave (20' 0.02" Tip Dia)
 - Specialist
 - Diamond Drag (90 deg 0.020")
 - Drills
 - Drill (0.250")
- Metric Tools

Tool Info

Name: End Mill (0.125 inch)

Tool Type: End Mill

Notes:

Geometry

Diameter (D): 0.125 inches

Cutting Parameters

Pass Depth: 0.125 inches

Stepover: 0.0925 inches 74.0 %

Feeds and Speeds

Spindle Speed: 8000 r.p.m

Feed Rate: 2.0 inches/sec

Plunge Rate: 0.5 inches/sec

Tool Number: 1

Apply

OK Cancel

4) Set up size, type, feeds and speeds of your drill bit. See sample set up from Daniel on the left. Press okay.

Toolpaths

Pocket Toolpath

Cutting Depths

Start Depth (D): 0.0 mm

Cut Depth (C): 2.0 mm

☐ Show advanced toolpath options

Tool: End Mill (0.125 inch)

Select ... Edit ...

Clear Pocket ...

☒ Offset ☐ Raster

Cut Direction

☐ Climb ☒ Conventional

Raster Angle: 0.0 degrees

Profile Pass: Last

☐ Ramp Plunge Moves

Distance: 1.0 mm

Safe Z: 5.08 mm

Home Position: X:0.00 Y:0.00 Z:20.32

Name: Pocket 1

Calculate Close

5) Press calculate

POCKET CUT

3D View

CUT_HALF

1) Automatically you will see output in 3D view. You can always change view during tool path creation

Toolpaths

Preview Toolpaths

Cherry

Solid Material Color

Machined Area Color ...

☒ Material Color

☐ Global Fill Color

☐ Toolpath Color

☐ Animate preview ☒ Draw tool

Preview Selected Toolpath

Speed

Preview All Sides

Preview All Toolpaths

Preview Visible Toolpaths

Reset Preview

Undo Last

Save Preview Image

Double click on waste areas in 3D view to remove them.

Close

☒ Toolpaths

☒ Pocket 1

2) Check your tool path placed in Toolpaths and in right order. Since this is first tool path, you will see only one tool path. Press close.


Add New Layer...


Active Sheet: 0

Drawing Modeling Clipart Layers

Ready

X:767.4966 Y:627.9026 Z: 0.0000





2D Profile Cut - Inside

Gadgets Help

2D View 3D View CUT_IN

Layers List

0
CUT_OUT
CUT_HALF
CUT_IN

Add New Layer...

Active Sheet: 0

Drawing Modeling Clipart Layers

1) You can see second tool path place under the first path you created(pocket)

Toolpaths

Preview Toolpaths

Cherry

Solid Material Color

Machined Area Color ...

Material Color

Global Fill Color

Toolpath Color

Set All

Animate preview Draw tool

Preview Selected Toolpath

Speed

Preview All Sides

Preview All Toolpaths

Preview Visible Toolpaths

Reset Preview Undo Last

Save Preview Image

Double click on waste areas in 3D view to remove them.

Close

Toolpaths


Pocket 1

Profile 3


X:921.2538 Y:564.0689 Z: 0.0000

56°F Clear ENG 1:45 AM

2D Profile Cut - Outside



1) Go to 2D view and select vectors in the last layer. In this layer, I place outer edges of my parts



2) Select 2D ProfileTool path function, as we did in previous step.


3) Set cut depth.


4) Set Tool


5) IMPORTANT, set Outside/Right when you cut outer edges of your part

6) Check Add tabs to toolpath, then set Length and Thickness for your tab. I found that 5mm/2mm works well. Click Edit Tabs to modify tab location.

7) After you set up tabs, click calculate.







2D Profile Cut - Outside

Gadgets Help

2D View 3D View CUT_OUT

Layers List

0
CUT_OUT
CUT_HALF
CUT_IN

Add New Layer...

Active Sheet: 0

Drawing Modeling Clipart Layers

Ready

DATA (D:)

PRUSA I3MK3 (E:)

Aspire 9.508 (Harvard ...)

2017

Google

Chrome

Out

X:864.7835 Y:316.8319

W:1179.200 H:1185.650 S:9

56°F Clear

ENG

1:48 AM

1) By clicking [T] sign, you can delete tabs on the edge. You can create new tabs simply by clicking on the edge. You can move your tabs by dragging the icon. Some of tabs located on joint side or curved side may not good location for the tabs. Add/Remove/Move tabs as you wish.

2) Click Close, and click Calculate

Add Tabs

☐ Constant Number 1
☒ Constant distance between tabs
Distance 200.0 mm
Min. number 1
Max. number 10

☒ First tab at machining start point

Add Tabs

Interactive tab entry

Add Tab - Click on a selected vector to insert a tab at the cursor position.


Delete Existing Tab - Click on it.

Move Tab - Click on it and drag it to the new position with the button pressed

Select or Deselect Vector - Press Shift key while clicking on the vector

Delete All Tabs

Close



2D Profile Cut - Outside

Gadgets Help

2D View 3D View CUT_OUT

Layers List

0
CUT_OUT
CUT_HALF
CUT_IN

Add New Layer...

Active Sheet: 0

Drawing Modeling Clipart Layers

Toolpaths

Preview Toolpaths

Cherry
Solid Material Color
Machined Area Color ...
Material Color
Global Fill Color
Toolpath Color
Animate preview Draw tool

Preview Selected Toolpath
Speed
Preview All Sides
Preview All Toolpaths
Preview Visible Toolpaths
Reset Preview Undo Last
Save Preview Image
Double click on waste areas in 3D view to remove them.

Close

Toolpaths

Pocket 1
Profile 3
Profile 4

1) Now you have one more 2D Profiletool path. Click Close.

Ready

DATA (D:)

PRUSA13MK3 (E:)

Aspire 9.508 (Harvard ...


56°F Clear 1:52 AM

Export Toolpath


enter - MA} - [ShopbotCut_03_threeChair_Final]

adgets Help

2D View 3D View CUT_OUT



- Layers List
- 0
 - CUT_OUT
 - CUT_HALF
 - CUT_IN



1) Review your tool path in 3D and 2D view. If you find everything placed in right position, click save icon.

Toolpaths

Material Setup

Set ... Z 0 5.08mm 12.0mm

Home Pos: X:0.0 Y:0.0 Z:20.32

XY Datum X: 20.0 Y: 16.755




- ☒ Toolpaths
- ☒ Pocket 1
 - ☒ Profile 3
 - ☒ Profile 4

Add New Layer...

Active Sheet: 0

Drawing Modeling Clipart Layers

Export Toolpath



enter - MA} - [ShopbotCut_03_threeChair_Final]

adgets Help

2D View

3D View

CUT_OUT

Layers List

- 0
- CUT_OUT
- CUT_HALF
- CUT_IN

Add New Layer...

Active Sheet: 0

Drawing Modeling Clipart Layers

Cut order 2 – Profile 3
Cut full depth (12mm) to cut hole
for chair handle. Tool path placed
inside of vector

Click to add text

Cut order 3 – Profile 4
Cut full depth (12mm) to cut
outmost edge of the part. Tool
path placed outside of vector

Cut order 1 - Pocket 1
Cut 2mm depth to engrave pattern on board.
Tool path placed inside of vector.

2) Review your setup of
drill bit for each tool path.
Click Save Toolpath and
save .sbp file.

Your file is ready to run
machine!

Toolpaths

Save Toolpaths

☒ Output all visible toolpaths to one file
☐ Output Tiled Toolpaths
☐ Add side to toolpath name

Toolpaths to be saved ...
Pocket 1
[1] End Mill (0.125 inch)
Profile 3
[1] End Mill (0.125 inch)
Profile 4
[1] End Mill (0.125 inch)

Post Processor
ShopBot (.inch)(*.sbp)
☐ Output direct to machine
Driver: ...
Save Toolpath(s) ...

Close

Toolpaths

☒ Pocket 1
☒ Profile 3
☒ Profile 4

1) Check toolpaths you
want to export. You can
selectively export tool path
in different file, or you can
export all tool path in single
file.