

# DC GENERATOR

MUBARAK

- Kerala PSC Expert

# DC Generator

Working principle

Construction

Working

Classification

Types of winding

Losses and efficiency

Armature reaction

Characteristics

Application

# Working Principle

## Faraday's law of electromagnetic induction

### First law

When a conductor moves in a magnetic field it cuts magnetic lines of force, which induces an electromagnetic force (EMF) in the conductor.



### Second Law

The magnitude of this induced EMF depends upon the rate of change of flux (magnetic line force) linkage with the conductor

# Construction

## Yoke or Frame

- Made of cast iron (small machine)
- cast steel or rolled steel (large machine)
- Mechanical support
- It carries magnetic flux



# Pole cores



## Pole cores

### Pole core

- Laminated cast iron or cast steel
- Modern machine : Thin lamination of annealed steel
- Thickness of lamination = 0.25 to 1 mm


### Pole Shoes

- Spread out the flux in the air gap
- Being large cross section , reduce the reluctance of the magnetic path.
- Support the exciting coil




# Pole Coil

- Consist of enameled copper coil
- usually finished off with an insulating varnish



# Armature core


- Houses the armature conductor
- It provides an easy path for the magnetic flux.
- silicon steel material is used
- laminated with a stamping of about 0.3 to 0.5 mm thickness
- Each lamination is insulated from the other by a coating of varnish.





# Armature winding



Consist of enameled copper coil







# Commutator

- Cylindrical in shape
- made from number of wedge-shaped hard drawn copper bars or segments insulated from each other and from the shaft.
- Each commutator segment is connected to the ends of the armature coils.
- It connects the rotating armature conductors to the stationary external circuit through brushes.
- It converts the induced alternating current in the armature conductor into the unidirectional current



# BRUSHES

- Carbon brushes are placed or mounted on the commutator
- They are usually made of high-grade carbon
- With the help of two or more carbon brushes current is collected from the armature winding.
- The brushes are pressed upon the commutator and form the connecting link between the armature winding and the external circuit.
- carbon is conducting material and at the same time in powdered form provides a lubricating effect on the commutator surface.



# BEARINGS AND SHAFT

## BEARINGS

- The ball or roller bearings are fitted in the end housings
- Mostly high carbon steel is used for the construction of bearings as it is a very hard material.

## SHAFT


- Shaft is made of mild steel with a maximum breaking strength.



# Working

The maximum emf is induced when the coil is perpendicular to the magnetic field.

The minimum emf is induced when the coil is parallel to the magnetic field




# Fleming Right Hand Rule

To find the direction of induced EMF

Thumb – Direction force or rotation

For finger – magnetic field

Middle finger – direction of induced current



# EMF EQUATION

$$E_g = \frac{\Phi Z N}{60} * \frac{P}{A}$$

$\Phi$  = flux per pole

Z = Total number of armature conductor = conductor per slots x number of slots

N = armature rotation in rpm

P = Number of poles

A = Number of parallel path



# Types of winding

## Lap winding

Number of parallel path = pole x m

## Wave winding

Number of parallel path = 2 x m

m = multiplex  
m = 1 for simplex  
m = 2 for duplex  
m = 3 for triplex  
m = 4 for quadruplex

