


DC GENERATOR

Part 4 Note

Losses



Copper losses

Armature copper loss

- About 30 to 40% of full load loss

Field copper loss

- 20 to 30 % of full load loss

Loss due to brush contact resistance

Iron loss

- Losses at core
- Also known as core losses or magnetic losses
- 20 to 30 % of full load loss

Classified into two

- Hysteresis loss
- Eddy current loss

Hysteresis loss

- This loss is due to the reversal of magnetization of the armature core.
- Energy wasted in the form of heat
- To reduce hysteresis loss, we are using silicon steel. silicon 3-4 %
- Losses calculated by Steinmetz formula.

$$W_h = \eta B_{max}^{1.6} f V \text{ watts}$$


- η = Steinmetz hysteresis constant , unit = joule/ m^2
- B_{max} = maximum flux density
- V = Volume of the core in m^3
- f = frequency
- Silicon steel = 191 joule/ m^2 cast iron = 2700-4000 joule/ m^2

Eddy current loss

- Armature cuts the magnetic flux and an emf will induce on it.
- Power loss due to flow of current through the armature core.
- By using laminated silicon steel , eddy current loss will reduce
- Power loss in the form of heat

$$W_e = K B_{max}^2 f^2 t^2 v^2 \text{ watts}$$

- K = eddy current constant
- B_{max} = maximum flux density
- V = Volume of the core in m^3
- f = frequency of magnetic reversal
- t = thickness of each lamination



- Magnetic losses are practically constant for shunt and compound generator.
 - Because field current approximately constant.

Mechanical losses

Friction loss

- At bearing and commutator


Windage loss

- Windage loss of rotating armature
- 10 to 20 % of full load loss

Stray losses

- Sum of magnetic and mechanical losses
- Also called rotational losses

Power stages of DC Generator



Generator Efficiency

- Mechanical efficiency


$$\eta = \frac{\text{total watt generated in armature}}{\text{mechanical power supplied}} = \frac{E_g I_a}{\text{output of driving engine}}$$

- Electrical efficiency

$$\eta = \frac{\text{watts available in load circuit}}{\text{total watts generated}} = \frac{VI}{E_g I_a}$$

- Overall efficiency

$$\eta = \frac{\text{watts available in load circuit}}{\text{mechanical power supplied}}$$



Condition for maximum efficiency

- Copper loss = core loss

- $I^2 R_a = W_c$

- $I = \sqrt{\frac{W_c}{R_a}}$