

# DC GENERATOR

MUBARAK

- Kerala PSC Expert

# DC Generator

Working principle

Construction

Working

Classification

Types of winding

Losses and efficiency

Armature reaction

Characteristics

Application

# Working Principle

## Faraday's law of electromagnetic induction

### First law

When a conductor moves in a magnetic field it cuts magnetic lines of force, which induces an electromagnetic force (EMF) in the conductor.



### Second Law

The magnitude of this induced EMF depends upon the rate of change of flux (magnetic line force) linkage with the conductor

# Construction

## Yoke or Frame

- Made of cast iron (small machine)
- cast steel or rolled steel (large machine)
- Mechanical support
- It carries magnetic flux



# Pole cores



## Pole cores

### Pole core

- Laminated cast iron or cast steel
- Modern machine : Thin lamination of annealed steel
- Thickness of lamination = 0.25 to 1 mm


### Pole Shoes

- Spread out the flux in the air gap
- Being large cross section , reduce the reluctance of the magnetic path.
- Support the exciting coil




# Pole Coil

- Consist of enameled copper coil
- usually finished off with an insulating varnish



# Armature core


- Houses the armature conductor
- It provides an easy path for the magnetic flux.
- silicon steel material is used
- laminated with a stamping of about 0.3 to 0.5 mm thickness
- Each lamination is insulated from the other by a coating of varnish.





# Armature winding



Consist of enameled copper coil







# Commutator

- Cylindrical in shape
- made from number of wedge-shaped hard drawn copper bars or segments insulated from each other and from the shaft.
- Each commutator segment is connected to the ends of the armature coils.
- It connects the rotating armature conductors to the stationary external circuit through brushes.
- It converts the induced alternating current in the armature conductor into the unidirectional current



# BRUSHES

- Carbon brushes are placed or mounted on the commutator
- They are usually made of high-grade carbon
- With the help of two or more carbon brushes current is collected from the armature winding.
- The brushes are pressed upon the commutator and form the connecting link between the armature winding and the external circuit.
- carbon is conducting material and at the same time in powdered form provides a lubricating effect on the commutator surface.



# BEARINGS AND SHAFT

## BEARINGS

- The ball or roller bearings are fitted in the end housings
- Mostly high carbon steel is used for the construction of bearings as it is a very hard material.

## SHAFT


- Shaft is made of mild steel with a maximum breaking strength.



# Working

The maximum emf is induced when the coil is perpendicular to the magnetic field.

The minimum emf is induced when the coil is parallel to the magnetic field




# Fleming Right Hand Rule

To find the direction of induced EMF

Thumb – Direction force or rotation

For finger – magnetic field

Middle finger – direction of induced current



# EMF EQUATION

$$E_g = \frac{\Phi Z N}{60} * \frac{P}{A}$$

$\Phi$  = flux per pole

Z = Total number of armature conductor = conductor per slots x number of slots

N = armature rotation in rpm

P = Number of poles

A = Number of parallel path



# Types of winding



## Lap winding

Number of parallel path = pole x m

## Wave winding

Number of parallel path = 2 x m


m = multiplex  
m = 1 for simplex  
m = 2 for duplex  
m = 3 for triplex  
m = 4 for quadruplex



# DC GENERATOR

Part 2 - Note

# Types of Generator



# Separately Excited

- Field magnets are energized by some external DC source

$$E_g = V + I_a R_a + 2V_b$$


$E_g$  = Generated voltage at armature

$V$  = Terminal voltage

$I_a$  = Armature current

$R_a$  = Armature resistance

$V_b$  = brush drop



$$P_{\text{generated}} = E_g I_a$$
$$P_{\text{output}} = V I_L$$

# Series Wound Generator

- Field coil connected series with armature winding
- Winding consist of thick wire of a few turns
- Normally resistance less than one ohm.

$$E_g = V + I_a (R_a + R_{se}) + 2V_b$$

$E_g$  = Generated voltage at armature

$V$  = Terminal voltage

$I_a$  = Armature current


$I_{se}$  = Series field current

$$I_a = I_{se} = I_L$$

$R_a$  = Armature resistance

$R_{se}$  = Series field resistance

$V_b$  = brush drop



$$P_{\text{generated}} = E_g I_a$$

$$P_{\text{output}} = V I_L$$

# Shunt Wound Generator

- Field winding connected across the armature
- Full voltage applied across it
- Winding consist of thin wire of a many turns
- Resistance of the order of 100 ohm.

$$E_g = V + I_a R_a + 2V_b$$

$E_g$  = Generated voltage at armature

$V$  = Terminal voltage

$I_a$  = Armature current

$I_{sh}$  = Shunt field current

$I_L$  = Load current


$$I_a = I_L + I_{sh}$$

$R_a$  = Armature resistance

$R_{sh}$  = Shunt field resistance

$V_b$  = brush drop

$$R_{sh} = \frac{V}{I_{sh}}$$



$$P_{\text{generated}} = E_g I_a$$

$$P_{\text{output}} = V I_L$$



# DC GENERATOR

Part 3 - Note

# Why Compound Generator

- In series wound generators, the output voltage is directly proportional with load current.
- In shunt wound generators, the output voltage is inversely proportional with load current.
- A combination of these two types of generators can overcome the disadvantages of both

# Long shunt Compound wound generator

- Shunt field winding parallel with both armature and series field winding

$$E_g = V + I_a (R_a + R_{se}) + 2V_b$$

$E_g$  = Generated voltage at armature

$V$  = Terminal voltage

$I_a$  = Armature current


$I_{se}$  = Series field current

$$I_a = I_{se} = I_L + I_{sh}$$

$R_a$  = Armature resistance

$R_{se}$  = Series field resistance

$V_b$  = brush drop



$$P_{\text{generated}} = E_g I_a$$

$$P_{\text{output}} = V I_L$$

# Short shunt Compound wound generator

- Shunt field winding parallel with armature only

$$E_g = V + I_a R_a + I_{se} R_{se} + 2V_b$$

$E_g$  = Generated voltage at armature

$V$  = Terminal voltage

$I_a$  = Armature current

$I_{se}$  = Series field current


$$I_a = I_L + I_{sh}$$

$$I_{se} = I_L$$

$R_a$  = Armature resistance

$R_{se}$  = Series field resistance

$V_b$  = brush drop



$$P_{\text{generated}} = E_g I_a$$

$$P_{\text{output}} = V I_L$$

# Cumulative and Differential Compound Generator

## Cumulative compound

- Magnetic flux produced by series winding assists the flux produced by shunt field winding
- **Total flux =  $\varphi_{sh} + \varphi_{se}$**

## Differential compound


- Series field flux opposes the shunt field flux
- **Total flux =  $\varphi_{sh} - \varphi_{se}$**

# DC GENERATOR

Part 4 Note



# Losses



# Copper losses

## Armature copper loss

- About 30 to 40% of full load loss

## Field copper loss

- 20 to 30 % of full load loss

## Loss due to brush contact resistance

# Iron loss

- Losses at core
- Also known as core losses or magnetic losses
- 20 to 30 % of full load loss

## Classified into two

- Hysteresis loss
- Eddy current loss

# Hysteresis loss

- This loss is due to the reversal of magnetization of the armature core.
- Energy wasted in the form of heat
- To reduce hysteresis loss, we are using silicon steel. silicon 3-4 %
- Losses calculated by Steinmetz formula.

$$W_h = \eta B_{max}^{1.6} f V \text{ watts}$$


- $\eta$  = Steinmetz hysteresis constant , unit = joule/ $m^2$
- $B_{max}$  = maximum flux density
- $V$  = Volume of the core in  $m^3$
- $f$  = frequency
- Silicon steel = 191 joule/ $m^2$       cast iron = 2700-4000 joule/ $m^2$

# Eddy current loss

- Armature cuts the magnetic flux and an emf will induce on it.
- Power loss due to flow of current through the armature core.
- By using laminated silicon steel , eddy current loss will reduce
- Power loss in the form of heat

$$W_e = K B_{max}^2 f^2 t^2 v^2 \text{ watts}$$

- $K$  = eddy current constant
- $B_{max}$  = maximum flux density
- $V$  = Volume of the core in  $m^3$
- $f$  = frequency of magnetic reversal
- $t$  = thickness of each lamination



- Magnetic losses are practically constant for shunt and compound generator.
  - Because field current approximately constant.



# Mechanical losses

Friction loss

- At bearing and commutator


Windage loss

- Windage loss of rotating armature
- 10 to 20 % of full load loss

# Stray losses

- Sum of magnetic and mechanical losses
- Also called rotational losses

# Power stages of DC Generator



# Generator Efficiency

- Mechanical efficiency


$$\eta = \frac{\text{total watt generated in armature}}{\text{mechanical power supplied}} = \frac{E_g I_a}{\text{output of driving engine}}$$

- Electrical efficiency

$$\eta = \frac{\text{watts available in load circuit}}{\text{total watts generated}} = \frac{VI}{E_g I_a}$$

- Overall efficiency

$$\eta = \frac{\text{watts available in load circuit}}{\text{mechanical power supplied}}$$



# Condition for maximum efficiency

- Copper loss = core loss

- $I^2 R_a = W_c$

- $I = \sqrt{\frac{W_c}{R_a}}$