



TA 202A

Lecture 3

Prof. Arvind Kumar
Liquid Metals Group
Mechanical Engineering

Machining

- In MACHINING, the shape, size, finish and accuracy are obtained by removing the excess material from the workpiece surface.
- Various surfaces are obtained as an interaction between a workpiece and a cutting tool with the help of a contrivance known as MACHINE TOOL.



Ancient Tools & Structures





Modern Machining Practice



5 axis



High speed



Complex part



New configurations

Modern Machining Practice



Conventional lathe



Abrasive water jet machine



CNC lathe



CNC milling




CNC Drilling

Why machining is important

- Variety of work materials can be machined
 - Most frequently used to cut metals
- Variety of part shapes and special geometric features possible:
 - Screw threads
 - Accurate round holes
 - Very straight edges and surfaces
- Good dimensional accuracy and surface finish

Disadvantages with Machining

- Wastage of material
 - Chips generated in machining are wasted material
 - At least in the unit operation
- Time consuming
 - A machining operation generally takes longer to shape a given part than alternative shaping processes



Dimensional tolerances as a function of part size for various manufacturing processes


Note that because many factors are involved, there is a broad range for tolerances.

Machining in the Manufacturing Sequence

- Generally performed after other manufacturing processes, such as casting, forging, and bar drawing
 - Other processes create the general shape of the starting workpart
 - Machining provides the final shape, dimensions, finish, and special geometric details that other processes cannot create

Material Removal Processes

- The family tree




Machining Operations


- Most important machining operations:
 - Turning
 - Drilling
 - Milling
- Other machining operations:
 - Shaping and planing
 - Broaching
 - Sawing

Turning

Single point cutting tool removes material from a rotating workpiece to form a cylindrical shape




Turning related operations





Drilling

Used to create a round hole, usually by means of a rotating tool (drill bit) with two cutting edges









Milling

- Rotating multiple-cutting-edge tool is moved across work to cut a plane or straight surface
- Two forms: (a) peripheral milling and (b) face milling



Nature of relative motion between the tool and workpiece

Operation	Motion of job	Motion of cutting tool	Figure of operation
Turning	Rotary	Translatory (Forward)	 <p>A hand-drawn diagram of a turning operation. A cylindrical workpiece is shown rotating, indicated by a curved arrow on its right end. A cutting tool is positioned against the workpiece, with an arrow pointing to the left indicating its translatory (forward) motion. The workpiece is labeled 'Workpiece' and the tool is labeled 'Tool'. Handwritten purple letters 'WP' and 'T' are next to the workpiece and tool respectively.</p>
Boring	Rotation	Translation (forward)	 <p>A hand-drawn diagram of a boring operation. A cutting tool is shown moving horizontally through a workpiece, indicated by a green arrow. The workpiece is rotating, indicated by a curved arrow at the top. The tool is labeled 'Tool' and the workpiece is labeled 'Workpiece'. Handwritten purple letters 'T' and 'WP' are next to the tool and workpiece respectively. A green arrow labeled $D + \Delta D$ indicates the diameter of the hole being bored. A green arrow labeled $K-D$ indicates the distance from the tool tip to the center of the workpiece.</p>
Drilling	Fixed (no motion)	Rotation as well as translatory feed	 <p>A hand-drawn diagram of a drilling operation. A drill bit is shown rotating and moving downwards into a workpiece, indicated by a green curved arrow at the top and a green arrow pointing down. The workpiece is labeled 'Work-piece'. The drill bit is labeled 'Tool'. Handwritten purple letters 'WP' and 'T' are next to the workpiece and tool respectively.</p>

Planing	Translatory	Intermittent translation	
Milling	Translatory	Rotation	
Grinding	Rotary / Translatory	Rotary	

What is the basic difference between ?

Turning
Boring
Planing
Single point



and



Drilling
Milling
Grinding
Multi points




- Single vs multi Points
- Continuous and Intermittent


Basic Mechanics Issues

- Shear strain
- Power, Plastic work
- Friction, Forces
- Temperature rise
- Tool materials, Rate limits


Cutting action

- Cutting action involves shear deformation of work material to form a chip, and as chip is removed, new surface is exposed: (a) positive and (b) negative rake tools






(a)



(b)



Cutting Tool Classification



1. Single-Point Tools



- One dominant cutting edge
- Point is usually rounded to form a nose radius
- Turning uses single point tools

2. Multiple Cutting Edge Tools

- More than one cutting edge
- Motion relative to work achieved by rotating
- Drilling and milling use rotating multiple cutting edge tools

(a) Single-point tool showing rake face, flank, and tool point; and (b) a helical milling cutter, representative of tools with multiple cutting edges







Two-dimensional cutting process, also called orthogonal cutting. Note that the tool shape and its angles, depth of cut, t_0 , and the cutting speed, V , are all independent variables.

Dependent Variables (Responses): Forces, Temperature (workpiece, tool, chip), tool wear, etc.



Cutting Tools and Types of Machining



A Typical Lathe Tool




Wedge-Shaped tool




Tool Angles

Rake Angle (α)

- Influence cutting forces, power and surface finish
- Large α
 - lowers forces and improves surface finish
 - In general, power consumption \downarrow by $\sim 1\%$ for 1 degree change in α
 - Has adverse effect on tool strength because less metal is available to support the tool
 - Greatly reduced capacity to conduct heat away from the cutting edge
 - Increases tool forces, but keeps the tool in compression and provides added support to the cutting edge
- 0 or negative rake angles employed on carbide, ceramic and similar “hard” tools
- Particularly important in making intermittent cuts and in absorbing impact during initial tool - workpiece contact
- Rake angles: 5 – 15 degrees for HSS; Lower for harder materials





Flank Angle

- Minimizes rubbing of flank faces with the machined surface
- Higher values of flank angle will reduce rubbing but also weaken the tool
- Flank angles have no influence on cutting forces and power. So angles large enough to avoid rubbing is generally chosen
- Angle: 5 – 12 degrees for HSS; higher for softer and lower for brittle material

Cutting Edge Angle

- Provided to clear the cutting edge from the machined surface
- To Reduce tool chatter
- Affects tool life as well as surface finish

Tool Parameter

Nose radius

- Improves tool life and surface finish
- Large nose radius
 - Increases cutting forces and power
 - Causes chatter (self-excited vibration)
- Recommended value: 1 – 3 mm


❖ Orthogonal Cutting (2-D Cutting):

Cutting edge is:


- (1) straight
- (2) parallel to the original plane surface on the work piece and
- (3) perpendicular to the direction of cutting. For example:
Operations: Lathe cut-off operation, Straight milling, etc.

❖ Oblique Cutting (3-D Cutting):

Cutting edge of the tool is inclined to the line normal to the cutting direction. In actual machining, Turning, Milling etc., cutting operations are oblique cutting(3-D)




Orthogonal Cutting



Oblique Cutting

Chip Formation

- More realistic view of chip formation, showing shear zone rather than shear plane
- Also shown is the secondary shear zone resulting from tool-chip friction



Schematic of chip formation




Four Basic Types of Chip in Machining

1. Discontinuous chip
2. Continuous chip
3. Continuous chip with Built-up Edge (BUE)
4. Serrated chip

Discontinuous Chip

Conditions

- Brittle work materials
- Low cutting speeds
- Large feed and depth of cut
- Small rake angle
- High tool-chip friction





Chip in the form of discontinuous segments:

- Easy disposal
- Good surface finish

Continuous Chip


Conditions

- Ductile work materials
- High cutting speeds
- Small feeds and depths
- Large rake angle (+ve)
- Sharp cutting edge
- Low tool-chip friction



Continuous chip results in:


- Good surface finish
- High tool life
- Low power consumptions



Continuous with BUE

Conditions

- Ductile materials
- Low-to-medium cutting speeds
- Large feed
- Small rake angle
- Tool-chip friction causes portions of chip to adhere to rake face
- BUE forms, then breaks off, cyclically




Built up Edge:

- High friction between Tool & Chip
- Particles of chip adhere to the rake face of the tool near cutting edge
- Some part of BUE get adhered to the machined surface hence poor surface finish

Serrated Chip

- Semi-continuous - saw-tooth appearance
- Cyclical chip forms with alternating high shear strain then low shear strain
- Associated with difficult-to-machine metals at high cutting speeds



(d)

Types of Chips

(a) Continuous chip with narrow, straight primary shear zone






(b) Secondary shear zone at the chip-tool interface

(c) Continuous chip with built-up edge

(d) Continuous chip with large primary shear zone

(e) Segmented (Serrated) or nonhomogeneous chip and

(f) Discontinuous chip



Source: After M. C. Shaw, P. K. Wright, and S. Kalpakjian

Chip-Breaking

- The chip breaker breaks the produced chips into small pieces.
- The work hardening of the chip makes the job of the chip breakers easy.
- When a strict chip control is desired, some sort of chip breaker has to be employed.
- The following types of chip breakers are commonly used:
 - a) Groove type
 - b) Step type
 - c) Secondary Rake type
 - d) Clamp type





Fig: Schematics of different types of **chip breakers**



(a) Schematic illustration of the action of a chip breaker. Note that the chip breaker decreases the radius of curvature of the chip. (b) Chip breaker clamped on the rake face of a cutting tool. (c) Groove in a cutting tool acts as a chip breaker.

Recap of the Lecture

- Introduction to machining
- Classification of material removal processes
- Cutting tool classification
- Chip formation and types of chips
- Chip-breaking tools

Next Lecture

Mechanics of metal cutting