

# Wemo ROBO C axis Zero calibration

Wemo ROBO C axis Zero calibration

# Ensure all axis in zero position

# Program and services

PW 159357

# Select Program and services

# Service axis

# Press  Button

# Enter ID ( 719 )

# Enter Value = 3


# select C axis write ( Press  2 times ) until C axis shows value = xxxx

# Select ESC

# Select Settings

# Select C axis

# Press



# Press Ok 2 times

# Select ESC

# save

# Take Home.