

Etching Procedure

James Taylor

October 14, 2019

Table of Contents

Introduction	1
Materials	1
Chemicals	1
Equipment	1
Procedure	2

Introduction

The purpose of this document is to show the step by step etching procedure of glass silica beads with NaOH etching solutions. The glass spheres will be of the sizes of 0.6mm, 2mm, and 4mm and the NaOH solution will be of 0.25 molar, 1 molar, and 2 molar. The glass spheres will be treated with the etching solution in a beaker and then set on an automatic swirler at an appropriate RPM. This is to prevent resistance in the mass transfer from the surface of the spheres to the etching solution.

Time, solution concentration and size of particle will be the parameters that will be varied to see the affect that NaOH as an enchanthas on the discharge of glass Beads in a hopper.

Materials

Chemicals

- Etching solution (NaOH solution)
- Ethanol 95 %
- Anti static solution

Equipment

- 1 L beaker
- 250 mL graduated cylinder
- Stop watch
- Vortex Mixer
- Drying dish
- Strainer
- Coffee filters

Procedure

1. Weigh out 600 grams of the desired bead size, record the weight.
2. Place beaker with weighed out beads on the vortex mixer and secure in place.
3. Add about 250 mL of etching solution to 1 L beaker. Note: *For the 1 L beaker the etching solution should fill the beaker, including beads, to the 500 mL mark.*
4. Turn on mixer and set the RPM to 160 and start the stop watch.
5. Once the desired time is reached, stop the vortex mixer and remove the beaker.
6. Decant the etching solution into a properly labeled waste container, and do one of the following depending on the particle size.
 - (a) Particles of size 2 mm and greater: Place beads in an appropriately sized kitchen strainer and wash thoroughly with distilled water, shake as much of the water out of the beads as possible.
 - (b) Particles less than 2 mm in size: Place a coffee filter in an appropriately sized kitchen strainer and wet with distilled, so that the coffee filter forms to the strainer. Wash beads thoroughly with distilled water, shake as much of the water out of the beads as possible.
7. Place beads into a drying dish and add Ethanol and anti static solution (just like for the untreated beads) and thoroughly mix the solution. Place out to dry in a fume hood.
8. Once dried, weigh the beads and record the loss in weight.
9. **Keep a small sample of the beads for future AFM testing.**