

# ME 206 Manufacturing Processes I (S1)

Vishal Neeli

March 16, 2021

**Note : In this course, notes for some parts of syllabus before midsem are missing**

## 1 Introduction

- The five M's of the manufacturing define the profitability of the manufacturing process
  - Men (women)
  - Machine
  - Materials
  - Money
  - Management
- Manufacturing processes can be classified into:
  - Shaping processes
  - alter the shape
    - \* Solidification process
    - \* Metal Removal process
    - \* Deformation process
    - \* Assembly process
  - Property enhancing processes
  - change the properties of the material  
Ex: annealing, hardening
  - Surface enhancing processes
  - clean the surfaces or coat them  
Ex: Surface oxidation
- Selection of manufacturing processes depends on various factors
  - Cost
  - Available infrastructure
  - Operating temperature
  - Required properties
  - Dimensions of required product

## 2 Casting Process

Pros:

- Complex forms, low cost
- Certain shapes cannot be machined
- One piece parts vs. multiple piece parts
- Design changes are easily incorporated
- High volume, low skilled labor
- Large, heavy parts can be made easily

Cons:

- Problems with internal porosity
- Dimensional variations due to shrinkage
- Trapped impurities, solids and gasses
- High-tolerance, smooth surfaces not possible
- More costly than stamping or extruding in some cases

## 2.1 Pattern

- It is the replica (usually a bit bigger) of the req product
- It should be cost efficient, easily machinable into common shapes.  
Possible choices are:
  - Wood : more than 90% of the production happens with wood, absorbs moisture, relatively lower life
  - Metal: longer life, used in large quantity production, Al, cast iron and bronze are most used
  - Plastic : good corrosion resistance, smooth surfaces, do not absorb moisture, dimensionally stable, low weight
- Pattern types
  - Single piece pattern: Name says it all
  - Split pattern
  - Cope
  - split pattern: Same as split pattern except that parts are moulded separately
  - Gated pattern: Tree like structure with each branch holding the required shape

## 2.2 Allowances

- Shrinkage Allowance  
When the metal changes from liquid to solid state and cools down in solid state, its volume reduces. So we make the pattern size more than the size required. This is called shrinkage allowance.
- Draft/ Taper Allowance  
To avoid damage to the sand mould and casted metal on the internal walls while removing the metal after it cools, we need to provide extra material on the walls of the pattern. We typically use a tapering angle(angle at which pattern is bent outwards) of 1 deg to 3 deg.
- Machining/Finishing allowance  
It is the extra material allowed to cut to smooth finish the product. The amount of machining depends on method of moulding method of molding and casting used, size and shape of casting, metal used in casting, required accuracy and finish
- Distortion / Camber allowance  
Due to typical shape of some patterns (non symmetric) (T, U, V, W), after cooling down the shape will change due to uneven shrinkage, so we need to allow distortion allowance i.e, we need to bend the pattern in opp dir to the expected distortion to get correct shape. This varies between 2 to 20 mm.

## 2.3 Molds

- Expendable Molds: A new mold has to be produced for every cycle. Types: green sand, dry sand, shell, investment, plaster
- Permanent molds: Multiple usages, used in: die casting, centrifugal, pressure die, injection molding
- Required properties of moulding sand:
  - Refractoriness: Ability to withstand higher temperatures
  - Permeability: For the air to escape
  - Cohesiveness: Adhesive forces in sand
  - Flowability: It should flow uniformly to all the portions

## 2.4 Gates

Gate is the hole through which the molten metal flows into the mould cavity. Mainly 3 types of gates are used:

- Top gating: The gate is present at the topmost portion of the cavity. In this case, the metal poured through the gate hit the mould cavity floor with some force. This can cause the sand to erode and mix up with the molten metal. But this can be avoided by making the passage from runner to gate a bit above the runner floor. This will slow the metal.
- Bottom gating: In this case, gate is present at the lowest part of the mould cavity. After filling some part of the mould cavity, the process slows down as the pressure difference driving the flow of metal is getting reduced.
- Parting line gating: Gate is present at parting line or joining line of cope and drag.
- A top gating design is preferred over bottom gating design and parting gating design because in the case of top gating design, the gravity helps the molten metal to flow to intricate corners of the pattern.

## 2.5 Types of Casting

- Sand casting:  
Advantages - This is cheap, this can be used for ferrous and non-ferrous materials. (Non-ferrous metals require high temp)  
Disadvantages - Rough finish
- Investment casting
  - We first create a pattern out of wax (optimised for this process) and then dip it in slurry (silica). The slurry solidifies on the outer surface to req thickness. Then we heat the thing to melt wax and remove the wax completely to create an outer wall for the req shape. The liq metal is poured into the solid slurry to create the req shape. After cooling down, outer shell can be removed
  - This has a smooth wall finish
  - It can be used to create complex shapes because wax can be easily bended
  - Also known as lost wax casting precision casting
  - This is relatively expensive compared to sand casting
- Centrifugal casting
  - Molten metal is poured into a long cylinder and rotated, and it is cooled on the outer surface
  - The outer part cools faster and has smaller grain size
  - The lighter impurities present in the metal get accumulated at the inner surface. This can be removed by machining process in the inner surface
- Shell moulding
  - The req shape in metal is heated and some silica or sand made to stick to the metal and an outer shell is made.
  - Then liquid metal is poured into the mould.
  - Axial symmetry things can be made easily by this.
- Lost Foam/ Evaporation Pattern
  - A pattern is created using polystyrene and sand is used to support it.
  - The metal is directly poured into the polystyrene and the polymer evaporates and creating req shape
- Continuous casting
  - Partially solidified (outer surface) metal is sent through the roller and cooling liquid is sprayed
  - This creates uninterrupted long strands of metal
- (Pressure) Die casting
  - High cost

- The dies are two shapes which lock into each creating a cavity in between.
- Before locking they are sprayed with some liq to prevent sticking of molten metal to die
- Metal is poured in cavity and pressure is applied to molten metal. Pressure ensures that metal reaches all the cavities and ensures that metal reaches everywhere before it starts solidifying. After removing ejector pins, dies get separated.
- Cooling channels are present in the die which cool the metal. The whole can be completed as fast as 1min.
- In cold chamber die casting - higher melting point metals (preferred because it can cost higher to maintain metal in liq state)
- In hot chamber die casting - lower melting metal (can also be used for higher melting metal)

## 2.6 Casting Defects

- Misrun : metal solidified before reaching all places
- Cold shut : meeting of two metal streams is not complete, i.e., metal flow was not able to reach parts of the mould cavity where two metal flows meet
- Cold shot : Due to turbulence during the pouring of the metal, some solid globules form which become entrapped in the metal.
- Sand blow : The gas bubble in the cavity which entered during pouring (or gases released by metal as it cools) stays in the cavity and creates bubble shaped cavity.
- Pinholes : The small pores in the metal which are due to the gases which are released during solidification
- Blowholes : Blowholes are similar to pinholes but with larger holes.
- Shrinkage cavity: Depression or internal void created due to shrinkage of metal volume while cooling is called shrinkage cavity
- Hot tearing : when the casting is restrained from contraction by an unyielding mold during the final stages of solidification or early
- Sand wash : Irregularity in the surface of the casting that results from erosion of the sand mold during pouring

## 2.7 Trends

- Change in casting metal
  - Steel to ductile iron - lower material and conversion cost
  - Al to Al-Mg-Ti alloys - increase in strength to weight ratio
  - In alloy casting, we need to ensure that the composition remains the same throughout.
- Change in geometry
  - Wall thickness is reducing. This is because in casting of thick pieces, distortion happens and we want straight parts. In case, we have multiple thickness, then we can use chill to start solidification earlier at thicker points
  - Weight reduction and increasing shape complexity

## 3 Metal flow in typical casting

- Metal flow is turbulent. Turbulence causes mixing with air, sand erosion
- When metal flows against the mold wall erosion, vortex formation (air pocket/slag), splashing against the mold walls, air aspiration (due to reaction with mold material) and metal solidification.
- We can determine the Reynolds numbers of molten metal.
- Velocity of the metal gets reduced due to loss by sudden change in cross section, etc.

$$v_{actual} = c_d \sqrt{2gh}$$

- Typical value of  $c_d$  is 0.6-0.8
- Friction can be ignored for considering loss in velocity of metal, losses due to change in cross section dominate the losses
- Sprue shape has to be shaped as a frustum pointing downwards because as the velocity of the metal increases (due to gravity), the area of cross section gets reduced ( $A_1v_1 = A_2v_2$ ). If the shape is cylindrical or frustum pointing upwards, the flow separates from the mould walls and form an air cavity which can lead to defects.
- For multiple top gates, L gate (gate at the end of the sprue) has higher  $c_d$  compared to T gate. L gate has the highest flow rate (even if it is the farthest) due to inertia.
- To reduce defects in casting process due to erosion of sand mould, we need to ensure that Stress due to impact > Sand mould strength
- Velocity of the metal should not be very high, because high vel makes erosion and causes defects in metal product
- Desired  $Re < 8000$

$$Re = \frac{\rho v D}{\mu}$$

- Surface turbulence (Jetting or fountaining effect) - Weber number ( $\gamma$  is the surface tension of the metal)

$$We = \frac{\rho v^2 d}{\gamma}$$

$We < 1$ : No surface turbulence

$We < 10$ : Mild

$We < 100$ : High turbulence

- Bond number (Related to buoyancy)

$$B = \frac{\rho d^2 g}{\gamma}$$

$B < 1$ : Surface tension dominate

$B > 1$ : buoyancy force overcomes surface tension and leads to surface instability

### 3.1 Fluidity

- **Fluidity** in case of metal casting refers to the distance the metal can travel before solidifying. This is different from the physics definition (inverse of viscosity)
- Fluidity can be increased by increasing pressure and/or pouring temperature.
- No of gates has to be increased if the fluidity is low
- Pure metals have higher fluidity than alloys
- Spiral test / honeycomb test can be carried out to find the fluidity. This can also be simulated using finite element analysis software like Ansys etc.
- This also can be roughly estimated by doing some calculations:  
Consider a metal at its melting point  $T_m$  poured into a channel of radius  $a$  with average flow velocity  $v$ . Let the metal solidify at a distance  $L_f$  in time  $t$ . The heat released by metal (latent heat) per unit time is equal to the heat conducted by the mold-metal interface. Let  $h$  be the heat transfer coefficient of mold-metal interface. Then

$$\rho_m \pi a^2 V \Delta H = (2\pi a L_f) h (T_m - T_0)$$

$$L_f = \frac{\rho_m v \Delta H a}{2h(T_m - T_0)}$$

- The above expression is valid only for pure metals since the melting point of alloys is not a single point but a range of temperatures
- Fluidity of alloys when solid grains are present can be expressed as

$$L_f = f_s^{cr} V t_s$$

where  $f_s^{cr}$  is the critical fraction of solid at which fluid stops

### 3.2 Aspiration effects in mold filling

- For a mold made up of permeable material (eg sand), the pressure of the metal stream should not be less than atmospheric pressure. Because if this happens gases from the baking of organic compounds in mold will enter the molten metal stream, producing porous casting. This is known as **aspiration effect**.
- Consider a sprue (part between pouring basin and gate) of uniform diameter of height  $h$  which lead to a mould cavity open to atmosphere (completely or partially through runner). Let the pressure at the start of the sprue be  $P$  and velocity  $v_1$ . The pressure at the end of the sprue is  $P_{atm}$  (since it is open to atmosphere) and let the velocity be  $v_2$ . Since the sprue diameter is uniform from continuity equation, we have  $v_1 = v_2$ . By applying Bernoulli principle,

$$P + \rho gh = P_{atm}$$

$$P = P_{atm} - \rho gh$$

Here, the pressure is less than the atmospheric pressure which causes aspiration.

## 4 Joining, Assembly and Welding

### 4.1 Joining

- Welding, brazing and soldering and adhesive are permanent joints
- Welding is with metal of low temp and brazing is with metal of high temp

### 4.2 Welding

- Two or more parts are coalesced at their contacting surfaces using heat or pressure.
- We can (depends on metals we use) use another metal to facilitate joining of two parts. The external metal should have high solubility with the parts being joined.
- **Pros:**
  - Welding is usually the most economical way to join parts
  - Can be done outside factory environment
- **Cons:**
  - This is usually done manually, so is costly
  - Cannot be easily disassembled
- Welding can be performed in various environment - vacuum (electron beam welding), normal atmosphere, underwater.
- Fusion welding: We melt the base metals and joined to create a homogenous joint. We can use a filler metal here to bond the two parts. In this, we can provide inert gas environment known as shielding gas.
- Solid state welding: No molten states. One of them is friction stir welding. No molten state prevents the formation of blowholes and pinholes because they do not absorb large amount of gases in molten which is the case in fusion welding. Increasing becoming popular
- Arc welding (Fusion welding): We create an electric arc between electrode and work piece (we bring them close but do not let them touch and apply high voltage between them). This heats up the electrode and the metal melts which acts filler. We need to use shielding gases to prevent absorption of gases by metal.
- Friction stir welding: Currently used for aluminium (this can easily get oxidised in fusion welding). In this process, we insert a pin between the parts to be joined and stir it at high speed and to generate heat moving through the joint, which will join the parts
- Laser welding : This is type of fusion process in which we use laser to melt the metal.

### 4.3 Fusion welding

- Shielding: When metal is in molten state, its gas adsorption capacity is very high which leads to pinholes and blow holes. To prevent this, an inert gas environment is provided. Usually, when the metal in the electrode is consumed, it releases some inert gases which create shielding.
- Popular welding in this category
  - GTAW - Gas Tungsten arc welding
  - GMAW - Gas
  - SMAW
  - OAW - oxy acetylene welding
- **Arc welding:**
  - We need to maintain a constant optimal gap to maintain the electrical arc.
  - A human cannot perform this very well, so we use machines to perform this. Machines can do this very efficiently.
- **Resistance welding:**
  - We put the two metal parts in a circuit with high current. Utilising joule's heating, we melt the metal. The metals are also put under pressure.
- **Oxy acetylene welding:** We use the oxyacetylene flame to melt the parts and join them. In this welding, a lot of mechanical pressure is not applied

### 4.4 Solid state welding

- Diffusion welding: We make the two part surface flat and put them together under pressure. We heat the combination under pressure. At high pressure, the area of contact increases and increasing temperature increases diffusion rate. So after some time, the metals have formed a homogenous bond. Usually this is for two parts of same metal

### 4.5 Parameters to evaluate welding

- **Power density:** Power supplied per unit surface area.
  - If it is too low, heat will be conducted and required temperature will not be achieved.
  - If it is too high, it will vapourise the metal
  - There are some practical ranges for this.
  - For example, in arc welding, it is focused and weld can occur upto a lot of depth but in the gas welding, it is not the case
  - Oxyfuel welding ( $10 \text{ Wmm}^{-1}$ ) can produce high temperature but as it is spread over a lot of area. upto  $3500^\circ$ ,
  - Laser beam welding ( $9000 \text{ Wmm}^{-1}$ ) / electron beam welding ( $10000 \text{ Wmm}^{-1}$ ) have a very high power density
  - Arc welding -  $50 \text{ Wmm}^{-1}$
  - It has to be high for thick weld
- **Welding speed:** It is high for electron beam but for gas welding it is low. We need to find an optimal speed.
- **Aspect ratio**  
Aspect ratio =  $z/(x, y)$   
For high aspect ratio, power density has to be high
- Unit energy for melting:
- $f_1$  Heat received by metal / Heat given by source (Heat transfer efficiency)
- $f_2$  Heat received by melt / Heat given to metal (Melting efficiency)
- Heat used  $H_w = f_1 f_2 H$
- Al and Cu present a problem because they have high thermal conductivity. They dissipate a lot of heat that they receive.

- Energy balance equation : Heat delivered  $H_w = U_w V$ , where  $U_w$  is the heat required per unit volume ,  $V$  is volume
- **Joining efficiency:**  
 Joining Efficiency =  $vt/P$   
 $v$  = trasverse speed mm/s  
 $t$  = thickness of weld mm  
 $P$  = incident power, kW



## 5 Metal Forming

- In many manufacturing processes, plastic deformation is used to shape the work piece.
- A tool (usually called die) applies stresses more than the yield stress of the metal and less than the fractures strength of the material.
- Stresses used to deform the work piece are usually compressive. Tensile stresses may also applied be on the work piece to stretch the metal.
- **Sheet Metal working** : In sheet metal working, the ratio  $\frac{V}{S}$  is lower (thickness is low), i.e, it is typically done on metal sheets, strips or coils.
- Desirable material properties (for metal forming):
  - Low yield strength (easy to deform)
  - High ductile

### 5.1 Bulk Deformation Processes

- Bulk refers to point that the ratio  $\frac{V}{S}$  is higher (thickness is higher).
- Rolling : Plate is squeezed between the rolls
- Forging : Work is squeezed between opposing dies
- Extrusion : squeezed through a die opening. Workpiece takes the shape of the opening.
- Wire and bar drawing : Diameter is reduced by pulling through the die opening.
- If the working temperature is below recrystallation temperature, it is called cold forming and if the working temperature is more than the recrystalisation temperature then it is called hot forming.
- If the direction of the flow of material and the piston is same, then the extrusion is called direct extrusion, if it is opposite, it is called indirect extrusion.
- **Strain hardening**: Strain Hardening is when a metal is strained beyond the yield point. An increasing stress is required to produce additional plastic deformation and the metal apparently becomes stronger and more difficult to deform. This is mainly seen in cold forming process.
- Behaviour in metal forming:
  - In plastic region, metal's behavior is expressed by the flow curve,

$$\sigma_f = K\epsilon^n$$

where  $\sigma_f$  = flow strength, K = strength coefficient and n = strain hardening exponent.

- Average flow stress ( $\bar{\sigma}_f$ )

$$\bar{\sigma}_f = \frac{\int_0^{\epsilon_f} K\epsilon^n d\epsilon}{\epsilon_f} = \frac{K\epsilon_f^n}{n+1}$$

where  $\epsilon_f$  = maximum strain during deformation

- Strain Rate:
  - As the strain rate increases, yield strength increases.
  - At room temperature, the effect of strain rate is negligible.
- **Recrystallization temperature**: Temperature at which recrystallization just reaches completion in 1 h.

$$0.3T_m < T_R < 0.6T_m$$

- **Annealing** is a heat treatment that alters the physical and sometimes chemical properties of a material to increase its ductility and reduce its hardness, making it more workable.
- Effect of temperature:
  - Temperature ranges for deformation:
    1. Cold working : Below recrystallisation temperature ( $< 0.3T_m$ )
    2. Warm working ( $0.3T_m - 0.5T_m$ )
    3. Hot working : Above recrystallisation temperature ( $0.5T_m - 0.7T_m$ )

- As temperature increases, ductility increases and yield strength decreases.
- At higher temperature, the effect of roughness of roll or die increases, ie., since the metal is soft at higher temperature the roughness on the die or roll gets printed on the work piece.

- **Cold working :**

- Performed at room temperature or slightly above.
- Important for mass production
- No machining is required
- Strain hardening is dominant and strength increases.
- Pros:
  - \* Better accuracy
  - \* No heating required
  - \* Strain hardening increases strength
- Cons:
  - \* High forces required
  - \* Ductility and strain hardening limit the deformation that can be performed
- **Percentage of cold working**

$$\% \text{ Cold working} = \frac{\text{Initial Area} - \text{Final Area}}{\text{Initial Area}} \times 100\%$$

- As cold working increases, yield strength increases and ductility decreases.

- **Hot working:**

- Performed above recrystallisation temperature
- Capability of hot working to perform deformation is lot more than cold working
- Pros:
  - \* Low forces and power required
  - \* Large amount of deformation can be carried
  - \* Strength properties are generally isotropic
- Cons:
  - \* Work piece susceptible to oxidation due to higher temperature
  - \* Shorter tool life

- If perform annealing on cold worked work piece (heat the material slowly), the ductility increases and tensile strength of the material decreases. As the temperature increases, the elongated grains dissolve to form new grains which combine to grow bigger grains.

## 5.2 Rolling

- Types of rolling:

- Flat rolling: used to reduce thickness
- Shaping rolling : used to shape the workpiece, for instance, into I-shaped beam

- Types of rolling

- Hot rolling: large of deformation is required
- Cold rolling : Dimensional accuracy and finishing is important

- Rolling mill configurations:

- Two-high : Two large opposing rolls
- Three-high : work passes through rolls in both directions
- Four-high : Two large rolls supporting the smaller rolls
- Cluster mill – multiple backing rolls on smaller rolls
- Tandem rolling mill – sequence of two-high mills

- **Flat rolling:**

- Contact length: The length of the work piece that is in contact with the material

- Bite angle: The angle subtended by contact length at center of the roll.
- Using geometry, we can derive that

$$R(1 - \cos \theta) = \frac{t_i - t_f}{2}$$

- As the work piece rolls through the roller, the velocity of the work piece increases since its volume remains the same but the length increases.

$$v_0 < v_r < v_f$$

- There is a point on the roller whose velocity is equal to the roller velocity. This point is called neutral point.
- Smaller-diameter rolls produce less contact length for a given reduction and therefore require lower force and less energy to produce a given change in shape but they are also more susceptible to deformation themselves. Hence, they are supported by larger rolls.

- **Thread rolling:**

- Die on which thread like intrusions are made is used to thread like structures on the bolts and screws.
- They are produced faster than the machining process using rolling.

- **Ring rolling:**

- In this a ring of smaller diameter is rolled into a thin-walled ring of larger diameter.
- The ring is passed between a idler roller and a main roller which apply stresses to elongate it, increasing the diameter.
- This is used to produce steel tires for railroad wheels, rings for pipes, pressure vessels, and rotating machinery.

### 5.3 Failure theories

: Let  $\sigma_1 \geq \sigma_2 \geq \sigma_3$  be the principal stresses and uniaxial yield stress be  $\sigma_Y$ .

Maximum shear stress =  $\frac{\sigma_1 - \sigma_3}{2}$ .

Maximum shear in uniaxial tensile test =  $\frac{\sigma_Y}{2}$

1. **Maximum principal stress theory** (Rankine' theory - for brittle materials):

Material will fail if maximum principal stress exceeds maximum stress in uniaxial tensile test.

$$\boxed{\sigma_1 \geq \sigma_Y}$$

2. **Maximum shear stress theory** (Tresca theory - for ductile materials):

Material will fail if maximum shear stress exceeds maximum shear stress in uniaxial tensile test.

$$\boxed{\frac{\sigma_1 - \sigma_3}{2} \geq \frac{\sigma_Y}{2}}$$

3. **Maximum principal strain theory** (St Venants) :

If the maximum principal strain exceed strain in uniaxial tensile test, then the material will fail i.e, if

$$\epsilon_Y = \frac{1}{E}(\sigma_1 - \nu(\sigma_2 + \sigma_3)) \geq \frac{\sigma_Y}{E}$$

4. **Total strain energy theory:**

The material fails if the strain energy with the principal stresses exceed the strain energy from the uniaxial tensile test, i.e,

$$\frac{1}{2E}[\sigma_1^2 + \sigma_2^2 + \sigma_3^2 - 2\nu(\sigma_1\sigma_2 + \sigma_2\sigma_3 + \sigma_3\sigma_1)] > \frac{1}{2E}\sigma_Y^2$$

5. **Distortional theory** (Von-Mises theory - for ductile materials):

$$\boxed{(\sigma_1 - \sigma_2)^2 + (\sigma_2 - \sigma_3)^2 + (\sigma_3 - \sigma_1)^2 \geq 2\sigma_Y^2}$$