

SSM 65437 Y piece1.pdf

Reference	SSM65437
Models	XF / X250 XJ / X351 F-TYPE / X152
Title	DTC P026A on Supercharged Engines only
Category	Engine
Last modified	21-May-2013 00:00:00
Symptom	402000 Cooling System Concerns
Content	<p><u>Issue:</u> DTC P026A found during DTC read.</p> <p><u>Cause:</u> DTC P026A "Charge Air Cooler efficiency below threshold" can be flagged in the PCM due to a blockage with the Supercharger Cooling System.</p> <p><u>Action:</u> Please follow the Diagnostic as detailed in TOPIx 100-00 for this DTC.</p> <p>If the DTC is persistent after the faults suggested in TOPIx have been investigated, please inspect the "Y" piece Connectors within the Supercharger Coolant Pipes for an obstruction as shown in the attachment (picture 1). The Pipe must be clear of any internal blockage (picture 2). If the Pipe is partially blocked (picture 3) or fully blocked (picture 4 section view), please replace the Hose assembly and submit an ePQR.</p>