

SOS Limited Functionality Message	18-22MY Range Rover, Range Rover Sport, F-Type 18-20MY RR Evoque, Velar, Discovery, Discovery Sport, XE, XF, I-Pace,
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">– SOS Limited Availability or SOS Not available warning message displayed <p><u>Technical Description:</u></p> <ul style="list-style-type: none">– Issue is caused due to TCU using the Back Up Battery when 12V Vehicle Battery is flat.– <p><u>Status:</u></p> <ul style="list-style-type: none">– Do NOT replace the TCU Back-up Battery– Follow the procedures outlined in SSM75647/SSM75646– Note: Ignition On will not charge the Back-up Battery. Ensure Engine is Running for the entire duration i.e., the vehicle is in Power Mode 7.	