

DTC	B2797	COMMUNICATION MALFUNCTION NO.1
-----	-------	--------------------------------

CIRCUIT DESCRIPTION


This DTC is output when an error occurs in normal communication.

HINT:

Some noise exists in the communication line.

DTC No.	DTC Detection Condition	Trouble Area
B2797	Keys are positioned too close to each other, or noise occurred in communication line	<ul style="list-style-type: none">• Key• Wire harness• Transponder key amplifier (Transponder key coil)• Transponder key ECU Assy

WIRING DIAGRAM



INSPECTION PROCEDURE

1	CHECK OPERATION OF TRANSPONDER KEY AMPLIFIER
---	--

(a) After replacing the transponder key amplifier, check that the engine starts.

OK

NORMAL
(TRANSPONDER KEY AMPLIFIER DEFECTIVE)

NG

REPLACE TRANSPONDER KEY ECU ASSY
