

## PROBLEM SYMPTOMS TABLE

### HINT:

Inspect the "Fuse" and "Relay" before confirming the suspected area as shown in the table below.

★ Refer to Camry Repair Manual (Pub. No. RM915E) (AUDIO SYSTEM).

Symptom	Suspect Area	See page
Pressing power switch does not start system.	1. Radio receiver assy power source circuit 2. Radio receiver assy	★
Turning on light switch does not light up night time illumination of radio receiver.	1. Radio receiver assy ILL terminal circuit 2. Radio receiver assy	★
No sound is heard from speaker in all modes.	1. Speaker circuit 2. Radio receiver assy power source circuit 3. Radio receiver assy	★
Sound quality is bad in all modes. (Volume is too low)	1. Speaker circuit 2. Radio receiver assy power source circuit 3. Radio receiver assy	★
Radio broadcast cannot be received. (Bad reception)	1. Antenna circuit 2. Radio receiver assy	★
Cassette tape cannot be inserted or played.	1. Cassette tape 2. Radio receiver assy power source circuit 3. Radio receiver assy	★
Cassette tape cannot be ejected.	1. Cassette tape 2. Radio receiver assy power source circuit 3. Radio receiver assy	★
Sound quality is bad only when playing tape.	1. Cassette tape 2. Radio receiver assy	★
Tape is tangled due to incorrect tape speed or auto-reverse malfunction.	1. Cassette tape 2. Radio receiver assy	★
CD cannot be inserted or is ejected right after insertion.	1. CD 2. Radio receiver assy power source circuit 3. Radio receiver assy	★
Although system is powered, CD cannot be played.	1. CD 2. Radio receiver assy power source circuit 3. Radio receiver assy	★
CD cannot be taken out.	1. CD 2. Radio receiver assy power source circuit 3. Radio receiver assy	★
Sound quality is bad only when CD is played. (Volume is too low)	1. CD	★
CD sound skips.	1. CD 2. Radio installation	★
Noise occurs.	–	★
Audio system cannot be operated with steering pad switch.	1. Steering pad switch circuit 2. Radio receiver assy	05-226 See pub. No. RM915E, page 67-3
Panel switches do not function.	1. Steering pad switch circuit 2. Radio receiver assy	05-226 See pub. No. RM915E, page 67-3