

Q2) a) Rotor winding Diagram

12 slots, 2-pole, single-layer full-pitch

1	2	3	4	5	6	7	8	9	10	11	12
a <sub>1</sub>	a <sub>2</sub>	-c <sub>1</sub>	-c <sub>2</sub>	b <sub>1</sub>	b <sub>2</sub>	-a <sub>1</sub>	-a <sub>2</sub>	c <sub>1</sub>	c <sub>2</sub>	-b <sub>1</sub>	-b <sub>2</sub>

Stator winding Diagram

18 slots, 2-pole, double-layer, 10/9 full-pitched

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
A <sub>1</sub>	A <sub>2</sub>	A <sub>3</sub>	-C <sub>1</sub>	-C <sub>2</sub>	-C <sub>3</sub>	B <sub>1</sub>	B <sub>2</sub>	B <sub>3</sub>	-A <sub>4</sub>	-A <sub>5</sub>	-A <sub>6</sub>	C <sub>4</sub>	C <sub>5</sub>	C <sub>6</sub>	-B <sub>4</sub>	-B <sub>5</sub>	-B <sub>6</sub>
-B <sub>3</sub>	A <sub>4</sub>	A <sub>5</sub>	A <sub>6</sub>	-C <sub>4</sub>	-C <sub>5</sub>	-C <sub>6</sub>	B <sub>4</sub>	B <sub>5</sub>	B <sub>6</sub>	-A <sub>1</sub>	-A <sub>2</sub>	-A <sub>3</sub>	C <sub>1</sub>	C <sub>2</sub>	C <sub>3</sub>	-B <sub>1</sub>	-B <sub>2</sub>


b) Draw the air-gap mmf distribution produced by the rotor at  $t = 1/150$  s.

$$I_a(t) = 10 \cos(100\pi t) \quad t = 1/150 \Rightarrow 10 \cos(2\pi/3) = -5A$$

$$I_b(t) = 10 \cos(100\pi t - \frac{2\pi}{3}) \Rightarrow 10A$$

$$I_c(t) = 10 \cos(100\pi t - \frac{4\pi}{3}) \Rightarrow -5A$$

Rotor  $\rightarrow$  10 turns each



c) Calculate the first-harmonic, open-circuit RMS stator voltage when

i) Rotor speed is zero.

ii) Rotor speed is 3000 rpm

iii) " " " -3000 rpm

c) i) First calculate the MMF (peak value of the fundamental =  $\hat{F}_1$ )  
 In order to do that, we need to calculate the winding factor ( $k_w$ ) of the rotor.

$$k_w = k_d k_c \quad k_c = 1 \text{ (because it's full pitched)}$$

$$k_w \Rightarrow k_d \Rightarrow 12 \text{ slots} \Rightarrow \alpha = 30^\circ \left( \frac{360}{12}, \text{ angle between slots} \right) \quad q = 2 \text{ (slots per pole per phase)}$$


$$k_d = \frac{\sin(9 \frac{\alpha}{2})}{9 \sin(\frac{\alpha}{2})} = \frac{\sin(2.70)}{2 \cdot \sin(\frac{30}{2})} = 0.966$$

$$\underline{k_w = 0.966}$$

$$\hat{F}_1 = \frac{3}{2} \cdot \frac{4}{\pi} \cdot k_w \cdot \frac{20 \cdot 10}{2} = 184.5 \text{ A} \cdot \text{t}$$

(pole number)  $\rightarrow$  20  
 $\rightarrow$  2 (from 3-phase)  
 $\rightarrow$  4 (fundamental magnitude of a square wave)  
 $\rightarrow$  winding factor  
 $\rightarrow$  2 (coil (phase) (2x10))

- Then, calculate the flux density ( $\hat{B}_1$ )




$$\hat{F}_1 = \hat{H}_1 \cdot g \quad \hat{H}_1 = \frac{\hat{B}_1}{\mu_0}$$

$$\hat{B}_1 = \frac{\mu_0}{g} \cdot \hat{F}_1$$

$$\hat{B}_1 = \frac{4\pi \cdot 10^{-7}}{0.002} \cdot 184.5 = \underline{\underline{0.116 \text{ T}}}$$

- Then, calculate the flux per-pole.



$$\Phi = \int B \cdot dA$$

easy way, get the average, multiply by pole area.

$$B_{av} = \frac{2}{\pi} \hat{B}_1$$

$$\Phi_{\text{pole}} = B_{av} \cdot A_{\text{pole}} \quad \text{area of cylinder}$$

$$= \frac{2}{\pi} \cdot \hat{B}_1 \cdot \frac{2\pi \cdot r \cdot l}{2} = \frac{2}{\pi} \cdot 0.116 \cdot \frac{2\pi \cdot 0.1 \cdot 0.3}{2}$$

$$\boxed{\Phi_{\text{pole}} = 6.96 \text{ mWb}}$$



c) Then, in order to calculate the induced stator voltage, we need stator winding factor.

$$\text{Stator } 10/9 \text{ pkkd} \Rightarrow 180 \cdot \frac{10}{9} = 200^\circ \text{ coil pitch}$$

$$k_c = \sin\left(\frac{\alpha}{2}\right) = \sin\left(\frac{200}{2}\right) = 0.98481$$

$$k_d = \frac{\sin\left(9 \cdot \frac{\alpha}{2}\right)}{9 \sin\left(\frac{\alpha}{2}\right)} = \frac{\sin\left(3 \cdot \frac{20}{2}\right)}{3 \sin\left(\frac{20}{2}\right)} = 0.9598$$

$$k_w = k_c k_d$$

$$k_w = 0.9452$$

$q=3$  (distributed over 3 slots)

$\alpha=20$  (18 slots)

$$U_{\text{phase}} = \underbrace{4.44}_{\frac{2\pi}{\pi}} \cdot \underbrace{N_{ph}}_{\text{number of turns per phase}} \cdot k_w \cdot f \cdot \phi_{\text{pole}}$$

$$= 4.44 \cdot \underset{\substack{\uparrow \\ (15 \times 6) \\ \text{turns per coil}}}{90} \cdot \underset{\substack{\uparrow \\ (10 \times 6) \\ \text{slots per phase}}}{0.9452} \cdot \underset{\substack{\uparrow \\ (100 \text{ Hz})}}{50} \cdot 6.96 \text{ m} = \boxed{131.4 \text{ V}}$$

ii) Rotor currents generate a rotating mmf at 3000 rpm ( $n = \frac{120f}{p}$  ← 50 Hz)  
Thus, if the rotor is rotating at 3000 rpm, the frequency of the rotor flux will be 100 Hz, with respect to stator windings. Therefore, the induced voltage will be doubled.

$$U_{\text{phase}} = 4.44 \cdot 90 \cdot 0.9452 \cdot \underset{\substack{\uparrow \\ (100 \text{ Hz})}}{100} \cdot 6.96 \text{ mWb} \\ = 262.8 \text{ V}$$

iii) If the rotor is rotating at the opposite direction, the stator winding will just see a constant flux ( $f=0 \text{ Hz}$ ), hence no voltage will be induced.

$$V_{\text{phase}} = 0 \text{ V (at -3000 rpm)}$$

3-phase, 50Hz, Y-connected, 380V c.c., negligible stator resistance,

CH-2

Q4

- Motor runs at 745 rpm at no load

-  $T_{start} = 236 \text{ Nm}$


-  $T_{max}$  at 600 rpm

a) Number of poles

$$\frac{120f}{p} \cong 745 \Rightarrow \underline{p = 8 \text{ poles}}$$

b) Referred rotor resistance ( $r_2'$ )

c) Referred rotor leakage reactance + stator leakage reactance ( $x_1 + x_2'$ )



At 600 rpm, torque is max

$$\rightarrow s = \frac{750 - 600}{750} = 0,2$$

Torque is max, when  $P_{gap}$  is max. Using max power transfer theorem

$$P_{gap} \text{ max if } (x_1 + x_2') = r_2' + \frac{(1-s)}{s} r_2'$$

$$(x_1 + x_2') = \frac{r_2'}{s} \leftarrow s_{max} = 0,2$$

$$\underline{5r_2' = (x_1 + x_2')}$$

$$T_{start} = 236 \text{ Nm} \quad s=1$$

$$T_e = \frac{3V_{th}^2}{\left(r_1 + \frac{r_2'}{s}\right)^2 + (x_1 + x_2')^2} \cdot \frac{r_2'}{s} \cdot \frac{1}{\omega_s} \Rightarrow \frac{3V_{th}^2 \cdot r_2'}{r_2'^2 + (x_1 + x_2')^2} \cdot \frac{1}{\omega_s} = 236$$

$$\omega_s = \frac{2\pi f_e}{p} \leftarrow \text{pole-pairs}$$

$$\omega_s = \frac{2\pi \cdot 50}{4}$$

$$\frac{3 \cdot \left(\frac{380}{\sqrt{3}}\right)^2 \cdot r_2'}{26r_2'^2} \cdot \frac{1}{\frac{2\pi \cdot 50}{4}} = 236$$

$$\Rightarrow \underline{r_2' = 0,3 \Omega}$$

$$\underline{(x_1 + x_2') = sr_2' = 1,5 \Omega}$$




CH-2

Q-4

d)  $P_{rot} = 1518 \text{ W}$

Find airgap power, rotor copper loss, internal mechanical power, net output power, efficiency if the rotor is rotating at 712.5 rpm



$$I = \frac{380/\sqrt{3}}{\sqrt{6^2 + 1.5^2}} = 35.47 \text{ A}$$

$$P_{gap} = 3 I^2 \cdot \frac{r_2}{s} = 3 \cdot (35.47)^2 \cdot 6 = 22.65 \text{ kW}$$

$$P_{cur} = 3 I^2 \cdot r_2 = 3 \cdot (35.47)^2 \cdot 0.3 = 1.13 \text{ kW}$$

$$P_{mech} = P_{gap} - P_{cur} = 21.52 \text{ kW}$$

$$P_{out} = P_{mech} - P_{loss} = \underline{\underline{20 \text{ kW}}}$$

$$\text{Efficiency} = \frac{P_{out}}{P_{in}} = \frac{20 \text{ kW}}{22.65 \text{ kW}} = \underline{\underline{88.3\%}}$$